

# **Cultural Resource Assessment Survey**

SR 9/I-95 @ SR 842/Broward Boulevard (Broward Boulevard from West of SW 24<sup>th</sup> Avenue to East of NW/SW 18<sup>th</sup> Avenue)

Project Development & Environment (PD&E) Study

**Efficient Transportation Decision Making (ETDM) No.: 14226** 

Broward County, Florida Financial Project ID Number: 435513-1-22-02

Prepared for: Florida Department of Transportation, District Four 3400 West Commercial Boulevard Fort Lauderdale, FL 33309

October 2017

The environmental review, consultation, and other actions required by applicable federal environmental laws for this project are being or have been carried out by FDOT pursuant to 23 U.S.C. §327 and a Memorandum of Understanding dated December 14, 2016 and executed by FHWA and FDOT.



# **Executive Summary**

The Florida Department of Transportation (FDOT), District Four, is currently conducting a Project Development and Environment (PD&E) Study that is evaluating potential improvements to the SR-9/I-95 and SR-842/Broward Boulevard (Blvd.) Interchange in the City of Fort Lauderdale, Broward County, Florida. The primary purpose of this study is to develop and evaluate design concepts to improve traffic flow to and from I-95 and along Broward Blvd., connectivity between the 95 Express Lanes and Broward Blvd., and intermodal connectivity. The primary need for this project is to enhance system linkage and modal interrelationships at the I-95/Broward Blvd. interchange. The objective of this cultural resource assessment survey (CRAS) was to identify cultural resources and assess their eligibility for listing in the National Register of Historic Places (National Register) according to the criteria set forth in 36 CFR Section 60.4.

This assessment complies with Section 106 of the National Historic Preservation Act (NHPA) of 1966 (Public Law 89-665, as amended), as implemented by 36 CFR 800 -- Protection of Historic Properties (incorporating amendments effective August 5, 2004); Stipulation VII of the Programmatic Agreement among the Federal Highway Administration (FHWA), the Advisory Council on Historic Preservation (ACHP), the Florida Division of Historical Resources (FDHR), the State Historic Preservation Officer (SHPO), and the FDOT Regarding Implementation of the Federal-Aid Highway Program in Florida (Section 106 Programmatic Agreement, effective March 2016, amended June 7, 2017); Section 102 of the National Environmental Policy Act (NEPA) of 1969, as amended (42 USC 4321 et seq.), as implemented by the regulations of the Council on Environmental Quality (CEQ) (40 CFR Parts 1500-1508); Section 4(f) of the Department of Transportation Act of 1966, as amended (49 USC 303 and 23 USC 138); the revised Chapter 267, Florida Statutes (F.S.); and the standards embodied in the FDHR's Cultural Resource Management Standards and Operational Manual (February 2003), and Chapter 1A-46 (Archaeological and Historical Report Standards and Guidelines), Florida Administrative Code. In addition, this report was prepared in conformity with standards set forth in Part 2, Chapter 8 (Archaeological and Historical Resources) of the FDOT Project Development and Environment Manual (effective June 14, 2017). All work also conforms to professional guidelines set forth in the Secretary of Interior's Standards and Guidelines for Archaeology and Historic Preservation (48 FR 44716, as amended and annotated).

Principal Investigators meet the Secretary of the Interior's Professional Qualification Standards (48 FR 44716) for archaeology, history, architecture, architectural history, or historic architecture. Archaeological investigations were conducted under the direction of James P. Pepe, M.A., RPA. Historic resource investigations were conducted under the direction of Amy Groover Streelman, M.H.P.

No newly or previously recorded archaeological sites were identified within the archaeological area of potential effect (APE). Background research and a reconnaissance survey determined that the APE has a low probability for archaeological sites. Subsurface testing was not feasible within the archaeological APE due to the presence of existing pavement, sidewalks, landscaping, berms, and buried utilities.



FPID: 435513-1-22-02

The CRAS identified a total of 52 historic resources within the historic APE. The identified historic resources include one cemetery (North Woodlawn Cemetery–8BD4879), two resource groups (Seaboard Air Line [CSX] Railroad–8BD4649 and the Salvation Army Complex–8BD6346), and 49 buildings (8BD1452 and 8BD6298–8BD6344). Four of the historic resources were previously recorded (8BD1452, 8BD3414, 8BD4649, and 8BD4879), and 48 are newly recorded (8BD6298–8BD6344 and 8BD6347).

Three historic resources, Seaboard Airline Railroad Station at 200 SW 21st Terrace (8BD1452), Seaboard Air Line (CSX) Railroad (8BD4649), and North Woodlawn Cemetery (8BD4879), were previously determined National Register—eligible by the SHPO. The Seaboard Airline Railroad Station (8BD1452) was determined eligible for the National Register in 1999. The portion of the Seaboard Air Line (CSX) Railroad (8BD4649) within the current APE was previously documented and found National Register—eligible as a result of the *CRAS* of the *SR* 9/I-95 PD&E Study from Stirling Road to North of Oakland Park Boulevard, conducted by Janus Research in 2013. North Woodlawn Cemetery (8BD4879) was also determined National Register—eligible by the SHPO as a result of the 2013 CRAS. The cemetery has already passed the state review board and is currently being reviewed for listing in the National Register by the national review board as of the time of this report. The field survey conducted as part of the current CRAS found that no notable alterations have taken place to any of these three significant historic resources since the time of their previous evaluations. Therefore, all three remain eligible for inclusion in the National Register.

All other historic resources located within the current APE are considered individually ineligible for inclusion in the National Register. Almost all the newly recorded historic buildings are representative of common postwar constructed architecture that does not possess sufficient significance for individual listing in the National Register. Many of these buildings also exhibit exterior modifications that compromise their historic integrity. The majority of the buildings are Masonry Vernacular in style, with few notable architectural features. The fieldwork found that the neighborhoods within the APE also contain a large number of demolitions and vacant lots, non-historic infill, and substantial alternations on many of the historic homes that do remain. Therefore, there is no potential for a National Register historic district anywhere within the current project APE.

All newly identified historic resources received Florida Master Site File (FMSF) forms. FMSF forms were not updated for the three National Register–eligible resources, as their physical characteristics and eligibility status remains unchanged. The FMSF form was updated for the previously recorded house located at 2015 NW 3<sup>rd</sup> Court (8BD3414), and this resource is still considered ineligible for the National Register. The previous forms for the three National Register–eligible resources, as well as all of the newly completed FMSF forms, are contained in **Appendix A**.



FPID: 435513-1-22-02

# **Contents**

Exe	cutive \$	Summary	i
Con	itents		iii
Li	st of A	opendices	v
Li	st of Ta	ables	vi
Li	st of Fi	gures	vi
Abb	reviatio	ons	ix
1.0	Intr	oduction	1
2.0	Pro	ject Summary	4
2.	.1 [	Description of Existing Facilities	4
2.	.2 [	Description of the Proposed Action	5
2.	.3 F	Purpose and Need	7
	2.3.1	System Linkage	7
	2.3.2	Modal Interrelationships	7
	2.3.3	Capacity	8
	2.3.4	Safety	8
	2.3.5	Transportation Demand	8
	2.3.6	Social Demands and Economic Development	8
	2.3.7	Emergency Evacuation	9
2.	.4 F	Proposed Improvements	9
	2.4.1	Mainline I-95 Build Alternative	9
	2.4.2	Broward Boulevard Interchange Build Alternatives	10
	2.4.3	Park-and-Ride Lot Build Alternatives	12
3.0	Pro	ject History	14
4.0	4.0 Related Active Projects within the Study Area		
5.0	Are	a of Potential Effect	16
6.0	Enν	vironmental Setting	21



FPID: 435513-1-22-02

6.1	Paleo-Environment and Macro-Vegetational Change	21
6.2	Regional Environment	22
6.3	Physical Environment of the Project Area	22
7.0	Precontact Overview	25
7.1	Paleoindian Period (12,000-7,500 BC)	25
7.2	Archaic Period (7,500-500 BC)	26
7.	.2.1 Early Archaic Period (7,500-5,000 BC)	26
7.	.2.2 Middle Archaic Period (5,000-3,000 BC)	27
7.	.2.3 Late Archaic Period (3,000-500 BC)	28
7.3	Formative Period (500 BC-AD 1513)	30
7.	.3.1 Glades Culture	32
8.0	Historical Overview	34
8.1	European Contact and Colonial Period (ca. 1513-1821)	34
8.2	The Territorial and Statehood Period (1821-1860)	35
8.3	Civil War and Post War Period (1860-1898)	36
8.4	Spanish-American War Period/Turn-of-the-Century (1898-1916)	40
8.5	World War I and Aftermath Period (1917-1920)	41
8.6	Florida Boom Period (1920-1930)	41
8.7	Depression and New Deal Period (1930-1940)	43
8.8	World War II and the Post War Period (1940-1950)	44
8.9	Modern Period (1950-Present)	45
9.0	Florida Master Site File Search and Literature Review	51
9.1	Previously Conducted Cultural Resource Surveys	51
9.2	Previously Recorded Archaeological Sites	53
9.3	Previously Recorded Historic Resources	55
9.4	Potential Historic Resources	55
9.5	Summary of ETDM Comments	56
10.0	Project Research Design and Site Location Model	57



10.1	1 Precontact Archaeological Site Location Model	57
10.2	2 Historic Archaeological Site Location Model	58
11.0	Methods	59
11.1	1 Archaeological Field Methods	59
11.2	2 Historic Resources Field Methods	59
11.3	Local informants and Certified Local Government Coordination	60
12.0	Results	61
12.1	1 Archaeological Results	61
12.2	2 Historic Resources Survey Results	63
12	2.2.1 Historic Resources Determined Individually National Register–eligible	73
12	2.2.2 Historic Resources Considered Individually National Register–ineligible	76
13.0	Conclusions	114
13.1	1 Unanticipated Finds	114
13.2	2 Curation	114
14.0	References	115

# **List of Appendices**

Appendix A | Florida Master Site File Forms

Appendix B | SHPO Letters for FMSF Survey Nos. 19752 and 20623

Appendix C | Field Conditions

Appendix D | Survey Log



# **List of Tables**

Table 1   Detailed Soil Types within the Archaeological APE	23
Table 2   Glades Cultural Sequence	33
Table 3   Land Apportionment in the Project Area as Recorded in the Tract Book Records	39
Table 4   Previous Cultural Resource Surveys within or adjacent to the Project Area	52
Table 5   Previously Recorded Archaeological Sites within One Mile of the Archaeological APE	53
Table 6   Previous Recorded Historic Resources within the Historic Resources APE	55
Table 7   Identified Historic Resources within the Historic APE	64
List of Figures	
Figure 1   Study Limits	3
Figure 2   Existing Park-and-Ride Conditions	6
Figure 3a   Project APE (Map 1 of 4)	17
Figure 3b   Project APE (Map 2 of 4)	18
Figure 3c   Project APE (Map 3 of 4)	19
Figure 3d   Project APE (Map 4 of 4)	20
Figure 4   Glades Cultural Region	31
Figure 5   1949 Aerial Photograph showing a portion of the Project APE	46
Figure 6   1958 Aerial Photograph showing a portion of the Project APE	47
Figure 7   1968 Aerial Photograph showing a portion of the Project APE	48
Figure 8   1973 Aerial Photograph showing a portion of the Project APE	49
Figure 9   Previously Recorded Archaeological Sites within One Mile and Archaeological Significant Zones	54
Figure 10   Landscaped Berm East Side of I-95 Along NW 21st Avenue, Facing Southwest	61
Figure 11   Utilities Along Broward Boulevard at NW 18 <sup>th</sup> Avenue, Facing East	62
Figure 12   Standing Water within I-95 ROW at Davie Boulevard, Facing South	62
Figure 13a   Identified Historic Resources (Overview Map)	68
Figure 13b   Identified Historic Resources (Map 1 of 4)	69
Figure 13c   Identified Historic Resources (Map 2 of 4)	70
Figure 13d   Identified Historic Resources (Map 3 of 4)	71
Figure 13e   Identified Historic Resources (Map 4 of 4)	72
Figure 14   Seaboard Airline Railroad Station, located at 200 SW 21st Terrace (8BD1452), facing Southeast	73
Figure 15   Seaboard Air Line (CSX) Railroad (8BD4649), as seen from Broward Boulevard overpass, facing	l
North	74
Figure 16   North Woodlawn Cemetery (8BD4879), facing West toward I-95	75



FPID: 435513-1-22-02

Figure 17   1958 aerial of Salvation Army Complex (8BD6347)	77
Figure 18   1968 aerial of Salvation Army Complex (8BD6347)	78
Figure 19   1988 aerial of Salvation Army Complex (8BD6347)	79
Figure 20   Current aerial of Salvation Army Complex (8BD6347), property boundaries in red	80
Figure 21   Salvation Army Complex (8BD6347), Warehouse 1, c. 1957, looking North	81
Figure 22   Salvation Army Complex (8BD6347), Warehouse 2, c. 1967, looking Northwest	82
Figure 23   Salvation Army Complex (8BD6347), Adult Rehabilitation Center, c. 1967, looking Northeast	83
Figure 24   Salvation Army Complex (8BD6347), Warehouse 4, c. 1985, looking West	85
Figure 25   Salvation Army Complex (8BD6347), Office 1, c. 1978, looking Northwest	86
Figure 26   Salvation Army Complex (8BD6347), Office 2, c. 1985, looking West	87
Figure 27   Salvation Army Complex (8BD6347), Super Store, c. 2000, looking Northeast	88
Figure 28   2015 NW 3 <sup>rd</sup> Court (8BD3414), c. 1951, facing North	89
Figure 29   1920–1932 NW 9 <sup>th</sup> Street (8BD6298), c. 1958, facing Southeast	90
Figure 30   808 NW 20 <sup>th</sup> Avenue (8BD6299), c. 1949, facing Northwest	90
Figure 31   729 NW 20 <sup>th</sup> Avenue (8BD6300), c. 1960, facing Southwest	91
Figure 32   632 NW 21st Avenue (8BD6301), c. 1952, facing Southwest	91
Figure 33   616 NW 22 <sup>nd</sup> Road (8BD6302), c. 1960, facing East	92
Figure 34   614 NW 22 <sup>nd</sup> Road (8BD6303), c. 1954, facing South	92
Figure 35   524 NW 21st Terrace (8BD6304), c. 1959, facing Southeast	93
Figure 36   516 NW 21st Terrace (8BD6305), c. 1963, facing Southeast	93
Figure 37   448 NW 21st Terrace (8BD6306), c. 1954, facing Southeast	94
Figure 38   444 NW 21st Terrace (8BD6307), c. 1956, facing Southeast	94
Figure 39   442 NW 21st Terrace (8BD6308), c. 1953, facing Northeast	95
Figure 40   428 NW 21st Terrace (8BD6309), c. 1955, facing Southeast	95
Figure 41   424 NW 21st Terrace (8BD6310), c. 1964, facing Southeast	96
Figure 42   420 NW 21st Terrace (8BD6311), c. 1962, facing Southeast	96
Figure 43   416 NW 21st Terrace (8BD6312), c. 1962, facing Northeast	97
Figure 44   412 NW 21st Terrace (8BD6313), c. 1962, facing Northeast	97
Figure 45   536 NW 21st Avenue (8BD6314), c. 1950, facing Northeast	98
Figure 46   532 NW 21st Avenue (8BD6315), c. 1950, facing Northeast	98
Figure 47   528 NW 21st Avenue (8BD6316), c. 1950, facing Southeast	99
Figure 48   524 NW 21 <sup>st</sup> Avenue (8BD6317), c. 1950, facing Northeast	99
Figure 49   520 NW 21 <sup>st</sup> Avenue (8BD6318), c. 1950, facing Northeast	100
Figure 50   516 NW 21st Avenue (8BD6319), c. 1950, facing Northeast	100
Figure 51   512 NW 21st Avenue (8BD6320), c. 1950, facing Southeast	101



FPID: 435513-1-22-02

## 



FPID: 435513-1-22-02

#### **Abbreviations**

**ACHP** Advisory Council on Historic Preservation

APE Area of Potential Effect

**CEQ** Council on Environmental Quality

CFR Code of Federal Regulation

CRAS Cultural Resource Assessment Survey

**FDEP** Florida Department of Environmental Protection

**FDHR** Florida Department of Historic Resources

**FDOT** Florida Department of Transportation

**FHWA** Federal Highway Administration

**FMSF** Florida Master Site File

**FS** Florida Statutes

FY Fiscal Year

**GLO** General Land Office

GPS Global Positioning System

**HOV** High Occupancy Vehicles

**LOS** Level of Service

**LDCA** Location and Design Concept Acceptance

**LRTP** Long Range Transportation Plan

MPO Metropolitan Planning Organization

NEPA National Environmental Policy Act

NHPA National Historic Preservation Act

PD&E Project Development and Environment Study

**ROW** Right of Way

SFRC South Florida Rail Corridor



ix

FPID: 435513-1-22-02

FPID: 435513-1-22-02 ETDM: 14226

SHPO State Historic Preservation Officer

SIS Strategic Intermodal System

**TIP** Transportation Improvement Program

**USDA** United States Department of Agriculture

**UTM** Universal Transverse Mercator

WAAS Wide Area Augmentation System



#### 1.0 Introduction

The Florida Department of Transportation (FDOT), District Four, is currently conducting a Project Development and Environment (PD&E) Study that is evaluating potential improvements to the SR-9/I-95 and SR-842/Broward Boulevard (Blvd.) Interchange in the City of Fort Lauderdale, Broward County, Florida. The primary purpose of this study is to develop and evaluate design concepts to improve traffic flow to and from I-95 and along Broward Blvd., connectivity between the 95 Express Lanes and Broward Blvd., and intermodal connectivity. The primary need for this project is to enhance system linkage and modal interrelationships at the I-95/Broward Blvd. interchange.

The project area extends along SR-9/I-95 from just south of Dave Blvd. to just south of Sunrise Blvd., a distance of approximately two miles, and along Broward Blvd. from NW 24th Avenue (Ave.) to NW 18th Ave., a distance of approximately one half mile. The study area includes the median ramp connections to the Park-and-Ride lots from I-95 north and south of Broward Blvd. These study limits are shown in **Figure 1**.

A PD&E Study is a process followed by the FDOT to evaluate social, economic and environmental impacts associated with a planned transportation improvement project. FDOT established the PD&E process as the state's procedure for complying with the National Environmental Policy Act (NEPA) of 1969. The goal of a PD&E Study is to obtain Location and Design Concept Acceptance (LDCA) from the project's lead federal agency, the Federal Highway Administration (FHWA) in the case of this study.

The purpose of this CRAS is to identify cultural resources and asses their eligibility for listing in the National Register according to the criteria set forth in 36 CFR Section 60.4.

This assessment complies with Section 106 of the *NHPA of 1966* (Public Law 89-665, as amended), as implemented by 36 CFR 800 -- *Protection of Historic Properties* (incorporating amendments effective August 5, 2004); Stipulation VII of the *Programmatic Agreement among the FHWA, the ACHP, the FDHR, the SHPO, and the FDOT Regarding Implementation of the Federal-Aid Highway Program in Florida* (Section 106 Programmatic Agreement, effective March 2016, amended June 7, 2017); Section 102 of the *NEPA of 1969*, as amended (42 USC 4321 et seq.), as implemented by the regulations of the Council on Environmental Quality (CEQ) (40 CFR Parts 1500–1508); Section 4(f) of the *Department of Transportation Act of 1966*, as amended (49 USC 303 and 23 USC 138); the revised Chapter 267, *F.S.*; and the standards embodied in the FDHR's *Cultural Resource Management Standards and Operational Manual* (February 2003), and Chapter 1A-46 (*Archaeological and Historical Report Standards and Guidelines*), *Florida Administrative Code.* In addition, this report was prepared in conformity with standards set forth in Part 2, Chapter 8 (*Archaeological and Historical Resources*) of the FDOT *Project Development and Environment Manual* (effective June 14, 2017). All work also conforms to professional guidelines set forth in the *Secretary of Interior's Standards and Guidelines for Archaeology and Historic Preservation* (48 FR 44716, as amended and annotated).

Principal investigators meet the Secretary of the Interior's Professional Qualification Standards (48 FR 44716) for archaeology, history, architecture, architectural history, or historic architecture. Archaeological



FPID: 435513-1-22-02


# Cultural Resource Assessment Survey I-95 at Broward Boulevard Interchange PD&E Study

FPID: 435513-1-22-02 ETDM: 14226

investigations were conducted under the direction of James P. Pepe, MA, RPA, and historic resource investigations were conducted under the direction of Amy Groover Streelman, MHP.



Figure 1 | Study Limits





# 2.0 Project Summary

### 2.1 Description of Existing Facilities

The Interchange of I-95 at Broward Blvd. is located in central Broward County in the City of Fort Lauderdale, between the Sunrise Blvd. Interchange (one mile to the north) and the Davie Blvd. Interchange (one mile to the south). The South Florida Rail Corridor (SFRC)/CSX Railroad is adjacent to and runs parallel along the west side of I-95 in this area. The limits for this report extend from just south of Dave Blvd. to just south of Sunrise Blvd. along I-95 and from NW 24th Ave. to NW 18th Ave. along Broward Blvd.

The typical section of I-95 within the study area varies. From the Davie Blvd. interchange to SW 5th Pl. the typical section of I-95 is an eight-lane facility comprised of three General Purpose Lanes in each direction and one Special Use Lane (previously designated for High Occupancy Vehicle (HOV) use and in transition to managed toll lanes) in each direction. From the vicinity of SW 5th Place (Pl.), where the northbound Collector-Distributor (CD) road ramp system merges traffic from I-595 into the General Purpose Lanes, and through to the Sunrise Blvd. interchange, I-95 is a 10-lane facility comprised of four General Purpose Lanes in each direction and one Special Use Lane in each direction. Southbound ingress to I-95 from Broward Blvd. is provided at the western terminal intersection by a single lane access ramp from eastbound Broward Blvd. and a double left turn lane from westbound Broward Blvd. Egress from southbound I-95 to Broward Blvd. is provided by a ramp with a single right turn lane for traffic heading west on Broward Blvd. and a double left turn lane for traffic heading east on Broward Blvd.

Currently, northbound ingress to I-95 from Broward Blvd. is provided by a single lane access ramp from westbound Broward Blvd. at the eastern terminal intersection and a single lane flyover from eastbound Broward Blvd. at the western terminal intersection. Egress to Broward Blvd. from northbound I-95 is provided by a ramp, which is part of the northbound CD road ramp system, that was recently reconstructed to include triple right turn lanes for traffic heading eastbound on Broward Blvd. and double left turn lanes for traffic heading westbound on Broward Blvd. Additional ingress and egress to I-95 is provided through the Park-and-Ride lot. For both directions of travel along I-95 ingress and egress is provided by single lane ramps that cross over the southbound lanes of I-95 and connect with the Special Use Lanes located in the center of I-95.

SR-842/Broward Blvd. is a six-lane urban divided roadway with a raised median within the vicinity of the I-95 Interchange. In its current configuration there are no provisions for bicycle traffic within these limits outside of the general travel lanes. Six foot wide sidewalks are provided on both sides of Broward Blvd. from NW/SW 22<sup>nd</sup> Ave. to NW/SW 18<sup>th</sup> Ave. West of NW/SW 22<sup>nd</sup> Ave. the sidewalk is eight feet in width. It provides the main entry way to the downtown Fort Lauderdale Central Business District from I-95 and the east-west connection between US-1 and SR-817/University Drive in the City of Plantation.

There are a number of transit options on Broward Blvd. that provide direct service and transfer connections along the corridor. These include passenger rails service (Tri-Rail and Amtrak) and bus service (Broward County Transit, Breeze, Sun Trolley, 95 Express Bus, Tri-Rail Shuttle and Tri-Rail NW



FPID: 435513-1-22-02

Community Link). There is a Park-and-Ride lot located within the interchange area. The existing conditions at the Park-and-Ride lot include the provision of 794 parking spaces throughout five parking lots, shown in **Figure 2**. Spaces in Lot 5 are designated for Amtrak and Tri-Rail parking only while the spaces in Lots 1-4 are available for any purpose, including car pools and 95 Express Bus. There are no designated bicycle facilities within the Park-and-Ride lot and minimal sidewalk facilities. Access to the Park-and-Ride lots is provided via Broward Blvd. and I-95. Ingress from eastbound Broward Blvd. is provided via right turn lane at SW 22nd Ave/SW 1st St. Ingress from westbound Broward Blvd. is provided via right turn lanes at NW 22nd Ave. and NW 24th Ave. Egress to westbound Broward Blvd. is provided via the intersections with NW 22nd Ave. and NW 24th Ave., requiring drivers coming from the south to circulate through the northern parking areas. Egress to eastbound Broward Blvd. is provided via SW 22nd Ave/SW 1st St and NW 24th Ave.

Ingress to southbound I-95 is provided on the south side of Broward Blvd. via a ramp that crosses over the southbound General Use Lanes of I-95 and connects to the southbound HOV lane. Ingress to northbound I-95 is provided by a ramp on the north side of Broward Blvd., accessed from the northern parking area, which crosses over the southbound General Use Lanes of I-95 and connects to the northbound HOV lane. Egress from both northbound and southbound I-95 are provided in a similar manner with northbound vehicles exiting on the south side of Broward Blvd. and merging into SW 21st Terrace and southbound vehicles existing on the north side of Broward Blvd. with connections to NW 22nd Ave. and SW 22nd Ave./SW 1st St. provided via access roads within the parking areas.

Broward Blvd.'s elevation over I-95 creates vertical access challenges for transit users, bicyclists and pedestrians looking to connect with the transit services available in the Park-and-Ride and Transit Station area northwest and southwest of the interchange. As a result of these challenges and due to its location as the entry way to downtown Fort Lauderdale, this interchange has been the subject of a variety of studies including the City of Fort Lauderdale's Gateway Vision and FDOT's Broward Boulevard Transit Corridor Study. Each of these studies has evaluated these challenges and recommended improvements to the west side of the interchange where connections to Tri-Rail and the 95 Express Bus services are offered. These prior studies and recommendations will be considered as the alternatives are developed during this study.


## 2.2 Description of the Proposed Action

This project proposes improvements to the I-95/Broward Blvd. Interchange complementing the surrounding multimodal facilities. The proposed interchange improvements will be compatible with the proposed 95 Express Phase 3 program which will introduce two tolled, express lanes each direction, in place of the existing HOV lanes, from Stirling Road in Broward County to Linton Blvd. in Palm Beach County. 95 Express Phase 3A, which extends from Broward Blvd. to south of SW 10th Street (St.), and includes the limits of the proposed interchange improvements, began construction in mid-2016. Functionality of the I-95 median ramps and Park-and-Ride road network is to be improved for the intermodal services within the interchange area.



FPID: 435513-1-22-02

Figure 2 | Existing Park-and-Ride Conditions





## 2.3 Purpose and Need

The primary purpose of this study is to develop and evaluate design concepts to improve traffic flow to and from I-95 and along Broward Blvd., connectivity between the 95 Express Lanes and Broward Blvd., and intermodal connectivity. Improved connections between the 95 Express Lanes and Broward Blvd., as well as the surrounding intermodal facilities, are desired. The primary need for this project is to enhance system linkage and modal interrelationships at the I-95/Broward Blvd. interchange.

Secondary considerations for the purpose and need are further described in the following sections that include Capacity, Safety, Transportation Demand, Social Demands, Economic Development, and Emergency Evacuation.

### 2.3.1 System Linkage

Broward Blvd. is a state road (SR 842) that provides the main entry way to the downtown Fort Lauderdale Central Business District from I-95 and the east-west connection between US-1 and SR 817/University Drive in the City of Plantation. Broward Blvd. continues west toward SR 823/Flamingo Road as a county road. The section of Broward Blvd. from I-95 to NE 3rd Ave. is part of the state's Strategic Intermodal System (SIS), which consists of high-priority transportation facilities and services of statewide and interregional significance. I-95 north and south of Broward Blvd. is also a SIS facility and serves as the primary north-south interstate facility that links all major cities along the Atlantic Seaboard and is one of the most important transportation systems in southeast Florida. These SIS facilities are critical to the movement of people and goods in Florida, and their function is considered to be vital to Florida's economic competitiveness.

#### 2.3.2 Modal Interrelationships

Transit services along Broward Blvd. are currently experiencing recurring congestion that reduces vehicle speeds, increases operating costs, and makes scheduling of buses from a system level challenging. There are a number of transit options on Broward Blvd. that provide direct service and transfer connections along the corridor. These include passenger rail service (Tri-Rail and Amtrak) and bus service (Broward County Transit, Breeze, Sun Trolley, 95 Express Bus, Tri-Rail Shuttle and Tri-Rail NW Community Link). The operation of these services is vital to the mobility of the entire corridor.

The desired geometric and operational improvements to the Broward Blvd. interchange and surrounding transit facilities will reduce bus travel times, improve intermodal connectivity, and improve access to bus stops and transfers. 95 Express Bus service is desired to access Broward Blvd. more effectively from the 95 Express Lanes and the existing Park-and-Ride lots. Functionality of the I-95 median ramps and Park-and-Ride road network is to be improved for the intermodal services within the interchange area.



FPID: 435513-1-22-02

#### 2.3.3 Capacity

I-95 within the project limits currently operates at Level of Service (LOS) F. Broward Blvd. within the project limits also operates at LOS F. Without improvements, the driving conditions will continue to operate well below acceptable LOS standards into the future. The 95 Express Phase 3 improvements will help improve the mainline I-95 corridor LOS by adding one travel lane in each direction in the form of an Express Lane, managing congestion along I-95. The improvements proposed as part of the interchange project will be developed to complement the 95 Express Lanes improvements by enhancing existing connectivity within the Park-and-Ride lots, improving existing I-95/Broward Blvd. terminal intersections, and providing improved Express Lane access to Broward Blvd..

#### 2.3.4 Safety

The comprehensive improvements to the interchange and surrounding transit facilities will improve the interaction between the different modes of transportation in the vicinity. The improvements are to include safe connections for pedestrians using transit services, circulation of traffic within the Park-and-Ride lot network, and access between the Express Lanes and Broward Blvd.. Additionally, the capacity improvements will aid in reducing the number of crashes within the project limits.

#### 2.3.5 Transportation Demand

The Broward Blvd. Interchange Project PD&E Study is included in the Broward Metropolitan Planning Organization's (MPO) Transportation Improvement Program (TIP) for Fiscal Years (FY) 2015-2019 and the FDOT Work Program FY 2015-2019.

The Broward MPO's 2035 Long Range Transportation Plan (LRTP) included improvements to all I-95 interchanges in Broward County under Illustrative Roadway Projects. Illustrative projects are those that cannot be included in the Cost Feasible Plan due to financial constraints but would be included in a future approved TIP. The MPO's 2040 LRTP, Commitment 2040, adopted by reference the Strategic Intermodal System 2040 Cost Feasible Plan, which includes modifications to the I-95/Broward Blvd. interchange in the first five years.

#### 2.3.6 Social Demands and Economic Development

Social and economic demands on the I-95 corridor will continue to increase as population and employment increase. The Broward MPO 2035 LRTP predicted that the population would grow from 1.7 million in 2005 to 2.3 million by 2035, an increase of 29 percent. Jobs were predicted to increase from 0.7 to 1 million during the same time period, an increase of 37 percent. Commitment 2040 revised the growth projections to 1.9 million persons and 0.8 million jobs by 2040. These numbers reflect growth rates of 13.4 percent for population and 10.4 percent for jobs by 2040. These numbers, however, only account for the projected growth in Broward County and do not reflect the number of commuters from adjacent areas who may use this interchange to access jobs.



FPID: 435513-1-22-02

#### 2.3.7 Emergency Evacuation

The project is anticipated to improve emergency evacuation capabilities by enhancing connectivity and accessibility to major arterials designated on the state evacuation route. I-95 serves as part of the emergency evacuation route network designated by the Florida Division of Emergency Management and Broward County. Broward Blvd. moves traffic from the east and west to I-95. I-95 is critical in facilitating traffic during emergency evacuation periods as it connects to other major arterials and highways of the state evacuation route network (i.e., I-595 and the Florida's Turnpike).

## 2.4 Proposed Improvements

The proposed improvements for the I-95 at Broward Blvd. Interchange consist of three elements:

- 1. Improvements to the mainline of I-95 to accommodate ingress and egress ramps for 95 Express and the existing Broward Blvd. Interchange ramps,
- 2. Three alternatives for the Broward Blvd. east and west terminal intersections to improve interchange operations, and
- 3. Conceptual plans for the Park-and-Ride lot to improve circulation and conditions for all users.

The mainline improvements are consistent across each of the three interchange alternatives. Each of the Park-and-Ride concepts was designed to work with the proposed mainline and interchange improvements.

#### 2.4.1 Mainline I-95 Build Alternative

The proposed improvements to the mainline account for the programmed implementation of 95 Express, which adds one additional Special Use Lane in each direction and modifies the use of these lanes to include managed toll lanes. The resulting typical section becomes a 12-lane facility comprised of four General Purpose Lanes and two Special Use Lanes in each direction. The ingress and egress ramps connecting to Broward Blvd. are proposed to be modified in a similar manner for each of the Interchange Build Alternatives. For northbound ingress to I-95 there are no proposed modifications to the existing single lane ramps that provide access from westbound and eastbound Broward Blvd. For northbound egress from I-95, the existing ramp is proposed to be widened to allow for additional storage, however the turn lane configuration remains the same with dual left and triple right turn lanes. Southbound ingress to I-95 differs based on the Interchange Build Alternative and is addressed in those sections that follow. Southbound egress from I-95 is proposed to be widened for each of the Interchange Build Alternatives to accommodate one additional turn lane for left turns and two additional turn lanes for right turns, resulting in triple left and triple right turn lanes.

The primary proposed improvements for the mainline are for the new ramps providing ingress and egress to the 95 Express lanes. In the southbound direction the proposed improvements include a braided ramp over the southbound I-95 General Use Lanes with a connection to the west terminal intersection of the Broward Blvd. service interchange to provide egress from 95 Express near NW 6th St./Sistrunk Blvd. This elevated braided ramp provides access to eastbound and westbound Broward Blvd. for southbound



FPID: 435513-1-22-02

95 Express traffic without requiring drivers to weave through the General Use Lanes. Similarly, ingress from the Broward Blvd. service interchange to the southbound 95 Express lanes is proposed through a braided ramp over the southbound I-95 General Use Lanes, just south of Broward Blvd. This elevated braided ramp provides direct access between Broward Blvd. and the southbound Express Lanes, using the existing west terminal intersection service interchange, for direct access to southbound 95 Express without requiring drivers to weave through the General Use Lanes.

For the northbound direction, egress from 95 Express near Davie Blvd. is proposed through the use of a braided ramp over the northbound I-95 General Use Lanes with a connection to the northbound CD road ramp system that terminates at the east terminal intersection of the Broward Blvd. service interchange. This elevated braided ramp provides access to eastbound and westbound Broward Blvd. for northbound 95 Express traffic without requiring drivers to weave through the General Use Lanes. Ingress from the Broward Blvd. service interchange to the northbound 95 Express lanes is proposed through a braided ramp over the northbound I-95 General Use Lanes in the vicinity of NW 6th St./Sistrunk Blvd. This elevated braided ramp provides direct access between Broward Blvd. and the northbound Express Lanes, using the existing eastbound to northbound flyover, and westbound to northbound ramp, for access to northbound 95 Express without requiring drivers to weave through the General Use Lanes.

#### 2.4.1.1 Typical Section

Graphic to be provided.

#### 2.4.2 Broward Boulevard Interchange Build Alternatives

The proposed improvements to Broward Blvd. include the replacement of the bridge that spans I-95 and the South Florida Rail Corridor with a wider and higher bridge span, the provision of three through lanes of traffic with six foot wide sidewalks and seven foot wide bicycle lanes in each direction, and three interchange alternatives, which are further described below. The replacement of this bridge span is common to all three interchange alternatives and is being proposed to accommodate necessary turn lanes at the intersections as well as to provide an envelope for a future premium transit stop with connectivity between East-West service along Broward Blvd., and the many multi-modal transit service provided in the Broward Blvd. P&R Lot/Transit Station on the north and south sides of Broward Blvd. In each of the interchange alternatives the service interchange ramps are proposed for reconstruction to accommodate the wider and higher proposed bridge span. Most of the ingress and egress ramps are also proposed to include additional lanes to accommodate the forecasted 2040 year traffic.

The proposed interchange alternatives include Tight Diamond, Displaced Left Turn, and Modified Displaced Left Turn. Each of these alternatives is described below. For each of these alternatives the northbound ingress to I-95 remains as a single lane access ramp.

#### 2.4.2.1 Interchange Build Alternative 1 – Tight Diamond

The Tight Diamond Interchange is a compressed version of the diamond interchange designed to accommodate right-of-way constraints. The interchange consists of two closely spaced signalized intersections at the crossing of the ramp terminals. The key operational aspect of a Tight Diamond



FPID: 435513-1-22-02

Interchange is signal coordination to ensure efficient progression of traffic and minimum storage of vehicles between the terminals. The existing interchange is a Tight Diamond Interchange and this alternative will improve the existing operation through the addition of turn lanes at the ramp terminal locations and optimization of the intersection signal timings. Specifically, one additional left turn lane is proposed for southbound ingress from Broward Blvd. to I-95 resulting in triple left turn lanes for traffic traveling westbound. An additional right turn lane is also proposed resulting in double right turn lanes for eastbound traffic on Broward Blvd. There are no proposed improvements to the northbound ingress ramps from Broward Blvd.

2.4.2.1.1 Typical Section Graphic to be provided.

#### 2.4.2.2 Interchange Build Alternative 2 – Displaced Left

The Displaced Left Turn Interchange is also known as the Continuous Flow Interchange. The main geometric feature of the Displaced Left Turn Interchange is the removal of left turn movements from the main intersection to an upstream signalized location to reduce the number of traffic signal phases and conflict points. For this alternative the westbound left turn movements are displaced at the east ramp terminal intersection to a new roadway that is south and runs parallel to the eastbound through lanes where it combines with the displaced left turn lanes from the northbound ramp. This configuration enables the westbound left turn lanes to execute the left turn simultaneously with the westbound through traffic and under a different signal phase also transition the traffic from the northbound ramp on to the westbound at the west ramp terminal intersection. This proposed alternative increases the number of right turn lanes for the southbound ingress to I-95 from eastbound Broward Blvd., resulting in dual right turn lanes. Although displaced as previously described, the left turn lanes for southbound ingress remain as dual left turn lanes as is currently provided.

2.4.2.2.1 Typical Section *Graphic to be provided.* 

#### 2.4.2.3 Interchange Build Alternative 3 – Modified Displaced Left

The Modified Displaced Left Turn Interchange alternative eliminates the displacement of the westbound left turn movements at the east ramp terminal intersection and maintains the displacement of the northbound ramp onto the new roadway that is on the south and runs parallel to the eastbound through lanes. The northbound ramp left turn traffic is then transitioned on to the westbound at the west ramp terminal intersection. Similar to the Displaced Left alternative, dual right turn lanes are provided for southbound ingress to I-95 from eastbound Broward Blvd. Ingress from westbound Broward Blvd. retains the existing dual left turn lanes as previously described.

**2.4.2.3.1 Typical Section** *Graphic to be provided.* 



FPID: 435513-1-22-02

#### 2.4.3 Park-and-Ride Lot Build Alternatives

Three concept alternatives were developed to address vehicular circulation through the northern lots, also referred to as Lots 1, 2, and 3 in the figure provided. Each of the alternatives includes a realignment of Access Road to provide for a straighter geometry and adjusts the parking areas and other roadway connections as necessary. Specifically, the parking spaces provided in Lot 3 will be shifted west and accommodated in the area currently identified as Lots 1 and 2. Each alternative also provides additional sidewalk throughout the northern parking areas, identifies crosswalks, and proposes a canopy for the sidewalks connecting the train station to the newly created area underneath the expanded Broward Blvd. bridge structure. The primary difference between these alternatives is the proposed location of the 95 Express Bus stops and the use of the newly created space underneath the expanded Broward Blvd. bridge structure. These alternatives are concepts and the details of the improvements will be determined as part of the Design phase of the project.

#### 2.4.3.1 Park-and-Ride Alternative 1

The 95 Express Bus stop in the northern parking area is retained in its current location and a Kiss-and-Ride facility is provided on the opposite side of the existing bus stop. The 95 Express Bus stops currently located on Access Road just south of the Broward Blvd. bridge structure are relocated north to allow for passenger loading underneath the expanded bridge structure. A traffic signal is proposed at the intersection of Access Road with the roadway that provides ingress and egress from I-95 on the north side of the parking area to accommodate left turns by transit vehicles. The additional space provided underneath the bridge structure is not identified for any specific use aside from being reserved to accommodate an elevator and other access features to allow for a transfer between the possible future transit station in the median of Broward Blvd. and this lower level.

2.4.3.1.1 Park-and-Ride Alternative 1 Concept Plan Graphic to be provided.

#### 2.4.3.2 Park-and-Ride Alternative 2

In this alternative the 95 Express Bus stop in the northern parking area is shifted south and a Kiss-and-Ride facility is provided on the east-west access road that becomes the I-95 ingress and egress ramps. At the terminus of the I-95 ramps in the northern lot a roundabout is proposed in lieu of the existing three-sided interchange. The area underneath the expanded bridge structure is proposed to be used for the 95 Express Bus stops currently located just south of the bridge structure. This concept provides for a more formal transit boarding and alighting area.

2.4.3.2.1 Park-and-Ride Alternative 2 Concept Plan Graphic to be provided.

#### 2.4.3.3 Park-and-Ride Alternative 3

This alternative builds on the previous Alternative 2 with the addition of a roundabout to access the formal transit station area created underneath the expanded bridge structure.



FPID: 435513-1-22-02

FPID: 435513-1-22-02 ETDM: 14226

2.4.3.3.1 Park-and-Ride Alternative 3 Concept Plan



# 3.0 Project History

The Broward Blvd. interchange has been the subject of several studies over recent years. In 2010, the I-95 Broward County Interchange Assessment Report identified the need to improve the southbound exit ramp. In 2013, FDOT completed a Concept Development Report for the interchange that was initiated by complaints the Department received about excessive delays being experienced by drivers. This Concept Development Report recommended reconstruction of the I-95 northbound exit ramp to provide three exclusive right-turn lanes and widening of the I-95 southbound exit ramp to two lanes. The alternatives will also consider the need to accommodate the 95 Express Lanes that are currently in the construction phase of the project development process.



FPID: 435513-1-22-02

# 4.0 Related Active Projects within the Study Area

As previously noted, the 95 Express Phase 3A project is currently under construction in the study area. FDOT's Five-Year Work Program also shows Urban Corridor Improvements for Broward Blvd. from Pine Island Road to I-95 currently under construction.



FPID: 435513-1-22-02

## 5.0 Area of Potential Effect

The Area of Potential Effect (APE) is determined by evaluating the type of improvements under consideration and the possible effects these improvements could have on cultural resources. Also to be considered are the locations and extent of any possible improvements.

The archaeological APE focuses upon identifying and evaluating resources within the geographic limits of the proposed improvements and its associated ground disturbing activities within the existing and proposed right of way (ROW). The archaeological APE, therefore, is confined to the footprint of the proposed project improvements (**Figure 3a–d**).

The historic resources APE is defined as the area within which potential effects for the improvements could be observed. The APE for historic resources where the improvements are within existing sound walls is limited to the existing ROW. The historic resources APE for improvements at grade is the footprint of the improvements and adjacent parcels within 150 feet. The historic resources APE is 250 feet from the footprint of improvements that include proposed elevated ramps. (**Figure 3a–d**).



FPID: 435513-1-22-02

Figure 3a | Project APE (Map 1 of 4)






Figure 3b | Project APE (Map 2 of 4)






Figure 3c | Project APE (Map 3 of 4)







Figure 3d | Project APE (Map 4 of 4)





# 6.0 Environmental Setting

Environmental and ecological factors through time have had a direct influence on the choice of occupation sites by precontact populations and early historic settlers. Therefore, factors such as geologic, hydrologic, and meteorological processes that may have affected the project APE and its biotic resources are important elements in the formulation of a settlement/subsistence model for precontact and early historic peoples.

## 6.1 Paleo-Environment and Macro-Vegetational Change

Although a comprehensive paleoenvironmental reconstruction is beyond the scope of this report, a brief description of the large-scale climatic and hydrologic conditions that have occurred since 31,050 BC is provided. This description is drawn primarily from the work of W. A. Watts (1969, 1971, 1975, and 1980) and Watts and Hansen (1988). Carbone (1983) has promoted the reconstruction of local paleoenvironments, or small-scale environmental change, with an effort towards developing regional paleoenvironmental mosaic landscapes. Vegetation and animals (including humans) either adapt to local areas (micro-habitats) or move to preferred locations. The descriptions given here provide some indication of the ecological context of precontact groups at different times, in particular the environmental limitations. However, these descriptions are general and cannot be used to reconstruct the microhabitats of the project APE.

Since the termination of the Pleistocene Epoch at the end of the Wisconsin glaciation, roughly 11,550 BC, Florida has undergone significant climatic and environmental change. Notable changes in climate and subsequently in flora and fauna required human groups to adapt to their surroundings. These adaptations resulted in cultural changes in their hunting/foraging strategies and seasonal migration patterns. Within the archaeological record, these changes can be observed by differences in settlement patterns, midden composition, refuse disposal patterns, and the kinds of stone tools or pottery made.

The first 5,000 years or so of the Holocene were marked by rapid rises in sea levels. This inhibited the development of estuaries along the Gulf Coast and may have had the same impact on the Atlantic coast (Griffin 1988). However, even though sea levels were rising, they were still considerably lower than present levels. This, combined with low interior water tables, resulted in arid conditions for the interior of southern Florida (Watts 1983; Watts and Hansen 1988). The marshes and swamps for which southern Florida are famous had not yet been formed (Webb 1990).

At about 3050 BC, give or take 1,000 years, sea levels had risen to within a few meters of their current levels (Griffin 1988). Increased rainfall resulted in the formation of Lake Okeechobee, the Everglades, and other modern ecosystems (Watts and Stuiver 1980; Brooks 1984:38; Gleason et al. 1984:311). The relative sea level stability combined with freshwater discharge allowed for the development of coastal estuaries (Widmer 1988). Around 750 BC, the rising sea level had slowed to the point that some modern beach ridges in southern Florida, like Cape Sable, began to form. Increased precipitation in the interior made cypress common in many areas, including the Big Cypress Swamp, and made droughts in the Everglades less common (Griffin 1988). The southern rim of Lake Okeechobee reached its maximum height about this time (Brooks 1984:38). Vegetation reached its present distributional patterning and



FPID: 435513-1-22-02

estuaries were fully formed and supplied by enough freshwater drainage to become highly productive (Widmer 1988; Griffin 1988).

## 6.2 Regional Environment

The project APE is located within the Atlantic Coastal Ridge physiographic region. The Atlantic Coastal Ridge is characterized by low, poorly drained flatlands that represent the shallow, flat bottoms of ancient seas. Features associated with this province include the Atlantic Ocean to the east, the Everglades to the west, and the Southern Slope to the south. Superimposed on this flat terrain are several linear sand ridges that parallel the coast and are remnants of ancient shorelines, dunes, or offshore bars (White 1970:Plate 1-C). Elevation along the Atlantic Coastal Ridge averages approximately 10–15 feet (3–4.5 meters).

Limestone and dolostone dominate the sediments of Broward County. Outcrops of silicified limestone, or chert, which were often sought out by precontact peoples as raw material sources for the manufacture of stone tools, do not occur in this area (Lane et al. 1980). The closest known outcrops lie to the west along the Peace River in the central part of the state (Scott 1978; Upchurch et al. 1982).

Water resources consist of both ground and surface water. The principal groundwater aquifer is the Floridan, which occurs under artesian conditions with slowly permeable clays and sands forming a confining layer that effectively prevents the vertical movement of water from the surficial aquifer to the Floridan aquifer (Lane 1980). Surface sand deposits contain the surficial aquifer, which is recharged through local rainfall. Because of low hydraulic gradients, movement of water within this zone is very slow. Water is discharged from the aquifer through lateral seepage to streams or lakes, evapotranspiration, or movement downward to the Floridan aquifer where sinkhole development has breached the underlying confining layer of clay (Lane 1980; Lane et al. 1980). Major rivers and streams in the vicinity of the project area include the North and South Fork of the New River.

## 6.3 Physical Environment of the Project Area

A review of the General Land Office (GLO) historic plat map (Florida Department of Environmental Protection [FDEP] 1870a) and surveyor's field notes (FDEP 1870b) was conducted to examine past environmental conditions within the vicinity of the archeological APE. The North and South Forks of the New River are illustrated on the plat map. Most of the project area is described as third rate pine in the surveyor's notes. A small creek with second rate low hammocks to the north and south of the creek crossed the project area approximately between what is now SW 10<sup>th</sup> Court and SW 11<sup>th</sup> Street. Near the northern end of the project, between NW 7<sup>th</sup> Street to South of NW 9<sup>th</sup> Street, the area is described as glades.

Aerial photographs from 1947, 1949, 1957, 1958, and 1968 (FDOT, Surveying and Mapping Office 2017; University of Florida, George A. Smathers Libraries 2017) were reviewed to examine land use within the vicinity of the archaeological APE during the 20<sup>th</sup> century. In the 1947 aerial, Broward Boulevard and the Seaboard Air Line Railroad are present. Some streets are laid out to the south of Broward Boulevard and north of the North Fork of the New River, but the area south of the river appears to be mostly undeveloped.



FPID: 435513-1-22-02

A few structures are visible adjacent to the railroad. No hammocks are visible along the river within the project area. Between the river and Broward Boulevard, the project area appears mostly cleared of trees. South of 4th Street, the area appears drier with scattered trees. North of the river, North Woodlawn Cemetery and several structures are visible along the streets. By 1957, residential development had increased dramatically. In the aerial for this year, structures are visible along the streets and residential developments are present to the west of the railroad. The area just to the east of the railroad where I-95 would be constructed appears mostly undeveloped with scattered trees. Development was increasing along Broward Boulevard but many parcels still appear undeveloped. In the 1968 aerial, I-95 is under construction south of SW 5th Street and more structures are visible along Broward Boulevard.

The Soil Survey of Broward County, Florida, Eastern Part (United States Department of Agriculture [USDA] 1984) was reviewed to help determine the predevelopment environment, assess the level of modification, and identify natural features within the project corridor indicative of increased archaeological site potential. The project area is located within the Duette-Urban land-Pomello, Immokalee-Urban land-Pompano, and Immokalee-Urban land soil associations. Much of these areas are covered in urban features. The Duette-Urban land-Pomello associate is found on slightly elevated broad knolls and ridges (USDA 1984:9). Natural vegetation includes slash and sand pine, laurel and scrub oak, saw palmetto, pineland threeawn, and other grasses. The Immokalee-Urban land-Pompano association is found on broad, low ridges interspersed with sloughs and broad flats (USDA 1984:9). Natural vegetation is slash pine, saw palmetto, and grasses. The Immokalee-Urban land association is found on low ridges interspersed with grassy sloughs (USDA 1984: 9–10). Natural vegetation is slash pine, laurel oak, saw palmetto, wax myrtle, pineland threeawn, and other grasses. Drainage characteristics and environmental association for each detailed soil type within the APE are included in **Table 1**. The soils suggest that the majority of the project area has been disturbed by construction activities.

Table 1 | Detailed Soil Types within the Archaeological APE

Drainage Characteristic	Soil Type	Environmental Association
Moderately well drained	Duette-Urban land Complex	Duette soils are found on low ridges and knolls. Most of this area is covered with structures, pavement, and other urban features and natural soils are no longer discernable.
Poorly Drained	Basinger fine sand	Broad sloughs and flats. Natural vegetation is pine, wax myrtle, and grasses.
	Immokalee-Urban land complex	Immokalee sand is found on broad, low ridges. Most of this area is covered with structures, pavement, and other urban features and natural soils are no longer discernable.
	Immokalee, limestone substratum-Urban land complex	Immokalee sand is found on broad, low ridges. Most of this area is covered with structures, pavement, and other urban features and natural soils are no longer discernable.
Not Applicable	Arents-Urban land complex	This area is covered in heterogeneous overburden material that has been used for land leveling. The area is



FPID: 435513-1-22-02

Drainage Characteristic	Soil Type	Environmental Association
		also covered in structures, pavement, and other urban features. Natural soils cannot be identified.
Not Applicable	Udorthents, shaped	These areas consist of a mixture of soil and geologic soil materials that has been shaped and contoured.
	Urban land	This area is covered in structures, pavement, and other urban features. Natural soils cannot be identified.

USDA 1984: 16-19, 24-29, 47-48

The project area is currently grassy roadway ROW with planted trees and landscaping. No natural vegetation remains.



FPID: 435513-1-22-02

## 7.0 Precontact Overview

Native peoples have inhabited Florida for at least 14,000 years. The earliest cultural stages are pan-Florida in extent, while later cultures exhibited unique cultural traits. The following discussion of the precontact time period in the vicinity of the APE is included in order to provide a framework within which the local archaeological record can be understood.

### 7.1 Paleoindian Period (12,000-7,500 BC)

The earliest period of precontact cultural development dates from the time people first arrived in Florida. The greatest density of known Paleoindian sites in Florida is associated with the rivers of northern and north-central Florida where distinctive lanceolate projectile points and bone pins have been found in abundance in and along the Santa Fe, Silver, and Oklawaha Rivers (Dunbar and Waller 1983). The majority of these have been found at shallow fords and river crossings where Native Americans presumably ambushed Pleistocene mammals. The bones of extinct species such as mammoth, mastodon, and sloth are commonly found preserved in the highly mineralized waters of the area's springs and rivers. Despite early claims to the contrary, present evidence strongly supports the contemporaneity of Paleoindians and these extinct mammals.

The climate of Florida during the late Pleistocene was cooler and drier, and the level of the sea was as much as 160 feet (49 meters) lower (Milanich 1994:38–41). Rising sea levels are assumed to have inundated many coastal sites dating to the Paleoindian and Early Archaic periods (e.g., Ruppe 1980; Goodyear and Warren 1972; Goodyear et al. 1980; Dunbar et al. 1988). It is difficult to determine the dependence of Paleoindian groups on estuarine and littoral resources because little is known of these submerged archaeological sites.

The prevailing view of the Paleoindian culture, a view based on the uniformity of the known tool assemblage and the small size of most of the known sites, is that of a nomadic hunting and gathering existence, in which now-extinct Pleistocene megafauna were exploited. Settlement patterns were restricted by availability of fresh water and access to high-quality stone from which the specialized Paleoindian tool assemblages were made. Waller and Dunbar (1977) and Dunbar and Waller (1983), from their studies of the distribution of known Paleoindian sites and artifact occurrences, have shown that most sites of this time period are found near karst sinkholes or spring caverns.

The majority of Paleoindian sites in Florida consist of surface finds. The most widely recognized Paleoindian tool in Florida is the Suwannee point, typically found along the springs and rivers of northern Florida. Other points, including Simpson and Clovis points, are found in lesser numbers. Other Paleoindian stone tools are known from the Harney Flats site (Daniel and Wisenbaker 1987:41–97), the Silver Springs site in Marion County (Neill 1958), and other northern Florida sites (Purdy 1981:8–32). These Paleoindian tools tend to be unifacial and plano-convex, with steeply flaked, worked edges (Purdy and Beach 1980:114–118; Purdy 1981). Bifacial and "hump-backed" unifacial scrapers, blade tools, and retouched flakes, including spokeshaves, have been found at these sites (Purdy 1981; Daniel and Wisenbaker 1987:62–81, 86–87). However, some tools are little more than flakes or blades that were struck from cores, used, and discarded (Milanich 1994:51).



FPID: 435513-1-22-02

By the end of the Paleoindian period, the climate had become warmer and wetter and it is possible that the modern wetlands of southern Florida began to emerge. Sea levels began a fairly rapid rise, shrinking the available land mass through coastal inundation. These dramatic climate changes, and possible pressure from Paleoindian hunters, led to the extinction of the Pleistocene megafauna and other species.

### 7.2 Archaic Period (7,500-500 BC)

During the Archaic period, climate and sea levels gradually stabilized. The Archaic period is known for the adaptations made by Florida's earliest inhabitants to the modernizing climate and landscape. At the beginning of the Archaic, lifeways in Florida were quite similar to those of the preceding Paleoindian period. However, by the end of the Archaic, Florida's natives had developed more sedentary lifestyles, made many technological innovations, the most important of which was the invention of pottery, and began to differentiate themselves into distinct regional subcultures. Florida's Archaic is divided into Early, Middle, and Late sub-periods, each of which have recognized horizons that are limited to restricted geographic areas and/or times.

#### 7.2.1 Early Archaic Period (7,500-5,000 BC)

With the wetter conditions that began about 8000 BC and the extinction of some of the Pleistocene animal species that helped to sustain earlier populations, Paleoindian subsistence strategies were no longer efficiently adapted to the Florida environment. As environmental conditions changed, surface water levels throughout the state increased and new locales became suitable for occupation. Early Archaic peoples might be viewed as a population changing from the nomadic Paleoindian subsistence pattern to the more sedentary coastal- and riverine-associated subsistence strategies of the Middle Archaic period.

The settlement patterns and tools of Early Archaic people in Florida were initially very similar to those of the preceding Paleoindian period. Cultural changes began after about 8000 BC with changes in projectile-point types, specifically a transition from lanceolate to stemmed varieties. Beginning about 7500 BC, Paleoindian points and knives were replaced by a variety of stemmed tools, such as the Kirk, Wacissa, Hamilton, and Arredondo types (Milanich 1994:63).

Kirk points and other Early Archaic diagnostic tools are often found at sites with Paleoindian components, suggesting that Early Archaic peoples and Paleoindians shared similar lifeways (Daniel and Wisenbaker 1987:33–34). However, it appears that the distribution of Early Archaic artifacts is wider than that of Paleoindian materials. Sites having both Paleoindian and Early Archaic components have been found to be largely restricted to natural springs and the extensive perched water sources of northern Florida.

Most of what is known about Early Archaic subsistence comes from highly preserved materials recovered from the anaerobic muck of the Windover Pond site in Brevard County. The Windover analysis (Andrews et al. 2002) indicates that Early Archaic peoples utilized the fibers of sabal palm, saw palmetto, and other plants in the weaving of baskets and textiles. Windover also illustrates that at least some Early Archaic populations had developed an intensive exploitation strategy focused on inland aquatic resources supplemented by terrestrial game (Dickel and Doran 2002:54). However, since the site has no correlates, it is unclear how representative it is of other Early Archaic sites in southern Florida (Dickel 2002).



FPID: 435513-1-22-02

#### 7.2.2 Middle Archaic Period (5,000-3,000 BC)

Throughout the Middle Archaic, environmental and climatic conditions would become progressively more like modern conditions, which would appear by the end of the period, circa 3000 BC. During this period, rainfall increased, surface water became much less restricted and, as a result, vegetation patterns changed. The Middle Archaic period is characterized by increasing populations and a gradual shift toward shellfish, fish, and other food resources from freshwater and coastal wetlands as a significant part of their subsistence strategy (Milanich 1994:75–84; Watts and Hansen 1988:310). Pollen evidence from Florida and south-central Georgia indicates that after about 4000 BC, a gradual change in forest cover took place, with oaks in some regions giving way to pines or mixed forests. The vegetation communities that resulted from these changes, which culminated by 3000 BC, are essentially the same as those found in historic times before widespread land alteration took place (Watts 1969, 1971; Watts and Hansen 1988).

The Middle Archaic artifact assemblage is characterized by several varieties of stemmed, broad-blade projectile points. The Newnan point is the most distinctive and widespread in distribution (Bullen 1975:31). Other stemmed points of this period include the less common Alachua, Levy, Marion, and Putnam points (Bullen 1968; Milanich 1994). In addition to these stemmed points, the Middle Archaic lithic industry, as recognized in Florida, includes production of cores, true blades, modified and unmodified flakes, ovate blanks, hammerstones, "hump-backed" unifacial scrapers, and sandstone "honing" stones (Clausen et al. 1975; Purdy 1981). Additionally, thermal alteration, a technique in stone tool production, reached its peak during the Middle to Late Archaic periods.

Three common types of Middle Archaic sites are known in Florida (Bullen and Dolan 1959; Purdy 1975). The first are small, special-use camps, which appear archaeologically as scatters of lithic waste flakes and tools such as scrapers, points, and knives. These sites are numerous in river basins and along wetlands and probably represent sites of tool repair and food processing during hunting and gathering excursions (Milanich 1994:78). The second common site type is the large base camp. This type of site may cover several acres or more, and contains several thousand or more lithic waste flakes and tools. The third common type of site is the quarry-related site that occurs in localities of chert outcrops.

Middle Archaic sites are found in a variety of locations, including, for the first time, freshwater shell middens along the St. Johns River and the Atlantic Lagoon. Middle Archaic sites have been found in the Hillsborough River drainage northeast of Tampa Bay, along the southwestern Florida coast, and in South Florida locales such as Little Salt Spring in Sarasota County. In addition, Middle Archaic sites occurred throughout the forests of the interior of northern Florida (Milanich 1994:76).

Due to rising sea levels since the Middle Archaic, many sites dating to this period are now submerged beneath the waters of the Gulf of Mexico and Atlantic Ocean. One such site in St. Lucie County may be the Douglass Beach Midden (8SL17), from which artifacts predating the Late Archaic have been recovered (Murphy and Cummings 1990).



FPID: 435513-1-22-02

#### 7.2.3 Late Archaic Period (3,000-500 BC)

By the beginning of the Late Archaic, all of the modern physiographic regions and ecosystems of southern Florida were present in essentially their modern forms. This includes the entire Kissimmee-Lake Okeechobee-Everglades drainage system. Although the environment of southern Florida had achieved some sense of stability, the archaeological record of this period is much more dynamic. Different ideas and perhaps, human populations, were moving into the area during this time. As a result, there is a great deal of variability between Late Archaic sites in central and southern Florida.

The one point upon which all researchers seem to agree is that, at the beginning of the Late Archaic, pottery had not yet been invented. How long this aceramic state persisted, what the earliest pottery types are and how they vary over space and time is a matter for considerable conjecture.

Until recently, variations of Bullen's chronology for the Late Archaic Orange culture in northeastern Florida were generally used for the Late Archaic in central and southern Florida. Using this scheme, fibertempered pottery, the earliest pottery type known for all of North America, was considered to be a marker for the pottery portion of the Late Archaic. The generally accepted chronological sequence for the Late Archaic was expressly unilineal, with plain (undecorated) fiber-tempered pottery, followed by decorated fiber-tempered pottery, replaced finally by plain pottery that was not tempered with fibers (Bullen 1954, 1955, 1972). It was also understood that sand was eventually added as a tempering agent to fiber-tempered pottery. As the Late Archaic progressed, the amount of sand temper was supposed to have increased while the amount of fiber temper decreased. Orange pottery tempered with both fiber and sand is sometimes referred to as "semi-fiber tempered." The application of this chronology to southern Florida seemed to indicate that most of the area, especially the Everglades, was sparsely settled during the Late Archaic due to the general absence of Orange pottery at sites (Griffin 2002:146-149; Widmer 1988:201-201).

The use of the "standard" fiber-tempered sequence for the Late Archaic in southern Florida eventually came into question by several researchers. Based on his research in southwestern Florida, Widmer (1988:68) hypothesized that the earliest sites there "include untempered chalky pottery and limestone-tempered pottery as well as the usual fiber-tempered Orange pottery." Austin (1997:136) states that the "identification of a true Orange Horizon in south Florida is debatable." He points out that, in the Kissimmee River Valley, pure fiber-tempered components are rare. Instead, what is more common is the presence of "semi-fiber tempered" pottery in the basal levels of middens, "often in association with thick St. Johns Plain or Sand-tempered Plain sherds, and overlying either culturally sterile sands, or sparse scatters of lithic artifacts" (Austin 1996, 1997:136). Both Widmer and Austin agree that semi-fiber tempered components at sites throughout southern Florida are "ephemeral" and soon replaced in the archaeological record by components consisting of exclusively sand-tempered pottery (Austin 1997:136; Widmer 1988:72-73).

Mike Russo has investigated the Joseph Reed Shell Ring on Jupiter Island (Russo and Heide 2002). Radiocarbon dates indicate that the site was constructed sometime between 3527-2746 CALYBP (Russo and Heide 2002:73). This confirms that the site dates to the Late Archaic period. However, no fiber-tempered pottery was recovered from the site. Instead, excavations yielded only chalky (possible early



FPID: 435513-1-22-02

St. Johns Plain) and plain sand-tempered pottery. This is an earlier appearance for these types of pottery than has been predicted for southeastern Florida. Radiocarbon dates indicate that the chalky pottery appears at the Joseph Reed Shell Ring between 3500 and 3300 CALYBP whereas sand-tempered pottery is hypothesized to appear around 3280 CALYBP. Based on the evidence obtained from excavations at the Joseph Reed Shell Ring, Russo and Heide tentatively proposed a new chronology for the Late Archaic in southeastern Florida. A period labeled Late Archaic I is proposed that is marked by fiber-tempered and/or semi-fiber tempered plain pottery. During the next proposed period, Late Archaic II, only chalky ware pottery, possibly early St. Johns Plain, is predicted to occur. This is based on the earliest pottery-bearing levels from the Joseph Reed Shell Ring. The next proposed period, Late Archaic III, is distinguished by the presence of plain sand-tempered pottery along with the chalky pottery. This period is based on the latest levels from the Joseph Reed Shell Ring. Russo and Heide point out that this chronology is closest in resemblance to the chronology proposed by Widmer (1988) for southwestern Florida, suggesting, among other things, that non-fiber-tempered pottery was developed earlier in southern Florida than elsewhere in the state.

It is worth noting that all of these researchers mention in their Late Archaic chronologies the presence of St. Johns Plain, or plain "chalky ware" pottery. Specimens of this type are usually described as "thick" or "thick walled." The same phenomenon has been mentioned for Late Archaic sites in the Everglades (Mowers and Williams 1972). Often, this pottery is described in reports as "early St. Johns Plain."

Of perhaps equal interest to the reported early manifestations of St. Johns Plain are the early reports of Sand-tempered Plain pottery from some sites in southern Florida. In addition to the early examples of Sand-tempered Plain sherds from the Joseph Reed Shell Mound, early examples of this type are also reported from southwestern Florida. At the Mulberry Midden (8CR697), Sand-tempered Plain pottery was dated at about 3390 and 3430 CALYBP (Lee et al. 1993:46; dates recalibrated by Russo and Heide 2002). Dates for Sand-tempered Plain from Heineken Hammock (8CR231) are even earlier, ranging from 4000 to 4500 CALYBP (Lee et al. 1998; dates recalibrated by Russo and Heide 2002). Again, using the standard fiber-tempered sequence for southern Florida, Sand-tempered Plain pottery should not be present at such early dates, only fiber-tempered pottery.

Finally and importantly, it is now becoming clear that many of the ubiquitous faunal bone middens located in the interior wetlands of southern Florida date to Late Archaic times, despite the fact that many of them lack pottery of any kind. These sites are notoriously difficult to date because, not only do they often lack chronologically diagnostic artifacts, but most of the faunal bone at the sites lacks collagen, the datable material in bone samples sent to radiocarbon labs. Nevertheless, many sites clearly have aceramic components that underlie pottery-bearing strata, logically indicating that these aceramic components most likely date at least as far back as Late Archaic times. Indeed, a few radiocarbon dates have been obtained from some of these components, mostly from shell artifacts or ecofacts. For instance, Taylor's Head (8BD74) yielded a radiocarbon date of 4840 ± 210 CALYBP from an aceramic stratum that lay beneath pottery-bearing strata, although no fiber-tempered pottery was identified (Masson et al. 1988:346). Additionally, radiocarbon dates from the lower, aceramic stratum at the Francis Groves Midden/Muhley site (8BD2911) are reported as ranging from 3960-3630 CALYBP (Pepe and Elgart 2006), despite the fact that fiber-tempered pottery is known during this time elsewhere in Florida (Russo and Heide 2002:Figure 11). Ongoing research by the National Park Service in the Big Cypress National



FPID: 435513-1-22-02

Preserve and Everglades National Park has also yielded dense aceramic faunal bone middens yielding radiocarbon dates between 4800 and 3500 CALYBP (Michael Russo, personal communication with James Pepe 2007; Schwadron 2006).

To explain this dichotomy between Late Archaic Everglades area sites that lack fiber-tempered pottery and large, coastal shell mounds that have abundant examples of early pottery, Pepe and Jester (1995:19) propose that there are two, distinct Archaic traditions in southeastern Florida. In this model, the fiber-tempered pottery tradition is largely a coastal phenomenon associated with shell mound building, while the aceramic Archaic or "Glades Archaic" is a more widespread tradition, perhaps giving rise to the distinctive regional culture of the Tequesta and their ancestors (Pepe 2000:29-32; Russo and Heide 2002:80; Wheeler et al. 2002:143-144).

Additionally, Austin suggests that the presence of "semi-fiber-tempered" pottery at sites in southern Florida may not actually date to the Late Archaic, but instead may signify the beginning of the subsequent post-Archaic Tradition (Austin 1997:138). In other words, Austin holds out the possibility that the ephemeral "semi-fiber-tempered" components in the basal levels of middens in southern Florida may better be incorporated into the initial periods of post-Archaic chronologies (i.e. Glades I Early, Okeechobee Basin I, etc.).

The preceding discussion illustrates that a lack of fiber-tempered pottery at a site in southern Florida does not necessarily mean that the site does not date to the Late Archaic. In fact, recent research indicates that, at some sites or in some areas, the earliest pottery present may be Sand-tempered Plain or thick, chalky (St. Johns?) wares. Finally, Austin holds out the possibility that fiber-tempered pottery in southern Florida may not date to the Late Archaic at all, but instead, may be markers of the earliest post-Archaic expressions in the region.

## 7.3 Formative Period (500 BC-AD 1513)

The Formative Period is represented by changes in pottery and technology occurring throughout Florida. The specific changes in pottery traditionally used by archaeologists to mark the beginning of this period include the replacement of fiber-tempered pottery with sand-tempered, limestone-tempered, and chalky-paste ceramics. Three different projectile point styles (basally notched, corner-notched, and stemmed) also occur in some areas in contexts contemporaneous with these new ceramic types. This profusion of ceramic and tool traditions suggests population movement and social interaction between culture areas. The earliest known major occupations of southern Florida date to this period (Bullen et al. 1968; Sears 1982).

The regional diversity marking this period has been attributed to local adaptation to varied ecological conditions. It has been described archaeologically in terms of cultural periods based on variations in ceramic types. The ceramic tradition for southern Florida, characterized by sand tempered bowls with incurvate rims, is known as the Glades or Everglades cultural tradition.

The project APE is located in the Glades (Milanich 1994:301). As defined by Milanich (1994:298), the Glades cultural region includes all of south Florida "east and south of the Caloosahatchee and




FPID: 435513-1-22-02

FPID: 435513-1-22-02 ETDM: 14226

Okeechobee regions. It includes most of St. Lucie County, the Everglades itself, a largely sawgrass marsh in Hendry, Palm Beach, Broward, Dade, and Monroe counties; the Big Cypress Swamp west of the Everglades in Collier County; and extensive saltwater marshes and mangrove forests ounce found along both coasts, now almost totally destroyed in Broward and Dade counties" (**Figure 4**).

Figure 4 | Glades Cultural Region



(Source: Milanich 1994)



#### 7.3.1 Glades Culture

Environmentally, the interior portions of the Everglades area are dominated by inundated or formerly inundated humic or peat soils which are drained by massive sheet-flow instead of river channeling. The Atlantic coast, which has developed from beach dune deposition, has a few rivers cutting through the Atlantic Coastal Ridge and a coast-parallel lagoon system.

John Goggin established a ceramic sequence for the Glades region on the basis of work he conducted from the 1930s to early 1950s (Goggin n.d.). Subsequent research has only served to refine his basic chronological framework. The most recent revision was presented by John Griffin (1988), who based his research on a series of radiocarbon dates from the Granada site in Dade County (Griffin et al. 1982) and research he conducted on the Bear Lake site in Everglades National Park. In presenting his revisions, Griffin makes a point to emphasize that the Glades sequence represents a chronology of stylistic and technological changes in ceramics to which other cultural traits have been added.

**Table 2** is based on Griffin's 1988 work and presents the most thorough chronological framework for southern Florida. Summaries of the ceramic markers associated with each period are provided, as well. It is important to note that the information provided in this table is most applicable to the heartland of the Glades archaeological area: the Big Cypress Swamp, Everglades, and coastal portions of southern Florida to south of Lake Okeechobee.

Glades period sites include those at Gordon's Pass (Goggin 1939), Goodland Point (Goggin 1950), Marco Island (Van Beck and Van Beck 1965), Useppa Island (Milanich et al. 1984), Horr's Island (McMichael 1982), Sanibel Island (Fradkin 1976), and the Turner River site (Sears 1956). An interesting feature of these large coastal sites is the progressive movement of habitation areas toward the water (Cushing 1896; Goggin 1950; Sears 1956), and indications are that dwellings may have been built to extend out over the water. Inland sites consist of shell and dirt middens along major watercourses (Laxson 1966) and small dirt middens containing animal bone and ceramic sherds in oak/palm hammocks or palm islands associated with freshwater marshes. The coastal Glades subsistence pattern is typified by the exploitation of fish and shellfish, wild plant food, and inland game, while Glades sites in the Big Cypress Swamp show a greater, if not exclusive, reliance on interior resources.



FPID: 435513-1-22-02

Table 2 | Glades Cultural Sequence

Period	Dates	Distinguishing Characteristics
Glades I early	500 BC-AD 500	First appearance of sand-tempered pottery; no decoration
Glades I late	AD 500–750	First appearance of decorated pottery: Fort Drum Incised, Fort Drum Punctated, Cane Patch Incised, Gordon's Pass Incised, Opa Locka Incised, Sanibel Incised; sand-tempered plain persists
Glades Ila	AD 750–900	Appearance of Key Largo Incised and Miami Incised; sand-tempered plain and Opa Locka Incised persist; none of the earlier decorated types are present
Glades IIb	AD 900–1100	Sand-tempered plain and Key Largo Incised persist; Matecumbe Incised appears; none of the earlier decorated types are present; certain rim modifications (incised lip arcs and lip crimping and grooving) also appear for the first time
Glades IIc	AD 1100–1200	Almost no decorated ceramics; some grooved lips but no more lip arcs or crimped rims; Plantation Pinched appears
Glades Illa	AD 1200–1400	Plantation Pinched is no longer present; Sand-tempered plain and grooved lips persist; appearance of Surfside Incised and St. Johns Check Stamped
Glades IIIb	AD 1400–1513	Glades Tooled, sand-tempered plain and St. Johns Check Stamped are present, Surfside Incised and grooved lips are not present
Glades IIIc	AD 1513-ca.1700	Same as previous period with the addition of historic artifacts

(Source: Griffin 1988:124-142)



FPID: 435513-1-22-02

## 8.0 Historical Overview

The intent of this section is to identify the possible locations of any historic sites within the cultural assessment project area and to provide a background for the determination of their historical potential. To this end, books, maps, and manuscripts located at the University of South Florida Special Collections Department, Florida Department of Environmental Protection, Division of State Lands, and Janus Research were examined, and interviews with local informants were conducted.

## 8.1 European Contact and Colonial Period (ca. 1513-1821)

The earliest contact between the native populations and the Europeans occurred through slave hunting expeditions. Evidence of these slave raids comes from the familiarity with the Florida coast stated by navigators of the earliest official coastal reconnaissance surveys (Cabeza de Vaca 1542: Chapter 4). Official credit for the European discovery of Florida belongs to Juan Ponce de León, whose voyage of 1513 took him along the eastern coast of the peninsula (Tebeau 1971:21). Other Spanish explorers followed Juan Ponce de León, and over the next 50 years the Spanish government and private individuals financed expeditions hoping to establish a colony in "La Florida." In 1565, King Philip II of Spain licensed Pedro Menéndez de Avilés to establish a settlement in St. Augustine, Florida. Between 1565 and 1566, Menéndez sailed along the Florida coast placing crosses at various locations and leaving Spaniards "of marked religious zeal" to introduce Christianity to the Native American people (Gannon 1965:29). Settlements with associated missions were established at St. Augustine, San Mateo (Ft. Caroline) and Santa Elena, and smaller outposts and missions were located in Ais, Tequesta, Calusa, and Tocobaga territory (Gannon 1965:29).

Jesuit missions were established in what are now referred to as the Central Peninsular Gulf Coast and Glades archaeological regions, including the mission of Carlos at Charlotte Harbor, the mission of Tocobaga at Tampa Bay, and a mission at a Tequesta village at the mouth of the Miami River. In 1567, Brother Francisco Villareal was sent to one of the large Tequesta villages located on Biscayne Bay. In 1568, a skirmish between the Spanish soldiers and the Tequesta Indians temporarily closed the mission. By the end of 1568, the Tequesta were willing to reopen the mission, largely due to the work of Don Diego, a Tequesta who had visited Spain. Despite zealous attempts, the native groups in Florida continued to resist conversion, and in 1572 Jesuit authorities decided to abandon their missionary efforts in Florida.

Undaunted, Menéndez turned his attention to another order, the Franciscans, and entreated them to send priests. The Franciscan mission effort was most successful in the northern areas of Florida. One possible reason may have been differences in Native American settlement patterns and economies. According to Milanich (1978:68), the failure of the Spanish missions among the southern Florida native populations was due partially to the groups' subsistence pattern, which required seasonal movement for maximum resource exploitation. Consequently, for the remainder of the First Spanish period (1565–1763), southern Florida was virtually ignored as the Spanish concentrated their efforts in the northern half of the peninsula.



FPID: 435513-1-22-02

Another attempt to build a mission in southeastern Florida took place nearly 150 years after the establishment of St. Augustine. Because it was in Spain's best interest to maintain control along the Florida coastline and alliances with the native groups inhabiting the coast, a missionary effort was supported in the Biscayne Bay area (Parks 1982:55–65). Father Joseph María Monaco and Joseph Xavier Alaña were sent from Cuba in 1743, and arrived at a Native American village located at the mouth of the Miami River. The village did not appear any more receptive towards accepting Christianity than before. After Joseph Xavier Alaña conveyed this to the Governor of Cuba, the mission was closed, and the fort they had erected was destroyed to prevent its fall into hostile hands (Parks 1982:55–65). Although the Spanish were resigned to the fact that missionization and settlement of South Florida came at too high a price, they did strive to maintain good relations with the various native people who lived in the area.

By the beginning of the eighteenth century, the Native American population of South Florida had declined considerably as a result of disease, slave raids, intertribal warfare, and attacks from a new group of Native Americans, the Seminoles. The Seminoles, descendants of Creek Indians, moved into Florida during the early eighteenth century to escape the political and population pressures of the expanding American colonies to the north (Wright 1986:218).

By the end of the eighteenth century, the Seminoles had become the dominant Native American group in the state. Groups of fugitive African American slaves also had settled among the Seminoles by the early nineteenth century (Brown 1991:5–19). Armed conflict with pioneers, homesteaders, and eventually the United States Army resulted in the removal of most of the Seminoles from Florida. This action forced the withdrawal of the remaining Seminole population to the harsh environment of the Everglades and Big Cypress Swamp by the late nineteenth century.

The first known non-Indian residents of what is now Fort Lauderdale were the Charles Lewis family, who arrived from the Bahamas with the British adventurer William Augustus Bowles in the late eighteenth century. Bowles tried to establish a sovereign nation of the native Creek Indians, and Lewis established a plantation along the New River. In 1810, the Spanish government awarded nobleman Juan Arrambide a huge land grant extending from New River south to Biscayne Bay. Arrambide developed this land as a lumber source and, in the process, introduced black slaves to the region (Historic Property Associates 1995:28–29).

## 8.2 The Territorial and Statehood Period (1821-1860)

In 1821, after several years of negotiations with Spain, the U.S. acquired Florida as a territory. The population of the territory at that time was still centered in the northern areas around Pensacola, St. Augustine, and Tallahassee. By 1830, the New River Settlement included approximately 60 to 70 inhabitants. The leader of the settlement was William Cooley. Richard Fitzpatrick established plantation practices on his property (Historic Property Associates 1995:29–30). His assistant was Stephen Russell Mallory, who traveled from Key West to the New River area in 1830 and established a plantation in the Fort Lauderdale vicinity. Only there 12 months, he spent his time fishing, hunting and learning woodcraft from the Seminoles, who fished around the coast (Kemper 1981:4–6). In 1840, a skirmish occurred between the Seminoles and a small command of soldiers near the West Lake tract (Kemper 1981:4).



FPID: 435513-1-22-02

Apparently, the Indians fired on two boats under the command of Lieutenant Rankin. The Indians were pursued inland but were not apprehended.

As more European-American settlers moved into the region, conflicts arose with the Seminole people over available land. Pressure began to bear upon the government to remove the Seminoles from northern Florida and relocate them farther south. The Treaty of Moultrie Creek (1823) restricted the Seminole people to approximately four million acres of land in the middle of the state, running south from Micanopy to just north of the Peace River (Mahon 1967: Rear foldout map). The Seminoles did not approve of this treaty because they were reluctant to move from their established homes to an area that they felt could not be cultivated. Other treaties soon followed such as Payne's Landing (1832) and Fort Gibson (1833), which called for Seminole emigration to the western territories (Mahon 1967:75–76, 82–83). These treaties fostered Seminole resentment of settlers that would culminate in the Second Seminole War in 1835.

At the beginning of the Second Seminole War, the conflict was centered near the Withlacoochee region. In 1838, U.S. troops moved south to pursue the retreating Seminoles into the Lake Okeechobee and Everglades regions. Colonel Zachary Taylor was sent to the area between the Kissimmee River and Peace Creek. Colonel Persifor Smith and his volunteers were dispatched to the Caloosahatchee River, and U.S. Navy Lt. Levi N. Powell was assigned the task of penetrating the Everglades (Mahon 1967:219–220). Powell's detachment had several skirmishes with Seminole people near Jupiter Inlet. Powell established a depot on the Miami River and erected Fort Dallas in the approximate location of present-day downtown Miami. For three months, Fort Dallas was a base of operations as Powell led his men into the Everglades in search of the Seminoles (Gaby 1993:47).

Following the Second Seminole War, the New River settlement was brought to an end. Seminoles massacred Cooley's family in 1836 and the settlers fled to Cape Florida. In March 1838, Major William Lauderdale of the Tennessee Volunteers and his troops constructed an outpost near New River called Fort Lauderdale, which was later replaced by two other forts. The Third Seminole war in 1855 was fought primarily in other parts of the state, but some troops did visit New River (Historic Property Associates 1995:32–35).

The Second Seminole War had a deleterious effect on new settlement in Florida. To encourage settlement in the middle portion of the territory after the war, the Armed Occupation Act of 1842 offered settlers 160 acres of land at no cost, provided they built a house, cleared five acres, planted crops, and resided on the land for five years. Any head of a family or single man over 18 years of age and able to bear arms, was eligible to receive a homestead. This act, plus the end of the Second Seminole War, created a small wave of immigration by Anglo-American pioneers to central Florida. Most of these immigrants were Anglo-American farmers and cattle ranchers, or "crackers," from the southeastern United States (Gaby 1993).

### 8.3 Civil War and Post War Period (1860-1898)

With the beginning of the Civil War, cattle were needed to help feed the Confederate Army. Herds from as far south as central Florida were driven to railheads near the Georgia border. However, cattle ranchers



FPID: 435513-1-22-02

discovered they could sell their herds in Cuba for a greater profit and began dealing with blockade-runners. The Union attempted to stop all shipping from Florida ports, but blockade-runners were too abundant. Cattle ranchers from all over Florida drove their cattle to Punta Rassa to be shipped to Cuba for payment in Spanish gold. Jacob Summerlin, a successful cattle rancher from the Fort Meade area, gave up his contract with the Confederate government to supply cattle and in 1863 teamed up with James McKay from the Tampa area. McKay, a successful and daring blockade-runner, supplied the schooners and Summerlin the cattle. It is not known how many cattle were shipped from the port during the Civil War. However, after the war as cattle continued to be shipped; it is reported that in the decade between 1870 and 1879, more than 165,000 head were shipped (Grismer 1949).

The New River region was sparsely settled during the Civil War. A Miami Unionist who served as a gunboat pilot, Isaiah Hall, and his family lived there after being driven from the Miami area by Confederate sympathizers (Historic Property Associates 1995:35). In 1868, hog farmer and beachcomber John J. "Pig" Brown settled on New River with his family, as well. Brown was elected to the Florida Legislature in 1876 and never returned from Tallahassee. During the same time, the United States Life Saving Service established 10 Government Houses of Refuge for shipwrecked sailors along the uninhabited eastern coastline, and the first permanent white settler in present day Fort Lauderdale came to the area in 1876 to occupy one of the cabins (Nance 1962:334). At this time, the population center of present-day Broward County was Pine Island, west of present-day Davie. Approximately 30 Seminole families cultivated gardens and roamed the Everglades in search of game (McGoun 1999).

Concern for future settlement created survey activity in Broward County. It had already been surveyed in 1845, but in 1870 many more areas were surveyed. The Florida Surveyor General approved a plat map on November 30, 1870 (Kemper 1981:12). Isolated events such as the surveying would lead to increased development of Broward County. Another such event was the purchase of four million acres of Florida's land with a drainage project in mind. The drainage project would turn swampland into agriculture and development lands.

In the 1880s, interest in the resources of South Florida increased due in large part to people like Hamilton Disston and Henry B. Plant. By 1881, the State of Florida faced a financial crisis involving a title to public lands. On the eve of the Civil War, land had been pledged by the Internal Improvement Fund to underwrite railroad bonds. After the War, when the railroads failed, the land reverted to the State. Almost \$1 million was needed by the state to pay off the principal and accumulated interest on the debt, thereby giving clear title.

Hamilton Disston, son of a wealthy Philadelphia industrialist, contracted with the State of Florida in two large land deals: the Disston Drainage Contract and the Disston Land Purchase. The Drainage Contract was an agreement between Disston and the State in which Disston and his associates agreed to drain and reclaim all overflow lands south of present-day Orlando and east of the Peace River in exchange for one-half the acreage that could be reclaimed and made fit for cultivation.

The Disston Land Purchase was an agreement between Disston and the State in which Disston agreed to purchase Internal Improvement Fund Lands at \$0.25 an acre to satisfy the indebtedness of the fund. A contract was signed on June 1, 1881 for the sale of 4,000,000 acres for the sum of \$1 million, the



FPID: 435513-1-22-02

estimated debt owed by the Improvement Fund. Disston was allowed to select tracts of land in lots of 10,000 acres, up to 3,500,000 acres. The remainder was to be selected in tracts of 640 acres (Davis 1938:206–207). Before he could fulfill his obligation, Disston sold half of this contract to a British concern, the Florida Land and Mortgage Company, headed by Sir Edward James Reed (Tischendorf 1954:123). In 1883, Reed became one of the primary owners of land in the vicinity of the current project area.

Disston changed Florida from a wilderness of swamps, heat, and mosquitoes into an area ripe for investment. During 1881 and 1882, channels were dug between the lake systems to the north and the Kissimmee River (Tebeau 1971:288). The Atlantic and Gulf Coast Canal and Okeechobee Land Company was responsible for opening up Lake Okeechobee to the Gulf of Mexico by dredging a channel to the Caloosahatchee River. Disston and his associates received 1,652,711 acres of land under the Drainage Contract, although they probably never permanently drained more than 50,000 acres (Tebeau 1971:280). Drainage operations began and the Florida Land and Improvement Company and Kissimmee Land Company were formed to help fulfill the drainage contract (Hetherington 1980:6).

Private land claims between 1881 and 1883 were probably squatters acquiring the land on which they lived prior to the land transfers under the Disston Land Purchase contract. The flurry of land transfers recorded in the early 1880s was mainly the result of two factors: large influxes of people as a result of the railroads, and the widespread unpopularity of the Disston Land Purchase and Drainage Contracts.

The Disston Land Purchase and Disston Drainage Contract were not very well liked among many of Florida's residents. They resented the \$0.25 per acre price Disston paid under the land contract, as they were required to pay \$1.25 per acre under the terms of the Homestead Act of 1876. Claims also were made that Disston was receiving title to lands that were not swamplands or wetlands (Tebeau 1971:278). Many residents bought up the higher, better-drained parcels of land for speculation, knowing that the surrounding wetlands and flatwoods would be deeded to Disston under the Land Purchase contract. Many hoped that their more desirable land purchases would increase in value.

In August 1881, at the same time Disston's companies were beginning their work, the legislature granted a state charter to the privately owned Florida Coast Line Canal & Transportation Company to construct a continuous waterway from the St. Johns River to Miami; the intracoastal channel would provide a sheltered, inland passage for shallow-draft vessels. The charter granted the company 3,840 acres of land for every mile of canal built. Construction began in 1883 on a 5-foot-deep, 50-foot-wide, intracoastal channel connecting coastal bays, rivers, and lakes (Buker 1975:117). Although the canal company dredged almost continuously from 1883 until the 268-mile channel was completed in 1912, the firm's waterway operations were never successful. While the channel was still under construction, the company faced a formidable challenge from competing transportation interests expanding into South Florida (Buker 1975:120).

Development in Broward County was slow, but sure. By the early 1890s, land was purchased and development was being planned (Kemper 1981:12). For example, in Hollywood, tract book records indicate the majority of the township's land, approximately 27 square miles out of the town's total 36 square miles, was purchased by the Florida Coast Line Canal and Transportation Company on September 24, 1890. By 1910, the first person lived in the Hollywood area. Fred Zirbs established a five-



FPID: 435513-1-22-02

acre farm where he grew peppers and tomatoes (Kemper 1981:12). New River was the site of a ferry and an overnight camp for stage line passengers. Frank Stranahan, who is regarded as the first permanent white settler of what is now Fort Lauderdale, ran both the ferry and the camp (Historic Property Associates 1995:38). **Table 3** shows the land apportionment in the current project APE.

Development and settlement would increase after the freezes of 1894 and 1895 that killed citrus crops, vegetables, and coconut palms north of Broward County. This event in part caused Henry M. Flagler to extend the Florida East Coast Railway 70 miles south to Miami, where no damaging frosts had occurred (Shepard Associates 1981:1–10). The completion of the railroad to Miami in 1896 launched the most significant period in the region's development. The railroad brought farmers from the north, and agriculture was developed. Other businesses also began to emerge (Historic Property Associates 1995:39–42).

The historic plat map for the project area was also examined and no evidence was found of historic homesteads or roads within the project area. There was an Indian Camp located within one mile of the project area in the southwest corner of Section 16. It sat along the northwestern banks of the South Fork. There was also an Old Fort located one mile from the project area in the northwest corner of Section 10. It sat north of the junction between North Fork, South Fork, and New River.

Table 3 | Land Apportionment in the Project Area as Recorded in the Tract Book Records

Township 50 South, Range 42 East				
Section	Portion Owned	Owner	Date of Deed or Sale	
4	All	Sir Edward James Reed	March 22, 1883	
5	All	Sir Edward James Reed	March 22, 1883	
8	All	Sir Edward James Reed	March 22, 1883	
9	All	Sir Edward James Reed	March 22, 1883	
16	All	Sir Edward James Reed	March 22, 1883	
	East ½ of NE ¼ and SE ¼	Arthur T. Williams	May 10, 1886	
	Lots 1, 2, 3, 4, and NE ¼ of SW ¼	Arthur T. William and James A. Harris	May 30, 1885	
17	NW ¼ of NW ¼	Arthur T. Williams	May 10, 1886	
	Lot 5	Emily W. Collins	July, 20, 1885	
	S ½ of SW ¼	Aaron Levy	November 11, 1885	



FPID: 435513-1-22-02

## 8.4 Spanish-American War Period/Turn-of-the-Century (1898-1916)

At the turn-of-the-century, Florida's history was marked by the outbreak of the Spanish-American War in 1898. As Florida is the closest state to Cuba, American troops were stationed and deployed from the state's coastal cities. Harbors in Tampa, Pensacola, and Key West were improved as more ships were launched with troops and supplies. "The Splendid Little War" was short in duration, but evidence of the conflict remained in the form of improved harbors, expanded railroads, and military installations (Miller 1990).

Fort Lauderdale saw growth at this time despite a yellow fever epidemic in 1899. In the same year, the area's first schoolhouse was built. The 1900 census reported 52 residents in Fort Lauderdale. The area's first incorporated communities were Dania in 1904, Pompano in 1908, and Fort Lauderdale in 1911; these communities predate the formal incorporation of Broward County (McGoun 1978:19). Fort Lauderdale's downtown began to develop at this time; the commercial area centered on the intersection of the railroad and the New River. Unfortunately, a fire in June of 1912 destroyed most of the business district, but the disaster did little to impair Fort Lauderdale's growth (Historic Property Associates 1995:42–47).

In 1904, Governor Napoleon Bonaparte Broward initiated significant reforms in Florida's politics. Several of Broward's major issues included the Everglades drainage project, railroad regulation, and the construction of roads. The draining of the Everglades resulted in the construction of canals, an increase in land available for agriculture, and the fueling of Fort Lauderdale's growth. One of the first elements of the project was the dredging of the North New River Canal. By 1912, the New River Canal extended all the way to Lake Okeechobee, and shipping of agricultural products along the water route was immediately the preferred method of transportation (Historic Property Associates 1995:44).

During this time, railroads were constructed throughout the state and automobile use became more prevalent. Improved transportation in the state opened the lines to export Florida's agricultural and industrial products (Miller 1990). As various products such as fruits and vegetables were leaving the state, people were arriving in Florida. Some entered as new residents and others as tourists. Between 1900 and 1910, the state population increased from 528,542 residents to 752,619. At this time, St. Lucie and Palm Beach counties were established, indicative of the increasing numbers of people moving to the east coast of the state.

Broward County incorporated in 1915 with a population of 8,000, and Fort Lauderdale was named county seat (Historic Property Associates 1995:50). The county was named after the former Governor Broward. As recently as 1910, the County had been a wilderness of pine trees and swampland and had few homesteaders. Agriculture was still the main economy (Wells et al.:8–12). Before 1915, Broward County had at times been part of St. Johns, Monroe, Mosquito, Dade, St. Lucie, Brevard, and Palm Beach counties. By the time of the County's incorporation, most citizens were living in the eastern areas along the coast such as Dania, Pompano, Fort Lauderdale, Deerfield, Hallandale, Davie, Colohatchee, and Progresso (Shepard Associates 1981:I-10).

The area's tourist trade began to emerge around the time of incorporation. Development of the Fort Lauderdale beach area began in 1914 when D. C. Alexander purchased 32 acres of beachfront property. In July 1915, the Dixie Highway, the first major highway linking Fort Lauderdale with the rest of the nation,



FPID: 435513-1-22-02

was completed. This highway and other new Broward County roads would play a significant role in Florida's growing tourist trade (Historic Property Associates 1995:50–51).

Rapid and widespread growth was the theme of this period in Florida history. Thousands of miles of railroad tracks were laid, including the Florida East Coast, Atlantic Coast Line, and Seaboard Air Line railroads. While agriculture, especially the citrus industry, had become the backbone of Florida's economy, manufacturing and industry began growing during the beginning of the century. Fertilizer production, boat building, and lumber and timber products were strong secondary industries (Weaver et al. 1996:3).

## 8.5 World War I and Aftermath Period (1917-1920)

The World War I and Aftermath period of Florida's history begins with the United States' entry into World War I in 1917. Wartime activity required the development of several training facilities in the state, and protecting the coastlines was a priority at this time. Although the conflict only lasted until November 1918, the economy was boosted greatly by the war. An indirect economic benefit of the war was an increase in agricultural production, as beef, vegetables, and cotton were in great demand (Miller 1990).

Area development was halted temporarily during World War I, although the construction of bridges from the mainland over to the beaches at Pompano, Hallandale, and Fort Lauderdale were completed in 1917 (Historic Property Associates 1995:51). Truck farming still dominated Broward County's economy before the 1920s Boom Times development began in earnest. Higher areas in the county were preferred for planting crops like beans, squash, cabbage, tomatoes, pineapples, and turpentine mangoes (Shepard Associates 1981:I-11–13, 34).

While Florida industrialization and agriculture flourished, immigration and housing development slowed during the war. Tourism increased as a result of the war in Europe, which forced Americans to vacation domestically. Tycoons such as Henry Flagler and Henry Plant were building the hotels and railroads for people desiring winter vacations in sunny Florida. These magnates took an interest in the improvements and promotion of Florida in an effort to bring in more tourist dollars. The end of the war marked a slight increase in population, and Flagler and Okeechobee counties were created at this time.

#### 8.6 Florida Boom Period (1920-1930)

After World War I, Florida experienced unprecedented growth. Many people relocated to Florida during the war to work in wartime industries or were stationed in the state as soldiers. Road building became a statewide concern as it shifted from a local to a state function. These roads made even remote areas of the state accessible and allowed the boom to spread. Besides the inexpensive property, Florida's legislative prohibition on income and inheritance taxes also encouraged more people to move into the state.

Earlier land reclamation projects created thousands of new acres of land to be developed. Real estate activity increased steadily after the war's end and drove up property values. Prices on lots were inflated to appear more enticing to out-of-state buyers. Every city and town in Florida had new subdivisions platted



FPID: 435513-1-22-02

and lots were selling and reselling for quick profits. Southeastern Florida, including cities such as Miami and Palm Beach, experienced the most activity, although the boom affected most communities in central and South Florida (Weaver et al. 1996:3).

In the late 1910s and early 1920s Fort Lauderdale was used as a setting for movies. Real estate sales increased as swamps were dredged and "finger islands," narrow strips of fill alternating with channels of water, were developed. Building included exclusive and moderately priced homes, as well as hotels and commercial structures downtown. These activities in Florida's southeastern "Gold Coast" represented the highest intensity of Florida's land boom. By 1925, Fort Lauderdale's population reached 16,000 people (Historic Property Associates 1995:51–54). Other cities in Broward County were incorporated during the Land Boom period including Hollywood, Deerfield, Davie, and Floranada (McGoun 1978:20).

In 1918, George Henry came to Fort Lauderdale to build the Broward Hotel. The city financed the development in part in hopes of bringing an economic boom similar to those that occurred in Palm Beach and St. Augustine. After the hotel's opening in 1919, tourists flocked to the area. In 1921, Joseph Young bought land that would transform the area of Hollywood from truck farming agricultural fields into a city. Development began full-scale in the summer of 1921; the town was based on the design for Indianapolis, Indiana, where Young had lived. By 1925, the town would have neighborhoods, a country club and golf course, and the famous Hollywood Beach Hotel (Shepard Associates 1981:I-11–13, 34).

An important development in Fort Lauderdale during the late 1920s was the division of the city into quadrants, which not only assisted tourists in finding their destinations, but also solidified racial segregation. Blacks arrived as laborers on the railroad and remained as farmers, settling in the northwestern section of the town. Following the adoption of the grid system, the city officially restricted black homes to the northwest quadrant (Historic Property Associates 1995:56–58).

The Boom period began to decline in August 1925, when the Florida East Coast Railway placed an embargo on freight shipments to South Florida. Ports and rail terminals were overflowing with unused building materials. In addition, northern newspapers published reports of fraudulent land deals in Florida. In 1926 and 1928, two hurricanes hit southeastern Florida, killing hundreds of people and destroying thousands of buildings. The 1926 hurricane hit Hollywood, killing 37 people there and 15 in Fort Lauderdale. The collapse of the real estate market and the subsequent hurricane damage effectively ended the boom. The 1929 Mediterranean fruit fly infestation that devastated citrus groves throughout the state only worsened the recession (Weaver et al. 1996:4).

It was also at this time that North Woodlawn Cemetery, partially located within the current project APE, was established. Fort Lauderdale had restricted the African American community to the northwest quadrant of the City, and North Woodlawn Cemetery was the only place where African Americans could be buried until 1962, due to this institutionalized racial segregation (Janus Research 2012).

For Broward County, 1926 saw a dramatic reversal of fortune, as real estate activity declined as a result of a stock market slump the previous November. People began defaulting on payments, and business came to a near standstill (Kemper 1981:47). Overspeculation in real estate, the F.E.C. Railway freight embargo, and the 1926 hurricane created economic havoc, further devastating the area's land boom (Historic Property Associates 1995:55–56). In order to promote morale and development, right-of-way



FPID: 435513-1-22-02

was granted to the Seaboard Air Line Railway (Shepard Associates 1981: I-43). The Mediterranean Revival-style Seaboard Airline Railroad Station, located within the current project APE, was also constructed at this time.

By the time the stock market collapsed in 1929, Florida was suffering from an economic depression. Construction activity had halted and industry dramatically declined. Subdivisions platted several years earlier remained empty and buildings stood on lots partially-finished and vacant (Weaver et al. 1996).

Despite the economic hardships of the Depression era, local financiers began a project to create a port in the Fort Lauderdale area. One of the greatest supporters of the port was the developer of the city of Hollywood, J. W. Young. Throughout the early 1920s, Young worked towards the creation of a deepwater harbor from a body of water originally known as Lake Mabel, but various circumstances including the bust of the real estate market, initially prevented its construction. A special act of the Florida Legislature established the Broward County Port Authority in 1927, and construction of the port was soon underway (Broward County 2001). After several years of financial difficulties, the port was opened in 1929 for use by cargo ships and military vessels. The name "Port Everglades" was chosen, as it represented the port as the "gateway to the rich agricultural area" of Florida (Broward County 2001). In July 1929, the construction of a railroad to the port was underway, and several months later it was decided that storage warehouses were needed on the port property (Eller 1971:17).

Another big event that took place during 1929 was the opening of the Merle Fogg Airport in Fort Lauderdale (known today as the Fort Lauderdale-Hollywood International Airport). Named after the city's renowned aviator, the Merle Fogg Airport opened in May 1929 with a ceremony attended by over 5,000 people (Nelson 1963:22).

## 8.7 Depression and New Deal Period (1930-1940)

This era of Florida's history begins with the stock market crash of 1929. As previously discussed, there were several causes for the economic depression in Florida, including the grossly inflated real estate market, the hurricanes, and fruit fly infestation. During the Great Depression, Florida suffered significantly. Between 1929 and 1933, 148 state and national banks collapsed, more than half of the state's teachers were owed back pay, and a quarter of the residents were receiving public relief (Miller 1990).

As a result of hard economic times, President Franklin D. Roosevelt initiated several national relief programs. Important New Deal—era programs in Florida were the Works Progress Administration (WPA) and the Civilian Conservation Corps (CCC). The WPA provided jobs for professional workers and laborers, who constructed or improved many roads, public buildings, parks, and airports in Florida. The CCC improved and preserved forests, parks, and agricultural lands (Miller 1990).

The Depression affected most areas of the state's economy. Beef and citrus production declined, manufacturing slowed, and development projects were stopped. Even the railroad industry felt the pressures of the 1930s, and had to downsize. In addition, the increasing use of the automobile lessened the demand for travel by rail. Despite the Depression, tourism remained an integral part of the Florida



FPID: 435513-1-22-02

economy during this period. New highways made automobile travel to Florida easy and affordable and more middle-class families were able to vacation in the "Sunshine State" (Miller 1990).

A slow recovery began as the thirties progressed in Broward County (Historic Property Associates 1995:58). In the mid-1930s, Federal loans were secured for several projects in Broward County, including the construction of U.S. 1, from south Dania to the Dade/Broward County line, and the construction of a water softening system at the municipal water plant in 1935 (Kemper 1981:49). Tourism and the hotel business were making a comeback. Additionally, Port Everglades was evolving into one of Florida's premier ports; it was ranked seventh in the state in imports and exports. At the end of 1934, the port's export commerce increased from 1,850 tons to 10,859 tons in one year (Burghard 1982:74).

In 1935, the first annual Collegiate Aquatic Forum was held at the Fort Lauderdale municipal pool, making Fort Lauderdale a popular college vacation destination (Historic Property Associates 1995:58–59). Agriculture and residential building began in the western suburbs of Hollywood, and several new businesses were started along Hollywood Boulevard (TenEick 1989:335–337,342).

#### 8.8 World War II and the Post War Period (1940-1950)

From the end of the Great Depression until after the close of the post-war era, Florida's history was inextricably bound with World War II and its aftermath. It became one of the nation's major training grounds for the various military branches including the Army, Navy, and Air Force. Prior to this time, tourism had been the state's major industry and it was brought to a halt as tourist and civilian facilities, such as hotels and private homes, were placed into wartime service. The influx of thousands of servicemen and their families increased industrial and agricultural production in Florida, and also introduced these new residents to the warm weather and tropical beauty of Florida.

Wartime activities brought an economic boom to Broward County (Shepard Associates 1981: I-51). Fort Lauderdale felt the conflict in December 1939 when the British cruiser Orion drove the German freighter Arauca into Port Everglades, which opened in 1928. The Arauca remained there for over a year. The 1942 attack of Allied shipping by German U-boats was visible from the shoreline. The area lent itself to military training, and the influx of military personnel brought business to Broward County (Historic Property Associates 1995:58–60). Two military training centers were opened in Hollywood, the United States Naval Air Gunners School and the United States Naval Indoctrination and Training School. Soldiers trained in the schools and on Hollywood's beaches. The Navy also maintained a station in Fort Lauderdale where naval aviators were trained, and the site of the current Broward County Community College was used for military training during the war. Some of the servicemen stationed here returned at the war's end to live permanently (Shepard Associates 1981: I-51).

Port Everglades was used extensively for military operations. The port possessed numerous tanks for petroleum storage and modern equipment used for loading and unloading. Fuel reserved for the defense of the Caribbean Islands and molasses, which would be used later in the production of explosives for the Navy, also were stored at the port. The seaport accommodated an undersea warfare experimental station and a Navy boat service used in the recovery of torpedoes dropped by planes at the Fort Lauderdale Naval Air Station during training (George 1991:6).



FPID: 435513-1-22-02

The wartime activities of Port Everglades were inextricably connected to those at the Fort Lauderdale Naval Air Station, the area's largest military installation. Fort Lauderdale was considered an ideal location for an air station due to its moderate climate, which allowed for year-round training, and its proximity to the Atlantic Ocean and the Everglades, that provided open areas for training, bombing targets, and ranges. Construction of the more than 1,000-acre naval air station began in 1942; the facility absorbed the City's Merle Fogg Airport. The facility, which could accommodate 3,000 people, included more than 4,000 feet of runways and 217 buildings. By late 1942, the base was complete. During the war, the Fort Lauderdale Naval Air Station was one of two facilities from Illinois to Florida equipped to combat train Navy pilots and crewmen in torpedo bomber planes (George 1991:7, 9). At the conclusion of the war, the facility was abandoned by the military and remained unused for several years.

During this time, railroads profited, since servicemen, military goods and materials needed to be transported. However, airplanes were now becoming the new form of transportation, and Florida became a major airline destination. The highway system was also being expanded at this time. The State Road Department constructed 1,560 miles of highway during the war era (Miller 1990).

Growth in Broward County continued to increase after the end of World War II, as a result of the leftover benefits of a wartime economy and the renewed availability of construction materials and durable goods (Kemper 1981:50, TenEick 1989:407). Servicemen stationed in the area returned to live, often convincing family and friends to return as well. Between 1940 and 1950, Fort Lauderdale's population more than doubled to 36,328. Lauderdale-by-the-Sea was established in 1951; Plantation and Lazy Lake in 1953; Margate and Miramar in 1955; Lighthouse Point in 1956; Sunrise, Davie, and Lauderdale Lakes in 1961; and Coconut Creek in 1967 (Broward County 2001).

Many single-family residences were constructed in the World War II era Dorsey Riverbend neighborhood, located partially within the APE. The overall boundaries of the historically African-American neighborhood include Sistrunk Boulevard at the north, NW 25<sup>th</sup> Avenue at the west, Broward Boulevard at the south, and NW 7<sup>th</sup> Avenue at the east (Olmeda and Huriash 2000). The no longer extant Dixie Court Public Housing Development, opened in 1938 as an apartment development for African-Americans in Fort Lauderdale, was completed prior to this time period. The historic 1949 aerial photograph (**Figure 5**) illustrates rapid development of the Dorsey Riverbend neighborhood, including the beginning of apartment construction. However, vacant lots in the area are still visible at this time (**Figure 5**).

## 8.9 Modern Period (1950-Present)

The population expansion fueled an increase in construction. Residential development in the vicinity of the APE is clearly expanding on the 1957 aerial photograph (**Figure 6**). All of the historic residences documented during this current survey that are located within the Dorsey Riverbend neighborhood are present by this time. By 1968, commercial businesses had appeared along much of Broward Boulevard in the vicinity of the APE (**Figure 7**). The surrounding residential neighborhoods had also been largely built out by this time (**Figure 7**). The 1973 aerial photograph shows the construction of I-95 through the project APE (**Figure 8**). Numerous buildings were demolished at that time to accommodate the new highway.



FPID: 435513-1-22-02

Figure 5 | 1949 Aerial Photograph showing a portion of the Project APE






Figure 6 | 1958 Aerial Photograph showing a portion of the Project APE








Figure 7 | 1968 Aerial Photograph showing a portion of the Project APE









Large portions of previously undeveloped Broward County were also transformed into residential developments in the 1950s and 1960s. As Broward County's population soared toward one million, several developers became overextended or came under criticism because of the close ties between their firms and the cities which they had created. Also, a growing number of newcomers feared that toorapid growth would create problems. At the beginning of the 1970s, residents began demanding that cities aim for slower growth and lower limits on the number of residences per acre. Gradually, governments began to respond (McGoun 1978).

During these years, the construction of I-95 affected many communities along Florida's east coast. Miles of fractured highway were incorporated into what would become the main vein of Florida's east coast. Construction of I-95 in southern Florida progressed throughout the 1960s. By 1976, most of the highway was complete from the Georgia State Line to Ft. Pierce and from Palm Beach Gardens to Miami, including the portion in Broward County. Within the project APE, I-95 was constructed through the portion of the North Woodlawn Cemetery that had previously been used as a potter's field.

Growth decreased in 1974, but not as a result of municipal actions. South Florida was hit by the recession sweeping the nation. Unsold properties were a major problem at this time, and at one point, there were an estimated 50,000 unsold condominium apartments in the area (McGoun 1978). By 1976, the building industry witnessed a revival. However, there were still concerns that the uncontrolled growth of the past would be repeated. A new county charter gave Broward's government broad powers to monitor and improve the quality of life and the environment. The passage of the 1977 Land Use Plan was a major step toward limiting urban sprawl and ensuring that the area's natural, economic, and social resources would be put to their best use (McGoun 1978).



FPID: 435513-1-22-02

#### 9.0 Florida Master Site File Search and Literature Review

An archaeological and historical literature and background information search pertinent to the study area has been performed. This research determined the chronological placement, types, and location patterning of cultural resources within the project APE.

This included a search of the FMSF, county and local site inventories, unpublished cultural resource management (CRM) reports, and other pertinent literature. The FMSF search will serve as a guide to the field investigations by identifying the possible locations of any archaeological sites and historic resources within the study area and providing expectations regarding the potential historic significance of any such sites. The FMSF serves as an archive and repository of information about Florida's recorded cultural resources. It represents an inventory of resources for which available information exists and describes their condition at a particular point of time. Because the inventory of resources is not all-inclusive on a statewide basis, gaps in data may exist. The FMSF is only as accurate and as comprehensive as the information that is submitted and users should be cognizant of the sometimes uneven quality of the information. The FMSF is an important planning tool that assists in identifying potential cultural resources issues and resources that may warrant further investigation and protection. It can be used as a guide but should not be used to determine the FDHR/SHPO's official position about the significance of a resource.

The work of previous investigators was reviewed in order to gather information about the types of precolumbian and early historic period sites that could be expected to occur within the study area. An extensive search of pertinent literature and records was conducted to determine the locations of previously recorded National Register of Historic Places (National Register)—listed, eligible, and potentially eligible resources within the study area, as well as any archaeological and historical assessments of other tracts of land within the study area.

# 9.1 Previously Conducted Cultural Resource Surveys

There has not been a comprehensive CRAS of the project corridor. The FMSF notes 17 previously conducted cultural resource surveys which intersected with or were within the project corridor. These surveys are described in **Table 4**. No archaeological testing has been conducted within the current APE during the previous surveys. The current I-95 ROW was surveyed during FMSF Survey No. 19752. No subsurface testing could be conducted within the majority of the I-95 ROW due to the presence of road berms and buried utilities. Four negative shovel tests were excavated just to the north of the current APE on the western edge of the ROW across from North Woodlawn Cemetery. Eight negative shovel tests were excavated just to the east of the current APE along the North Fork of the New River during FMSF Survey No. 20623.



FPID: 435513-1-22-02

Table 4 | Previous Cultural Resource Surveys within or adjacent to the Project Area

FMSF Survey No.	Title	Author(s)	Publication Date
730	Broward County Comprehensive Survey, Phase I	Carr, Robert S., Marlyn Kemper, and Hershall Shepard	1981
769	Archaeological Survey of Properties Designated for Construction of the Wingate Road Sludge Processing/disposal Facility and Connecting Pipeline Route to the NW 6th St. Pumping Station, Ft. Lauderdale	Kennedy, William J.	1982
2125	Historic properties survey of Fort Lauderdale, Florida.	Adams, William R., Sidney Johnston, and Stephen A. Olausen	1989
4075	An Archaeological Survey of Southeast Broward County, Florida: Phase 3	Carr, Robert S., Willard S. Steele, and Jorge Zamanillo	1995
5844	Tri-County Commuter Rail Authority Double Track Corridor Improvement Program for Segment 56756	Janus Research, Inc.	1999
6756	Cultural Resource Assessment Survey Technical Memorandum Rail Bridge Over the South Fork of the New River, Broward County, Florida	Schwarz, Rebecca Spain	2001
8198	New River Cultural and Environmental Survey	Work, Deborah	2002
10446	An Archaeological and Historical Assessment for the Existing NW 25th Terrace Cellular Tower, Broward County, Florida	Groff, Amanda T., and Jennifer L. F. Nash	2004
14376	Historic Resources Reconnaissance Survey and Archaeological Desktop Analysis I-95 Managed Lanes Pilot Project: 95 Express from: I-395 (Miami-Dade County) To: I- 595 (Broward County)	Janus Research	2007
18852	Archaeological Reconnaissance Survey of the Proposed Remilling and Expansion of SR 842/Broward Boulevard from Just East of SR 7/US 441 to NW 7 Avenue, Broward County, Florida. State Project No. 86006-3512, Work Program Item No. 4110742	Campbell, Ken, and Scott P. Lewis	1997
19752	Cultural Resource Assessment Survey SR 9 / I-95 PD&E Study from Stirling Road to North of Oakland Park Boulevard FM 42980412201 / ETDM 13168, Broward County, Florida	Janus Research	2012
20623	Cultural Resource Assessment Survey Update for the Broward Boulevard Bridge, Broward County, Florida FM# 429958.1	Janus Research	2013
21548	CRAS for Eight Potential Roadway Transfers from the FDOT, District 4, to Broward County: SR 824/Pembroke Rd., SR 848/Stirling Rd., Riverland Rd., SR 736/Davie Blvd., Las Olas Blvd., SR 849/NE 31st Ave., SR 844/NE 14th St.	Janus Research	2014
21985	Final Report Geophysical Investigation North Woodlawn Cemetery (BD4879) Fort Lauderdale, Florida	Taylor, Christopher	2015



# 9.2 Previously Recorded Archaeological Sites

No previously recorded archaeological sites were identified within or adjacent to the archaeological APE during a search of the FMSF. Twelve previously recorded sites were identified within one mile of the archaeological APE (**Table 5**; **Figure 9**). The project area intersects with a City of Fort Lauderdale Archaeologically Significant Zone along the North Fork of the New River at two locations: Broward Boulevard East of NW 18<sup>th</sup> Avenue and I-95 from 550 feet north of Broward Boulevard to NW 3<sup>rd</sup> Court (**Figure 9**).

Table 5 | Previously Recorded Archaeological Sites within One Mile of the Archaeological APE


•	_		
FMSF Site No.	Site Name	Site Type	National Register Eligibility*
8BD3	New River Earthworks	Precontact earthenworks, burial mound, midden	Not Evaluated by SHPO
8BD87	Rivermount	Precontact midden	Not Evaluated by SHPO
8BD102	Ft Lauderdale #1	Historic 19 <sup>th</sup> century fort	Not Evaluated by SHPO
8BD196	New River Midden	Glades period midden	Eligible
8BD203	Sailboat Bend Midden	Glades period midden	Not Evaluated by SHPO
8BD204	Ackerman Site	Glades period midden	Not Evaluated by SHPO
8BD205	Rose Site	Precontact midden	Not Evaluated by SHPO
8BD207	Sayward Site	Precontact and Seminole period midden	Not Evaluated by SHPO
8BD208	Hortt Site	Precontact midden	Not Evaluated by SHPO
8BD2906	Seminole Burial Ground	Seminole cemetery	Not Evaluated by SHPO
8BD2915	Annie Tommy Camp	Seminole camp	Not Evaluated by SHPO
8BD3943	Symphony Site	Historic refuse	Not Evaluated by SHPO

<sup>\*</sup> As recorded in the FMSF; may require re-evaluation



FPID: 435513-1-22-02

Figure 9 | Previously Recorded Archaeological Sites within One Mile and Archaeological Significant Zones





# 9.3 Previously Recorded Historic Resources

A search of the FMSF identified four previously recorded resources within the historic resources APE: Seaboard Airline Railroad Station (8BD1452), 2015 Northwest 3<sup>rd</sup> Court (8BD3414), Seaboard Air Line (CSX) Railroad (8BD4649), and the North Woodlawn Cemetery (8BD4879). **Table 6** lists the four resources. The Seaboard Airline Railroad Station (8BD1452), located at 200 SW 21<sup>st</sup> Terrace, was determined eligible for listing in the National Register by the SHPO in 1999. The historic structure located at 2015 Northwest 3<sup>rd</sup> Court (8BD3414) is a Frame Vernacular residence that was not evaluated by SHPO for its National Register–eligibility. The Seaboard Air Line (CSX) Railroad (8BD4649) within the current APE has been determined eligible for listing in the National Register by the SHPO in 2013. The North Woodlawn Cemetery (8BD4879) is located adjacent to the current ROW. The cemetery has been determined National Register–eligible by the SHPO and has already passed the state review board. It is currently being reviewed for listing in the National Register by the national review board as of the time of this report. No improvements are planned adjacent to the cemetery.

Table 6 | Previous Recorded Historic Resources within the Historic Resources APE

FMSF Site No.	Site Name / Address	Resource Type / Style	Date	National Register Eligibility
8BD1452	Seaboard Airline Railroad Station / 200 SW 21 <sup>st</sup> Terrace	Mediterranean Revival	1926– 1927	Eligible
8BD3414	2015 NW 3 <sup>rd</sup> Court	Frame Vernacular	1951	Not Evaluated by SHPO
8BD4649	Seaboard Air Line (CSX) Railroad	Historic Railroad Segment	c. 1927	Eligible
8BD4879	North Woodlawn Cemetery	Historic Cemetery	c. 1926	Under Review for Listing

#### 9.4 Potential Historic Resources

A search of the Broward County Property Appraisers identified 51 parcels within the historic resources APE with historic Actual Year Built (AYRB) dates of 1969 or earlier. Although fieldwork is needed to confirm the presence of extant historic resources on these parcels, as well as potential additional resources, the property appraiser search serves as a useful guide to the locations of potential resources within the APE. A review of aerial photographs from 1958 and 1968 (FDOT, Surveying and Mapping Office 2014) was also conducted to identify any unrecorded historic resources located within the historic resources APE. No historic bridges or other potentially unrecorded historic resources were identified within the historic resources APE during the background research.



FPID: 435513-1-22-02

## 9.5 Summary of ETDM Comments

The project was assigned a moderate degree of effect by the Florida Department of State (FDOS) and FDOT, District 4. The agencies reported that the majority of the project area was comprehensively surveyed as part of the SR 9 / I-95 PD&E Study from Stirling Road to North of Oakland Park Boulevard (Janus Research 2012), but that the current project should be compared to previous surveys. National Register–eligible historic resources identified within the project area included the CSX Railroad (8BD4649) and the Seaboard Airline Railroad Station (8BD1452). They noted that direct impacts to these resources should be avoided.

They also noted the Annie Tommy Camp archaeological site (8BD2915) in the vicinity of the project area, which is considered a sensitive site. The site is not within the current archaeological APE.



FPID: 435513-1-22-02

# 10.0 Project Research Design and Site Location Model

## 10.1 Precontact Archaeological Site Location Model

Four environmental factors are typically employed in predicting site locations: distance to fresh (potable) water, distance to hardwood hammocks, topography, and soil type (soil drainage). Zones of archaeological site potential are designated based on these environmental factors and previous research conducted within the Glades cultural region.

Probability zones along existing roads can be affected by underground utilities and the resulting effects of road construction which often include berms and ditches. Areas that may have originally been moderate or high site potential zones and are directly affected by modern development may decrease in potential due to soil disturbance.

Fresh water is obviously an important resource, as the need for water is universal. This variable would have been of greater importance during the Paleoindian and Early Archaic periods (12,000–5000 BC) when the perched water system was more restricted. The North Fork of the New River intersects the northern portion of the project area and the South Fork of the New River is to the south of the project area.

Hardwood hammocks (hydric, mesic, or xeric) provide a variety of resources that would have been exploited by the aboriginal inhabitants of this region. Often, areas of higher relative elevation correspond with better-drained soils or the presence of hardwood hammocks (xeric and mesic). Hammocks were described in the 1870 surveyor's notes to the north and south of a small creek that crossed the project area approximately between what is now SW 10<sup>th</sup> Court and SW 11<sup>th</sup> Street.

The project area is relatively flat at an elevation of approximately 5 feet above sea level.

The characteristics of soils have been used successfully by several researchers in the formulation of predictive models for precontact site location. As mentioned previously, most of the soils within the project area are poorly drained and have been disturbed by the construction of roadways and other urban features.

Based on the background research, the project area has low archaeological site potential for the presence of intact archaeological sites. The majority of the area has been heavily disturbed by previous construction activities. As mentioned earlier, the project area intersects with a City of Fort Lauderdale Archaeologically Significant Zone along the North Fork of the New River at two locations: Broward Boulevard East of NW 18<sup>th</sup> Avenue and I-95 from 550 feet north of Broward Boulevard to NW 3<sup>rd</sup> Court. These two areas are within the project APE of FMSF Survey Nos. 19752 and 20623, which have received SHPO concurrence (**Appendix B**).



FPID: 435513-1-22-02

# 10.2 Historic Archaeological Site Location Model

The historic plat maps were also reviewed for evidence of other early settlement. This review of the historic plat maps and surveyor's notes identified no military forts, roads, encampments, battlefields, homesteads, or historic Native American villages or trails located within or adjacent to the archaeological APE. The archaeological APE has low probability for intact historic archaeological sites.



FPID: 435513-1-22-02

## 11.0 METHODS

## 11.1 Archaeological Field Methods

The archaeological field survey included a surface inspection which consisting of a visual inspection of exposed ground to look for evidence of archaeological sites. Additionally, a careful surface inspection was undertaken in areas of minimal vegetation and/or upturned soil such as drainage ditches, recent clearings, and animal burrows. No subsurface testing was conducted in the vicinity of buried utilities due to the potential for substantial fines if a utility is damaged and concern for the safety of archaeological field teams.

Standard archaeological methods for recording field data was followed throughout the project. Field conditions and the locations of buried utilities were recorded on field aerial maps of the project APE.

## 11.2 Historic Resources Field Methods

An architectural historian and historic technician conducted a historic resources survey in order to ensure that resources built during or before 1969 within the project APE were identified, properly mapped, and photographed. The historic resources survey used standard field methods to identify and record historic resources. Resources within the APE received a preliminary visual reconnaissance. Resources with features indicative of 1969 or earlier construction materials, building methods, or architectural styles were noted on aerial photographs.

For each identified historic resource, FMSF forms were filled out with field data, including notes from site observations and research findings. The estimated date of construction, distinctive features, and architectural style were noted. Photographs were taken with a high resolution digital camera. A log was kept to record the building's physical location and compass direction of each photograph. The FMSF form was also updated for the previously recorded Seaboard Air Line (CSX) Railroad (8BD4649), as this linear resource was not previously evaluated within the current APE.

In addition to a search of the FMSF, Broward County Property Appraiser information was also used to approximate building construction dates within the project APE. Together, the GIS Data Sets and property appraiser information usually yield the dates of the majority of the historic resources located within the project APE. The project architectural historian identifies any resource not accounted for by this information in the field based on the aforementioned methods.

Each resource's individual significance was then evaluated for its potential eligibility for listing in the National Register. Historic physical integrity was determined from site observations, field data, and photographic documentation. Local information was consulted to assist in the research for known significant historical associations.

Concentrations of historic resources within the APE for the project were noted in terms of the potential for inclusion in a historic district. Each resource's present condition, location relative to other resources,



FPID: 435513-1-22-02

FPID: 435513-1-22-02 ETDM: 14226

and distinguishing neighborhood characteristics were noted and photographed for accurate assessment of National Register Historic District eligibility.

## 11.3 Local informants and Certified Local Government Coordination

Local informants may often provide valuable information which is otherwise not available through official records or library collections. The City of Fort Lauderdale is included on the July 14, 2017 list of Certified Local Governments (CLG) available on the FDHR website (FDHR 2017). Therefore, Ms. Linda Mia Franco, Fort Lauderdale Historic Preservation Liaison, was contacted via email on October 5, 2017 for input on the proposed project and information on potential cultural resources within the project APE. Ms. Franco responded later the same day via email stating that she had forwarded the coordination email to Trisha Logan, the City's Historic Preservation Planner, for her review and input. Ms. Logan responded via email on October 10, 2017 and provided a list of locally designated historic landmarks that are located in or near the project APE. North Woodlawn Cemetery and the Seaboard Air Line Railroad Station are located within, or partially within, the current APE, and are discussed in this report. Avis McSmith House, located at 611 NW 15<sup>th</sup> Avenue, Haehle House, located at 315 SW 19<sup>th</sup> Avenue, and the Sailboat Bend Historic District were also noted by Ms. Logan, but all are located outside of the current project APE.



## 12.0 Results

## 12.1 Archaeological Results

No previously recorded or newly recorded archaeological sites were identified within the archaeological APE. Background research and a pedestrian survey indicated that there is a low probability of finding intact archaeological sites within the archaeological APE. The majority of the project area has been previously surveyed during FMSF Survey Nos. 19752 and 20623 (Janus Research 2012, 2013) that have received SHPO concurrence (**Appendix B**). Subsurface archaeological testing was not feasible within the previously unsurveyed portion of the archaeological APE due to the existence of pavement, sidewalks, berms, buried utilities, landscaping, and residential and commercial frontage (**Appendix C**). Representative photographs of the archaeological APE are included below (**Figures 10–12**).

Figure 10 | Landscaped Berm East Side of I-95 Along NW 21st Avenue, Facing Southwest





FPID: 435513-1-22-02

Figure 11 | Utilities Along Broward Boulevard at NW 18th Avenue, Facing East



Figure 12 | Standing Water within I-95 ROW at Davie Boulevard, Facing South





## 12.2 Historic Resources Survey Results

The CRAS identified a total of 52 historic resources within the historic APE. The identified historic resources include one cemetery (North Woodlawn Cemetery–8BD4879), two resource groups (Seaboard Air Line [CSX] Railroad–8BD4649 and the Salvation Army Complex–8BD6346), and 49 buildings (8BD1452 and 8BD6298–8BD6344). Four of the historic resources were previously recorded (8BD1452, 8BD3414, 8BD4649, and 8BD4879), and 48 are newly recorded (8BD6298–8BD6344 and 8BD6347).

Three historic resources, Seaboard Airline Railroad Station at 200 SW 21st Terrace (8BD1452), Seaboard Air Line (CSX) Railroad (8BD4649), and North Woodlawn Cemetery (8BD4879), were previously determined National Register—eligible by the SHPO. The Seaboard Airline Railroad Station (8BD1452) was determined eligible for the National Register in 1999. The portion of the Seaboard Air Line (CSX) Railroad (8BD4649) within the current APE was previously documented and found National Register—eligible as a result of the *CRAS* of the *SR* 9/I-95 PD&E Study from Stirling Road to North of Oakland Park Boulevard, conducted by Janus Research in 2013. North Woodlawn Cemetery (8BD4879) was also determined National Register-eligible by the SHPO as a result of the 2013 CRAS. The cemetery has already passed the state review board and is currently being reviewed for listing in the National Register by the national review board as of the time of this report. The field survey conducted as part of the current CRAS found that no notable alterations have taken place to any of these three significant historic resources since the time of their previous evaluations. Therefore, all three remain eligible for inclusion in the National Register.

All other historic resources located within the current APE are considered individually ineligible for inclusion in the National Register. Almost all the newly recorded historic buildings are representative of common postwar constructed architecture that does not possess sufficient significance for individual listing in the National Register. Many of these buildings also exhibit exterior modifications that compromise their historic integrity. The majority of the buildings are Masonry Vernacular in style, with few notable architectural features.

A visual assessment in the vicinity of the project APE along NW 21st Avenue and NW 3rd Court was undertaken in order to determine National Register historic district potential in the African-American Dorsey Riverbend neighborhood. Although portions of the subdivisions which make up the Dorsey Riverbend neighborhood had been platted by 1912, most existing examples of historic residences and commercial buildings within Dorsey Riverbend are post-World War II era through the 1960s. The Dorsey Riverbend neighborhood was previously assessed for potential National Register historic district eligibility during the CRAS for Powerline Road/NW 9th Avenue from Broward Boulevard to Sistrunk Boulevard, Fort Lauderdale, Broward County, Florida, conducted by Janus Research in 2015. This previous survey found that area of the Dorsey Riverbend neighborhood within that survey's APE would not qualify for inclusion in the National Register as a historic district, and that the immediately surrounding area did not appear to meet National Register criteria for listing. The portion of the neighborhood within and in the immediate vicinity of the 2015 APE did not possess historic integrity as the area had been substantially altered. The SHPO concurred with this finding on November 23, 2015. A portion of the Dorsey Riverbend neighborhood was again surveyed by Janus Research during the 2017 CRAS of the Design Build



FPID: 435513-1-22-02

Broward Mobility Project, Group 5B (Sequences 190, 200, 210, 220, 230, 240, 250, and 270), Broward County, Florida. Again, Janus Research found that the section of the neighborhood within the APE for this previous 2017 project did not possess historic integrity, and so did not meet the criteria for a National Register historic district. Based on the fieldwork, the current survey concurs with these earlier findings that the Dorsey Riverbend neighborhood does not meet the criteria for National Register historic district eligibility. As such, newly recorded historic resources within the APE in this neighborhood are ineligible for listing in the National Register as part of a historic district.

A portion of the APE along NW 21<sup>st</sup> Terrace to the west of I-95 also includes part of the River Garden/Sweeting Estates. The historic buildings within this neighborhood are also comprised of postwar Masonry Vernacular residences. However, the fieldwork found that this neighborhood also contains a large number of demolitions and vacant lots, non-historic infill, and substantial alternations on many of the historic homes that do remain. Therefore, there is no potential for a National Register historic district within in this area. Similar characteristics were observed in the vicinity of all the other documented resources within the current APE, and as such there is no potential for a National Register historic district anywhere within the current project APE.

Table 7 lists all resources identified as part of the current study, and their physical location is depicted on current aerial mapping contained in Figures 13a-e. Figures 14-75 include photographs of all identified historic resources. While the FMSF forms, as well as the general explanation above regarding the lack of eligibility for the historic resources within the APE, is sufficient for most of these resources, the Salvation Army Complex (8BD6347) required additional explanation. Therefore, a narrative description and further explanation of eligibility for this resource group is included below. Brief explanations of the eligibility for the three previously determined National Register-eligible historic resources (8BD1452, 8BD4649, and 8BD4879) are also included below. FMSF forms were not updated for these three National Register-eligible resources, as their eligibility status remains unchanged due to the lack of any notable alterations since their previous recordation. The FMSF form was updated for the previously recorded house located at 2015 NW 3rd Court (8BD3414), and this resource is still considered ineligible for the National Register. The three National Register-eligible resources are discussed immediately following the identified resources maps (Figures 13a-e), and are followed by photographs of each of the remaining historic resources within the APE (Figures 17-75). The photographs are in order by FMSF number, with the exception of the Salvation Army Complex (8BD6347) (Figures 17–27), which is placed beforehand as it requires additional explanation. The previous forms for the three eligible resources, as well as all of the newly completed FMSF forms, are contained in Appendix A.

Table 7 | Identified Historic Resources within the Historic APE

FMSF No.	Name / Address	Year Constructed	Type / Style	National Register Status
8BD1452	Seaboard Airline Railroad Station / 200 SW 21 <sup>st</sup> Terrace	1926–1927	Mediterranean Revival	Determined Eligible
8BD3414	2015 NW 3 <sup>rd</sup> Court	1951	Frame Vernacular	Considered Ineligible



FPID: 435513-1-22-02

FMSF No.	Name / Address	Year Constructed	Type / Style	National Register Status
8BD4649	Seaboard Air Line (CSX) Railroad	c. 1927	Historic Railroad Segment	Determined Eligible
8BD4879	North Woodlawn Cemetery	c. 1926	Historic Cemetery	Under Review for Listing
8BD6298	1920–1932 NW 9 <sup>th</sup> Street	c. 1958	Masonry Vernacular	Considered Ineligible
8BD6299	808 NW 20 <sup>th</sup> Avenue	c. 1949	Masonry Vernacular	Considered Ineligible
8BD6300	729 NW 20 <sup>th</sup> Avenue	c. 1960	Masonry Vernacular	Considered Ineligible
8BD6301	632 NW 21st Avenue	c. 1952	Masonry Vernacular	Considered Ineligible
8BD6302	616 NW 22 <sup>nd</sup> Road	c. 1960	Masonry Vernacular	Considered Ineligible
8BD6303	614 NW 22 <sup>nd</sup> Road	c. 1954	Masonry Vernacular	Considered Ineligible
8BD6304	524 NW 21st Terrace	c. 1959	Masonry Vernacular	Considered Ineligible
8BD6305	516 NW 21st Terrace	c. 1963	Masonry Vernacular	Considered Ineligible
8BD6306	448 NW 21 <sup>st</sup> Terrace	c. 1954	Masonry Vernacular	Considered Ineligible
8BD6307	444 NW 21 <sup>st</sup> Terrace	c. 1956	Masonry Vernacular	Considered Ineligible
8BD6308	442 NW 21 <sup>st</sup> Terrace	c. 1953	Masonry Vernacular	Considered Ineligible
8BD6309	428 NW 21st Terrace	c. 1955	Masonry Vernacular	Considered Ineligible
8BD6310	424 NW 21 <sup>st</sup> Terrace	c. 1964	Masonry Vernacular	Considered Ineligible
8BD6311	420 NW 21 <sup>st</sup> Terrace	c. 1962	Masonry Vernacular	Considered Ineligible
8BD6312	416 NW 21 <sup>st</sup> Terrace	c. 1962	Masonry Vernacular	Considered Ineligible
8BD6313	412 NW 21 <sup>st</sup> Terrace	c. 1962	Masonry Vernacular	Considered Ineligible
8BD6314	536 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6315	532 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6316	528 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible



FMSF No.	Name / Address	Year Constructed	Type / Style	National Register Status
8BD6317	524 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6318	520 NW 21st Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6319	516 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6320	512 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6321	508 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6322	504 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6323	500 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6324	444 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6325	440 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6326	436 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6327	432 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6328	428 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6329	424 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6330	420 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6331	416 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6332	412 NW 21 <sup>st</sup> Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6333	408 NW 21st Avenue	c. 1950	Masonry Vernacular	Considered Ineligible
8BD6334	404 NW 21 <sup>st</sup> Avenue	c. 1951	Masonry Vernacular	Considered Ineligible
8BD6335	2019 NW 3 <sup>rd</sup> Court	c. 1955	Masonry Vernacular	Considered Ineligible
8BD6336	2016 NW 3 <sup>rd</sup> Court	c. 1965	Masonry Vernacular	Considered Ineligible
8BD6337	2008 NW 3 <sup>rd</sup> Court	c. 1962	Masonry Vernacular	Considered Ineligible
8BD6335 8BD6336	2019 NW 3 <sup>rd</sup> Court 2016 NW 3 <sup>rd</sup> Court	c. 1955 c. 1965	Masonry Vernacular Masonry Vernacular	Ineligible Considered Ineligible Considered Ineligible Considered



FMSF No.	Name / Address	Year Constructed	Type / Style	National Register Status
8BD6338	2001 NW 3 <sup>rd</sup> Court	c. 1959	Masonry Vernacular	Considered Ineligible
8BD6339	1800–1803 W Broward Boulevard	c. 1963	Masonry Vernacular	Considered Ineligible
8BD6340	709 SW 20 <sup>th</sup> Terrace	c. 1954	Masonry Vernacular	Considered Ineligible
8BD6341	713 SW 20 <sup>th</sup> Terrace	c. 1953	Masonry Vernacular	Considered Ineligible
8BD6342	717 SW 20 <sup>th</sup> Terrace	c. 1953	Masonry Vernacular	Considered Ineligible
8BD6343	1914 SW 8 <sup>th</sup> Street	c. 1953	Masonry Vernacular	Considered Ineligible
8BD6344	1910 SW 8 <sup>th</sup> Street	c. 1955	Masonry Vernacular	Considered Ineligible
8BD6347	Salvation Army Complex / 1901 W Broward Boulevard	c. 1957	Building Complex	Considered Ineligible



Figure 13a | Identified Historic Resources (Overview Map)






Figure 13b | Identified Historic Resources (Map 1 of 4)






Figure 13c | Identified Historic Resources (Map 2 of 4)







Figure 13d | Identified Historic Resources (Map 3 of 4)





Figure 13e | Identified Historic Resources (Map 4 of 4)





## 12.2.1 Historic Resources Determined Individually National Register–eligible

Figure 14 | Seaboard Airline Railroad Station, located at 200 SW 21st Terrace (8BD1452), facing Southeast



### 8BD1452 Seaboard Airline Railroad Station

The circa-1926/1927 Seaboard Airline Railroad Station (8BD1452) (**Figure 14**) is located at 200 SW 21<sup>st</sup> Terrace and still serves its original purpose as a railroad station. It was designed by architect Gustav A. Maass in the Mediterranean Revival style, and is representative of the transportation boom that took place in Fort Lauderdale and across southeast Florida during the Boom Times of the 1920s. For significance under Criteria A and C in the areas of Transportation and Architecture, the SHPO determined on December 20, 1999 that the Seaboard Airline Railroad Station was eligible for listing in the National Register. This building is also locally-designated within the City of Fort Lauderdale.



FPID: 435513-1-22-02

Figure 15 | Seaboard Air Line (CSX) Railroad (8BD4649), as seen from Broward Boulevard overpass, facing North



### 8BD4649 Seaboard Air Line (CSX) Railroad

The segment of the Seaboard Air Line (CSX) Railroad (8BD4649) (**Figure 15**) within the APE is located between Sunrise Boulevard and SW 5<sup>th</sup> Place, and features a double-track configuration over a gravel ballast. The approximate 1.06 miles of tracks within the APE maintains its historic orientation and configuration and is significant for its contributions to the patterns of development and transportation in the State. Therefore, the SHPO determined on March 27, 2013 that the current segment of the Seaboard Air Line (CSX) Railroad was eligible for listing in the National Register under Criterion A in the areas of Community Planning and Development and Transportation.



FPID: 435513-1-22-02

Figure 16 | North Woodlawn Cemetery (8BD4879), facing West toward I-95



### 8BD4879 North Woodlawn Cemetery

North Woodlawn Cemetery (8BD4879) (**Figure 16**) was established in 1926, and is located on the west side of NW 19<sup>th</sup> Avenue, between NW 9<sup>th</sup> Street and Sunrise Boulevard. The cemetery serves as the final resting place for many of the areas pioneering African American residents. It was the only cemetery in Fort Lauderdale where African Americans could be buried until 1962 (Janus Research 2012). North Woodlawn Cemetery possesses local significance under Criterion A in the area of ethnic heritage, for its connection to the early African American community in the northwest quadrant Fort Lauderdale. The cemetery also meets National Register Criteria Consideration D for its connection to historical events, as it is one of the few remaining resources associated with Fort Lauderdale's African American community during the period of racial segregation. North Woodlawn Cemetery was determined eligible for the National Register by the SHPO on March 27, 2013. The cemetery has already passed the state review board and is currently being reviewed for listing in the National Register by the national review board as of the time of this report. North Woodlawn Cemetery is also locally-designated within the City of Fort Lauderdale.



FPID: 435513-1-22-02

## 12.2.2 Historic Resources Considered Individually National Register-ineligible

### 8BD6347 Salvation Army Complex

This resource group is comprised of seven concrete block Masonry Vernacular and two metal frame Industrial Vernacular style building located on an approximately 14.5-acre property at 1901 W Broward Boulevard in Section 4 of Township 50 South, Range 42 East on the Fort Lauderdale South (1962, photorevised 1983) United States Geological Survey (USGS) quadrangle map. The property is bounded by I-95 to the west, W Broward Boulevard to the south, the North Fork Riverfront Park in the northeast corner, and the North Fork of the New River to the east and north. Although the historic buildings were likely associated with demolished historic buildings west of the boundaries, much of the area around the intersection of W Broward Boulevard and the Seaboard Air Line (CSX) Railroad (8BD4649) was affected by the construction of I-95. Since the buildings in the area that may have been associated with the extant historic buildings were demolished for I-95, the current western boundary for the Salvation Army Complex follows I-95, which curves in a northwest-southeast direction.

Most of the property is paved, with landscaping around the buildings, and the edges of the property. Four of the Masonry Vernacular building are historic, and the other seven buildings on the complex are non-historic. Two buildings are located within the project APE, the c. 1967 Adult Rehabilitation Center and the c. 2000 Super Store. The Adult Rehabilitation Center is the largest building on the complex, and portions of the building serve as storage, auction area, and the donation drop off location.

The development of the Salvation Army Complex and the area around it has been gradual. The original use of the property is unknown, but the Salvation Army obtained the property in 1980 (Broward County 1980). A review of historic aerials shows that four of the Masonry Vernacular buildings are historic. The oldest building on the complex, Warehouse 1, can be seen in the 1958 aerial (**Figure 17**). By 1968, five more buildings were constructed: Warehouse 2, Warehouse 3, the Adult Rehabilitation Center, and two smaller buildings in the northwest and southeast corners of the property that were demolished in the 1990s (**Figure 18**). The 1958 and 1968 aerials also show a building next to the railroad that may have been a train station, but this building and three others that may have been associate with the Salvation Army Complex were demolished in the 1970s when I-95 was built. By 1988, Warehouses 4 and 5 and Offices 1 and 2 were constructed (**Figure 19**). A current aerial shows the addition to the Adult Rehabilitation Center, c. 1990, and the Super Store, c. 2000 (**Figure 20**).



FPID: 435513-1-22-02





Figure 40 L4000 conicles Columbiae America Commission (ODDC) 47





FPID: 435513-1-22-02 ETDM: 14226

Figure 19 | 1988 aerial of Salvation Army Complex (8BD6347)









FPID: 435513-1-22-02 ETDM: 14226


Figure 21 | Salvation Army Complex (8BD6347), Warehouse 1, c. 1957, looking North



#### Warehouse 1

Warehouse 1 is the oldest building on the complex having been constructed c. 1957 (**Figure 21**). This one and a half story Masonry Vernacular warehouse was built in two phases. The west half of the building was completed c. 1957, and shortly after in 1958 the east half of the building was completed. The building is constructed of concrete block painted white. There are nine bays with rolling garage doors on each of the north and south sides. The windows on the west end of the building have iron security bars, which make it impossible to see what style the windows are. There is a set of stairs with a small platform leading to a metal door on the west side. That is the only known entrance, because the east side of the building is not visible. There are flat roof overhangs on the north, east, and south sides of the east half of the building. The building has a flat built-up roof.





#### Warehouse 2

This one and a half story Masonry Vernacular building sits just south of Warehouse 1. It was constructed c. 1967 of concrete block covered in white stucco (**Figure 22**). There are two bays with rolling garage doors on each of the north and south sides. The building has no windows, and there is no other visible entrance. The west end of the building is only one story tall with no windows or doors, and its purpose is unclear. The building has a flat, built-up roof.


#### Warehouse 3

This one and a half story Masonry Vernacular building sits just north of Warehouse 1. It has a simple form and was constructed c. 1967 of concrete block with a shed roof overhang on the north side. There are three loading bays on the north side. The main entrance is a west-facing panel door in the southwest corner. There are two double windows and three single windows on the west side. Iron security bars cover the windows. The south side of the building is blank, and the east side is not visible. The building has a flat, built-up roof.



FPID: 435513-1-22-02

Figure 23 | Salvation Army Complex (8BD6347), Adult Rehabilitation Center, c. 1967, looking Northeast



#### Adult Rehabilitation Center

This Masonry Vernacular building sits southeast of Warehouses 1 and 2, at the northwest corner of W Broward Boulevard and NW 18<sup>th</sup> Avenue. It was once a warehouse, but is currently used as the Salvation Army Adult Rehabilitation Center (**Figure 23**). This building was constructed c. 1967 of concrete block and is covered in brick painted grey. It has always been irregularly shaped, originally having four large connected massings. The two-story portion of the building in the northwest corner was likely the original office. It has evenly spaced one-over-one single-hung-sash windows on the east side of the second story. The west side has several single door entrances on the first floor and double windows on the second floor. There are only two windows on the south side of the second story. All the windows sit under flat roof overhangs.

The one-story, L-shaped massing south of the two-story office is currently used as the entrance to the Adult Rehabilitation Center. It has one-light fixed windows on the south side. A concrete screen wall encloses the uncovered patio. There is a large Salvation Army sign on the southern concrete screen wall. A single, south-facing commercial glass door with transom and side light serves as the only entrance from the building to the uncovered patio. The building's main entrance sits under a flat roof overhang supported by one large concrete block column. The south-facing commercial glass double door has storefront windows surrounding it. A secondary entrance sits under the same roof overhang. It is a simpler east-facing commercial glass door with a transom and no side lights. There is landscaping around this portion of the building with shrubs and trees lining the south side, entrance, and uncovered patio.



FPID: 435513-1-22-02

The central and east portions of the building were originally warehouses with loading bays on the north and south sides. The central portion is five bays wide. The bays have been enclosed with what appears to be plywood painted grey to match the brick. There is a small roof overhang above the bays. The original north side bays are no longer visible due to a large addition completed c. 1990. The north and west sides of the addition are not visible. However, from NW 18<sup>th</sup> Avenue three single metal door entrances and one loading bay are visible on the east side of the addition. No windows are visible. There are two doors and a bay recessed in a raised loading dock on the east side of the original central portion of the building. The large north addition is currently used as the "as is" auction area.

The original east portion of the building was extended south c. 1980, so that its south side was in line with the south side of the central portion of the building. The extension is five bays wide like the central portion. On the east side of the extension, which is not in line with the original east side, has a metal double door entrance. The original east side is blank except for three one-light fixed windows. There are flat roof overhands along the south and east sides of the east portion. The north side continues to be used as a loading dock, as this is currently the donation drop off location. The raised loading dock is L-shaped along the north side of the east portion and the east side of the original central portion of the building. Due to low visibility it's unclear exactly how many bays are recessed in the raised loading dock, but there are at least two bays. One bay is east-facing, and the other is north-facing. The loading dock has a flat roof extension with four supports along the north side, and a ramp at the northeast corner.

All portions and additions of the building have flat, built-up roofs Most of the area around the Adult Rehabilitation Center has been paved for parking and loading. There have been several alterations and additions to this building. Most of the windows appear to have been replaced in the 1980s. The main south-facing entrance was likely altered to accommodate the 1980s commercial glass double doors and window wall. Many other doors also appear to be 1980s replacements.



FPID: 435513-1-22-02

Figure 24 | Salvation Army Complex (8BD6347), Warehouse 4, c. 1985, looking West



#### Warehouse 4

This Industrial Vernacular building sits just north of the Adult Rehabilitation Center. It has a simple form and was constructed c. 1985 with a metal steel frame covered in metal siding (**Figure 24**). The north and south sides are blank with no window or door openings. The west side of the building is not visible. The east side has a simple metal door in the southeast corner with a two-light sliding window to its right. There are also two large bays with rolling garage doors on the east side. The roof is side-gabled and covered in standing seam metal sheets.

#### Warehouse 5

This Masonry Vernacular building sits just west of Warehouse 1. It has a simple form and was constructed c. 1985 of concrete block covered in stucco. The north and south sides are blank with no window or door openings. The north side is longer than south side, so that the slanted west side is parallel to the I-95 ramp west of it. The west side of the building is not visible and backs up to a line of trees and I-95. The east side has two metal doors, two widows, and two loading bays with rolling garage doors. The loading bays are in the northeast and southeast corners. The windows are one-light fixed and covered in metal security bars. The building has a flat, built-up roof.



FPID: 435513-1-22-02

ETDM: 14226

Figure 25 | Salvation Army Complex (8BD6347), Office 1, c. 1978, looking Northwest



### Office 1

This Industrial Vernacular building sits just northwest of Warehouse 4 (**Figure 25**). It has a simple form and was constructed c. 1978 with a metal steel frame covered in metal siding. The northwest side is blank with no window or door openings. The northeast side has six five-light awning windows, three in the center and three on the left side. The southwest side is not visible. The entrance is a simple metal door on the southeast side, which sits under a canvas awning. There is a similar awning over the three windows. The three windows are five-light awning similar to those on the northeast side. The front-gabled roof is covered in 5V crimped metal sheets.





### Office 2

This two-story Masonry Vernacular building sits in the northwest corner of the property along the North Fork of the New River (Figure 26). It was constructed c. 1985 of concrete block and is covered in grey stucco. The building has an irregular form, and the west portion of the building was formerly a warehouse. The north and west sides of the building are not visible. The east portion of the building is only one-story tall, and contains both the main and secondary entrances recessed along its south side. The east side has four recessed bays with metal, one-light fixed windows at the top. The east-facing main entrance is a metal door with a square light recessed in the southeast corner under a canvas awning. There are four south-facing thin vertical windows recessed in the same space. The south-facing secondary entrance is a simple metal door to the left of the main entrance. It is also recessed and has a canvas awning. There were originally seven bays along the south side of the two-story portion of the building. Only the bay in the southwest corner has remained altered. The one directly to the right of it was completely enclosed with plain stucco. Each of the remaining five bays to the right were enclosed with scored stucco and a row of five four-light awning windows at the top. Both portions of the building have a flat, built-up roof.



FPID: 435513-1-22-02

FPID: 435513-1-22-02 ETDM: 14226



Figure 27 | Salvation Army Complex (8BD6347), Super Store, c. 2000, looking Northeast

### Super Store

This Masonry Vernacular building sits just east of the Adult Rehabilitation Center, at the northeast corner of W Broward Boulevard and NW 18<sup>th</sup> Avenue. The Super Store was constructed c. 2000 of concrete blocked and covered in stucco (**Figure 27**). The building is generally rectangular; however, the southwest and southeast corners extend out slightly. There are storefront windows that run from just north of and around the southwest corner, along the south side, around the southeast corner, and ending just north of the southeast corner. There are metal awnings over the windows. The south-facing commercial glass double doors with transom and side lights sits amongst the storefront windows under a portico. A two-story entry portico is located centrally along the south side, and is taller than the rest of the building. Other than the storefront windows, the east and west sides are blank with no other openings. The north side has a simple metal door and a loading bay with rolling garage door in the northeast corner. There are stucco walls around the AC units on the north side. Most of the area around the Super Store is paved for parking. The building has a flat, built-up roof.

The Salvation Army was founded in London in 1865 by William Booth (Salvation Army 2014). He was dedicated to working with the poor and homeless. In 1879 the Salvation Army came to the United States starting in Philadelphia before quickly expanding into New York (Salvation Army 2014). The organization was instrumental in both World Wars in providing help to soldiers and civilians alike.

In Broward County, Ivy Stranahan helped establish the Salvation Army in 1926 and was one of its original board members (Salvation Army 2014). Today, the group owns several properties throughout Broward County. They acquired the property discussed here in 1980. The historic buildings on the property had



ETDM: 14226

served a different purpose before that is unclear. Despite the proximity to the Seaboard Air Line (CSX) Railroad (8BD4649), the building complex does not appear associated with the railroad.

The Industrial Vernacular and Masonry Vernacular styles are highly prevalent approaches to architectural design for industrial complexes in Florida and the Salvation Army Complex buildings are common examples of the styles from their period and place of construction. Of the nine buildings within the complex, four are historic. The area around the complex has been substantially altered through the 1970s construction of I-95 and the development along Broward Boulevard. Additionally, the four historic Masonry Vernacular buildings have sustained substantial alterations. Therefore, the Salvation Army Complex located at 1901 W Broward Boulevard is considered National Register—ineligible under Criteria A, B, C, or D, both individually and as part of a historic district.










Figure 30 | 808 NW 20th Avenue (8BD6299), c. 1949, facing Northwest





Figure 31 | 729 NW 20th Avenue (8BD6300), c. 1960, facing Southwest



Figure 32 | 632 NW 21st Avenue (8BD6301), c. 1952, facing Southwest





Figure 33 | 616 NW 22<sup>nd</sup> Road (8BD6302), c. 1960, facing East



Figure 34 | 614 NW 22<sup>nd</sup> Road (8BD6303), c. 1954, facing South





Figure 35 | 524 NW 21st Terrace (8BD6304), c. 1959, facing Southeast



Figure 36 | 516 NW 21st Terrace (8BD6305), c. 1963, facing Southeast





Figure 37 | 448 NW 21st Terrace (8BD6306), c. 1954, facing Southeast



Figure 38 | 444 NW 21st Terrace (8BD6307), c. 1956, facing Southeast





Figure 39 | 442 NW 21st Terrace (8BD6308), c. 1953, facing Northeast



Figure 40 | 428 NW 21st Terrace (8BD6309), c. 1955, facing Southeast





Figure 41 | 424 NW 21st Terrace (8BD6310), c. 1964, facing Southeast



Figure 42 | 420 NW 21st Terrace (8BD6311), c. 1962, facing Southeast





Figure 43 | 416 NW 21st Terrace (8BD6312), c. 1962, facing Northeast



Figure 44 | 412 NW 21st Terrace (8BD6313), c. 1962, facing Northeast





Figure 45 | 536 NW 21st Avenue (8BD6314), c. 1950, facing Northeast



Figure 46 | 532 NW 21st Avenue (8BD6315), c. 1950, facing Northeast





Figure 47 | 528 NW 21st Avenue (8BD6316), c. 1950, facing Southeast



Figure 48 | 524 NW 21st Avenue (8BD6317), c. 1950, facing Northeast





Figure 49 | 520 NW 21st Avenue (8BD6318), c. 1950, facing Northeast



Figure 50 | 516 NW 21st Avenue (8BD6319), c. 1950, facing Northeast





ETDM: 14226

Figure 51 | 512 NW 21st Avenue (8BD6320), c. 1950, facing Southeast



Figure 52 | 508 NW 21st Avenue (8BD6321), c. 1950, facing Southeast





ETDM: 14226

Figure 53 | 504 NW 21st Avenue (8BD6322), c. 1950, facing Southeast



**Figure 54** | 500 NW 21st Avenue (8BD6323), c. 1950, facing Northeast





**Figure 55** | 444 NW 21<sup>st</sup> Avenue (8BD6324), c. 1950, facing Northeast



Figure 56 | 440 NW 21st Avenue (8BD6325), c. 1950, facing Southeast





Figure 57 | 436 NW 21st Avenue (8BD6326), c. 1950, facing Southeast



**Figure 58** | 432 NW 21<sup>st</sup> Avenue (8BD6327), c. 1950, facing Northeast







Figure 60 | 424 NW 21st Avenue (8BD6329), c. 1950, facing Southeast






Figure 61 | 420 NW 21st Avenue (8BD6330), c. 1950, facing Southeast



Figure 62 | 416 NW 21st Avenue (8BD6331), c. 1950, facing Northeast





**-**



**Figure 64** | 408 NW 21<sup>st</sup> Avenue (8BD6333), c. 1950, facing Northeast







Figure 66 | 2019 NW 3<sup>rd</sup> Court (8BD6335), c. 1955, facing Northeast





Figure 67 | 2016 NW 3<sup>rd</sup> Court (8BD6336), c. 1965, facing South



**Figure 68** | 2008 NW 3<sup>rd</sup> Court (8BD6337), c. 1962, facing Southeast





Figure 69 | 2001 NW 3<sup>rd</sup> Court (8BD6338), c. 1959, facing North



Figure 70 | 1800–1803 W Broward Boulevard (8BD6339), c. 1963, facing Northwest







Figure 72 | 713 SW 20th Terrace (8BD6341), c. 1953, facing West





**Figure 73** | 717 SW 20<sup>th</sup> Terrace (8BD6342), c. 1953, facing Southwest



Figure 74 | 1914 SW 8th Street (8BD6343), c. 1953, facing Southwest





**Figure 75** | 1910 SW 8<sup>th</sup> Street (8BD6344), c. 1955, facing Southwest





# 13.0 Conclusions

The objective of the CRAS for the SR-9/I-95 at SR 842/Broward Boulevard Interchange Project Development & Environment (PD&E) Study in the City of Fort Lauderdale, Broward County, Florida was to identify cultural resources within the project APE and assess their eligibility for listing in the National Register according to the criteria set forth in 36 CFR Section 60.4.

No newly or previously recorded archaeological sites were identified within the archaeological APE. Subsurface testing was not feasible within the archaeological APE due to the presence of existing pavement, sidewalks, berms, landscaping, and buried utilities. The pedestrian survey of the archaeological APE confirmed the developed nature of the project corridor and confirmed the low potential for finding intact archaeological sites.

The CRAS identified a total of 52 historic resources within the historic APE. The identified historic resources include one cemetery (North Woodlawn Cemetery–8BD4879), two resource groups (Seaboard Air Line [CSX] Railroad–8BD4649 and the Salvation Army Complex–8BD6346), and 49 buildings (8BD1452 and 8BD6298–8BD6344). Four of the historic resources were previously recorded (8BD1452, 8BD3414, 8BD4649, and 8BD4879), and 48 are newly recorded (8BD6298–8BD6344 and 8BD6347). Three historic resources, Seaboard Airline Railroad Station at 200 SW 21st Terrace (8BD1452), Seaboard Air Line (CSX) Railroad (8BD4649), and North Woodlawn Cemetery (8BD4879), were previously determined National Register–eligible by the SHPO. The current CRAS found that all three of these significant resources remain eligible for inclusion in the National Register. The remaining 49 historic resources located within the current APE are considered individually ineligible for inclusion in the National Register.

# 13.1 Unanticipated Finds

Although unlikely, should construction activities uncover any archaeological remains, it is recommended that activity in the immediate area of the remains be stopped while a professional archaeologist evaluates the remains. In the event that human remains are found during construction or maintenance activities, Chapter 872.05 of the Florida Statutes will apply and FDOT's Standard Specifications for Road and Bridge Construction require that all construction cease. Chapter 872.05 states that, when human remains are encountered, all activity that might disturb the remains shall cease and may not resume until authorized by the District Medical Examiner or the State Archaeologist. The District Medical Examiner has jurisdiction if the remains are less than 75 years old or if the remains are involved in a criminal investigation. The State Archaeologist has jurisdiction if the remains are 75 years of age or more.

# 13.2 Curation

Original and updated site file forms (**Appendix A**), survey log sheet (**Appendix D**), and photographs are curated at the FMSF in Tallahassee, along with a copy of this report. Field notes and other pertinent project records are temporarily stored at Janus Research until their transfer to the FDOT storage facilities.



FPID: 435513-1-22-02

# 14.0 References

- Andrews, R. L., J. M. Adovasio, B. Humphrey, D.C. Hyland, J.S. Gardner, and D.G. Harding, (with J. S. Illingworth and D.E. Strong)
- 2002 Conservation and Analysis of Textile and Related Perishable Artifacts. In *Windover: Multidisciplinary Investigations of an Early Archaic Florida Cemetery*, edited by Glen Doran, pp. 121-165. University Press of Florida, Gainesville.

#### Austin, Robert J.

- 1996 Prehistoric Chert Procurement and Mobility Strategies on the Lake Wales Ridge. *The Florida Anthropologist* 49(4):218–221.
- 1997 The Economics of Lithic-Resource Use in South-Central Florida. Unpublished Ph.D. dissertation, University of Florida, Gainesville.

#### Brooks, H. K.

Lake Okeechobee. In *Environments of South Florida: Present and Past II* (2d ed.), edited by P. J. Gleason, pp. 38–68. Miami Geological Society, Coral Gables.

# Broward County, Records, Taxes and Treasury Division

1980 Special Warranty Deed. Granted by William R. Robbins (a.k.a. W. R. Robbins) to The Salvation Army, Inc., a Georgia corporation. For the portions of Section 4 of Township 50 South, Range 42 East, which make up the Salvation Army Complex.

#### Brown, Canter, Jr.

1991 Florida's Peace River Frontier. University of Central Florida Press, Orlando.

#### Buker, George S.

1975 Sun, Sand and Water: A History of the Jacksonville District, U.S. Army Corps of Engineers, 1821–1975. Found online at: http://www.saj.usace.army.mil/history/.

#### Bullen, Ripley P.

- 1954 Further Notes on the Battery Point Site, Bayport, Hernando County, Florida. *The Florida Anthropologist* 7: 103–108.
- 1955 Stratigraphic Tests at Bluffton, Volusia County, Florida, Florida Anthropologists 8:1–16.
- The Orange Period of Peninsular Florida. In *Fiber-tempered Pottery in Southeastern United States and Northern Colombia: Its Origins, Context, and Significance*, edited by R. P. Bullen and J. B. Stoltman, pp.9–33. Florida Anthropological Society Publications 6, Gainesville.

#### Bullen, R. P., A. K. Bullen, and C. J. Clausen

1968 The Cato Site Near Sebastian Inlet, Florida. The Florida Anthropologist 21:14–16.

#### Cabeza de Vaca, Alvar Nuñez

1542 La Relación que dio Alvar Nuñez Cabeza de Vaca de lo Acaescido en las Indias...Zamora, 1542. Reproduced in Colección de Libros y documentos referentes a la Historia de America. Madrid, 1906.



FPID: 435513-1-22-02

#### Carbone, V. A.

Late Quaternary Environments in Florida and the Southeast. The Florida Anthropologist 26(1-2):3–17.

#### Carr. Robert S.

- 1986 Preliminary Report on Excavations at the Cutler Fossil Site in Southern Florida. Paper presented at the 38<sup>th</sup> annual meeting of the Florida Anthropological Society, Gainesville.
- The Archaeology of Everglades Tree Islands. In *Tree Islands of the Everglades*, edited by Fred H. Sklar and Arnold Van der Valk, pp. 187-206. Kluwer Academic Publishers, Boston.

#### Carr, Robert S., Joe Davis, and Bill Steele

1994 A Phase I Archaeological Survey of the Blockbuster Parcel, Broward County, Florida. AHC Technical Report #104. Archaeological and Historical Conservancy, Miami. Manuscript on fle, Florida Division of Historical Resources. Tallahassee.

# Carr, Robert S., Amy Felmley, Richard Ferrer, Willard S. Steele, and Jorge Zamanillo

1991 An Archaeological Survey of Broward County, Florida: Phase One. AHC Technical Report #34. Archaeological and Historical Conservancy, Miami. Manuscript on file, Florida Division of Historical Resources, Tallahassee.

#### Cushing, Frank H.

1896 Exploration of Ancient Key Dwellers' Remains on the Gulf Coast of Florida. *Proceedings: American Philosophical Society* Volume 35 (153):329–448.

#### Daniel, I. Randolph, and Michael Wisenbaker

1987 Harney Flats: A Florida Paleo-Indian Site. Baywood Press, Farmingdale, New York.

## Davis, Joe, and Robert S. Carr

An Archaeological and Historical Assessment of the Weston Increment III Area, Phase II, Broward County, FL. *AHC Technical Report #79*, Archaeological and Historical Conservancy, Miami. Manuscript on file, Florida Division of Historical Resources, Tallahassee.

# Davis, T. Fredrick

1938 The Disston Land Purchase. *The Florida Historical Quarterly* 17(3):200–210.

#### Dickel, David N.

2002 Analysis of Mortuary Patterns. In *Windover: Multidisciplinary Investigations of an Early Archaic Florida Cemetery*, edited by Glen H. Doran, pp. 73–96. University Press of Florida, Gainesville.

# Dickel, David N., and Glen H. Doran

2002 An Environmental and Chronological Overview of the Region. In *Windover: Multidisciplinary Investigations of an Early Archaic Florida Cemetery*, edited by Glen H. Doran, pp. 39–58. University Press of Florida, Gainesville.

#### Dixon, E.J.

1999 Human Colonization of the Americas: Timing, Technology, and Process. *Quaternary Science Reviews* 1–68.



FPID: 435513-1-22-02

Dunbar, James S., Michael K. Faught, and S. David Webb

1988 An Underwater Paleo-Indian Site in Northwestern Florida. The Florida Anthropologist 41:442–453.

Dunbar, James, and Ben I. Waller.

1983 A Distribution Analysis of the Clovis/Suwannee Paleoindian Sites of Florida—A Geographic Approach. *The Florida Anthropologist* 36(1-2):18–30.

Eller, Warren

1971 Port Everglades Florida.

Emslie, Steven D., and Gary S. Morgan

1995 Taphonomy of a Late Pleistocene Carnivore Den, Dade County, Florida. *In Late Quaternary Environments and Deep History: A Tribute to Paul S. Martin*, edited by David W. Steadman and Jim I. Mead, pp. 65-83. Scientific Papers Vol. 3. The Mammoth Site of Hot Springs, Hot Springs, South Dakota.

Farr, Grayal Earle

2006 A Reevaluation of Bullen's Typology for Preceramic Projectile Points. M.A. Thesis, Department of Anthropology, Florida State University, Tallahassee.

Florida Department of Environmental Protection (FDEP)

1870a Plat Map for Township 50 South, Range 42 East. Division of State Lands, Board of Trustees Land Document System. Electronic document, http://tlhdslweb.dep.state.fl.us/, accessed April 25, 2017.

1870b Surveyor's Notes for Township 50 South, Range 42 East. Electronic document, http://labins.org/survey\_data/landrecords/landrecords.cfm, accessed April 25, 2017.

Florida Department of Transportation (FDOT), Surveying and Mapping Office

2017 Aerial Photography Archive. Electronic documents, https://fdotewp1.dot.state.fl.us/AerialPhotoLookUpSystem/, accessed July 24, 2017.

Fradkin, A.

The Wightman Site: A Study of Prehistoric Culture and Environment on Sanibel Island, Lee County, Florida. M.A. Thesis, Department of Anthropology, University of Florida, Gainesville.

Gaby, Donald C.

1993 The Miami River and Its Tributaries. The Historical Association of South Florida, Miami, Florida.

Gannon, Michael V.

1965 The Cross in the Sand: The Early Catholic Church in Florida 1513–1870. University of Florida Press, Gainesville.



FPID: 435513-1-22-02

# George, Paul S.

1991 Submarines and Soldiers: Fort Lauderdale and World War II. *Broward Legacy*, Volume 14, Numbers 1–2.

Gleason, P. J., A. D. Cohen, P. Stone, W. G. Smith, H. K. Brooks, R. Goodrick, and W. Spackman, Jr.

The Environmental Significance of Holocene Sediments from the Everglades and Saline Tidal Plain. In *Environments of South Florida: Present and Past II*, edited by P. J. Gleason, pp. 297-351. Miami Geological Society, Coral Gables.

#### Goggin, John M.

1939 A Ceramic Sequence for South Florida. New Mexico Anthropologist 3:35–40.

1950 Cultural Occupation at Goodland Point, Florida. *The Florida Anthropologist* 2:65–91.

n.d. The Archaeology of the Glades Area, Southern Florida. [Written about 1949, with additions in subsequent years into the 1950s.] Typescript. Manuscript on file, Florida Museum of Natural History, Gainesville.

#### Goodyear, Albert C., Sam B. Upchurch, and Mark J. Brooks

1980 Turtlecrawl Point: An Inundated Early Holocene Archaeological Site on the West Coast of Florida. In Southeastern Geological Society Guidebook 22, edited by S. B. Upchurch, pp. 24–33. Tallahassee.

# Goodyear, Albert C., and Lyman O. Warren

1972 Further Observations on the Submarine Oyster Shell Deposits of Tampa Bay. *The Florida Anthropologist* 25(2, part 1):52–66.

#### Griffin, John W.

1988 The Archaeology of Everglades National Park: A Synthesis. Contract CX 5000-5-0049. SEAC.

2002 Archaeology of the Everglades. University Press of Florida, Gainesville.

Griffin, J. W., S. B. Richardson, M. Pohl, C. D. MacMurray, C. M. Scarry, S. K. Fish, E. S. Wing, L. J. Loucks, and M. K. Welch

1982 Excavations at the Granada Site: Archaeology and History of the Granada Site, Volume I. Florida Division of Archives, History and Records Management, Tallahassee.

## Grismer, Karl

1949 The Story of Ft. Myers. St. Petersburg Printing Co., St. Petersburg.

#### Hetherington, Alma

1980 The River of the Long Water. The Mickler House Publishers, Chuluota, Florida.

#### Historic Property Associates

1995 Architectural & Historical Survey of Fort Lauderdale: Original Town Limits. November, 1995.



FPID: 435513-1-22-02

#### Janus Research

- 2012 Cultural Resource Assessment Survey SR 9 / I-95 PD&E Study from Stirling Road to North of Oakland Park Boulevard FM 42980412201 / ETDM 13168, Broward County, Florida. Manuscript on file, Florida Department of State, Division of Historical Resources, Tallahassee.
- 2013 Cultural Resource Assessment Survey Update for the Broward Boulevard Bridge, Broward County, Florida FM# 429958.1. Manuscript on file, Florida Department of State, Division of Historical Resources, Tallahassee.

## Kemper, Marilyn

1981 Broward County Comprehensive Survey: Phase I: Historic Broward County Preservation Board. On file Division of Historical Resources, Tallahassee.

# Kutbach, J. E., and H. E. Wright

1985 Simulation of the Climate of 18,000 Years B.P.: Results for the North American/North Atlantic/European Sector and Comparison with the Geologic Record of North America. *Quaternary Science Reviews* 4:147-188.

#### Lane, Ed

1980 Environmental Geology Series West Palm Beach Sheet. *Florida Bureau of Geology Map Series* No. 100, Tallahassee.

# Lane, E. M., S. Knapp and T. Scott

1980 Environmental Geology Series: Fort Pierce Sheet. *Florida Bureau of Geology Map Series* No. 80, Tallahassee.

#### Laxson, D. D.

1966 The Turner River Jungle Gardens Site, Collier County, Florida. The Florida Anthropologist 19:125– 140.

#### Lee, Arthur R., and John Beriault (with Walter Buschelamn and Jean Belknap)

1993 A Small Site—Mulberry Midden, 8Cr697—Contributes to Knowledge of Transitional Period. *The Florida Anthropologist* 46:43–52.

Lee, Arthur R., John G. Beriault, Jean Belknap, Walter M. Buschelman, John W. Thompson, and Carl B. Johnson

1998 Heineken Hammock, 8CR231: A Late Archaic Corridor Site in Collier County. *The Florida Anthropologist* 51(4):223-239.

#### Littman, Sherri Lynn

2000 Pleistocene/Holocene Sea Level Change in the Georgia Bight: A Paleoenvironmental Reconstruction of Gray's Reef National Marine Sanctuary and J Reef. M.A. thesis, Department of Geology, University of Georgia, Athens.

## McGoun, Bill

1978 A History of Broward County. Broward Legacy, Volume 2, Numbers 3–4.



FPID: 435513-1-22-02

#### McMichael, Alan

1982 A Cultural Resource Assessment of Horrs Island, Collier County, Florida. Miscellaneous Project Report Series Number 15. Department of Anthropology, Florida State Museum, Gainesville.

Mahon, John K.

1967 History of the Second Seminole War. University of Florida Press, Gainesville.

Masson, Marilyn A., Robert S. Carr, and Debra S. Goldman

1988 The Taylor's Head Site (8BD74): Sampling a Prehistoric Midden on an Everglades Tree Island. The Florida Anthropologist 41(3):336-350.

Milanich, Jerald T.

1978 The Western Timucua: Patterns of Acculturation and Change. In Tacachale: Essays on the Indians of Florida and Southeastern Georgia during the Historic Period, pp. 59–88. The University Presses of Florida, Gainesville.

1994 Archaeology of Precolumbian Florida. University Presses of Florida, Gainesville.

Milanich, Jerald T., Jefferson Chapman, Ann S. Cordell, Stephen Hale, and Rochelle A. Marrinan
1984 Prehistoric Development of Calusa Society in Southwest Florida: Excavations on Useppa Island.
In *Perspectives on Gulf Coast Prehistory*, edited by David D. Davis, pp. 258–314. Gainesville: University of Florida Press/FMNH.

Miller, James J. (compiler)

1990 State of Florida Draft Comprehensive Historic Preservation Plan. Manuscript on file, Florida Division of Historical Resources, Tallahassee.

Mowers, Bert, and Wilma B. Williams

1972 The Peace Camp Site, Broward County, Florida. The Florida Anthropologist 25:1-20.

Murphy, Larry E., and Linda Scott Cummings

1990 8SL17: Natural Site-Formation Processes of a Multiple Component Underwater Site in Florida. Southwest Cultural Resources Center Professional Papers No. 39, National Park Service, Santa Fe, New Mexico.

Nance, Ellwood C.

1962 *The East Coast of Florida, A History, Volume I.* The Southern Publishing Company, Delray Beach.

Neill, Wilfred T.

1958 A Stratified Early Site at Silver Springs, Florida. The Florida Anthropologist 12:33–52.

Nelson, Martha

1963 Weed Patch to 161,867 Landings. *Miami Herald*, 27 January 1963.

Newman, Christine L.

1993 The Cheetum Site: An Archaic Burial in Dade County, Florida. *The Florida Anthropologist* 46:37–42.



FPID: 435513-1-22-02

# Parks, Arva Moore

1982 Archaeology and History of the Granada Site, Volume II, Where the River Found the Bay: Historical Study of the Granada Site, Miami, Florida. Florida Department of State, Division of Archives, History and Records Management, Tallahassee.

#### Pepe, James P.

2000 An Archaeological Survey of St. Lucie County, Florida. AHC Technical Report #280. Archaeological and Historical Conservancy, Miami. Copies available from Florida Division of Historical Resources, Tallahassee.

#### Pepe, James P., and Alison Elgart

2006 Strombus Celt Caches in Southern Florida: A Functional Interpretation. Paper presented at the 58<sup>th</sup> Annual Meeting of the Florida Anthropological Society, Stuart.

# Pepe, James, and Linda Jester

1995 An Archaeological Survey and Assessment of the Mt. Elizabeth Site, 8Mt30, Martin County, Florida. AHC Technical Report #126, Miami.

# Purdy, Barbara Ann

1981 Florida's Prehistoric Stone Tool Technology. University of Florida Press, Gainesville.

#### Purdy, Barbara A., and Laurie M. Beach

1980 The Chipped Stone Tool Industry of Florida's Preceramic Archaic. *Archaeology of Eastern North America* 8:105–124.

#### Ruppe, Reynold J.

1980 The Archaeology of Drowned Terrestrial Sites: A Preliminary Report. *Florida Bureau of Historic Sites and Properties Bulletin* 6:35–45.

#### Russo, Michael

1991 Archaic Sedentism on the Florida Coast: A Case Study from Horr's Island. Ph.D. dissertation, University of Florida, Gainesville.

# Russo, Michael, and Gregory Heide

2002 The Joseph Reed Shell Ring. The Florida Anthropologist 55(2):55–87.

#### Schwadron, Margo

2006 Everglades Tree Islands Prehistory: Archaeological Evidence for Regional Holocene Variability and Early Human Settlement. *Antiquity* 80(310). Electronic document, http://antiquity.ac.uk/projgall/schwadron/index.html.

#### Scott, Thomas M.

1978 Environmental Geology Series: Orlando Sheet. *Florida Bureau of Geology Map Series* No. 85, Tallahassee.

#### Sears, William H.

1956 The Turner River Site, Collier County, Florida. *The Florida Anthropologist* 9:47–60.



FPID: 435513-1-22-02

1982 Fort Center: An Archaeological Site in the Lake Okeechobee Basin. Ripley P. Bullen Monographs in Anthropology and History No. 4. University Presses of Florida, Gainesville.

# **Shepard Associates**

1981 An Architectural Survey of the City of Hollywood, Florida. In Broward County Comprehensive Survey: Phase I pp. II:ii–II:140.

#### Tebeau, Charlton W.

1971 A History of Florida. University of Miami Press, Miami.

## TenEick, Virginia Elliot

1989 History of Hollywood (1920 to 1950), Reprinted. Published by Patricia M. Smith and Florida Classics Library, Port Solerno, Florida. Originally published in 1966 by the City of Hollywood, Florida.

# The Salvation Army, Broward County

2014 Our History. Subpage of the Main Salvation Army website. Webpage accessed on October 4, 2017, at http://www.salvationarmyflorida.org/fortlauderdale/about-us/our-mission.

#### Tischendorf, A. P.

1954 Florida and the British Investor: 1880–1914. Florida Historical Quarterly 33(2):120–129.

## Torrence, Corbett McP.

1996 From Objects to the Cultural System: A Middle Archaic Columella Extraction Site on Useppa Island. M. A. thesis, Department of Anthropology, University of Florida, Gainesville.

## United States Department of Agriculture (USDA)

1984 Soil Survey of Broward County, Eastern Part, Florida. United States Department of Agriculture/Natural Resources Conservation Service.

# University of Florida, George A. Smathers Libraries

2017 Aerial Photography: Florida Collection. University of Florida Digital Collections. Electronic documents, http://ufdc.ufl.edu/aerials, accessed April 25, 2017.

#### Upchurch, Sam B., Richard N. Strom, and Mark G. Nuckels

1982 Methods of Provenance Determination of Florida Cherts. Manuscript on file, Florida Division of Historical Resources, Tallahassee.

#### Van Beck, J. C., and L. M. Van Beck

1965 The Marco Midden, Marco Island, Florida. The Florida Anthropologist 18:1–20.

# Waller, Benjamin I., and James Dunbar

1977 Distribution of Paleo-Indian Projectiles in Florida. *The Florida Anthropologist* 30:79–80.



FPID: 435513-1-22-02

#### Watts, William A.

- 1969 A Pollen Diagram from Mud Lake, Marion County, North-central Florida. *Geological Society of America, Bulletin* 80:631–642.
- 1971 Post-Glacial and Interglacial Vegetation History of Southern Georgia and Central Florida. *Ecology* 52:676–689.
- 1975 A Late Quaternary Record of Vegetation from Lake Anne, South-Central Florida. *Geology* 3:344–346.
- Late Quaternary Vegetation History at White Pond on the Inner Coastal Plain of South Carolina. *Quaternary Research* 13:187–199.
- 1983 Vegetational History of the Eastern United States 25,000 to 10,000 Years Ago. In Late Quaternary Environments of the United States, edited by H. E. Wright, Jr., Vol. 1, pp. 294–310. University of Minnesota Press, Minneapolis.

# Watts, William A., and Barbara C. S. Hansen

Environments of Florida in the Late Wisconsin and Holocene. In *Wet Site Archaeology*, edited by Barbara A. Purdy, pg. 307–323. The Telford Press, Caldwell, New Jersey.

# Watts, W. A., and M. Stuiver

1980 Late Wisconsin Climate of Northern Florida and the Origin of Species Rich Deciduous Forest. *Science* 210:325–327.

Weaver, Paul L. III, Historic Property Associates, Inc., and Pappas Associates, Inc.

1996 Model Guidelines for Design Review: A Guide for Developing Standards for Historic Rehabilitation on Florida Communities. Florida Department of State, Division of Historic Resources, Tallahassee.

#### Webb, S. David

1990 Historical Biogeography. In *Ecosystems of Florida*, edited by Ronald L. Myers and John J. Ewel, pp. 70-100. University of Central Florida Press, Orlando.

#### Wheeler, Rvan J.

- 1994 Cultural Resources Survey and Assessment of the Proposed Farr Prison Site, Okeechobee County, Florida. Environmental Management Systems, Inc. Submitted to Richard T. Creech, Inc. Manuscript on file, Florida Division of Historical Resources, Tallahassee.
- 2004 Southern Florida Sites associated with the Tequesta and their Ancestors: National Historic Landmark/National Register of Historic Places Theme Study, Florida Division of Historical Resources, Tallahassee.

# Wheeler, Ryan J., Wm. Jerald Kennedy, and James P. Pepe

2002 The Archaeology of Coastal Palm Beach County. The Florida Anthropologist 55(3-4):119–156.

#### Widmer, Randolph J.

1988 The Evolution of the Calusa, A Non-Agricultural Chiefdom on the Southwest Florida Coast. University of Alabama Press, Tuscaloosa.

FDOT

FPID: 435513-1-22-02

FPID: 435513-1-22-02 ETDM: 14226

White, William A.

1970 The Geomorphology of the Florida Peninsula. *Geological Bulletin* No. 51, Bureau of Geology, State of Florida Department of Natural Resources.

Wright, H. E., Jr.

1981 Vegetation East of the Rocky Mountains 18,000 Years Ago. Quaternary Research 15(2):113–125.

Wright, Leitch J.

1986 Creeks and Seminoles, Destruction and Regeneration of the Muscogulgee People. University of Nebraska Press, Lincoln.



124

# **Appendix A | Florida Master Site File Forms**

☐ Original ☑ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD03414
Field Date	9-27-2017
Form Date	10-3-2017
Recorder #	28

Site Name(s) (address if none) 2015 NW 3rd Court	Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Boulevard Interchange	
National Register Category (please check one) ■ building ■ structure [	
$\textbf{Ownership:} \\ \square \textbf{private-profit}  \\ \square \textbf{private-nonprofit}  \\ \blacksquare \textbf{private-individual}  \\ \square \textbf{private-nonspectation} \\$	cific
LOCATION &	& MAPPING
Street Number Direction Street Name	Street Type Suffix Direction
Address: 2015 NW 3rd	Court
Cross Streets (nearest/between) N side btwn NW 20th Ave and NW 2	
USGS 7.5 Map Name FORT LAUDERDALE SOUTH US	GS Date 1983 Plat or Other Map
City / Town (within 3 miles) Fort Lauderdale In City Limits?	
Township <u>50s</u> Range <u>42E</u> Section <u>4</u> ¼ section: □N	W □SW □SE □NE Irregular-name:
Tax Parcel # 5042 04 30 0880	Landgrant
Subdivision Name Dorsey Riverbend	Block Lot
Tax Parcel # 5042 04 30 0880  Subdivision Name Dorsey Riverbend  UTM Coordinates: Zone □16 図17 Easting 5 8 3 1 7 3 Northin	ng 2 8 8 9 8 4 4
Other Coordinates: X: Y: Co	oordinate System & Datum
Name of Public Tract (e.g., park)	
HIST	ODV
Construction Year: <u>1951</u> ■ approximately  year listed or ea	rlier □ year listed or later
Original Use Private Residence (House/Cottage/Cabin) From	om (year): 1951 To (year):
Current Use Private Residence (House/Cottage/Cabin) From	om (year): To (year):2017
Other Use From	om (year): To (year):
Moves: ☐yes ☑no ☐unknown Date: Original ac	ddress
	Entry moved; some windows altered
	SE entry addition; NE addition
Architect (last name first): unknown	
Ownership History (especially original owner, dates, profession, etc.)	
le the Descurse Affected by a Legal Proconnation Ordinance?	no Flunknown Doccribo
Is the Resource Affected by a Local Preservation Ordinance?  yes	10 Markuomii nescrine
DESCRI	PTION
Style Masonry Vernacular Exterior Plan	
Exterior Fabric(s) 1. Stucco 2.	
Roof Type(s) 1. Hip 2. Flat Roof Material(s) 1. Composition shingles 2. Built-u	J J J
Roof secondary strucs. (dormers etc.) 1.	2.
Windows (types, materials, etc.) Metal 1/1 single-hung-sash and 1-	
1980s to accommodate AC unit	<u> </u>
Distinguishing Architectural Features (exterior or interior ornaments) Some m	etal window awnings and hurricane shutters; iron
enclosure and gate in front of entry in c. 1970 additio	
Ancillary Features / Outbuildings (record outbuildings, major landscape features; us	e continuation sheet if needed.) Paved half-circle driveway; paved
uncovered front patio; paved walkway from secondary ent	rance to sidewalk
DHR USE ONLY OFFICIAL EV	ALUATION DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NR listing: ☐yes	
	no Date
☐Owner Objection   NR Criteria for Evaluation: ☐a ☐b ☐c ☐d	(see National Register Bulletin 15, p. 2)

Site #8 BD03414


	DESCRIPTION	ON (continued)	
Chimney: Noo_ Chimney Material(s): 1 Structural System(s): 1Concrete blo Foundation Type(s): 1Continuous Foundation Material(s): 1Concrete Blo Main Entrance (stylistic details) _S-facing 19 entry on S side of NE addition Porch Descriptions (types, locations, roof types, etc.)	ck       2.         80s panel door with f		
Condition (overall resource condition):		idence has an irregular fo	rm and several additions
Archaeological Remains			Check if Archaeological Form Completed
	SEADOU METHO	DDS (check all that apply)	
RF	SEARCH METHC	DDS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐Historic aeri</li> <li>Bibliographic References (give FMSF manuscript #</li> </ul>		□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
OPI	INION OF RESOU	RCE SIGNIFICANCE	
Appears to meet the criteria for National Regis Appears to meet the criteria for National Regis Explanation of Evaluation (required, whether significance are reighborhood lacks integrity with a Area(s) of Historical Significance (see National Registration).	ster listing as part of a distri ificant or not; use separate sheet if bend neighborhood, what several alterations, Register Bulletin 15, p. 8 for category 4.	ict?yesXnoinsuffiif needed)This residence is on ich is a historic Africandemolitions, and in-fills.  ries: e.g. "architecture", "ethnic heritage", "compared to the compared to t	American neighborhood. The
	DOCUME	NTATION	
Accessible Documentation Not Filed with the 1  1) Document type Field maps Document description  2) Document type Field notes Document description	N	laintaining organization  Janus Research  File or accession #'s  Janus Research  Janus Research	
	DECODDED IS	NEODMATION	
	RECORDER IN	NTORMATION	
Recorder Contact Information		_ Affiliation Janus Research 07 / (813) 636-8200 / janus	s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06298
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	1

Site Name(s) (address if none) 1920-1932 NW 9th St	
Survey Project Name I-95 at Broward Boulevar	
National Register Category (please check one)	
Ownersnip: 🔀 private-profit 🔲 private-nonprofit 🔲 private-indivi	idual □private-nonspecific □city □county □state □federal □Native American □foreign □unknown
	LOCATION & MAPPING
Street Number Direction Street Name	Street Type Suffix Direction
Address: 1920-1932 NW 9th	Street
Cross Streets (nearest/between) S side btwn I-95	
	USGS Date 1983 Plat or Other Map
Toy Darcol # 5040 04 30 0030	
Tax Pallet # 5042 04 32 0030  Subdivision Nama	Landgrant Lot Lot
UTM Coordinates: Zone □16 ☑17 Easting 5 8	3 1 2 4  Northing   2 8 9 0 8 1 7
Other Coordinates: X: Y: Y:	Coordinate System & Datum
Name of Public Tract (e.g., park)	
	HISTORY
Construction Year:1958_   ☑ approximately	Dupar listed or earlier Dupar listed or later
Original Use Commercial	
Current Use Commercial	From (year): To (year): To (year):
Other Use	From (year): To (year):
Moves: Tyes Ino Tunknown Date:	Original address
Alterations: xyes no	Nature Replaced windows/doors, painted signage
Additions: ☐yes ☒no ☐unknown Date:	Nature
Architect (last name first): unknown	Builder (last name first): unknown
Ownership History (especially original owner, dates, profession	ı, etc.)
le the Deceured Affected by a Local Preservation Ordin	nance? □yes ⊠no □unknown Describe
IS the Resource Affected by a Local Freservation Grain	Mance? Liyes Xino Liurkhown Describe
	DESCRIPTION
Chila Maganny Varnagular	Exterior Plan Rectangular Number of Stories 1
Style Masonry vernacular  Everior Eabric(s) 1 Studeo	Exterior Plan Rectangular Number of Stories 1  2. 3.
Poof Tyne(s) 1 Flat.	2
Roof Material(s) 1. Built-up	2 3 2 3
Roof secondary strucs. (dormers etc.) 1.	2
Windows (types, materials, etc.) Metal 1/1 single-h	nung-sash and 1-light fixed; 1-light fixed appear to be 1980s
replacements	
	maments) Eight rolling garage doors on north and south sides; metal
bars on all windows	
A sellent Factures / Outh tildings (second suth tildings mais	in the state of th
Ancillary Features / Outbuildings (record outbuildings, major north side; two sheds on west side of buildings)	or landscape features; use continuation sheet if needed.) Paved and unpaved parking on the
NOTTH Side; two sheds on west side of Dai	ilding
- DUD LICE ONLY	OFFICIAL EVALUATION DUDINGE ONLY
DHR USE ONLY	OFFICIAL EVALUATION DHR USE ONLY
	for NR listing: Init Init
KEEPER – Determined eligible:	yes no Date
■Owner Objection NR Criteria for Evaluation: ■a	□b □c □d (see <i>National Register Bulletin 15</i> , p. 2)

Site #8 \_ BD06298


DESCRIPTION (continued)	
Chimney: Noo_Chimney Material(s): 1	
Condition (overall resource condition):   Narrative Description of Resource  This Masonry Vernacular building has a simple form and few built for commercial use with eight separate offices. The businesses in the building has a simple form and few years.  Archaeological Remains	
G C C C C C C C C C C C C C C C C C C C	leck if Archaeological Form Completed
RESEARCH METHODS (check all that apply)	
□FL State Archives/photo collection □city directory □occupant/owner interview □property appraiser / tax records □newspaper files □neighbor interview □F□cultural resource survey (CRAS) □historic photos □interior inspection □F□cultural resource survey (CRAS) □historic photos □interior inspection □F□cultural resource survey (CRAS) □historic aerial photography	Sanborn maps plat maps Public Lands Survey (DEP) HABS/HAER record search
Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)	
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?     Jyes   Image: Insufficient info	ormation
Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community	
1.       3.       5.         2.       4.       6.	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important do Document type Field maps Maintaining organization Janus Research  1) Document description File or accession #'s	
Occument type Field notes Maintaining organization Janus Research	
Document description File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janu (address/phone/fax/e-mail)	us-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06299
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	2.

	if none) 808 NW 20th Ave			Multiple Listing (DHR o	
	1-95 at Broward Boulevard I			Survey # (DHR only) _	
	tegory (please check one) ■ building rofit □ private-nonprofit ■ private-individual				foreign Dunknown
Ownershipprivate-p	Tonit private-nonpront private-individual	<u></u>	<u></u> соинку <u></u> state		oreign <u>u</u> uriknown
	LO	CATION & MAP	PING		
Street Num			Street Type	Suffix Direction	
	NW 20th		Avenue		
	/between) NW corner of NW 20th			thor Man	
	eFORT_LAUDERDALE_NORTH rels)				
	Range 42E Section 4 19				
Subdivision Name	04 19 0020	La R	inagrani	I nt	<del></del>
UTM Coordinates: 7	one □16 ☑17 Easting 5 8 3 0	9 4 <b>N</b> orthing 2 8 9	0679	<b>L</b> ot	
Other Coordinates: >	X: Y:	Coordinate	System & Datum	1	
Name of Public Tract	(e.g., park)		- /		
		HISTORY			
Construction Voors	1949 Manprovimatoly Dy	oar listed or earlier -	Typer listed or let	tor	
Original Use Priva	$1949$ $\blacksquare$ approximately $\square$ y ate Residence (House/Cottage/	Cabin) From (Var)	. 1949	To (vear).	
Current Use Priva	te Residence (House/Cottage/	Cabin) From (year)	·	To (year). 2017	
Other Use		From (year):	·	To (year):	
Moves: Tyes N	≼no □unknown Date:	Original address		() /	
Alterations: xyes		Nature Porch ex	nclosed		
Additions: xyes	o Date: c1965/c19			rtheast enclosure	
	t): unknown				
Ownership History (es	specially original owner, dates, profession, etc.				
1 11 5					
Is the Resource Affect	cted by a Local Preservation Ordinand	ce? ∐yes ⊠no ∐unk	nown Describe		
		DESCRIPTION	V		
0: 1	_			N 1 60	
Style Masonry Ver	rnacular	Exterior Plan Irregu	lar	Number of S	tories1
Exterior Fabric(s) 1.	Stucco			3	
<b>P</b> oof Matorial(s) 1.	Cross-gabled Composition shingles			3	
Roof secondary	strucs. (dormers etc.) 1.		2	J	
Windows (types materia	als, etc.) Metal 2- and 3-light	awning	2		
trinaens (types, materia	15, 616.)				
Distinguishing Archite	ectural Features (exterior or interior orname	ents) Metal window	awnings and s	hutters on most window	vs; cross-
gable in roof is	s on northeast addition with	slight roof overha	ng; east side	porch enclosed	
•	Outbuildings (record outbuildings, major land	·			ith gable
roof in northeas	st corner of property; concre	ete block and chain	-link fence a	round property	
DHR U	JSE ONLY C	OFFICIAL EVALUAT	ION	DHR USE ON	LY
NR List Date	SHPO – Appears to meet criteria for N	R listing: Tyes Tho T	Tinsufficient info	Date	Init
IVIN LISE DATE	KEEPER – Determined eligible:	yes $\square$ no		Date	
Owner Objection	NR Criteria for Evaluation: ☐a ☐b	—, —	nal Register Bulletii		

	DESCRIPTIO	(continued)	
Chimney: Noo Chimney Material(s): 1	2 2		
Porch Descriptions (types, locations, roof types, etc.)	None observed; orig	inal porch enclosed	
Condition (overall resource condition):   Narrative Description of Resource  This Mass utility room on the south side. The this house its current irregular for Archaeological Remains	onry Vernacular resi c. 1965 north exten	dence was originally rectar sion and the c. 1970 northe	
RES	EARCH METHO	DS (check all that apply)	
☐FL State Archives/photo collection ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	□library research □city directory □newspaper files □historic photos □ photography	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
Bibliographic References (give Fins Finanuscript # if	relevant, use continuation sneet	ir needed)	
OPIN	HON OF RESOLU	RCE SIGNIFICANCE	
Appears to meet the criteria for National Registe Appears to meet the criteria for National Registe Explanation of Evaluation (required, whether significate of the criteria for National Registeria). It lacks historic significations is the criteria for National Registeria for National Registeri	er listing individually? er listing as part of a distric ant or not; use separate sheet if n		ent information ent information a common style in South
Area(s) of Historical Significance (see National Reg. 1	3	5	
2	4	6	
	DOCUMEN	NTATION	
Accessible Documentation Not Filed with the Sit  1) Document type Field maps Document description	Ma F	intaining organization Janus Research ile or accession #'s	
2) Document type Field notes			
Document description			
	RECORDER IN	FORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward (address / phone / fax / e-mail)		Affiliation Janus Research 7 / (813) 636-8200 / janus@	janus-research.com


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06300
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	3


Site Name(s) (address if none) 729 NW 20th Avenue	Multiple Listing (DHR only)
	Survey # (DHR only)
National Register Category (please check one) ■ building Ownership: □ private-profit □ private-nonprofit ▼ private-individual	Structure ☐ district ☐ site ☐ object ☐ private-nonspecific ☐ city ☐ county ☐ state ☐ federal ☐ Native American ☐ foreign ☐ unknown
1.0	CATION & MAPPING
Charat Name have Discretized Charat Name	Charles Time
Address: 729 NW 20th	Avenue Sum Direction
Cross Streets (nearest/between) <u>SW corner of NW 20th</u>	
	USGS Date 1983 Plat or Other Map
	n City Limits? ⊠yes □no □unknown County <u>Broward</u>
Township <u>50s</u> Range <u>42E</u> Section <u>4</u> ½	4 section: NW SW SE NE Irregular-name:
Tax Parcel # 5042 04 18 0400	Landgrant
Subdivision Name	Landgrant Lot
UTM Coordinates: Zone 116 121/ Easting 5 8 3 0	[9]7] <b>N</b> orthing[2]8[9]0[5]5[8]
	Coordinate System & Datum
Name of Public Tract (e.g., park)	
	HISTORY
Construction Year: 1960	ear listed or earlier
	Cabin) From (year): 1960 To (year):
Current Use Private Residence (House/Cottage/	Cabin) From (year): 2017
Other Use	From (year): To (year):
Moves:   yes   no   unknown Date:	Original address
Alterations:    yes □no □unknown Date: 2000s	From (year): To (year): Original address Nature Windows and doors replaced
Additions: Tyes Ino Tunknown Date:	Nature
Architect (last name first): unknown	Builder (last name first): unknown )
OWNERShip History (especially original owner, dates, profession, etc.	)
Is the Resource Affected by a Local Preservation Ordinand	ce? □yes ⊠no □unknown Describe
	DESCRIPTION
Ctula Magangy Varnagular	
Evitorior Fabric(s) 1 Studgo	Exterior Plan Irregular Number of Stories 1 2. 3.
Roof Type(s) 1 Flat	2 3
Roof Material(s) 1. Built-up	2. 3.
Roof secondary strucs. (dormers etc.) 1.	2 3
Windows (types, materials, etc.) Metal 1/1 single-hung	-sash and 2-light fixed; fixed windows appear to be 2000s
replacements	
	ents) Carport in southeast corner with metal supports; front
porch under roof extension with scrolled ire	on supports and raised concrete pad
Anaillany Footures / Outhwildings (constant with the	the first term of the first te
porch; chain-link fence around property	dscape features; use continuation sheet if needed.) Paved walkway from road to front
poten, chain-time tence around property	
DHR USE ONLY (	OFFICIAL EVALUATION DHR USE ONLY
	R listing: Syes One Sinsufficient info Date Init
KEEPER – Determined eligible:  □Owner Objection NR Criteria for Evaluation: □a □b	☐ yes ☐ no ☐ Date ☐ ☐ ☐ d (see <i>National Register Bulletin 15</i> , p. 2)

Site #8 \_ BD06300


DESCRIPTION (continued)	
Chimney: Noo_ Chimney Material(s): 1	
Porch Descriptions (types, locations, roof types, etc.) Front entry porch under roof extension with raised concrete pad an scrolled iron supports	d
Condition (overall resource condition): ☐excellent ☑good ☐fair ☐deteriorated ☐ruinous  Narrative Description of Resource ☐ This Masonry Vernacular residence has a simple form and few alterations.	
Archaeological Remains Check if Archaeological Form	Completed
RESEARCH METHODS (check all that apply)	
☑FMSF record search (sites/surveys) ☐ Ilibrary research ☐ building permits ☐ Sanborn maps ☐ city directory ☐ occupant/owner interview ☐ plat maps ☐ plat maps ☐ reighbor interview ☐ reighbor interview ☐ public Lands Survey (Important of the property appraiser / tax records ☐ newspaper files ☐ neighbor interview ☐ public Lands Survey (Important of the property appraiser) ☐ public Lands Survey (Important of the property appraiser) ☐ public Lands Survey (Important of the property appraiser) ☐ public Lands Survey (Important of the property appraiser) ☐ public Lands Survey (Important of the property appraiser) ☐ public Lands Survey (Important of the property appraiser) ☐ public Lands Survey (Important of the property appraiser) ☐ Important of the property appraiser / tax records appraiser / ta	
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   yes   no  insufficient information  Appears to meet the criteria for National Register listing as part of a district?   yes   no  insufficient information  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This building is of a common style in Sou  Florida. It lacks historic significance and integrity.	ith
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development" 1 3 5 5	
2 4 6	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  Document typeField maps	
2) Document type Field notes Maintaining organization Janus Research  File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com  (address/phone/fax/e-mail)	

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06301		
Field Date	9-26-2017		
Form Date	9-29-2017		
Recorder #	6		

	if none) 632 NW 21st Avenue			_ Multiple Listing (DHR only)
	I-95 at Broward Boulevard I			_ Survey # (DHR only)
	tegory (please check one)			Endowed Children Association Characters Characters
Ownership:private-p	roiit private-nonprofit private-individual	private-nonspecific city	county <b>s</b> tate <b>r</b>	ederal  □Native American  □foreign  □unknown
	LO	CATION & MAPP	ING	
Street Num			Street Type	Suffix Direction
	NW 21st		Avenue	
	/ between) W side of NW 21st Ave			or Mon
	FORT LAUDERDALE NORTH			
				untyBroward
Tay Parcol # 5042	Range 42E Section 5 %	Section. Livy Livy	□SE □NE III grapt	regular-name:
Subdivision Namo	05 03 0280	Lanu	yrani	Lot
IITM Coordinates: 70	one □16 図17 Easting 5 8 2 9	3 0 Northing 2 8 9 0	3 7 0	<b>L</b> ot
Other Coordinates: >	(: Y:	Coordinate Sv	rstem & Datum	
Name of Public Tract	(e.g., park)	Gooramate of		
		HISTORY		
Construction Voor	1952 Mannravimetaly Dy	oor listed or oarlier	oor listed or later	
Original Lea Priva	1952 $\blacksquare$ approximately $\square$ y te Residence (House/Cottage/	Cabin) From (year)	tai iisteu oi iater 1952 – T	o (vear):
Current Use Priva	te Residence (House/Cottage/	Cabin) From (year):	I(	2 (year): 2017
Other Use	need measures (measure, escatage,	From (year):	T(	o (year):
Moves: Tyes N	⊴no □unknown Date:	Original address		. ((0.0.7)
Alterations: xyes		Nature Enclosed	front porch w	ith new door
Additions: □yes ▶	Ino □unknown Date:	Nature		
Architect (last name first	t): <u>unknown</u>	Builder (last	name first): unkno	own
Ownership History (es	specially original owner, dates, profession, etc.			
			- "	
Is the Resource Affect	cted by a Local Preservation Ordinand	e? □yes ☑no □unkno	wn Describe	
		DESCRIPTION		
Style Masonry Ve	rnacular	Exterior Plan Rectangu	lar	Number of Stories1
Exterior Fabric(s) 1.	Stucco	_ 2		3
Roof Material(s) 1.	Gable on hip	_ Z		3 3
Poof secondary	Strucs. (dormers etc.) 1.	_ Z	2	3
Windows (types materia	als, etc.) Metal 2/2 single-hung		Z ov shutters o	r awnings
types, materia	ns, etc.)	Bubli, mode covered a	oy Bilacocis c.	
Distinguishing Archite	ectural Features (exterior or interior orname	nts) Metal window aw	nings/shutter	s; scored stucco "slanted
	n half of north and east side			
,	Outbuildings (record outbuildings, major land	•		
gate on east sid	de of property, chain-link fe	nce around rest of p	roperty; two	steps up to front door
DHR U	JSE ONLY C	OFFICIAL EVALUATIO	DN	DHR USE ONLY
NR List Date	SHPO – Appears to meet criteria for NI	R listing: Twos The Tin	nsufficient info	Date Init
INIX LIST DATE	KEEPER – Determined eligible:	R listing. □ yes □ no □ lin	ISUMUCEM IMIU	Date
Owner Objection	NR Criteria for Evaluation: ☐a ☐b	—, —	l Register Bulletin 1	
- ,		,	U	


Site #8 BD06301


	DESCRIPTION	JN (continued)	
Chimney: Noo_ Chimney Material(s) Structural System(s): 1. Concrete Foundation Type(s): 1. Concrete Foundation Material(s): 1. Concrete	us       2.         Block       2.		
Main Entrance (stylistic details)East-fa	cing 1990s panel door wit	h decorative square patter	en on enclosed entry porch;
two steps up to door  Porch Descriptions (types, locations, roof types)	oc atc.) None observed		
Forch Descriptions (types, locations, roof type	ss, etc.)world_observed		
Condition (overall resource condition): Dexce			nd few alterations.
Archaeological Remains			Check if Archaeological Form Completed
	DECEADOH METHO	DC (-1111-(1(1-)	
	RESEARCH METHO	DDS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐ Historic</li> </ul>		□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
Bibliographic References (give FMSF manu	script # if relevant, use continuation shee	et if needed)	
	OPINION OF RESOU	DOE CIONIFICANCE	
	OPINION OF RESOU.	RCE SIGNIFICANCE	
Appears to meet the criteria for National Appears to meet the criteria for National Explanation of Evaluation (required, whether Florida. It lacks historic signals	Register listing as part of a distrier significant or not; use separate sheet if	ct? □yes ☑no □insuffic	cient information cient information a common style in South
Area(s) of Historical Significance (see Nat			community planning & development", etc.)
2			
	DOCUME	NTATION	
Accessible Documentation Not Filed with  1) Document type Field maps Document description	M	aintaining organization	
2) Document type _Field notes			
Document description		File or accession #'s	
	RECORDER IN	NFORMATION	
Recorder Name Janus Research		Affiliation Janus Research	
Recorder Contact Information 1107 M (address / phone / fax / e-mail)			s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06302
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	5

	if none) 616 NW 22nd Road	Multiple Listing (DHR only)
	I-95 at Broward Boulevard	
		□ structure □ district □ site □ object  I □ private-nonspecific □ city □ county □ state □ federal □ Native American □ foreign □ unknown
Ownership. Dprivate-p		
		OCATION & MAPPING
Street Num		Street Type Suffix Direction
	NW 22nd	Road
		Ct and NW 6th St/Sistrunk Blvd USGS Date 1983 Plat or Other Map
		In City Limits?  yes  no  unknown  County  Broward
		14 section: □NW □SW □SE □NE Irregular-name:
Tax Parcel # 5042	05 03 0240	I andgrant
Subdivision Name	00 00 0110	Landgrant Lot Lot
UTM Coordinates: Zo	one □16 ☑17 Easting 5 8 2 9	9 2 4 Northing 2 8 9 0 3 1 0
Other Coordinates: >	<: Y:	Coordinate System & Datum
Name of Public Tract	(e.g., park)	
		HICTORY
		HISTORY
Construction Year:	1960 <b>■</b> approximately <b>□</b>	year listed or earlier ☐ year listed or later
Original Use Priva	te Residence (House/Cottage	/Cabin) From (year): 1960 To (year):
Current Use Priva	te Residence (House/Cottage	/Cabin) From (year): To (year): 2017
Other Use		From (year): To (year):
	no □unknown Date:	Original address
Alterations: xyes		Nature Windows and doors replaced
Additions: □yes ☑	Ino □unknown Date:	Nature
Architect (last name firs	i): unknown	Builder (last name first): unknown
Ownership history (es	specially original owner, dates, profession, etc	G.)
Is the Resource Affect	ted by a Local Preservation Ordinar	nce? □yes ⊠no □unknown Describe
15 the Resource 7 the	tod by a Local Propervation Gramai	·
		DESCRIPTION
Style Masonry Ve	rnacular	Exterior Plan Rectangular Number of Stories 1
Exterior Fabric(s) 1.	Stucco	23
Roof Type(s) 1.	Gable	23
Roof Material(s) 1.	Composition shingles	2 3
Roof secondary	strucs. (dormers etc.) 1.	2
Windows (types, materia	als, etc.) Metal 2-light fixed $a$	and 2-light sliding; appear to be 1990s replacements
51.11		
	ectural Features (exterior or interior ornam	nents) Faux shutters on southwest windows; security bars on front
door		
	)uthuildings (record outhuildings, major lan	odecano features: use continuation sheet if peeded.) Chain link fonge around hack
Ancillary Features / C		ndscape features; use continuation sheet if needed.) Chain-link fence around back
Ancillary Features / C		ndscape features; use continuation sheet if needed.) Chain-link fence around back property; paved walkway from sidewalk to front door
Ancillary Features / C		·
Ancillary Features / C		·
Ancillary Features / Cyard; paved driv	veway in southwest corner of	property; paved walkway from sidewalk to front door
Ancillary Features / Cyard; paved driv	veway in southwest corner of	·
Ancillary Features / C yard; paved driv	JSE ONLY  SHPO – Appears to meet criteria for N	OFFICIAL EVALUATION  OFFICIAL EVALUATION  OFFICIAL OFFICIAL EVALUATION  OFFICIAL OFFICIAL EVALUATION  OFFICIAL OFFICIAL OFFICIAL EVALUATION  OFFICIAL OFFICIAL EVALUATION  OFFICIAL EVALUATION  OFFICIAL OFFICIAL EVALUATION  OFFICIAL OFFICI
Ancillary Features / C yard; paved driv	JSE ONLY	OFFICIAL EVALUATION  NR listing:   yes   no   linsufficient info   Date   linit.   linit

Site #8 BD06302


	DESCRIPTION	JN (continued)	
Chimney: No. o Chimney Material(s): 1.		2	
Chimney: No. o Chimney Material(s): 1. Structural System(s): 1. Concrete block	ock 2	3.	
Foundation Type(s): 1. Continuous	2		
Foundation Material(s): 1. Concrete Blo Main Entrance (stylistic details) Southwest-f			y bars and concrete stoop
		The with over right, because	, surs and concrete seep
Porch Descriptions (types, locations, roof types, etc.	None observed		
Condition (overall resource condition): ☐excellen	⊠good □fair □de	teriorated	
Narrative Description of Resource			nd few alterations.
Archaeological Remains			Check if Archaeological Form Completed
RI	ESEARCH METHO	DDS (check all that apply)	
▼FMSF record search (sites/surveys)	□library research	□ building permits	☐ Sanborn maps
☐FL State Archives/photo collection	□ city directory	occupant/owner interview	□ plat maps
☑ property appraiser / tax records ☐ cultural resource survey (CRAS)	<ul><li>□ newspaper files</li><li>□ historic photos</li></ul>	☐ neighbor interview☐ interior inspection	☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
■ other methods (describe) Historic aer		Hillenoi inspection	HIADS/HAER record search
Bibliographic References (give FMSF manuscript		et if needed)	
OP	INION OF RESOU	RCE SIGNIFICANCE	
Appears to meet the criteria for National Reg	ister listing individually?	□yes <b>⊠</b> no □insuffic	cient information
Appears to meet the criteria for National Reg			cient information
Explanation of Evaluation (required, whether sign		needed) This building is of	a common style in South
Florida. It lacks historic signification	cance and integrity.		
Area(s) of Historical Significance (see National	Register Bulletin 15, p. 8 for catego	ries: e.g. "architecture", "ethnic heritage", "c	ommunity planning & development", etc.)
1	3	5. <u></u>	
2	4	6	
	DOCUME	NTATION	
A consider Decompositation Net Filed with the	Cha Ella III III III III III		
Accessible Documentation Not Filed with the  Document type Field maps	Site File - including field notes, a	analysis notes, photos, plans and other impo- aintaining organization <u>Janus Research</u>	ortant documents
1) Document description		File or accession #'s	
2) Document typeField notes			
Document description		File or accession #'s	
	RECORDER IN	NFORMATION	
Decorder Name Tanua Bassash			
Recorder Name <u>Janus Research</u> Recorder Contact Information 1107 N. W		_ Affiliation Janus Research	s@ianus-research.com
(address / phone / fax / e-mail)		. , (013, 033 0200 , Janua	

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

# PHOTOGRAPH





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06303
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	4

	fnone) 614 NW 22nd Road			ultiple Listing (DHR only)
	I-95 at Broward Boulevard			urvey # (DHR only)
	egory (please check one)  building			I Disting American Dispersion Dumberson
Ownership:private-pri	onit <b>I</b> private-nonprofit <b>E</b> private-individual	private-nonspecificcitycou	unty <b>s</b> tate <b></b> redera	Il □Native American □foreign □unknown
	LO	CATION & MAPPIN	NG	
Street Numb				uffix Direction
Address: 614	NW 22nd	Ro		
	between) <u>NE side btwn NW 6th</u>			
USGS 7.5 Map Name	FORT LAUDERDALE NORTH	<b>U</b> SGS Date <u>1983</u>	Plat or Other Ma	ap
	es) Fort Lauderdale			
Township 50s F	Range 42E Section 5	4 section: LINW LISW LI	SE LINE Irregul	ar-name:
Tax Parcel # 5042	05 03 0250	Landgra	int	Lot
JULIA Coordinatos: 70	no 114 VIII Facting Elelale	Morthing 2 9 9 0 2	06	Lot
Other Coordinates: X	пе 🗖 10 🔼 17 — Еаѕппу <u>га от 21 э</u> . У∙	Coordinate Syste	T⊇[o]	
Name of Public Tract	 (e.g., park)	Coordinate Syste	iii & Datuiii	
	(o.g., party			
		HISTORY		
0 1 11 1/	1054			
Construction Year:	1954 <b>⊠</b> approximately □y	year listed or earlier ☐ year	listed or later	
Original Use Privat	ce Residence (House/Cottage,	(Cabin) From (year):	1954 IO (ye	ar):
Other Use Private	te Residence (House/Cottage,			ar):ar):
Moves.	no 🗖 unknown Date:	Original address	10 (ye	ai)
Alterations: Syes	Ino Dunknown Date: 1980s	Nature Some windows	s and doors rep	olaced
Additions: ☐yes ☒			<u> </u>	
	: unknown	Builder (last nar	me first): unknown	
	pecially original owner, dates, profession, etc			
Is the Resource Affect	ted by a Local Preservation Ordinan	ce? □yes <b>⊠</b> no □unknown	Describe	
		DESCRIPTION		
				Number of Stories1
Exterior Fabric(s) 1	Stucco	2	3	
<b>R</b> 001 Type(S) 1 <b>P</b> oof Material(s) 1	Gable Composition shingles			
Poof secondary	Strucs. (dormers etc.) 1.	Z	3 ?	
Windows (types material	s, etc.) <u>Metal 6/6 and 8/8 sir</u>	ale-hung-sash: some apr	2 bear to be 1980	s replacements
ttindows (types, material	3, ctc.)	1910 Harry Sastry Some app	7041 00 20 1700	2 20024004102
Distinguishing Archite	ctural Features (exterior or interior ornam	ents) Textured stucco ex	xterior; plain	stucco window surrounds and
	n southwest side; secondary			
				d concrete pad at entrance;
<u>chain-link</u> fence	around property; paved dri	veway along northwest e	dge of property	У
DHR U	ISE ONLY (	OFFICIAL EVALUATION		DHR USE ONLY
NR List Date	SHPO – Appears to meet criteria for N KEEPER – Determined eligible:			te Init te
		yesno		
■Owner Objection	NR Criteria for Evaluation: ☐a ☐l	o 🗍c 🦳d (see <i>National Re</i>	<i>egister Bulletin 15</i> , p	2)

Site #8 \_ BD06303


	DESCRIPTION	DN (continued)	
Chimney: Noo Chimney Material(s): 1. Structural System(s): 1. Concrete block Foundation Type(s): 1. Continuous Foundation Material(s): 1. Concrete Block Main Entrance (stylistic details) Northwest-file	2 ock 2		
Porch Descriptions (types, locations, roof types, etc	) None observed		
Condition (overall resource condition): ☐excellent Narrative Description of Resource			nd few alterations.
Archaeological Remains			Check if Archaeological Form Completed
RI	ESEARCH METHO	DS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐Historic aer:</li> <li>Bibliographic References (give FMSF manuscript</li> </ul>	☐library research ☐city directory ☐newspaper files ☐historic photos ial photography	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
OP	INION OF RESOUL	RCE SIGNIFICANCE	
Appears to meet the criteria for National Regi Appears to meet the criteria for National Regi Explanation of Evaluation (required, whether sign Florida. It lacks historic significations	ister listing individually? ister listing as part of a distric ificant or not; use separate sheet if		cient information  cient information  a common style in South
Area(s) of Historical Significance (see <i>National</i> 1.			ommunity planning & development", etc.)
2	4	6	
	DOCUMEN	NTATION	
Accessible Documentation Not Filed with the  1) Document type Field maps Document description	<b>M</b> a	nintaining organization	
2) Document type Field notes Document description			
	RECORDER IN	FORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. War (address / phone / fax / e-mail)		Affiliation Janus Research	s@janus-research.com


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original ☐ Update



Site Name(s) (address if none) 524 NW 21st Terrace

Survey Project Name I-95 at Broward Boulevard Interchange

# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06304
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	8

Multiple Listing (DHR only)

Survey # (DHR only)

· ·	egory (please check one) ⊠bi ofit □private-nonprofit ☑private-ir	<u> </u>			ve American ☐foreign ☐unknown
		LOCATION & MA			
	/ between) E side btwn NW	6th St/Sistrunk Blvd a:	nd NW 5th St		
USGS 7.5 Map Name	FORT LAUDERDALE NORT es) Fort Lauderdale	H USGS Dat	e 1983 Plat or	Other Map	
					e:
Tax Parcel # 5042	05 07 0050		andgrant		
Subdivision NameF	River Garden	Old Old Old Morthing 210	Block	L	ot
Other Coordinates: X	/:Y:	Coordinat	ie System & Datur	m	
	(e.g., park)				
		HISTORY			
Construction Year:	1959 🗷 approximately	□ year listed or earlier	□ year listed or la	ater	
Original Use Priva	te Residence (House/Cot	tage/Cabin) From (year	ır): <u>1959</u>	To (year):	
Other Use Priva	te Residence (House/Cot		ır): ır):		
Moves:  □yes 🗷	no □unknown Date:	Original address_			
Alterations:   yes   Additions:   Wheel	no unknown Date:	Nature Nature Shed i	n gouthough g	orner of prov	
Additions:  yes  Architect (last name first	jno Ljunknown Date: <u>c.</u> ): <u>unknown</u>				
	specially original owner, dates, profes				
Is the Resource Affect	ted by a Local Preservation O	rdinance? □yes ⊠no □u	nknown Describe	9	
		DESCRIPTIO	N		
Style Masonry Ver	rnacular	Exterior Plan Recta	angular		Number of Stories1
	Stucco				
Roof Material(s) 1.	Gable Composition shingles	2 2.		3 3.	
Roof secondary	strucs. (dormers etc.) 1.		2		
Windows (types, materia	ls, etc.) <u>Metal 2/2 single</u>	-hung-sash; triple win	dow on west si	ide	
<b>D</b> istinguishing Archite	ctural Features (exterior or interio	or ornaments) <u>Metal awning</u>	s on most wind	dows; vinyl s	siding at gable ends
					<del></del>
Ancillary Features / C	outbuildings (record outbuildings, n	najor landscape features; use continu	ation sheet if needed.)	Bricks outl	ine walkways; stucco
	de; driveway paved wit	n concrete squares; cha	ain-link fence	around prope	erty; c. 1965 shed in
SE corner					
DHR L	JSE ONLY	OFFICIAL EVALUA	TION	DH	R USE ONLY
NR List Date		ia for NR listing: □yes □no	☐insufficient info		Init
 ☐Owner Objection	KEEPER – Determined eligible NR Criteria for Evaluation:		tional Register Bulle	Date otin 15. p. 2)	


Site #8 \_ BD06304

DESCRIPTION (continued)	
Chimney: Noo_Chimney Material(s): 1	
Porch Descriptions (types, locations, roof types, etc.) None observed	
Condition (overall resource condition):     Excellent   Image: Im	shed in the southeast
Archaeological Remains	☐Check if Archaeological Form Completed
RESEARCH METHODS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐Ibrary research</li> <li>☐ building permits</li> <li>☐ occupant/owner interview</li> <li>☑ property appraiser / tax records</li> <li>☐ newspaper files</li> <li>☐ neighbor interview</li> </ul>	□ Sanborn maps □ plat maps □ Public Lands Survey (DEP) □ HABS/HAER record search
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This building is of a Florida. The residence is in the River Garden neighborhood, which is not associated	information common style in South with a significant
developer. The neighborhood lacks integrity with several alterations, demolitions, a Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "comm 1 3 5 5	nunity planning & development", etc.)
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important Document type Field maps Maintaining organization Janus Research  The procument description File or accession #'s	
2) Document type Field notes Maintaining organization Janus Research Document description File or accession #'s	
RECORDER INFORMATION	
Recorder NameJanus Research	anus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

# PHOTOGRAPH **SKETCH MAP** 8BD6304



☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06305					
Field Date	9-26-2017					
Form Date	9-29-2017					
Recorder #	9					

Curvoy Droject Name	none) <u>516 NW 21st Terrace</u>			Multiple Listing (DHR only)			
	Project Name _I-95 at Broward Boulevard Interchange  Register Category (please check one)				Survey # (DHR only)		
Ownership:private-pro	it □private-nonprofit ☑private-indivi	dualprivate-nonspecificcity	countystate	☐rederal ☐iNative American ☐fore	gn <b></b> unknown		
		LOCATION & MAI	PPING				
Street Number			Street Type	Suffix Direction			
Address: 516	NW 21st		Terrace				
	petween) E side btwn NW 6tl						
City / Town (within 2 miles	FORT LAUDERDALE NORTH  Fort Lauderdale	USGS Date	1983 Plat Of C	County Programs			
	ange 42E Section 5	-					
Tay Parcel # 5042 0	ange 42E <b>S</b> ection 5	_ 74 Section. LINVV LISV La	ndarant	irregular-flattie			
Subdivision Name Ri	5 07 0070  ver Garden	La	ilock	Lot			
UTM Coordinates: Zon	e □16 ⊠17 Easting 5 8	2 9 3 6 <b>N</b> orthing 2 8 9	0 1 1 0	<b>L</b> ot			
Other Coordinates: X:	Y:	Coordinate	System & Datum				
Name of Public Tract (	e.g., park)						
`							
		HISTORY					
Construction Year 1	963 <b>x</b> approximately	□vear listed or earlier □	Tvear listed or lat	er			
Original Use Privat	e Residence (House/Cotta	ge/Cabin) From (vear)	1963	To (vear):			
Current Use Privat	e Residence (House/Cotta	ge/Cabin) From (year)	:	To (year): 2017			
Other Use		From (year)	:	To (year):			
Moves:  □yes 🗷 r	o 🗖 unknown Date:	Original address					
Alterations:		Os NatureDoor_re	placed; carpo	rt enclosed; W side			
Additions: □yes ⊠r	o □unknown Date:	Nature					
Architect (last name first):	unknown	Builder (I	last name first): unl	nown			
Ownership History (esp	ecially original owner, dates, profession	, etc.)					
Is the Pasource Affects	ad by a Local Preservation Ordin	nanca? Dvos Vno Dunk	rnown Describe				
Is the Resource Affecte	ed by a Local Preservation Ordin	nance? □yes ☑no □unk	known Describe				
Is the Resource Affecto	ed by a Local Preservation Ordin	nance? □yes ⊠no □unk  DESCRIPTION					
		DESCRIPTION	V		20 1		
Style Masonry Vern	nacular	DESCRIPTION  Exterior Plan Irregu	lar	Number of Stori	es <u>1</u>		
Style Masonry Verne Exterior Fabric(s) 1. s	nacular tucco	DESCRIPTION  Exterior Plan Irregulation 2. Stone	lar	Number of Stori			
Style Masonry Verner Exterior Fabric(s) 1. Second Type(s) 1. Here	nacular tucco ip	DESCRIPTION  Exterior Plan Irregu  2. Stone 2. Flat	lar	Number of Stori 3 _ 3			
Style Masonry Vern Exterior Fabric(s) 1. S Roof Type(s) 1. H Roof Material(s) 1. C	nacular tucco	DESCRIPTION  Exterior Plan Irregu  2. Stone  2. Flat  2. Built-up	lar	Number of Stori 3 3 3 3			
Style Masonry Vern Exterior Fabric(s) 1. S Roof Type(s) 1. H Roof Material(s) 1. C	nacular tucco ip omposition shingles TUCS. (dormers etc.) 1.	DESCRIPTION  Exterior Plan Irregu  2. Stone  2. Flat  2. Built-up	lar	Number of Stori 3 3 3 3			
Style Masonry Verne Exterior Fabric(s) 1. Second Type(s) 1. He Roof Material(s) 1. Cecond Roof Secondary Stylindows (types, materials)	tucco ip omposition shingles TUCS. (dormers etc.) 1	DESCRIPTION  Exterior Plan Irregu  2. Stone  2. Flat  2. Built-up	N lar 2	Number of Stori			
Style Masonry Verne Exterior Fabric(s) 1. Secondary Style Roof Material(s) 1. Center Roof Secondary Style Windows (types, materials Distinguishing Architect	tucco ip omposition shingles rucs. (dormers etc.) 1 , etc.) Boarded up	DESCRIPTION  Exterior Plan Irregu  2. Stone  2. Flat  2. Built-up	lar  2. window and do	Number of Stori 3. 3. 3. 3. 3. or surrounds; stone vene			
Style Masonry Verne Exterior Fabric(s) 1. Secondary Style Roof Material(s) 1. Center Roof Secondary Style Windows (types, materials Distinguishing Architect	tucco ip omposition shingles TUCS. (dormers etc.) 1	DESCRIPTION  Exterior Plan Irregu  2. Stone  2. Flat  2. Built-up	lar  2. window and do	Number of Stori 3. 3. 3. 3. 3. or surrounds; stone vene			
Style Masonry Verne Exterior Fabric(s) 1. Style Roof Type(s) 1. Hoof Material(s) 1. Consort Roof Secondary Style Windows (types, materials)  Distinguishing Architectin the 2000s on book Roof Roof Secondary Style Roof Secondary Secon	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.) Boarded up tural Features (exterior or interior or ottom half of west side	DESCRIPTION  Exterior Plan Irregul  2. Stone  2. Flat  2. Built-up  naments) Plain stucco and enclosed carport	lar  2 window and do in southwest	Number of Stori 3 3 3 or surrounds; stone vene	er added		
Style Masonry Verne Exterior Fabric(s) 1. Second Type(s) 1. He Roof Material(s) 1. Cecond Roof Secondary St Windows (types, materials)  Distinguishing Architectin the 2000s on be Ancillary Features / Output	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)	DESCRIPTION  Exterior Plan Irregul  2. Stone  2. Flat  2. Built-up  naments) Plain stucco and enclosed carport	lar  2 window and do in southwest	Number of Stori 3 3 3 or surrounds; stone vene	er added		
Style Masonry Verne Exterior Fabric(s) 1. Style Roof Type(s) 1. Hoof Material(s) 1. Consort Roof Secondary Style Windows (types, materials)  Distinguishing Architectin the 2000s on book Roof Roof Secondary Style Roof Secondary Secon	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)	DESCRIPTION  Exterior Plan Irregul  2. Stone  2. Flat  2. Built-up  naments) Plain stucco and enclosed carport	lar  2 window and do in southwest	Number of Stori 3 3 3 or surrounds; stone vene	er added		
Style Masonry Verne Exterior Fabric(s) 1. Second Type(s) 1. He Roof Material(s) 1. Cecond Roof Secondary Stylindows (types, materials)  Distinguishing Architectin the 2000s on be Ancillary Features / Output	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)	DESCRIPTION  Exterior Plan Irregul  2. Stone  2. Flat  2. Built-up  naments) Plain stucco and enclosed carport	lar  2 window and do in southwest	Number of Stori 3 3 3 or surrounds; stone vene	er added		
Style Masonry Verne Exterior Fabric(s) 1. Second Type(s) 1. He Roof Material(s) 1. Cecond Roof Secondary Stylindows (types, materials)  Distinguishing Architectin the 2000s on be Ancillary Features / Output	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)	DESCRIPTION  Exterior Plan Irregul  2. Stone  2. Flat  2. Built-up  naments) Plain stucco and enclosed carport	lar  2 window and do in southwest	Number of Stori 3 3 3 or surrounds; stone vene	er added		
Style Masonry Verne Exterior Fabric(s) 1. Style Roof Type(s) 1. Hoof Material(s) 1. Construction Roof Secondary Style Windows (types, materials) Distinguishing Architection the 2000s on but the 2000s on but corner of properties.	tucco ip omposition shingles  TUCS. (dormers etc.) 1, etc.)Boarded up  tural Features (exterior or interior or ottom half of west side  tbuildings (record outbuildings, major y	Exterior Plan Irregulary 2. Stone 2. Flat 2. Built-up  naments) Plain stucco and enclosed carport rlandscape features; use continuation	lar  2.  window and do in southwest on sheet if needed.)	Number of Stori	er added		
Style Masonry Verne Exterior Fabric(s) 1. Style Roof Type(s) 1. Hoof Material(s) 1. Consort Roof Secondary Style Windows (types, materials) Distinguishing Architectin the 2000s on but Ancillary Features / Outcorner of property	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)	DESCRIPTION  Exterior Plan Irregul  2. Stone  2. Flat  2. Built-up  naments) Plain stucco and enclosed carport	lar  2.  window and do in southwest on sheet if needed.)	Number of Stori 3 3 3 or surrounds; stone vene	er added		
Style Masonry Verne Exterior Fabric(s) 1. Style Roof Type(s) 1. Hoof Material(s) 1. Consort Roof Secondary Style Windows (types, materials) Distinguishing Architectin the 2000s on but Ancillary Features / Outcorner of property	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)Boarded up  dural Features (exterior or interior or ottom half of west side  tbuildings (record outbuildings, major y  SE ONLY  SHPO - Appears to meet criteria for the content of	Exterior Plan Irregulary 2. Stone 2. Flat 2. Built-up  naments) Plain stucco and enclosed carport r landscape features; use continuation	lar  2.  window and do in southwest on sheet if needed.)	Number of Stori	er added		
Style Masonry Verrexterior Fabric(s) 1. Secondary Style Roof Type(s) 1. Head Roof Material(s) 1. Construction Roof Secondary Stylindows (types, materials)  Distinguishing Architection the 2000s on become of property	tucco ip omposition shingles rucs. (dormers etc.) 1, etc.)Boarded up  tural Features (exterior or interior or ottom half of west side  tbuildings (record outbuildings, major y  SE ONLY  SHPO - Appears to meet criteria fr KEEPER - Determined eligible:	Exterior Plan Irregulary 2. Stone 2. Flat 2. Built-up  naments) Plain stucco and enclosed carport r landscape features; use continuation of the co	lar  2.  window and do in southwest on sheet if needed.)	Number of Stori _ 3	er added vest		


Site #8 BD06305

	DESCR	IPIION (continued)		
Chimney: Noo Chimney Ma Structural System(s): 1Con Foundation Type(s): 1Con Foundation Material(s): 1Con	ntinuous	2		
	est-facing 2000s panel do d carport	oor with oval light a		stoop; secondary panel foor
Condition (overall resource condition): Narrative Description of Resource				and few alterations. The
carport in the southwest				
Archaeological Remains				Check if Archaeological Form Completed
	RESEARCH MI	ETHODS (check all t	hat apply)	
☐FL State Archives/photo colled ☐ property appraiser / tax record ☐ cultural resource survey (CRA ☐ other methods (describe) _ His			ner interview rview ction	□ Sanborn maps □ plat maps □ Public Lands Survey (DEP) □ HABS/HAER record search
	OPINION OF RE	ESOURCE SIGNIF	ICANCE	
Appears to meet the criteria for NAppears to meet the criteria for NExplanation of Evaluation (require Florida. The residence is	National Register listing as part o od, whether significant or not; use separa s in the River Garden nei	If a district?	no [insuffice]ino insuffice ilding is of not associate	ed with a significant
developer. The neighborhod Area(s) of Historical Significance 1		for categories: e.g. "architecture",	"ethnic heritage", "co	
2	4		6	
	DOC	UMENTATION		
Accessible Documentation Not F  1) Document type Field maps Document description	iled with the Site File - including fie	<b>M</b> aintaining organization	Janus Research	
	RECORD	ER INFORMATIO	N .	
Recorder Name Janus Resea Recorder Contact Information (address / phone / fax / e-mail)		Affiliation Janus FL 33607 / (813) 636-		@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06306
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	10

Site Name(s) (address if none) 448 NW 21st Terrace Survey Project Name I-95 at Broward Boulevard I	Multiple Listing (DHR only)  Interchange Survey # (DHR only)
National Register Category (please check one)	
Address: 448 Direction Street Name Address: 448 NW 21st  Cross Streets (nearest / between) E side of intersection USGS 7.5 Map Name FORT LAUDERDALE NORTH  City / Town (within 3 miles) Fort Lauderdale   Ir  Township 50s Range 42E Section 5 %  Tax Parcel # 5042 05 07 0110  Subdivision Name River Garden  UTM Coordinates: Zone □16 ▼17 Easting 5 8 2 9	Coordinate System & Datum
	HISTORY
Original Use Current Use Other Use  Moves:	ear listed or earlier
Is the Resource Affected by a Local Preservation Ordinano	ce?  yes  no  unknown  Describe
	DESCRIPTION
Exterior Fabric(s) 1. Stucco  Roof Type(s) 1. Gable  Roof Material(s) 1. Composition shingles  Roof secondary strucs. (dormers etc.) 1.	Exterior Plan Rectangular Number of Stories 1  2. Wood siding 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Distinguishing Architectural Features (exterior or interior orname gable end on west side	ents) Plain stucco window surrounds on west side; wood siding at
Ancillary Features / Outbuildings (record outbuildings, major land southwest corners; walkways along north and	scape features; use continuation sheet if needed.) Two driveways at northwest and south sides
DHR USE ONLY C	OFFICIAL EVALUATION DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NI KEEPER – Determined eligible:  □Owner Objection NR Criteria for Evaluation: □a □b	R listing: Syes Some Sinsufficient info Date Some Some Some Some Some Some Some Som


Site #8 BD06306

	DESC	RIPTION (continued)		
Chimney: Noo_ Chimney Ma Structural System(s): 1co	nterial(s): 1 ncrete block	2	3.	
Foundation Type(s): 1. Co Foundation Material(s): 1. Co Main Entrance (stylistic details) T stoops; some appear repl	ncrete Block wo north-facing panel d	_ 2		ors; all have concrete
Porch Descriptions (types, locations		red		
Condition (overall resource condition) Narrative Description of Resource				nd few alterations.
Archaeological Remains				Check if Archaeological Form Completed
	RESEARCH M	IETHODS (check all	that apply)	
☑FMSF record search (sites/st ☐FL State Archives/photo colle ☑property appraiser / tax recor ☐cultural resource survey (CR/ ☑other methods (describe) _His Bibliographic References (give FM)	ction	d □occupant/ov illes □ neighbor into os □ interior inspo	vner interview erview ection	□Sanborn maps □plat maps □Public Lands Survey (DEP) □HABS/HAER record search
	ODINION OF I	RESOURCE SIGNII	ELCANCE	
	OPINION OF R	ESOURCE SIGNII	FICANCE	
Appears to meet the criteria for I Appears to meet the criteria for I Explanation of Evaluation (require Florida. The quadraplex developer. The neighborh	National Register listing as par ed, whether significant or not; use sep is in the River Garden	t of a district?yes _ [ arate sheet if needed) <u>This bu</u> neighborhood, which is	xno □insuffici uilding is of s not associat	ed with a significant
Area(s) of Historical Significance  1.	e (see <i>National Register Bulletin 15</i> , p.	8 for categories: e.g. "architecture"	, "ethnic heritage", "co 5	
2	4		6	
	DO	CUMENTATION		
Accessible Documentation Not F  Document type Field maps  Document description	Filed with the Site File - including	Maintaining organization	Janus Research	
2) Document type Field notes		Maintaining organization	Janus Research	
	RECOR	DER INFORMATIO	ON	
Recorder Name Janus Resear Recorder Contact Information (address / phone / fax / e-mail)		Affiliation Janua FL 33607 / (813) 636		@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06307
Field Date	9-26-2017
Form Date	10-2-2017
Recorder #	11

Site Name(s) (address if none) 444					e Listing (DHR only)	
Survey Project Name I-95 at					/ # (DHR only)	
National Register Category (please						
Ownership: □private-profit □private-	nonprofit <b> X</b>  private-individual <b> </b>	private-nonspecificcity	countystate	e <b>ll</b> federal <b>ll</b> f	Native American Ltoreign	<b></b> unknown
	LOG	CATION & MAP	PING			
Street Number Dir	ection Street Name		Street Type	Suffix D	<u>Virection</u>	
Address: 444	NW 21st		Terrace			
Cross Streets (nearest / between) <u>E</u>						
USGS 7.5 Map Name FORT LE	UDERDALE NORTH	<b>U</b> SGS Date_	<u> 1983</u> Plat or	Other Map _		
City / Town (within 3 miles) Fort La						
Township 50s Range 42E	Section 5 1/4	section: NW SW	/ □SE □NE	E Irregular-na	ame:	
Tax Parcel # 5042 05 07 011	.1	Lai	ndgrant			
Tax Parcel # 5042 05 07 011 Subdivision Name River Gard UTM Coordinates: Zone □16	len	B Nambhina Ololo	IOCK		_ <b>L</b> ot	
Other Coordinates: V:	71/ Easting [2] 8 2 [9] 3	SII Northing 2 8 9	System 9 Datu	ım		
Other Coordinates: X:			System & Datu	m		
Name of Public Tract (e.g., park)						
		HISTORY				
Construction Year: 1956	■ approximately	ar listed or earlier	]year listed or I	later		
Original Use Private Reside						
Current Use Duplex			1990s			
Other Use	Data			_ 10 (year):_	<del></del>	
Moves:	own Date:	Natureoors/w:	indows repla	aced conve	erted dupley	
Additions: Syes Ino Inchine	wn Date:	Nature NE part:	ially enclos	sed porch	iceu dupiex	
Architect (last name first): unknown	wii Date. <u>C. 1990</u>	Ruilder (1	ast name first). 111	nknown		
Ownership History (especially original						
Is the Resource Affected by a Loc	cal Preservation Ordinance	e? □yes ⊠no □unk	nown Describ	e		
•		DECCRIPTION	.T	_		_
		DESCRIPTION	Ν ,			
Style Masonry Vernacular						
Exterior Fabric(s) 1. Stucco		2		3		
Roof Type(s) 1. Flat		2. Shed		3		
Roof Material(s) 1. Built-up				3		
Roof secondary strucs. (dorm			2			
Windows (types, materials, etc.) Me	tal 1/1 single-hung-	sash and 2-light a	wning; sing	le-hung-sa	sh appear to be 1	.980s
Pictinguishing Architectural Foats	IFOC (outsiler or interior ernamer	to) Torrigad atuat		nlain atu	ago banding and r	rindor.
Distinguishing Architectural Featusurrounds on west side; p						willdow
Barroanas on west state, p	arciarry enerosea pe	oren ander norenea	be blica 1001	L CACCIISTOI	1	
Ancillary Features / Outbuildings	(record outbuildings, major lands	cape features: use continuation	on sheet if needed	) Paved dri	veway on northwe	st.
corner of property; chair				<u>,                                    </u>		
DHR USE ONL	/ _O	FFICIAL EVALUAT	ION		OHR USE ONLY	
1						
	opears to meet criteria for NR	· _ · _	insufficient info		Init	
	Determined eligible:	□yes □no	nal Dogister Dell			
Owner Objection NR Criteria	for Evaluation:   a b	□c □d (see <i>Nation</i>	nal Register Bulle	eun 15, p. 2)		


Site #8 BD06307


	DESCRIPT	ION (continued)	
Chimney: No. o Chimney Mater	ial(s): 1	2	
Structural System(s): 1. Conc	rete block 2.	2 3.	<del></del>
Foundation Type(s): 1. Cont	inuous 2		
Foundation Material(s): 1conc	rete Block 2		
		with fanlight; two secondary	entrances on north side,
panel doors with 1/1 singl			
		rtheast corner of building ur	nder shed roof extension;
partially enclosed and scr	reened in; c. 1990 addition		
Condition (overall resource condition):		deteriorated Druinous	
		uplex was originally a single	e-family residence. The
back porch addition, c. 19	90, was completed when the	residence was converted into	o a duplex. A few
alterations were made duri			
Archaeological Remains			_ Check if Archaeological Form Completed
	RESEARCH METH	IODS (check all that apply)	
■ FMSF record search (sites/surve)		building permits	☐ Sanborn maps
☐FL State Archives/photo collection		occupant/owner interview	□ plat maps
☑ property appraiser / tax records		neighbor interview	☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
☐ cultural resource survey (CRAS)  ☐ other methods (describe) _ History		☐ interior inspection	☐ HADS/HAER Tectoru Sedicii
		heet if needed)	
Zibilogi aprilo reorororos (give rilier	manasanpi # # relevant, use community		
	OPINION OF RESO	URCE SIGNIFICANCE	
	Of INION OF RESO	UNCE SIGNIFICANCE	
Appears to meet the criteria for Nat			cient information
	tional Register listing as part of a dis		cient information
		etifneeded) This building is of	
		ood, which is not associated eral alterations, demolitions	
		egories: e.g. "architecture", "ethnic heritage", "c	
		5	
2	4		
	DOCUM	ENTATION	
	DOCUM	ENTATION	
Accessible Documentation Not File	d with the Site File - including field note	es, analysis notes, photos, plans and other impo	ortant documents
1) Document type Field maps		Maintaining organization Janus Research	
Document description		File or accession #'s	
		Maintaining organization	
Document description		File or accession #'s	
	RECORDER	INFORMATION	
December News			
Recorder Name Janus Research		Affiliation <u>Janus Research</u> 3607 / (813) 636-8200 / janus	gelianus rassansk
(address / phone / fax / e-mail)	U/ N. Waru St., Tampa FL 3.	3001 / (013) 036-8200 / Janus	owjanus-research.com


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original
☐ Update



Site Name(s) (address if none) 442 NW 21st Terrace

# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06308
Field Date 9-26-2017
Form Date 9-29-2017
Recorder # 12

Multiple Listing (DHR only) \_\_\_

						_ Survey i	# (DHR only)
National Register Ca							
Ownership: □private-p	rofit private-nonprof	it 🗷 private-individual 🗌	private-nonspecif	ic □city □county	□state □fe	ederal 🔲 Na	itive American ☐foreign ☐unknown
		LOC	ATION &	MAPPING			
Street Num	ber <u>Direction</u>			Street Ty		Suffix Dire	ection
Address: 442	NW	21st		Terra	ace		
Cross Streets (nearest	/between) E side	btwn NW 5th St	and NW 4th	St			
					Plat or Othe	er Map	
City / Town (within 3 mi	les) Fort Lauder	dale In (	ity Limits? 🗖	ves Ono Ounk	nown Cor	intv F	Broward
							ne:
Toy Dorool # 5040	Namye 42E	5 74 3	ection. Livi	Landgrant		zyulai-Hai	iic
Cubdivision Name	05 07 0130			Lanuyrani _			Lot
JULIA Coordinates 7	River Garden	Fasting Floral ala	Manthia a	DIUCK	<u> </u>		Lot
Other Coordinates: Zo	ne 🗀 16 💌 17	Easing [5] 8] 2] 9] 3	Northing	] 2 8 9 0 0 2	<u> </u>		
				ordinate System &	& Datum _		
Name of Public Tract	(e.g., park)						
			HISTO	RY			
Construction Year: _							
Original Use Priva	te Residence (	House/Cottage/Ca	abin) From	n (year):195	3 To	(year):	
Current Use Priva	te Residence (	House/Cottage/Ca					
Other Use				n (year):	To	(year):	
	no unknown	Date:	Original add	dress			
Alterations:		Date:1980s	Nature <u>c</u>	arport, porch	, doors,	some wi	ndows
Additions: ☐yes ☑		Date:					
Ownership History (e	specially original owner	, dates, profession, etc.) _					
Is the Resource Affect	cted by a Local Pre	servation Ordinance?	? □yes ⊠nd	□unknown D	escribe		
			DESCRIE	PTION			
01.1							N I COLL
							Number of Stories1
Exterior Fabric(s) 1.	Stucco		2			3	
Roof Type(s) 1.	Hip		2. <u>Flat</u>			3	
				)		3	
		1			2		
					most wind	lows not	visible due to closed
		ar to be 1980s re					
							"brick" and geometric
pattern on west	side and carpo	ort supports; ca	rport and e	nclosed porch	have fla	at roof	
Ancillary Features / (	Outhuildings (record	outhuildings major landsc	ane features: use	continuation sheet if r	needed) Par	ved driv	reway in northwest
,	•		•				eway in northwest
corner of prope	rty; paved wall		•				eway in northwest ; chain-link fence
,	rty; paved wall		•				
corner of prope	rty; paved wall		•				
corner of propes	rty; paved wall	sway leads from o	•	west and sout		of house	
corner of propes	JSE ONLY	sway leads from (	FICIAL EVA	west and sout	h sides o	of house	; chain-link fence
corner of proper around back yard	JSE ONLY	OF to meet criteria for NR I	FICIAL EVA	ALUATION	h sides o	of house	; chain-link fence
corner of propes	JSE ONLY  SHPO – Appears KEEPER – Deterr	OF to meet criteria for NR I	FICIAL EVA	ALUATION	h sides o	Date	; chain-link fence

Site #8 BD06308


	DESCRIPT	ION (continued)	
Chimney: No. o Chimney Mater	ial(s): 1	23.	
Foundation Type(s): 1. <u>cont</u>	inuous 2		
	rete Block 2		
		ith screen door on enclosed	original porch under flat
	of types etc) None observed: or	iginal porch on southwest co	orner was been enclosed in
	ed to the new exterior wall		
	lexcellent ⊠good □fair □c		
		sidence has a simple form ar	
	ended west, the porch was e	nclosed, doors were replaced	d, and some of the windows
were replaced.			
Archaeological Remains			_ <b>C</b> heck if Archaeological Form Completed
	RESEARCH METH	ODS (check all that apply)	
<b>▼</b> FMSF record search (sites/surve	eys) 🔲 library research	□ building permits	☐ Sanborn maps
☐FL State Archives/photo collection		occupant/owner interview	□ plat maps
<b>⊠</b> property appraiser / tax records	□ newspaper files	☐ neighbor interview	☐ Public Lands Survey (DEP)
□cultural resource survey (CRAS)		interior inspection	☐ HABS/HAER record search
▼other methods (describe) _ Histo			
Bibliographic References (give FMSF	manuscript # if relevant, use continuation sh	eet if needed)	
	OPINION OF RESOU	URCE SIGNIFICANCE	
Appears to meet the criteria for Nat	ional Dogistor listing individually?	□yes <b>⊠</b> no □insuffic	cient information
	ional Register listing as part of a dis		cient information
		tifneeded) This building is of	
		rhood, which is not associat	
		ral alterations, demolitions	
Area(s) of Historical Significance (set 1		gories: e.g. "architecture", "ethnic heritage", "co	ommunity planning & development", etc.)
2	4	6	
	DOCUMI	ENTATION	
A			
Accessible Documentation Not File  Document type Field maps	d with the Site File - including field notes 	s, analysis notes, photos, plans and other impo	ortant documents
1) Document description		File or accession #'s	
<b>D</b> ocument description		File of accession # 5	
	RECORDER I	NFORMATION	
Recorder Name Janus Researc	eh	Affiliation Janus Research	
		607 / (813) 636-8200 / janus	s@janus-research.com
(address / phone / fax / e-mail)			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06309
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	13

	ifnone) 428 NW 21st Terrace			Multiple Listing (DHR only)
	I-95 at Broward Boulevard I			Survey # (DHR only)
	egory (please check one)  building			federal ☐Native American ☐foreign ☐unknown
Ownership. Dprivate-pr			-	rederal Mative American Moreign Munknown
		CATION & MAPP		
Address: Street Numb	Direction         Street Name           NW         21st		Street Type Terrace	Suffix Direction
	/ between) E side btwn NW 5th St		Terrace	
			983 Plat or Oth	er Map
City / Town (within 3 mil	es) <u>Fort Lauderdale</u> <b>[r</b>	n City Limits? ■ yes □ no	□unknown Co	ountyBroward
Township _50s I	Range 42E Section 5 1/2	section: NW SW	□SE □NE Im	regular-name:
Tax Parcel # 5042	05 07 0160	Land	Igrant	
Subdivision NameF	liver Garden	Blo	ck	Lot
Other Coordinates: Zo	ne ∐16 🗷1/ Easting [5] 8] 2 [9]	3 1 Northing 2 8 8 9	9 7 0	
Name of Public Tract	(e.g., park)	Coordinate Sy	/stem & Datum _	
TWATTE OF FUNDIC FIREL	(o.g., park)			
		HISTORY		
Construction Voor	1955 Vanprovimatoly Dy	par listed or parlier	nar listed or later	
Original Use Priva	$1955$ $\square$ approximately $\square$ y te Residence (House/Cottage/	cabin) From (vear).	1955 T	o (vear):
Current Use Priva	te Residence (House/Cottage/	Cabin) From (year):	T	o (year): 2017
Other Use				o (year):
	no 🗖 unknown Date:	Original address		<del>-</del>
Alterations: xyes	]no □unknown Date: 1990s	NatureDoors rep	laced	
Additions: Syes  Architect (Leabness See	no unknown Date: 1970s	Nature North sid	le storage roo	om with flat roof
	g: unknown specially original owner, dates, profession, etc.			nwo
Ownership History (es	pecially original owner, dates, profession, etc.,	/		
Is the Resource Affec	ted by a Local Preservation Ordinand	:e? □yes ⊠no □unkno	own Describe	
		DESCRIPTION		
Style Masonry Ver	macular	Exterior Plan L-shaped	<u>1</u>	Number of Stories 1
Poof Type(s) 1.	Stucco	_ Z		3 3
Roof Material(s) 1	Composition shingles	2. Fiac 2 Built-up		3
Roof secondary	strucs. (dormers etc.) 1.		2	<u> </u>
	ls, etc.) Metal 2/2 single-hung			
0 0				d south sides; faux shutters;
1970s storage ro	oom on north side is attached	to the house via it	s flat roof	
Ancillary Features / C	outhuildings (record outhuildings major land	scane features: use continuation	sheet if needed ) Tr	nformal driveway in northwest
,	rty; paved walkway from front	•	Sheet ii needed.)	ITOTIMAT ATTVEWAY III HOTEHWODE
DHR L	JSE ONLY C	OFFICIAL EVALUATION	DN	DHR USE ONLY
NR List Date				
INV TISE DATE	SHPO – Appears to meet criteria for NI KEEPER – Determined eligible:	R ilsting: □yes □no □il □yes □no	ISUITICIETIL ITIIU	Date Init Date
Owner Objection	NR Criteria for Evaluation: ☐a ☐b	—, —	nl Register Bulletin 1	


Site #8 BD06309


	DESCRIPTION	JN (continued)	
Chimnov: No. o Chimnov Material(s):	1	2	
Chimney: No. o Chimney Material(s): Structural System(s): 1. Concrete in	1	2	
Foundation Type(s): 1. Continuous	<u>7100k</u> 2	5.	
Foundation Material(s): 1. Concrete B			
Main Entrance (stylistic details) West-faci			
Main Littrance (stylistic details)west-lact	ing 1990s panier door wit	in concrete stoop	
Porch Descriptions (types, locations, roof types,	otal None observed		
Torch Descriptions (types, locations, roof types,	etc.) _None obbet ved		
Condition (overall resource condition): □excell	ent Monord Offair Ode	teriorated □ruinous	
Narrative Description of ResourceThis			nd few alterations. The
storage room on the north side			
Archaeological Remains			Check if Archaeological Form Completed
			_ <b></b>
	RESEARCH METHO	DDS (check all that apply)	
TEMOS accorded to the last transfer of the second of the s	<b>—</b> 19	- h 9.10	
▼FMSF record search (sites/surveys)	□ library research	□ building permits	☐ Sanborn maps
☐FL State Archives/photo collection	□ city directory	□ occupant/owner interview	□ plat maps
☑ property appraiser / tax records	□ newspaper files	☐ neighbor interview	☐ Public Lands Survey (DEP)
□cultural resource survey (CRAS)	☐historic photos	☐ interior inspection	☐ HABS/HAER record search
▼other methods (describe) Historic a			
Bibliographic References (give FMSF manusc	ript # if relevant, use continuation shee	et if needed)	
	PINION OF RESOLU	RCE SIGNIFICANCE	
Appears to meet the criteria for National R	egister listing individually?	□yes <b>⋈</b> no □insuffic	eient information
Appears to meet the criteria for National R	egister listing as part of a distri	ict? □yes ⊠no □insuffic	eient information
Explanation of Evaluation (required, whether	significant or not; use separate sheet if	needed) This building is of	a common style in South
Florida. The residence is in the	: River Garden neighborh	nood, which is not associat	ed with a significant
developer. The neighborhood lack	s integrity with severa	al alterations, demolitions	, and in-fills.
Area(s) of Historical Significance (see Nation			
1	3	5	
2	4	6	
	DOCUME	NITATION	
	DOCUME	NIAIION	
Accessible Documentation Not Filed with t	ho Sito Filo including field notes	analysis nates, photos, plans and other impo	artant documents
Document type Field maps	M	laintaining organization Janus Research	ortant documents
1) Document description		File or accession #'s	
2) Document type Field notes			
Document description		File or accession #'s	
	RECORDER IN	NFORMATION	
	——————————————————————————————————————		
Recorder Name _ Janus Research		Affiliation Janus Research	
Recorder Contact Information1107 N.	Ward St., Tampa FL 336	07 / (813) 636-8200 / janus	@janus-research.com
(address / phone / fax / e-mail)			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06310
Field Date 9-26-2017
Form Date 9-29-2017
Recorder # 14

Site Name(s) (address if none) 424 NW 21st Terrace	Multiple Listing (DHR only)
Survey Project Name <u>I-95 at Broward Boulevard</u>	
National Register Category (please check one) ⊠building	
Ownership: □private-profit □private-nonprofit ☑private-individu	ual private-nonspecific city county state federal Native American foreign unknown
L	OCATION & MAPPING
Street Number <u>Direction</u> Street Name	Street Type Suffix Direction
Address: 424 NW 21st	Terrace
Cross Streets (nearest/between) E side btwn NW 5th	
	USGS Date 1983 Plat or Other Map
	_ In City Limits? ☑ yes ☐ no ☐ unknown County
Township 50s Range 42E Section 5	¼ section: □NW □SW □SE □NE Irregular-name:
Tax Parcel # 5042 05 07 01/0	Landgrant Lot
UTM Coordinates: Zone ☐16 ☑17 Easting 5 8 2	BIUCK LUI LUI
Other Coordinates: X: Lasting Street	Coordinate System & Datum
Name of Public Tract (e.g., park)	Coolullate System & Datum
Mattic of Fubility Track (o.g., party	
	HISTORY
2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- Park I Provide Barbara
Construction Year: 1964  approximately Contract Private Residence (House/Cottage	
	ge/Cabin)         From (year):         1964         To (year):         1980s           From (year):         1980s         To (year):         2017
Current Use Quadraplex Other Use	From (year): 10 (year): 2017 From (year): To (year):
	Original address
Alterations: \( \text{Yyes} \) \( \text{Ino} \) \( \text{Unknown} \) \( \text{Date:} \) \( \text{1970s/1:} \)	980s Nature Porch removed / windows, doors replaced
Additions: Xyes Ino Inknown Date: 1980:	s Nature West additions made house rectangular
Architect (last name first): unknown	Builder (last name first): unknown
Ownership History (especially original owner, dates, profession,	etc.)
	·
Is the Resource Affected by a Local Preservation Ordina	ance? □yes ☑no □unknown Describe
	DECODIDITION
	DESCRIPTION
Style Masonry Vernacular	Exterior Plan Rectangular Number of Stories 1
Exterior Fabric(s) 1. Stucco	2. Wood siding 3
Roof Type(s) 1. Gable	2 3
Doof Material(s) 1 Composition shingles	2 3
roon waterial(s) 1. composition siningles	5
Roof secondary strucs. (dormers etc.) 1.	2
Roof secondary strucs. (dormers etc.) 1.	2
Roof secondary strucs. (dormers etc.) 1	2
Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 and 2/2 s  Distinguishing Architectural Features (exterior or interior ornal	2. single-hung-sash; appear to be 1980s replacements  aments) Wood siding under gable end; 1980s west addition made house
Roof secondary strucs. (dormers etc.) 1	2. single-hung-sash; appear to be 1980s replacements  aments) Wood siding under gable end; 1980s west addition made house
Roof secondary strucs. (dormers etc.) 1	2. single-hung-sash; appear to be 1980s replacements  aments) Wood siding under gable end; 1980s west addition made house
Roof secondary strucs. (dormers etc.) 1	2. single-hung-sash; appear to be 1980s replacements aments) Wood siding under gable end; 1980s west addition made house draplex
Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 and 2/2 s  Distinguishing Architectural Features (exterior or interior ornal rectangular for its conversion into a quad-Ancillary Features / Outbuildings (record outbuildings, major I	2. single-hung-sash; appear to be 1980s replacements aments) Wood siding under gable end; 1980s west addition made house draplex
Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 and 2/2 s  Distinguishing Architectural Features (exterior or interior ornal rectangular for its conversion into a quad-Ancillary Features / Outbuildings (record outbuildings, major I	2. single-hung-sash; appear to be 1980s replacements aments) Wood siding under gable end; 1980s west addition made house draplex
Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 and 2/2 s  Distinguishing Architectural Features (exterior or interior ornal rectangular for its conversion into a quad-Ancillary Features / Outbuildings (record outbuildings, major I	2. single-hung-sash; appear to be 1980s replacements aments) Wood siding under gable end; 1980s west addition made house draplex
Roof secondary strucs. (dormers etc.) 1	2. single-hung-sash; appear to be 1980s replacements  aments) Wood siding under gable end; 1980s west addition made house draplex  landscape features; use continuation sheet if needed.) Paved parking for 3-4 cars on the
Roof secondary strucs. (dormers etc.) 1	2.  single-hung-sash; appear to be 1980s replacements  aments) Wood siding under gable end; 1980s west addition made house draplex  landscape features; use continuation sheet if needed.) Paved parking for 3-4 cars on the  OFFICIAL EVALUATION DHR USE ONLY
Roof secondary strucs. (dormers etc.) 1	2.  single-hung-sash; appear to be 1980s replacements  aments)Wood siding under gable end; 1980s west addition made house draplex  landscape features; use continuation sheet if needed.) Paved parking for 3-4 cars on the  OFFICIAL EVALUATION DHR USE ONLY  or NR listing:yesnoinsufficient infoDate
Roof secondary strucs. (dormers etc.) 1	2. single-hung-sash; appear to be 1980s replacements  aments) Wood siding under gable end; 1980s west addition made house draplex  landscape features; use continuation sheet if needed.) Paved parking for 3-4 cars on the  OFFICIAL EVALUATION DHR USE ONLY


Site #8 BD06310

	DESCRIPTI	UN (continued)	
Chimney: No. o Chimney Materi	al(c)· 1	2	
Structural System(s): 1 Congress	al(s): 1 2	2	
Foundation Type(s): 1 Contri	inuous 2.	5.	
	rete Block 2.		
	outh-facing and 2 north-faci		oncrete stoops; northwest
door has 1/1 single hung-s			
	of types, etc.) None observed; or:	iginal porch on north side 1	cemoved in the 1970s
<del></del>			
	lexcellent ⊠good □fair □de		
	This Masonry Vernacular qua		
irregular form to its curr	n into a quadraplex, the bu	ilding had a west addition t	nat changed its original
	ent rectangular form.		Check if Archaeological Form Completed
Archaeological Kemains			_ Licheck if Archaeological Form Completed
	RESEARCH METH	ODS (check all that apply)	
₩CE record coarch (cited/curve	Ulibrary receased	Dhuilding normits	Canhara mana
☑ FMSF record search (sites/surve)  ☐ FL State Archives/photo collection  ☐ FL State Archives/photo co		<ul><li>□ building permits</li><li>□ occupant/owner interview</li></ul>	☐ Sanborn maps ☐ plat maps
✓ property appraiser / tax records	□ newspaper files	☐ neighbor interview	☐ Public Lands Survey (DEP)
□ cultural resource survey (CRAS)		☐ interior inspection	HABS/HAER record search
■other methods (describe) _ Histo:		Hitterior inspection	Th (Both) (Elected Search
	manuscript # if relevant, use continuation she	eet if needed)	
	· · · · · · · · · · · · · · · · · · ·	, <del></del>	
	·		
	ODINION OF DESOL	URCE SIGNIFICANCE	
	Of INION OF RESOL	TRUE SIGNIFICANCE	
Appears to meet the criteria for Nati			cient information
	ional Register listing as part of a dist		cient information
	whether significant or not; use separate sheet		
	in the River Garden neighbo		
	l lacks integrity with sever		
_	ee <i>National Register Bulletin 15</i> , p. 8 for categ		
1		5 6	
	DOCUME	ENTATION	
Accessible Degumentation Not File	d with the Cite File to built a feld and	and the state of t	antoni da como ente
Document type Field maps	d with the Site File - including field notes,	, analysis notes, pnotos, plans and otner impo Maintaining organization — Janus Research	ortant documents
1) Document description		File or accession #'s	
Decument time Field not on			
Document description			
	RECORDER I	NFORMATION	
Recorder Name Janus Researc	h	Affiliation Janus Research	
	07 N. Ward St., Tampa FL 336		s@ianus-research.com
(address / phone / fax / e-mail)		, (122, 120 0200 , Julius	

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06311
Field Date	9-26-2017
Form Date	9-29-2017
Recorder #	15


Site Name(s) (address if none) 420 NW 21st Terrace	Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Boulevard Interchange	
National Register Category (please check one)	
LOCATION &	
Address: Street Number Direction Street Name  **Page 1.5	Street Type Suffix Direction Terrace
Cross Streets (nearest/between) E side btwn NW 5th St and NW 4th	
USGS 7.5 Map Name FORT LAUDERDALE NORTH USG	
City / Town (within 3 miles) Fort Lauderdale In City Limits?	yes □no □unknown CountyBroward
Township <u>50s</u> Range <u>42E</u> Section <u>5</u> ¼ section: □NW	□SW □SE □NE Irregular-name:
Tax Parcel # _5042 05 07 0180  Subdivision Name _ River Garden	Landgrant
Subdivision Name River Garden  LTM Coordinates: 7 one 114 M17 Feeting Floral Global Morthing	Block Lot Lot
UTM Coordinates: Zone □16 図17 Easting 5 8 2 9 3 6 Northing Other Coordinates: X: Y: Coordinates:	rdinate System & Datum
Name of Public Tract (e.g., park)	Tulliate System & Datum
HISTO	RY
Construction Year:1962_	er
Original Use Private Residence (House/Cottage/Cabin) From	n (year): 1962 To (year):
Current Use Private Residence (House/Cottage/Cabin) From	n (year): To (year):
Other Use From	n (year): To (year):
Moves:yesnounknown Date: Original add	Messome windows replaced
Alterations: Syes Ino Inknown Date: 2000s Nature State Nature Nature Inches Nature Nature	
Architect (last name first): unknown Eate.   Nature	Suilder (last name first): unknown
Ownership History (especially original owner, dates, profession, etc.)	diada (da mano moy)
Is the Resource Affected by a Local Preservation Ordinance? ☐yes ☑no	□unknown Describe
DESCRI	TION
Style       Masonry       Vernacular       Exterior Plan         Exterior Fabric(s)       1. Stucco       2.	
Roof Type(s) 1. Gable 2. Flat	3.
Roof Material(s) 1. Composition shingles 2. Built-up	3
Roof secondary strucs. (dormers etc.) 1.	2
Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some to	rindows boarded up; double window right of front
door; west side windows appear to be 2000s replacements	
<u>Distinguishing Architectural Features</u> (exterior or interior ornaments) <u>Carport</u> screen west wall	on West side has flat roof and concrete block
Beleefi webe wall	
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use	continuation sheet if needed.) Planters at carport west wall;
paved half-circle driveway; chain-link fence around back	yard
	LUATION BURLING ONLY
DHR USE ONLY OFFICIAL EVA	ALUATION DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NR listing: ☐yes	□no □insufficient info Date Init
KEEPER – Determined eligible:	no Date
□Owner Objection NR Criteria for Evaluation: □a □b □c □d (s	ee <i>National Register Bulletin 15</i> , p. 2)

Site #8 \_ BD06311


	DESCRIPTION	JN (continued)	
Chimney: Noo_ Chimney Material Structural System(s): 1. Concre Foundation Type(s): 1. Contin Foundation Material(s): 1. Concre Main Entrance (stylistic details) West-	uous 2 te Block 2		
Porch Descriptions (types, locations, roof	ypes, etc.) Back porch on north	h side with concrete stoop	
Condition (overall resource condition):   Narrative Description of Resource  carport under the flat roof	This Masonry Vernacular res	idence features a concrete	block screen on the
Archaeological Remains			Check if Archaeological Form Completed
	RESEARCH METHO	DDS (check all that apply)	
■ FMSF record search (sites/surveys) ■ FL State Archives/photo collection ■ property appraiser / tax records ■ cultural resource survey (CRAS) ■ other methods (describe) _ Histori Bibliographic References (give FMSF me	S)	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
	OPINION OF RESOU	RCE SIGNIFICANCE	
Appears to meet the criteria for Nation Appears to meet the criteria for Nation Explanation of Evaluation (required, wh Florida. The residence is in developer. The neighborhood	nal Register listing as part of a distri ether significant or not; use separate sheet if the River Garden neighborh	ct? yes Ino insufficenceded) This building is of lood, which is not associate	ed with a significant
Area(s) of Historical Significance (see 1			
2	3 4	6	
	DOCUME	NTATION	
Document description	with the Site File - including field notes, a M	aintaining organization Janus Research File or accession #'s	ortant documents
	RECORDER IN	FORMATION	
Recorder Name Janus Research Recorder Contact Information 1107 (address / phone / fax / e-mail)			s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original □Update



Site Name(s) (address if none) 416 NW 21st Terrace

Survey Project Name <u>I-95</u> at Broward Boulevard Interchange

# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06312
Field Date	9-26-2017
Form Date	10-2-2017
Recorder #	16

Multiple Listing (DHR only) \_\_\_\_\_

Survey # (DHR only)

**Shaded Fields** represent the minimum acceptable level of documentation. Consult the *Guide to Historical Structure Forms* for detailed instructions.

National Register Category (please check one) ⊠building ☐ structure ☐ district ☐ site ☐ object  Ownership: ☐ private-profit ☐ private-nonprofit ☑ private-individual ☐ private-nonspecific ☐ city ☐ county ☐ state ☐ federal ☐ Native American ☐ foreign ☐ unknown
Cross Street Number   Direction   Street Name   Street Type   Suffix Direction
HISTORY
Construction Year: 1962
Is the Resource Affected by a Local Preservation Ordinance?  yes  unknown Describe
DESCRIPTION
Style Masonry Vernacular Exterior Plan Irregular Number of Stories 1  Exterior Fabric(s) 1. Stucco 2. Stucco 3. Wood siding  Roof Type(s) 1. Gable 2. 3.  Roof Material(s) 1. Composition shingles 2. 3.  Roof secondary strucs. (dormers etc.) 1. 2.  Windows (types, materials, etc.) Metal 1/1 single-hung-sash; most covered by metal awnings
Distinguishing Architectural Features (exterior or interior ornaments) Stone veneer on west side; front door has small roof overhang; wood siding at gable end
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Shed in northeast corner of property has wood siding and 5V crimped metal gable roof; entry concrete stoop and paved walkway leading to sidewalk
DHR USE ONLY OFFICIAL EVALUATION DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NR listing: Superance Shear Shear Superance Shear She

Site #8 BD06312


	DESCRIPT	ION (continued)	
Chimnov: No. o Chimnov Mator	ial(s). 1	2	
Structural Systom(s): 1 Cong	rate block	2 3.	<del></del>
Foundation Type(s): 1. Cont	invois 2.	J.	
Foundation Material(s): 1conc			
		ron screen security door and	gongrata gtoon, two gouth
facing secondary entrances		ton screen security door and	concrete stoop; two south-
Porch Descriptions (types, locations, ro			
Toren Descriptions (types, locations, to	or types, etc.)		
Condition (overall resource condition):	Texcellent ⊠good □fair □	deteriorated	
		esidence has a simple form.	It was originally
		t its current L-shape.	
Archaeological Remains			Check if Archaeological Form Completed
J			
	RESEARCH METH	HODS (check all that apply)	
TEMOS was and a south /s'testando		Entra 9 de marca de marco	
▼FMSF record search (sites/surve		building permits	☐ Sanborn maps
☐FL State Archives/photo collection		□ occupant/owner interview	□ plat maps
☑ property appraiser / tax records		☐ neighbor interview	□ Public Lands Survey (DEP)
□cultural resource survey (CRAS)		☐ interior inspection	☐ HABS/HAER record search
▼other methods (describe) Histo			
Bibliographic References (give FMSF	manuscript # if relevant, use continuation s	sheet if needed)	
	OPINION OF RESO	URCE SIGNIFICANCE	
		3-	
Appears to meet the criteria for Nat			cient information
Appears to meet the criteria for Nat			cient information
		eetifneeded) This building is of	
		orhood, which is not associat	
		eral alterations, demolitions	
Area(s) of Historical Significance (s		egories: e.g. "architecture", "ethnic heritage", "c	
1	3	5	
2	4	6	
	DOCUM	ENTATION	
	DOCUM	ENTATION	
Accessible Documentation Not File	d with the Site File - including field not	es, analysis notes, photos, plans and other imp	ortant documents
Document type Field maps	d with the Site File including held hot	Maintaining organization Janus Research	ortant documents
1) Document description		File or accession #'s	
Document time Field not as		Maintaining organization Janus Research	
<b>D</b> ocument description		The or accession # 3	
	RECORDER	INFORMATION	
Recorder Name		Affiliation Janus Research	
	07 N. Ward St., Tampa FL 3	3607 / (813) 636-8200 / janus	s@janus-research.com
(address / phone / fax / e-mail)			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

# PHOTOGRAPH





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06313
Field Date	9-26-2017
Form Date	10-2-2017
Recorder #	17

	if none) 412 NW 21st Terrace			Multiple	Listing (DHR only) _	
	I-95 at Broward Boulevard				# (DHR only)	
	tegory (please check one)					
Ownersnip:private-p	rofit private-nonprofit private-individual	private-nonspecific city	countystate	tederalN	ative Americanforeign	<b></b> unknown
	LO	OCATION & MAP	PING			
Street Num			Street Type	Suffix Di	rection	
Address: 412	NW 21st		Terrace			
	/between) E side btwn NW 5th S					
	e FORT LAUDERDALE NORTH					
	les) Fort Lauderdale					
Township <u>50s</u>	Range 42E Section 5	¼ section: □NW □SW	/ □SE □NE	Irregular-na	me:	
Tax Parcel # 5042	05 07 0183 River Garden	Lai	ndgrant			
Subdivision NameI	River Garden	B North Cololo	lock		_ <b>L</b> ot	
UTIVI Coordinates: Zo	one 🗀 16 💌 17 🕒 Easting [5] 8[2] 9	9 3 7  NIONTING 2 8 8	3 9 9 1 0			
Viner Coordinates: 7	(: Υ : Υ :	Coordinate	System & Datum	1		
Maine of Public Tract	(e.g., park)					
		HISTORY				
Construction Year:	1962 <b>⊠</b> approximately □	year listed or earlier	] year listed or la	ter		
Original Use Priva	te Residence (House/Cottage)	/Cabin) From (year):	1962	To (year):		
Current Use Priva	te Residence (House/Cottage,	/Cabin) From (year):	:	To (year):	2017	
Other Use		From (year):	:	To (year):		
	Ino □unknown Date:	Original address		1 . 5 7	- 4 +	
Alterations: Xyes		Nature Some win				
Additions: Jyes Architect (lest name fire	t): unknown Date:t	Nature	lost name first):	len or m		
Ownershin History (as	specially original owner, dates, profession, etc	<b>D</b> ulluel (i	ast flame first). um	KIIOWII		
Ownership mistory (c.	specially original owner, dates, profession, etc	··)				
Is the Resource Affect	cted by a Local Preservation Ordinan	ice? ∏ves ⊠no ∏unk	nown Describe			
		DESCRIPTION	N .			
Style Masonry Ve	rnacular	Exterior Plan Rectan	gular		Number of Stories	1
	Stucco					
	Gable					
Roof Material(s) 1.	Composition shingles	2. Built-up		3.		
	strucs. (dormers etc.) 1.					
Windows (types, materia	als, etc.) Metal 2/2 single-hung	g-sash, 1-light fixe	ed, and multi	-paned jal	ousie; some wind	ows
were altered in	the 1970s to accommodate AC	units				
Distinguishing Archite	ectural Features (exterior or interior ornam	nents) <u>Carport used</u> a	as porch unde	er flat roo	of extension; woo	d
siding at gable	end					
•	Outbuildings (record outbuildings, major lan	dscape features; use continuation	on sheet if needed.)_	Asphalt-pa	aved half-circle	
driveway						
DHR U	JSE ONLY (	OFFICIAL EVALUAT	ION		HR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for N	JR listing: Type Tno T	Tinsufficient info	Data	Init	
TVIX LIST DUTC	KEEPER – Determined eligible:	yes □no	_insumerent into		IIII	
Owner Objection	NR Criteria for Evaluation: ☐a ☐I		nal Register Bullet			
*		·				


Site #8 BD06313

	DESCRIP	TION (continued)	
Foundation Type(s): 1. <u>co</u>	ntinuous 2. ncrete Block 2.	flat roof extension for carpo	
Porch Descriptions (types, locations flat roof with simple so		t was converted into front po	rch on west side; under
Narrative Description of Resource		deteriorated pruinous residence has a simple form a is currently being used as th	
Archaeological Remains			Check if Archaeological Form Completed
		HODS (check all that apply)	
	rveys)	building permits ccupant/owner interview neighbor interview interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
	OPINION OF RES	OURCE SIGNIFICANCE	
Appears to meet the criteria for N Explanation of Evaluation (require Florida. The residence in developer. The neighborh	s in the River Garden neigh ood lacks integrity with se	district?  yes  no  insuffi neet if needed)  This building is of corhood, which is not associate veral alterations, demolitions	ed with a significant
Area(s) of Historical Significance  1		ategories: e.g. "architecture", "ethnic heritage", "o 5	community planning & development", etc.)
2	4	5 6	
	DOCUN	MENTATION	
Document type Field maps     Document description      Document type Field notes		otes, analysis notes, photos, plans and other imp  Maintaining organization  File or accession #'s  Maintaining organization  File or accession #'s	
	RECORDER	RINFORMATION	
Recorder Name Researce Recorder Contact Information (address / phone / fax / e-mail)		Affiliation <u>Janus Research</u> 33607 / (813) 636-8200 / janu	s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06314
Field Date	9-27-2017
Form Date	10-2-2017
Recorder #	5.0

	Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Boulevard	
National Register Category (please check one) Subuilding	
Ownership: I private-profit I private-nonprofit I private-individu	ual private-nonspecific city county state federal Native American foreign unknown
	OCATION & MAPPING
Street Number Direction Street Name	Street Type Suffix Direction
Address: 536 NW 21st	Avenue
Cross Streets (nearest / between) E side btwn NW 5th	
City / Town (within 3 miles) Fort Lauderdale	USGS Date 1983 Plat or Other Map
	14 section: NW SW SE NE Irregular-name:
Tay Parcel # 5042 04 30 0290	I andurant
Subdivision Name Dorsey Riverbend	Block Lot
UTM Coordinates: Zone ☐16 区17 Easting 5 8 3	Landgrant Lot
Other Coordinates: X: Y:	Coordinate System & Datum
Name of Public Tract (e.g., park)	
	WETADY
	HISTORY
Construction Year: 1950   ■ approximately	year listed or earlier  □ year listed or later
Original Use Private Residence (House/Cottag	ge/Cabin) From (year): 1950 To (year):
Current Use Private Residence (House/Cottag	ge/Cabin) From (year): To (year):
Other Use	From (year): To (year):
Moves:	Original address
Alterations: Syes One Ounknown Date: 2000	s Nature Windows, doors, porch supports replaced
Additions: ☐yes ☒no ☐unknown Date:  Architect (last name first): unknown	Nature Builder (last name first): unknown
	etc.)
Ownership History (especially original owner, dates, profession,	
Ownership History (especially original owner, dates, profession,	etc.)
Ownership History (especially original owner, dates, profession, Is the Resource Affected by a Local Preservation Ordinal	ance?  yes  no  unknown  Describe  DESCRIPTION
Ownership History (especially original owner, dates, profession, ls the Resource Affected by a Local Preservation Ordina  Style Masonry Vernacular	ance?
Ownership History (especially original owner, dates, profession, less the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco	ance?
Ownership History (especially original owner, dates, profession, ordinal list the Resource Affected by a Local Preservation Ordinal StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable	ance?
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	ance?
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	ance?
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal StyleMasonry Vernacular Exterior Fabric(s) 1Stucco Roof Type(s) 1Gable Roof Material(s) 1Composition shingles Roof secondary strucs. (dormers etc.) 1	DESCRIPTION  Exterior Plan L-shaped Number of Stories 1  2. 3. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1 Windows (types, materials, etc.)Metal 1/1 single-hureplacements Distinguishing Architectural Features (exterior or interior ornal structure)	DESCRIPTION  Exterior Plan L-shaped Number of Stories 1  2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements	DESCRIPTION  Exterior Plan L-shaped Number of Stories 1  2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior orms surrounds; 2000s porch supports are rectangles)	ance?  yes  no  unknown Describe    DESCRIPTION  Exterior Plan L-shaped  Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior orns surrounds; 2000s porch supports are rectan Ancillary Features / Outbuildings (record outbuildings, major of the support of the surrounds).	ance?  yes  no  unknown Describe  DESCRIPTION  Exterior Plan L-shaped  Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior ornsurrounds; 2000s porch supports are rectar Ancillary Features / Outbuildings (record outbuildings, major I side of front porch; gravel driveway frames)	ance?  yes  no  unknown Describe    DESCRIPTION  Exterior Plan L-shaped  Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior orns surrounds; 2000s porch supports are rectan Ancillary Features / Outbuildings (record outbuildings, major of the support of the surrounds).	ance?  yes  no  unknown Describe  DESCRIPTION  Exterior Plan L-shaped  Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior ornsurrounds; 2000s porch supports are rectar Ancillary Features / Outbuildings (record outbuildings, major I side of front porch; gravel driveway frames)	ance?  yes  no  unknown Describe  DESCRIPTION  Exterior Plan L-shaped  Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior ornsurrounds; 2000s porch supports are rectar Ancillary Features / Outbuildings (record outbuildings, major I side of front porch; gravel driveway frames)	ance?  yes  no  unknown Describe  DESCRIPTION  Exterior Plan L-shaped  Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Ownership History (especially original owner, dates, profession, or list the Resource Affected by a Local Preservation Ordinal StyleMasonry Vernacular Exterior Fabric(s) 1Stucco Roof Type(s) 1Gable Roof Material(s) 1Composition shingles Roof secondary strucs. (dormers etc.) 1 Windows (types, materials, etc.) _Metal 1/1 single-hureplacements  Distinguishing Architectural Features (exterior or interior orns surrounds; 2000s porch supports are rectar Ancillary Features / Outbuildings (record outbuildings, major I side of front porch; gravel driveway frame property	DESCRIPTION  Exterior Plan L-shaped Number of Stories 1 2. 3. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.


Site #8 \_ BD06314


DESCRIPTION (continued)			
Chimney: Noo_ Chimney Material(s) Structural System(s): 1. Concrete Foundation Type(s): 1. Continuo Foundation Material(s): 1. Concrete Main Entrance (stylistic details) West-fa raised concrete pad  Porch Descriptions (types, locations, roof types supports and a raised concrete	es, etc.) Entry porch on wes	th rectangular light under	entry porch roof overhang;
Condition (overall resource condition): ☐excellent ☑good ☐fair ☐deteriorated ☐ruinous  Narrative Description of Resource _ This Masonry Vernacular residence has a simple form and few alterations.			
Archaeological Remains			<b>□C</b> heck if Archaeological Form Completed
	RESEARCH METHO	DDS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐Historic</li> <li>Bibliographic References (give FMSF manual</li> </ul>	☐ library research ☐ city directory ☐ newspaper files ☐ historic photos aerial photography	☐ building permits ☐ occupant/owner interview ☐ neighbor interview ☐ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
OPINION OF RESOURCE SIGNIFICANCE			
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in South  Florida. It is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood. The neighborhood lacks integrity with several alterations, demolitions, and in-fills.  Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)			
1	3	5	
2	4	6	
	DOCUME	NTATION	
Accessible Documentation Not Filed with  1) Document type Field maps Document description  2) Document type Field notes	M	laintaining organization Janus Research File or accession #'s	ortant documents
2) Document description			
RECORDER INFORMATION			
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com  (address/phone/fax/e-mail)			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original □Update



Site Name(s) (address if none) 532 NW 21st Avenue

## HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06315		
Field Date	9-27-2017		
Form Date	10-2-2017		
Recorder #	49		

\_\_ Multiple Listing (DHR only) \_\_\_\_\_

	I-95 at Broward Boulevard Interchange Survey # (DHR only)
maliunai registei Gat	egory (please check one) 🗷 building 🗆 structure 🗖 district 🗖 site 🗖 object
	ofit □private-nonprofit ☑private-individual □private-nonspecific □city □county □state □federal □Native American □foreign □unknown
	LOCATION & MADDING
Street Numl	LOCATION & MAPPING  Direction Street Name Street Type Suffix Direction
	NTA 21 at
Cross Straats (nogreet	/ between) E side btwn NW 5th St and NW 6th St
	FORT LAUDERDALE NORTH USGS Date 1983 Plat or Other Map
City / Town (within 3 mil	es) Fort Lauderdale In City Limits? In county Broward
	Range 42E Section 4 1/4 section: DNW DSW DSE DNE Irregular-name:
Toy Dorool # 5040	Adige 42E Section 4 74 Section. Livvy List Live inegular-name.
Subdivision Name T	Dorgan Pinarband Lat
JITM Coordinates: 70	04 30 0300       Landgrant         Porsey Riverbend       Block       Lot         ne □16 図17 Easting 5 8 3 1 4 5       Northing 2 8 9 0 1 8 6
Other Coordinates: X	:: Y: Coordinate System & Datum
Mamo of Dublic Tract	(e.g., park)
Name of Fublic Hact	(e.g., park)
	HISTORY
Construction Year:	1950 ☑ approximately ☐ year listed or earlier ☐ year listed or later
	te Residence (House/Cottage/Cabin) From (year): 1950 To (year):
	te Residence (House/Cottage/Cabin) From (year): To (year): 2017
Other Use	From (year): To (year):
Moves: □yes 🗷	no unknown Date: Original address
Alterations: xyes	no unknown Date: 1980s Nature Windows/door replaced, stucco band added
Additions: xyes	
	): <u>unknown</u> Builder (last name first): <u>unknown</u>
Ownership History (es	specially original owner, dates, profession, etc.)
Is the Resource Affect	ted by a Local Preservation Ordinance? □yes 🗷no □unknown Describe
Is the Resource Affect	
Is the Resource Affect	ted by a Local Preservation Ordinance?
Style Masonry Ver	DESCRIPTION  Exterior Plan Rectangular Number of Stories 1
Style Masonry Ver	DESCRIPTION  Exterior Plan Rectangular Number of Stories 1
Style Masonry Ver Exterior Fabric(s) 1. Roof Type(s) 1.	DESCRIPTION           gracular         Exterior Plan         Rectangular         Number of Stories         1           Stucco         2.         3.           Gable         2.         3.
Style Masonry Ver Exterior Fabric(s) 1. Roof Type(s) 1.	DESCRIPTION           cnacular         Exterior Plan         Rectangular         Number of Stories         1           Stucco         2.         3.
Style Masonry Ver Exterior Fabric(s) 1. Roof Type(s) 1. Roof Material(s) 1. Roof secondary	DESCRIPTION           cmacular         Exterior Plan         Rectangular         Number of Stories         1           Stucco         2.         3.           Gable         2.         3.           Composition shingles         2.         3.           Strucs. (dormers etc.) 1.         2.         2.
Style Masonry Ver Exterior Fabric(s) 1. Roof Type(s) 1. Roof Material(s) 1. Roof secondary	DESCRIPTION           gracular         Exterior Plan         Rectangular         Number of Stories         1           Stucco         2.         3.           Gable         2.         3.           Composition shingles         2.         3.
Style Masonry Ver Exterior Fabric(s) 1. Roof Type(s) 1. Roof Material(s) 1. Roof secondary Windows (types, material	DESCRIPTION           gracular         Exterior Plan         Rectangular         Number of Stories         1           Stucco         2.         3.           Gable         2.         3.           Composition shingles         2.         3.           Strucs. (dormers etc.) 1.         2.           Js, etc.)         Metal 1/1 single-hung-sash; appear to be 1980s replacements
Style Masonry Ver Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material	DESCRIPTION    Creating the state of the sta
Style Masonry Ver Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material	DESCRIPTION           gracular         Exterior Plan         Rectangular         Number of Stories         1           Stucco         2.         3.           Gable         2.         3.           Composition shingles         2.         3.           Strucs. (dormers etc.) 1.         2.           Js, etc.)         Metal 1/1 single-hung-sash; appear to be 1980s replacements
Style Masonry Ver Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Archited windows, door, as	DESCRIPTION    Contacular
Style Masonry Verence Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Architecture windows, door, and ancillary Features / Common	DESCRIPTION    Construction   Exterior Plan   Rectangular   Number of Stories   1
Style Masonry Verence Exterior Fabric(s) 1. Roof Type(s) 1. Roof Material(s) 1. Roof Secondary Windows (types, material Distinguishing Archite windows, door, and Ancillary Features / Csidewalk; paveneer	DESCRIPTION    Contacular
Style Masonry Verence Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Architecture windows, door, and ancillary Features / Common	DESCRIPTION    Construction   Exterior Plan   Rectangular   Number of Stories   1
Style Masonry Verence Exterior Fabric(s) 1. Roof Type(s) 1. Roof Material(s) 1. Roof Secondary Windows (types, material Distinguishing Archite windows, door, and Ancillary Features / Csidewalk; paveneer	DESCRIPTION    Construction   Exterior Plan   Rectangular   Number of Stories   1
Style Masonry Verence Exterior Fabric(s) 1. Roof Type(s) 1. Roof Material(s) 1. Roof Secondary Windows (types, material Distinguishing Archite windows, door, as Ancillary Features / Csidewalk; pavements	DESCRIPTION    Construction   Exterior Plan   Rectangular   Number of Stories   1
Style Masonry Verence Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Architection windows, door, at Ancillary Features / Considerable, pavements around property	DESCRIPTION    Construction   Exterior Plan   Rectangular   Number of Stories   1
Style Masonry Verence Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Architection windows, door, at Ancillary Features / Considerable, pavements around property	DESCRIPTION    Compact   Exterior Plan   Rectangular   Number of Stories   1
Style Masonry Verent Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Architection windows, door, at Ancillary Features / Considerable, pavement around property  DHR L  NR List Date	DESCRIPTION    Canacular
Style Masonry Verent Exterior Fabric(s) 1 Roof Type(s) 1 Roof Material(s) 1 Roof secondary Windows (types, material Distinguishing Architection windows, door, at Ancillary Features / Considerable, pavement around property	DESCRIPTION    Composition   C


Site #8 BD06315


DESCRIPTION (continued)
Chimney: Noo_ Chimney Material(s): 1
Porch Descriptions (types, locations, roof types, etc.) West front porch has square stucco supports with decorative banding and a concrete stoop; under gable roof extension
Condition (overall resource condition):     Excellent   Second   Gair   Geteriorated   Gair   Gair
Archaeological RemainsCheck if Archaeological Form Completed
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys) ☐ Ilibrary research ☐ building permits ☐ Sanborn maps ☐ city directory ☐ occupant/owner interview ☐ plat maps ☐ plat maps ☐ public Lands Survey (DEP) ☐ cultural resource survey (CRAS) ☐ historic photos ☐ interior inspection ☐ HABS/HAER record search ☑ other methods (describe) ☐ Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Tyes  Ino insufficient information  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in South  Florida. It is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood. The neighborhood lacks integrity with several alterations, demolitions, and in-fills.  Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1
DOCUMENTATION
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document type Field maps Maintaining organization Document description File or accession #'s  2) Document type Field notes Maintaining organization Document description File or accession #'s File or accession #'s
RECORDER INFORMATION
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06316
Field Date	9-27-2017
Form Date	10-2-2017
Recorder #	4.8

Survey Project Name _ 1 - 92 at Broward Boulevard Interchange	Site Name(s) (address if none) 528 NW 21st Avenue		Multiple Listing (DHR only)
Ownership:			
Street Number   Direction   Street Name   Street Name   Avenue			
Address 528 NW 21st Avenue  Cross Streets (reseest Jobbowen) E side button NM 5th St and NM 6th St  USGS 7.5 Map Name	LO	CATION & MAPPING	
Notices   Private   Private   Residence   House/Cottage/Cabin   From (year)   To (year)			Suffix Direction
USGS 7.5 Map Name   PORT LAUDREALE NORTH	Addless: 526 NW 218t	Avenue	
City   Town   within 3 miles  Port_Lauderdale   In City Limits?   Byes   In 0   unknown   County   Exoward			ther Man
Township 503			
Tax Parcel # 5042 04 30 0310   Landgrant			
Other Coordinates: X: Y: Coordinate System & Datum  Name of Public Tract (e.g., park)    HISTORY	Tax Parcel # 5042 04 30 0310	Landgrant	
Other Coordinates: X: Y: Coordinate System & Datum  Name of Public Tract (e.g., park)    HISTORY	Subdivision Name Dorsey Riverbend	Block	Lot
Name of Public Tract (e.g., park)   HISTORY	UTM Coordinates: Zone ☐16 ☑17 Easting 5 8 3 1	4 5 Northing 2 8 9 0 1 7 0	
Construction Year: 1950	Other Coordinates: X: Y: Y:	Coordinate System & Datum	
Construction Year: 1950	Name of Public Tract (e.g., park)		
Original Use Private Residence (House/Cottage/Cabin) From (year): 1950 To (year): Current Use Private Residence (House/Cottage/Cabin) From (year): To (year): 2017 To (year): To		HISTORY	
Original Use Private Residence (House/Cottage/Cabin) From (year): 1950 To (year): Current Use Private Residence (House/Cottage/Cabin) From (year): To (year): 2017 To (year): To	Construction Year: 1950	ear listed or earlier  year listed or late	er
Other Use	Original Use Private Residence (House/Cottage/	Cabin) From (year): 1950	To (year):
Additions:	Current Use Private Residence (House/Cottage/	Cabin) From (vear):	To (year): 2017
Additions:	Other Use	From (year):	To (year):
Additions:	Moves: Date:	Original address	- 3
Architect (last name first): unknown Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?	Additions: Name of the Additions of	Nature Southeast covered por	rch addition
Style   Masonry   Vernacular   Exterior Plan   L-shaped   Number of Stories   1	Architect (last name first): unknown	Ruilder (last name first): unk	nown
Style   Masonry   Vernacular   Exterior Plan   L-shaped   Number of Stories   1	Ownership History (especially original owner, dates, profession, etc.)	Dander (last halle in sty.	
Style Masonry Vernacular Exterior Plan L-shaped Number of Stories 1  Exterior Fabric(s) 1. Stucco 2. 3.  Roof Type(s) 1. Cross-gabled 2. 3.  Roof Material(s) 1. Composition shingles 2. Sheet metal:5V crimp 3.  Roof secondary strucs. (dormers etc.) 1. 2.  Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some boarded up; appear to be 1980s replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded foam "brick" on bottom half of west side; c. 2014 back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY OFFICIAL EVALUATION DHR USE ONLY  NR List Date SHPO - Appears to meet criteria for NR listing: Dyes Do Dinsufficient info Date Init. Init.			
Style Masonry Vernacular Exterior Plan L-shaped Number of Stories 1  Exterior Fabric(s) 1. Stucco 2. 3. Roof Type(s) 1. Cross-gabled 2. 3. Roof Material(s) 1. Composition shingles 2. Sheet metal:5V crimp 3. Roof Secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some boarded up; appear to be 1980s replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded foam "brick" on bottom half of west side; c. 2014 back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY OFFICIAL EVALUATION DHR USE ONLY  NR List Date SHPO - Appears to meet criteria for NR listing: yes no insufficient info Date Init.	Is the Resource Affected by a Local Preservation Ordinano	·	
Exterior Fabric(s) 1. Stucco 2. 3. Roof Type(s) 1. Cross-gabled 2. 3. Roof Material(s) 1. Composition shingles 2. Sheet metal:5V crimp 3. Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some boarded up; appear to be 1980s replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded foam "brick" on bottom half of west side; c. 2014 back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY OFFICIAL EVALUATION DHR USE ONLY  NR List Date SHPO - Appears to meet criteria for NR listing: yes no insufficient info Date init.		DESCRIPTION	
Roof Type(s)  1. Cross-gabled  2. Sheet metal:5V crimp  3. Roof Secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some boarded up; appear to be 1980s replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded foam "brick" on bottom half of west side; c. 2014 back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  NR List Date  SHPO - Appears to meet criteria for NR listing:     Distinguishing Architectural Features   2.	Style Masonry Vernacular	Exterior Plan L-shaped	Number of Stories1
Roof Material(s)  1. Composition shingles  2. Sheet metal:5V crimp  3. Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some boarded up; appear to be 1980s replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded foam "brick" on bottom half of west side; c. 2014 back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  SHPO - Appears to meet criteria for NR listing: Jyes Ino Insufficient info Date Init.	Exterior Fabric(s) 1. Stucco	_ 2	_ 3
Roof secondary strucs. (dormers etc.) 1	Roof Type(s) 1. Cross-gabled	2	_ 3
Windows (types, materials, etc.) Metal 1/1 single-hung-sash; some boarded up; appear to be 1980s replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded foam "brick" on bottom half of west side; c. 2014 back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  NR List Date  SHPO - Appears to meet criteria for NR listing:   Output  Distinguishing Architectural Features (exterior or interior ornaments)  Molded foam "brick" on bottom half of west side; c. 2014  back porch under metal cross gable roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)  Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  Init	Poof secondary structs (dermore etc.) 1	_ 2. Sheet metal:5V crimp	_ 3
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  NR List Date  SHPO - Appears to meet criteria for NR listing:   yes  no  insufficient info  Date  Init	Windows (types, materials, etc.) Metal 1/1 single-hung	-sash; some boarded up; appear t	to be 1980s replacements
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Paved driveway in northwest corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  NR List Date  SHPO - Appears to meet criteria for NR listing:   yes  no  insufficient info  Date  Init	Distinguishing Architectural Features (exterior or interior orname	nts) Molded foam "brick" on bott	tom half of west side; c. 2014
Corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  NR List Date  SHPO - Appears to meet criteria for NR listing:   yes  no  insufficient info  Date  Init			
Corner of property; paved walkway from front porch to sidewalk; chain-link fence around property  DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  NR List Date  SHPO - Appears to meet criteria for NR listing:   yes  no  insufficient info  Date  Init	Ancillary Features / Outhuildings (record outhuildings, major land	scano foaturos: uso continuation shoot if pooded )	David drivoway in northwest
DHR USE ONLY  OFFICIAL EVALUATION  NR List Date  SHPO – Appears to meet criteria for NR listing:   yes  no  insufficient info  Date  Init			
NR List Date SHPO – Appears to meet criteria for NR listing:  yes  no  insufficient info  Date  Init			
NR List Date SHPO – Appears to meet criteria for NR listing:  yes no insufficient info Date Init	<del></del>		
NR List Date SHPO – Appears to meet criteria for NR listing:  yes no insufficient info Date Init			
NR List Date SHPO – Appears to meet criteria for NR listing: ☐yes ☐no ☐insufficient info Date Init	DHR USE ONLY C	OFFICIAL EVALUATION	DHR USE ONLY
I KEEDER – Determined eligible: □ves □no □veto □			Date Init
REEPER - Determined engible.	KEEPER – Determined eligible:	☐yes ☐no ☐c ☐d (see <i>National Register Bulletin</i>	Date


Site #8 BD06316


	DESCRIPT	CION (continued)	
Foundation Type(s): 1. <u>conformation Material(s)</u> : 1. <u>conformation Material(s): 1. conformation Material(s): 1. conformation Material(s): 1. conformation Material(s): 1. conformation Ma</u>	tinuous 2 acrete Block 2	23	
	rooflypes, etc.) Entry porch on w 2014 porch under southeast m	est side with concrete stoop etal cross-gable roof	and simple supports under
Narrative Description of Resource		deteriorated □ruinous esidence has a simple form a nder a metal cross-gable roo	
Archaeological Remains			Check if Archaeological Form Completed
	RESEARCH METH	IODS (check all that apply)	
☑FMSF record search (sites/sur ☐FL State Archives/photo collect ☑property appraiser / tax record ☐cultural resource survey (CRA ☑other methods (describe) ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	rveys)	☐ building permits ☐ occupant/owner interview ☐ neighbor interview ☐ interior inspection	□ Sanborn maps □ plat maps □ Public Lands Survey (DEP) □ HABS/HAER record search
	OPINION OF RESO	URCE SIGNIFICANCE	
Appears to meet the criteria for N Explanation of Evaluation (require Florida. It is in the Dox	sey Riverbend neighborhood,		-American neighborhood. The
	(see National Register Bulletin 15, p. 8 for cate	egories: e.g. "architecture", "ethnic heritage", "o	
	DOCUM	ENTATION	
Document type Field maps     Document description      Document type Field notes	led with the Site File - including field note	es, analysis notes, photos, plans and other imp Maintaining organization Janus Research File or accession #'s  Maintaining organization Janus Research	
	RECORDER	INFORMATION	
Recorder Name Janus Resea Recorder Contact Information (address / phone / fax / e-mail)		Affiliation Janus Research 3607 / (813) 636-8200 / janu	s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06317		
Field Date	9-27-2017		
Form Date	10-2-2017		
Recorder #	47		

Site Name(s) (address if none) 524 NW 21st Avenue	Multiple Listing (DHR only)  survey # (DHR only)		
National Register Category (please check one)	□ structure □ district □ site □ object □ private-nonspecific □ city □ county □ state □ federal □ Native American □ foreign □ unknown		
Address: 524 Direction NW 21st  Cross Streets (nearest / between) E side btwn NW 5th St USGS 7.5 Map Name FORT LAUDERDALE NORTH  City / Town (within 3 miles) Fort Lauderdale In Township 50s Range 42E Section 4 ¼ Tax Parcel # 5042 04 30 0320  Subdivision Name Dorsey Riverbend  UTM Coordinates: Zone □16 ▼17 Easting 5 8 3 1 1	USGS Date 1983 Plat or Other Map  City Limits? Yes no nunknown County Broward  section: NW SW SE NE Irregular-name:  Landgrant  Block Lot  Worthing 2890155  Coordinate System & Datum		
	HISTORY		
Current Use Other Use  Moves: yes \( \) no \( \) unknown  Alterations: \( \) yes \( \) no \( \) unknown  Additions: \( \) yes \( \) no \( \) unknown  Architect (last name first): \( \) unknown	Para listed or earlier		
Is the Resource Affected by a Local Preservation Ordinance	e?		
Exterior Fabric(s) 1. Stucco  Roof Type(s) 1. Gable  Roof Material(s) 1. Composition shingles  Roof secondary strucs. (dormers etc.) 1.	Exterior Plan Rectangular Number of Stories 1  2. 3. 3. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.		
Distinguishing Architectural Features (exterior or interior ornaments) Textured stucco exterior; decorative vents on north and south sides; faux shutters on west side windows; c. 1978 northeast addition under shed roof  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Concrete paving around original front porch to extend porch area; chain-link fence around property			
DHR USE ONLY O	FFICIAL EVALUATION DHR USE ONLY		
NR List Date SHPO – Appears to meet criteria for NR KEEPER – Determined eligible:	R listing:   yes   no   insufficient info   Date   Init.		


Site #8 \_ BD06317


	DESCRIPTION	JN (continued)	
Chimney: Noo Chimney Material(s): 1.  Structural System(s): 1. Concrete bl.  Foundation Type(s): 1. Concrete Bl.  Foundation Material(s): 1. Concrete Bl.  Main Entrance (stylistic details) West-facing door  Porch Descriptions (types, locations, roof types, etc. scrolled iron supports under roof.  Condition (overall resource condition): Dexcellent	2	ry porch roof extension with side has been extended with under southeast roof extended	th concrete stoop; original th additional paving,
Narrative Description of Resource	asonry Vernacular res		nd a c. 1978 shed roof
Archaeological Remains			Check if Archaeological Form Completed
D	ESEADOU METHO	DC (alcale all 4l-4 l -	
R	ESEARCH METHO	DS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>□FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>□cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐ Listoric aer</li> </ul>		□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
Bibliographic References (give FMSF manuscrip	# if relevant, use continuation shee	t if needed)	
OF	INION OF RESOU	RCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?     Jyes   Image: Im			
Area(s) of Historical Significance (see <i>National</i> 1.	Register Bulletin 15, p. 8 for categor	ries: e.g. "architecture", "ethnic heritage", "co	ommunity planning & development", etc.)
2	_ 4	6	
	DOCUME	NTATION	
Accessible Documentation Not Filed with the Document type Field maps  Document description	Ma	aintaining organization _Janus Research	
2) Document type Field notes			
Document description	F	File or accession #'s	
	RECORDER IN	FORMATION	
Recorder Name _Janus Research		Affiliation Janus Research	
Recorder Contact Information 1107 N. W (address / phone / fax / e-mail)	ard St., Tampa FL 3360	07 / (813) 636-8200 / janus	@janus-research.com


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD03618
Field Date	9-27-2017
Form Date	10-2-2017
Recorder #	46

Site Name(s) (address if none) 520 NW 21st Avenue Survey Project Name I-95 at Broward Boulevard I	Multiple Listing (DHR only) Survey # (DHR only)
National Register Category (please check one)	□ structure □ district □ site □ object □ private-nonspecific □ city □ county □ state □ federal □ Native American □ foreign □ unknown
Street Number Address: 520  Cross Streets (nearest / between) USGS 7.5 Map Name FORT LAUDERDALE NORTH City / Town (within 3 miles) Fort Lauderdale Introduction Township Sos Range 42E Section 4 M Tax Parcel # 5042 04 30 0330 Subdivision Name Dorsey Riverbend UTM Coordinates: Zone  Direction Street Name  21st Lauderdale Introduction M Street Name Lauderdale Introduction M M Section M M M Section M M M M Sth Section M M M M M M M M M M M M M M M M M M M	USGS Date 1983 Plat or Other Map
	HISTORY
Current Use Other Use  Moves:	Cabin)         From (year):         1950         To (year):         To (year):         2017
Is the Resource Affected by a Local Preservation Ordinand	ce?
	DESCRIPTION
Exterior Fabric(s) 1. Stucco  Roof Type(s) 1. Gable  Roof Material(s) 1. Composition shingles	Exterior Plan L-shaped Number of Stories 1  2.
Distinguishing Architectural Features (exterior or interior orname	ents) Plain stucco window/door surrounds and banding on west west side; decorative vents on north/south sides
Ancillary Features / Outbuildings (record outbuildings, major land sidewalk	scape features; use continuation sheet if needed.) Paved walkway from front porch to
DHR USE ONLY (	OFFICIAL EVALUATION DHR USE ONLY
	R listing:  yes no insufficient info Date Init Date

Site #8 \_ BD03618


DESCRIPTION (continued)			
Chimney: Noo_ Chimney Material(s): 1			
Porch Descriptions (types, locations, roof types, etc.) Entry porch under west roof extension with square supports and rai concrete pad	sed		
Condition (overall resource condition): ☐excellent ☑good ☐fair ☐deteriorated ☐ruinous  Narrative Description of Resource ☐ This Masonry Vernacular residence has a simple form and few alterations.			
Archaeological Remains Check if Archaeological Form	Completed		
RESEARCH METHODS (check all that apply)			
☑FMSF record search (sites/surveys) ☐ Ilibrary research ☐ building permits ☐ Sanborn maps ☐ Joccupant/owner interview ☐ plat maps ☑ plat maps ☑ property appraiser / tax records ☐ newspaper files ☐ neighbor interview ☐ ultural resource survey (CRAS) ☐ historic photos ☐ interior inspection ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (Interior inspection) ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Interior inspection ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Interior inspection ☐ In			
OPINION OF RESOURCE SIGNIFICANCE			
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in Scretification.   This residence is of a common style in Scretification.   This residence is of a common style in Scretification.   The provided is a historic African-American neighborhood neighborhood lacks integrity with several alterations, demolitions, and in-fills.			
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development" 1 3 5 5			
2			
DOCUMENTATION			
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents    Document type Field maps			
2) Document type Field notes Maintaining organization Janus Research File or accession #'s			
RECORDER INFORMATION			
Recorder Name Janus Research  Recorder Contact Information (address / phone / fax / e-mail)  Affiliation Janus Research  Affiliation (813) 636-8200 / janus@janus-research.com			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06319
Field Date	9-27-2017
Form Date	10-2-2017
Recorder #	45


Site Name(s) (address if none) 516 NW 21st Avenue	Multiple Listing (DHR only)
	Survey # (DHR only)
National Register Category (please check one) ⊠building Ownership: ☐private-profit ☐private-nonprofit ☑private-individual	Structure ☐ district ☐ site ☐ object ☐ private-nonspecific ☐ city ☐ county ☐ state ☐ federal ☐ Native American ☐ foreign ☐ unknown
LO	CATION & MAPPING
Street Number Direction Street Name	Street Type Suffix Direction
Address: 516 NW 21st	Avenue
Cross Streets (nearest/between) E side btwn NW 5th S	
	USGS Date 1983 Plat or Other Map
	n City Limits?   yes  no  unknown  County  Broward
Township <u>50s</u> Range <u>42E</u> Section <u>4</u> ½	4 section: NW SW SE NE Irregular-name:
Tax Parcel # 5042 04 30 0340	Landgrant Lot
Subdivision Name Dorsey Riverbend	Block Lot
UTM Coordinates: Zone 116 121/ Easting 5 8 3 1	[5] 0 Northing [2] 8   9   0   1   2   5
Name of Public Tract (e.g., park) Y:	Coordinate System & Datum
Name of Public Tract (e.g., park)	
The second second	HISTORY
1050 Elementary	
Construction Year: 1950 Sapproximately Springer (House Cottage)	
Original USe Private Residence (House/Cottage/	Cabin) From (year): 1950 To (year): 2017
Other Use Private Residence (House/Cottage/	Cabin)         From (year):         To (year):         2017           From (year):         To (year):
Moves: □yes ⊠no □unknown Date:	From (year): To (year): Original address Nature Doors and windows replaced
Alterations: Syes Ino Industrial Date: 2000s	Mature Doors and windows replaced
Additions: Syes Ino Indianown Date: 2000s	Nature Large east side addition with flat roof
Architect (last name first): unknown	Builder (last name first): unknown
Ownership History (especially original owner, dates, profession, etc.	)
Is the Resource Affected by a Local Preservation Ordinano	ce? Jyes Ino Junknown Describe
	DESCRIPTION
	Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco	2 3
Roof Type(s) 1. Gable	
Roof Material(s) 1. Composition shingles	2. Built-up 3.
Roof secondary strucs. (dormers etc.) 1.	2
Windows (types, materials, etc.) Metal 1-light fixed a	nd 2-light sliding; appear to be 2000s replacements
Distinguishing Architectural Features (exterior or interior organic	ents) Rafter tails at west porch roof extension; decorative vents
	ens) Raiter tails at west porch roof extension; decorative vents apports; c1965 east side addition has flat roof
OII HOLUH/DOUGH DIGGD, DOLOLII	pports, cross case side dadreron and rive
, , , , , , , , , , , , , , , , , , , ,	
	scane features: use continuation sheet if needed.) Paved driveway in northwest
Ancillary Features / Outbuildings (record outbuildings, major land	dscape features; use continuation sheet if needed.) Paved driveway in northwest porch to sidewalk; chain-link fence around property
Ancillary Features / Outbuildings (record outbuildings, major land	
Ancillary Features / Outbuildings (record outbuildings, major land	
Ancillary Features / Outbuildings (record outbuildings, major land	
Ancillary Features / Outbuildings (record outbuildings, major land corner of property; paved walkway from entry	y porch to sidewalk; chain-link fence around property
Ancillary Features / Outbuildings (record outbuildings, major land corner of property; paved walkway from entry  DHR USE ONLY	OFFICIAL EVALUATION  DHR USE ONLY
Ancillary Features / Outbuildings (record outbuildings, major land corner of property; paved walkway from entry  DHR USE ONLY	y porch to sidewalk; chain-link fence around property


Site #8 \_ BD06319


DESCRIPTION (continued)	
Chimney: Noo_Chimney Material(s): 1	on with scrolled iron supports and
Condition (overall resource condition): Dexcellent Egood Description of Resource This Masonry Vernacular residence has a simple addition on the east side more than doubled the original square footage	le form. The c. 1965 large flat roof
Archaeological Remains	Check if Archaeological Form Completed
RESEARCH METHODS (check all that	
☑FMSF record search (sites/surveys) ☐ library research ☐ building permits ☐FL State Archives/photo collection ☐ city directory ☐ occupant/owner ☑property appraiser / tax records ☐ newspaper files ☐ neighbor intervie ☐ cultural resource survey (CRAS) ☐ historic photos ☐ interior inspectio ☑ other methods (describe) ☐ Historic aerial photography  Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) ☐	□ Sanborn maps interview □ plat maps □ Public Lands Survey (DEP) n □ HABS/HAER record search
OPINION OF RESOURCE SIGNIFIC	ANCE
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This resident is in the Dorsey Riverbend neighborhood, which is a historical neighborhood lacks integrity with several alterations, demolitions, and	African-American neighborhood. The
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "eth	
1	5 6
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans  1) Document type Field maps Maintaining organization Jacob Document description File or accession #'s Maintaining organization Jacob Maintaining organization Jacob Document type Field notes Maintaining organization Jacob Document type Field notes	nus Research
2) Document description File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information (address / phone / fax / e-mail)  Affiliation Janus Research  N. Ward St., Tampa FL 33607 / (813) 636-82	

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06320
Field Date 9-27-2017
Form Date 10-2-2017
Recorder # 44

	if none) 512 NW 21st Avenue			<b>M</b> ultiple Listing (DHR only)	
	I-95 at Broward Boulevard 1			Survey # (DHR only)	
	egory (please check one)			Tendanal Matting American Mension C	7l.m.am
Ownershipprivate-pr	rofit private-nonprofit private-individual	private-nonspecificcity [	countystate	Jiederai 🔲 ivative American 🔲 ioreign 🗀	<b>J</b> unknown
	LO	CATION & MAPI	PING		
Street Numb			Street Type	Suffix Direction	
Address: 512	NW 21st		Avenue		
	/between) E side btwn NW 5th S				
USGS 7.5 Map Name	FORT LAUDERDALE NORTH	<b>U</b> SGS Date _1	L983 Plat or Oth	ner Map	
	es) Fort Lauderdale				
Township 50s	Range 42E Section 4	4 section: LINW LISW	USE ∐NE Ir	regular-name:	
Cubdivision Name	04 30 0350	Lan	agrant	Lat	
JULIA Coordinates: 7	04 30 0350 Corsey Riverbend one □16 ☑17 Easting 5 8 3 1	Morthing 21 91 91	OL 1 LO LO	<b>L</b> 0l	
Other Coordinates: X	(: Y: Y:	Coordinate S	System & Datum		
Name of Public Tract	(e.g., park)	Cooldinate 3	ystem & Datum _		
	(o.g., party				
		HISTORY			
O - madematik V	1050		and the second second		
Construction Year:	1950 <b>■</b> approximately <b>□</b> y	/ear listed or earlier	year listed or late	r 	
Original Use Priva	te Residence (House/Cottage/	(Cabin) From (year):_	1950	0 (year):	
Other Use Priva	te Residence (House/Cottage/			o (year):	
Moves.	no 🗖 unknown Date:	Original address	I	0 (year)	
Alterations: Syes	Ino Munknown Date: 2010s	Nature Windows	and doors rep	laced	
Additions: Xyes \( \bigsize \)	Ino Dunknown Date: g. 1975	Nature Northeas	t flat roof a	ddition	
	): unknown				
	specially original owner, dates, profession, etc.				
		·			
Is the Resource Affect	ted by a Local Preservation Ordinand	ce? □yes ⊠no □unkn	own Describe _		
		DESCRIPTION			
201					
	rnacular				
Exterior Fabric(s) 1.	Stucco			3	
Roof Material(s) 1.	Gable Composition roll			3	
Roof secondary	Strucs. (dormers etc.) 1.	ZBullt-up		J	
	als, etc.) <u>Metal 2-light casemen</u>				
trindows (types, materia	13, ctc.)	TO THE TO THE TOTAL THE TOTAL TO THE TOTAL TOTAL TO THE T			
Distinguishing Archite	ectural Features (exterior or interior orname	ents) Metal window a	wning left of	front door; c. 1975 northe	east
	at, built-up roof; scrolled :				
Ancillary Features / C	Outbuildings (record outbuildings, major land	dscape features; use continuation	n sheet if needed.) <u>s</u>	tone-paved walkway on sout	h side
of house, from e	entry to sidewalk, and on par	rt of driveway; chai	n-link fence	around property	
DHR L	JSE ONLY (	OFFICIAL EVALUATION	ON	DHR USE ONLY	
ND List Data	CLIDO Appears to most criterio for N	ID licting: Ducc. Dno. D	incufficient info	Data Init	
NR List Date	SHPO – Appears to meet criteria for N KEEPER – Determined eligible:	lk ilsting: □yes □no □ □yes □no	IIISUIIICIEIIL IIIIO	Date Init Date	
Owner Objection	NR Criteria for Evaluation:	—, —	al Register Bulletin		

Site #8 \_ BD06320


	DESCRII	PTION (continued)	
Foundation Type(s): 1. <u>Con</u> Foundation Material(s): 1. <u>Con</u>	tinuous 2. crete Block 2.	2	
Porch Descriptions (types, locations, concrete stoop	oof types, etc.) Entry porch und	der west roof extension with	scrolled iron supports and
	This Masonry Vernacular		n. It was originally L-shaped, rectangular shape.
Archaeological Remains			Check if Archaeological Form Completed
	RESEARCH MET	THODS (check all that apply)	
<ul> <li>☑FMSF record search (sites/sun</li> <li>☐FL State Archives/photo collect</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS</li> <li>☑other methods (describe)Hist</li> <li>Bibliographic References (give FMS</li> </ul>	veys)	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	□ Sanborn maps  □ □ plat maps □ □ Public Lands Survey (DEP) □ □ HABS/HAER record search
	OPINION OF RES	OURCE SIGNIFICANCE	E
Florida. It is in the Dor	ational Register listing as part of a , whether significant or not; use separate s sey Riverbend neighborhood	district?yesnoinsheet if needed)This residence is	sufficient information sufficient information s of a common style in South an-American neighborhood. The
	see <i>National Register Bulletin 15</i> , p. 8 for 3	categories: e.g. "architecture", "ethnic heritage	e", "community planning & development", etc.)
2			
	DOCU	MENTATION	
1) Document type Field maps		notes, analysis notes, photos, plans and other  Maintaining organization Janus Resear  File or accession #'s	ch
		Maintaining organization Janus Resear File or accession #'s	ch
	RECORDE	R INFORMATION	
Recorder NameJanus Resear Recorder Contact Information1 (address / phone / fax / e-mail)		Affiliation Janus Research 33607 / (813) 636-8200 / ja	nus@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06321
Field Date	9-27-2017
Form Date	10-2-2017
Recorder #	43


	fnone) 508 NW 21st Avenue				(DHR only)
	I-95 at Broward Boulevard				? only)
	egory (please check one)				
Ownership:private-pro	ofit □private-nonprofit ☑private-individual	private-nonspecificcity	countystate	☐rederai ☐iNative Am	erican <b></b> roreign <b></b> unknown
	LO	CATION & MAP	PING		
Street Numb			Street Type	Suffix Direction	
Address: 508	NW 21st		Avenue		
	between) E side btwn NW 5th S				
USGS 7.5 Map Name	FORT LAUDERDALE NORTH	USGS Date_	1983 Plat or O	other Map	
	es) Fort Lauderdale				
Township 50s F	Range 42E Section 4 9	4 section: LINW LISW	/ USE UNE	Irregular-name: _	
Tax Parcel # 5042	04 30 0360	Lar	nagrant	1 -4	
Subdivision Name D	04 30 0360 Porsey Riverbend ne □16 ⊠17 Easting 5831	Morthing 21 01 0	lock	<b>L</b> 0l _	
Other Coordinates: Y	. V. Casilly 1 0 1 1 € 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Coordinate	Systom & Datum		
Name of Public Tract	: Y: (e.g., park)		System & Datum		
	(c.g., park)				
		HISTORY			
	1050				
Construction Year:	1950 <b>⊠</b> approximately □y	/ear listed or earlier	Jyear listed or lat	er	
Original Use Privat	te Residence (House/Cottage/	(Cabin) From (year):	1950	To (year):	
Other Use Private	te Residence (House/Cottage/				
Movos:	no 🗖 unknown Date:	Original addross		To (year):	
Alterations: Syes	Ino Munknown Date: 1980s	Nature Windows	replaced, se	curity screen a	dded
Additions: Syes	Ino Dunknown Date: Various	Nature SW corne	er, N carport	/porch, E side	
	: unknown	Builder ():	ast name first); unk	nown	
	pecially original owner, dates, profession, etc.				
Is the Resource Affect	ted by a Local Preservation Ordinand	ce? □yes ⊠no □unk	nown Describe		
		DESCRIPTION	J		
Ctulo Magazza Vasa				Mun	ahor of Ctorios
Evention Fabric(s) 1	macular Stucco	_ Exterior Plant Irregu.	lar	<b>IN</b> UII	ibei di Sidhes1
	Cross-gabled				
Roof Material(s) 1.	Composition roll	2. Built-up		3 3.	
. ,	strucs. (dormers etc.) 1.		2.		
	ls, etc.) Metal 1/1, 3-light aw				center and 5-
	either side; some appear to				
<b>D</b> istinguishing Architec	ctural Features (exterior or interior orname	ents) <u>Some metal wir</u>	ndow awnings;	low wall separ	ating carport and
porch; carport a	nd porch under flat roof; ca	arport has simple s	upports		
•	utbuildings (record outbuildings, major land	•	on sheet if needed.)_	Chain-link fend	ce around yard;
informal drivewa	y; paved carport; stone tree	e planters			
					0= 0.11.1
DHR U	JSE ONLY (	OFFICIAL EVALUAT	ION	DHR U	SE ONLY
NR List Date	SHPO – Appears to meet criteria for N	IR listing: Tives Tino T	7insufficient info	Date	Init
	KEEPER – Determined eligible:	lik listing. □yes □no □		Date	
Owner Objection	NR Criteria for Evaluation: ☐a ☐b	—, —	nal Register Bulletii		


Site #8 BD06321

	DESCRIPTION	ON (continued)	
Chimnov: No. o Chimnov Material(s	١٠ 1	2	
Chimney: No. o Chimney Material(s Structural System(s): 1. Concrete	). I	2	<del></del>
Foundation Type(s): 1. Continuo	: DIOCK 2		
Foundation Material(s): 1. Concrete			
Main Entrance (stylistic details) <u>West-fa</u>			lor ontry norgh
West-12	icing paner door with 1990	os security screen door unc	er entry porch
Porch Descriptions (types, locations, roof types)	as atc) Entry porch on wes	t side under flat roof with	h rectangular stucco
support; raised concrete pad;		e blue under ride roor wre.	ir receangurar beaced
suppore, rarsea concrete paa,	execuaca north e. 1376		
Condition (overall resource condition): ☐exc	ellent 🗖 good 🗖 fair 🗖 de	eteriorated Druinous	
Narrative Description of ResourceTh			antial alterations. The
southwest room was the first			
completed c. 1978. The large			
Archaeological Remains			Check if Archaeological Form Completed
J			
	RESEARCH METHO	DDS (check all that apply)	
TEMOS accorded to the design of the design o	E Plane management	Entry 1 diamental and 10	
▼FMSF record search (sites/surveys)	□ library research	□ building permits	☐ Sanborn maps
☐FL State Archives/photo collection	□city directory	□ occupant/owner interview	□ plat maps
☑ property appraiser / tax records	newspaper files	neighbor interview	□ Public Lands Survey (DEP)
□cultural resource survey (CRAS)	□ historic photos	☐ interior inspection	☐ HABS/HAER record search
■ other methods (describe) Historic Bibliographic References (give FMSF man		-1.15	
bibliographic References (give FMSF man	uscript # if relevant, use continuation snee	et ir needed)	
	<b>OPINION OF RESOU</b>	RCE SIGNIFICANCE	
Appears to meet the criteria for Nationa		,	cient information
Appears to meet the criteria for Nationa			cient information
Explanation of Evaluation (required, wheth			
Florida. It is in the Dorsey F			
neighborhood lacks integrity v			
Area(s) of Historical Significance (see Na			
1			
2	4	0	
	DOCUME	NTATION	
	2 3 3 3 1112	1,1111101,	
Accessible Documentation Not Filed with	h the Site File - including field notes,	analysis notes, photos, plans and other imp	ortant documents
1) Document type Field maps	M	laintaining organization	
Document description		File or accession #'s	
Desument time Field not as			
2) Document description			
	RECORDER IN	NFORMATION	
Decorder Name Towns Daniel		Affiliation 7	
Recorder Name <u>Janus Research</u> Recorder Contact Information 1107	N Ward Ob Brown Dr 225	_ Affiliation Janus Research	20
(address / phone / fax / e-mail)	N. Walu St., Tampa FL 336	01 / (013) 036-8200 / Janu	swjanus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06322
Field Date 9-27-2017
Form Date 10-2-2017
Recorder # 42


Site Name(s) (address if none) 504				Itiple Listing (DHR only)
Survey Project Name I-95 at 1				vey # (DHR only)
National Register Category (please				
Ownership:private-profitprivate-i	nonprofit <b>Ex</b> iprivate-individual <b>Li</b> priv	ate-nonspecific Licity Licoun	ty <b></b> state <b></b> rederal	□ Native American □ foreign □ unknown
	LOCA	ΓΙΟΝ & MAPPING	G	
Street Number Dire	ection Street Name	Street		fix Direction
Address: 504	NW 21st	Ave	nue	
Cross Streets (nearest / between) E				
USGS 7.5 Map Name FORT LA	UDERDALE NORTH	<b>U</b> SGS Date 1983_	Plat or Other Ma	p
City / Town (within 3 miles) Fort La				
Township 50s Range 42E	Section 4 1/4 sect	ion: □NW □SW □S	E □NE Irregula	r-name:
Tax Parcel # 5042 04 30 037	0	Landgran	t	Lot
Subdivision Name Dorsey Riv	erbend	Block _		<b>L</b> ot
UTM Coordinates: Zone 116 2	11/ <b>L</b> asting 5 8 3 1 4 6		/ 8	
			n & Datum	
Name of Public Tract (e.g., park) _				
		HISTORY		
		IIISTUKY		
Construction Year:1950	■ approximately  □ year lis	sted or earlier  year li	sted or later	
Original Use Private Residen				r):
Current Use Private Resider	nce (House/Cottage/Cabi	n) From (year):	To (yea	r):2017
Other Use		From (year):		
Moves:  □yes 🗷 no □unkno	wn Date: (	Original address		
Alterations:	wn Date: <u>1990s</u> l	Nature Door replaced	d	
Additions: ☐yes ☒no ☐unkno				
Architect (last name first): unknown			e first): <u>unknown</u>	
Ownership History (especially origina	l owner, dates, profession, etc.)			
	15 " 0 " 0 "		D	
Is the Resource Affected by a Loc	al Preservation Ordinance?	_yes ⊠no □unknown	Describe	
	D	ESCRIPTION		
Style Masonry Vernacular	Exte	erior Plan L-shaped		Number of Stories1
Exterior Fabric(s) 1. Studeo			3	
Roof Type(s) 1. Gable			3	
Roof Material(s) 1. Compositi	on shingles 2.		3	
Roof secondary strucs. (dorme			_ 2	
Windows (types, materials, etc.) Boa	rded up, not visible			
Distinguishing Architectural Feature	roc (outarior or interior ernamenta)	Dogovatino monta or	nowth and go	th gides under gable ands.
scrolled iron front porch				uth sides under gable ends;
scrotted from from poten	supports, farter tails	on energ poren room	L excension	
Ancillary Features / Outbuildings (	record outhuildings major landscape	features: use continuation sheet	if needed ) Inform	al dirt driveway in
				ink fence around property
nordimore definer or prope	10,, pavea marima, 110.	. IIOno poion do bia	3.141.11 J	imi remee drediid property
DUD HEE ONLY	/ OFFI	CIAL EVALUATION		DUD LICE ONLY
DHR USE ONLY	UFFI	CIAL EVALUATION		DHR USE ONLY
NR List Date SHPO – Ap	pears to meet criteria for NR listin	na: 🗆 ves 🗖 no 🗖 insuffic	cient info Date	e Init
	Determined eligible:	□yes □no	Date	<u> </u>
		□yes □no		


Site #8 BD06322

DESCRIPTION (continued)
Chimney: No. o Chimney Material(s): 1. 2. 3.  Structural System(s): 1. Concrete block 2. 3.  Foundation Type(s): 1. Continuous 2.  Foundation Material(s): 1. Concrete Block 2.  Main Entrance (stylistic details) West-facing 1990s panel door with oval light under entry porch with concrete stoop
Porch Descriptions (types, locations, roof types, etc.) Entry porch under roof extension on west side with scrolled iron supports and concrete stoop; rafter tails on roof extension visible
Condition (overall resource condition):     Excellent   Image: Im
Archaeological Remains Check if Archaeological Form Completed
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys) ☐ Ilibrary research ☐ building permits ☐ Sanborn maps ☐ plat maps ☑ property appraiser / tax records ☐ newspaper files ☐ neighbor interview ☐ Public Lands Survey (DEP) ☐ cultural resource survey (CRAS) ☐ historic photos ☐ interior inspection ☐ HABS/HAER record search ☑ other methods (describe) ☐ Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in South  Florida. It is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood. The neighborhood lacks integrity with several alterations, demolitions, and in-fills.  Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1.
DOCUMENTATION
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents    Document type Field maps   Maintaining organization   Janus Research
RECORDER INFORMATION
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06323
Field Date	9-27-2017
Form Date	10-3-2017
Recorder #	41

	Multiple Listing (DHR only)
	Survey # (DHR only)
National Register Category (please check one) ⊠building ☐structure ☐district ☐site ☐district ☐structure ☐district ☐site ☐dist	
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county st	atefederalNative Americanforeignunknown
LOCATION & MAPPING	
<u>Street Number</u> <u>Direction</u> <u>Street Name</u> <u>Street Type</u>	Suffix Direction
Address: 500 NW 21st Avenue	
Cross Streets (nearest / between) NE corner of NW 21st Ave and NW 5th St	
USGS 7.5 Map Name FORT LAUDERDALE NORTH USGS Date 1983 Plat	or Other Map
City / Town (within 3 miles) Fort Lauderdale In City Limits? ■ yes □ no □ unknow	
Township <u>50s</u> Range <u>42E</u> Section <u>4</u> ¼ section: □NW □SW □SE □I	NE Irregular-name:
Tax Parcel # _5042 04 30 0380 Landgrant	
Tax Parcel # 5042 04 30 0380 Landgrant	Lot
UTM Coordinates: Zone 116 117 Easting 5 8 3 1 5 1 Northing 2 8 9 0 0 6 4	
Other Coordinates: X: Y: Y: Coordinate System & Da	itum
Name of Public Tract (e.g., park)	
HISTORY	
moron	
Construction Year: 1950 ■ approximately □ year listed or earlier □ year listed or	or later
Original Use Private Residence (House/Cottage/Cabin) From (year): 1950	To (year):
Current Use Private Residence (House/Cottage/Cabin) From (year):	
Other Use From (year):	To (year):
Moves: ☐yes ☑no ☐unknown Date: Original address	/ 5
Alterations: Myes on on on one of the control of th	
Additions:  yes no no no Date: c. 1970 Nature Large east side a Architect (last name first): unknown Builder (last name first):	
Architect (last name lifst). unknown Dullder (last name lifst).	
	dikilowii
Ownership History (especially original owner, dates, profession, etc.)	
Ownership History (especially original owner, dates, profession, etc.)	
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   yes   no  unknown Description	
Ownership History (especially original owner, dates, profession, etc.)	
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION	ibe
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular   Exterior Plan Irregular	ibe
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style  Masonry Vernacular  Exterior Fabric(s) 1. Stucco  2.	Number of Stories 1
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat	Number of Stories
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2.	Number of Stories 1
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat 2. Built-up	Number of Stories 1 3333
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition	Number of Stories 1 3. 3. 3. 3. 1970 to match windows on the large
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on nore	Number of Stories 1 3. 3. 3. 1970 to match windows on the large
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition	Number of Stories 1 3. 3. 3. 3. 1970 to match windows on the large  th/south sides of original house;
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on nor metal window awnings; second gable on addition with flat roof portion be	Number of Stories
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on normetal window awnings; second gable on addition with flat roof portion be  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.	Number of Stories
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on nor metal window awnings; second gable on addition with flat roof portion be	Number of Stories 1 3. 3. 3. 3. 1970 to match windows on the large th/south sides of original house; stween gables
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on normetal window awnings; second gable on addition with flat roof portion be  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)	Number of Stories
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on normetal window awnings; second gable on addition with flat roof portion be  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)	Number of Stories
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2.  Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on normetal window awnings; second gable on addition with flat roof portion be Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needs side in front of c. 1970 carport; chain-link fence around back yard	Number of Stories 1 3. 3. 3. 3. 1970 to match windows on the large  th/south sides of original house; tween gables  ed.) Stone-paved driveway on south
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2. Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on normetal window awnings; second gable on addition with flat roof portion be  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)	Number of Stories 1 3. 3. 3. 3. 1970 to match windows on the large th/south sides of original house; stween gables
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?     DESCRIPTION	Number of Stories 1 3. 3. 3. 1970 to match windows on the large  th/south sides of original house; tween gables  ed.) Stone-paved driveway on south  DHR USE ONLY
Ownership History (especially original owner, dates, profession, etc.)  Is the Resource Affected by a Local Preservation Ordinance?   DESCRIPTION  Style Masonry Vernacular Exterior Plan Irregular  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1. 2.  Windows (types, materials, etc.) Metal 3-light awning windows; windows replaced c. addition  Distinguishing Architectural Features (exterior or interior ornaments) Decorative vents on normetal window awnings; second gable on addition with flat roof portion be Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needs side in front of c. 1970 carport; chain-link fence around back yard	Number of Stories 1 3. 3. 3. 1970 to match windows on the large  th/south sides of original house; tween gables  ed.) Stone-paved driveway on south  DHR USE ONLY


Site #8 \_ BD06323

DESCRIPTION (continued)			
Chimney: Noo Chimney Material Structural System(s): 1. Concrete Foundation Type(s): 1. Concrete Foundation Material(s): 1. Concrete Main Entrance (stylistic details) West-	2.           te Block         2.		
Porch Descriptions (types, locations, roof types, etc.) Entry porch under west side roof extension with decorative iron supports and concrete stoop			
Condition (overall resource condition):   Narrative Description of Resource  that includes a carport. The it its current irregular for  Archaeological Remains	his Masonry Vernacular resi addition more than doubled m.	dence has a large c. 1970	
RESEARCH METHODS (check all that apply)			
<ul> <li>☑FMSF record search (sites/surveys</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐Histori</li> <li>Bibliographic References (give FMSF mathematics)</li> </ul>	□city directory □newspaper files □historic photos c aerial photography	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
OPINION OF RESOURCE SIGNIFICANCE			
Appears to meet the criteria for National Register listing individually?     Jyes   Xno     Insufficient information			
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)			
1	3 4.	5 6.	
DOCUMENTATION			
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document type Field maps Maintaining organization Janus Research File or accession #'s			
2) Document type Field notes	Ma	aintaining organization Janus Research	
RECORDER INFORMATION			
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com (address/phone/fax/e-mail)			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07


Site #8 BD06324
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 40


Survey Project Name <u>I-95 at Broward Boulevard</u> National Register Category (please check one) <b>X</b> building	Multiple Listing (DHR only)  Survey # (DHR only)  Survey # (DHR only)  private-nonspecific
Address: A44 Direction NW 21st  Cross Streets (nearest / between) E side btwn NW 3rd of USGS 7.5 Map Name FORT LAUDERDALE NORTH  City / Town (within 3 miles) Fort Lauderdale  Township 50s Range 42E Section 4  Tax Parcel # 5042 04 30 0760  Subdivision Name Dorsey Riverbend  UTM Coordinates: Zone 16 X17 Easting 5 8 3 1	USGS Date 1983 Plat or Other Map  n City Limits? ■ yes □ no □ unknown County ■ Broward  4 section: □NW □SE □NE Irregular-name: □ Landgrant □ Block □ Lot □ Coordinate System & Datum
	HISTORY
Current Use Other Use Other Use  Moves:	Cabin   From (year): 1950   To (year):
Is the Resource Affected by a Local Preservation Ordinar	ce? □yes ☑no □unknown Describe
Exterior Fabric(s) 1. Stucco  Roof Type(s) 1. Gable	DESCRIPTION           Exterior Plan         L-shaped         Number of Stories         1           2.         3.            2.         3.            2.         3.            g-sash; appear to be 2000s replacements         2
Distinguishing Architectural Features (exterior or interior ornan	
Ancillary Features / Outbuildings (record outbuildings, major lar corner of property; chain-link fence around DHR USE ONLY	dscape features; use continuation sheet if needed.) Gravel driveway in southwest

	DESCRIPTIO	on (continued)	
Chimnov: No. a Chimnov Material(s): 1		2	
Chimney: No. o Chimney Material(s): 1 Structural System(s): 1Concrete block	2	2	
Foundation Type(s): 1. Continuous		J.	
Foundation Material(s): 1. Concrete Block			
Main Entrance (stylistic details) West-facing 20			ry porch
	•		
Porch Descriptions (types, locations, roof types, etc.)E supports	Entry porch under w	est side roof extension w	ith simple square wood
Condition (sussell resource and divine): Daycollont	Zanad Ofair Odate	priorated Pruinque	
Condition (overall resource condition): Dexcellent Narrative Description of Resource This Mason			nd few alterations
Marrative Description of Nesource	iry vernacular resi	defice has a simple form as	ita iew arterations.
Archaeological Remains			Check if Archaeological Form Completed
RESE	CARCH METHO	DS (check all that apply)	
▼FMSF record search (sites/surveys)  □	library research	☐ building permits	☐Sanborn maps
	city directory	occupant/owner interview	□ plat maps
	newspaper files	neighbor interview	☐ Public Lands Survey (DEP)
	historic photos	☐ interior inspection	☐HABS/HAER record search
▼other methods (describe) Historic aerial		·	
Bibliographic References (give FMSF manuscript # if re	levant, use continuation sheet	if needed)	
OPINI	ON OF RESOUR	RCE SIGNIFICANCE	
	OIT OI RESOUL	CL SIGIMICIA (CL	
Appears to meet the criteria for National Register			cient information
Appears to meet the criteria for National Register			cient information
Explanation of Evaluation (required, whether significan			
Florida. It is in the Dorsey Riverben			
neighborhood lacks integrity with sev			
Area(s) of Historical Significance (see <i>National Regist</i>			
1 3	1.	5 6	
2			
	DOCUMEN	NTATION	
Accessible Documentation Not Filed with the Site	File - including field notes, a	nalysis notes, photos, plans and other imp	ortant documents
1) Document type Field maps Document description	IVIA	intaining organization Janus Research	
Document typeField notes     Document description			
<b>D</b> ocument description	r	lie of accession # S	
	RECORDER IN	FORMATION	
		Affiliation Janus Research	
Recorder Contact Information1107 N. Ward (address / phone / fax / e-mail)	St., Tampa FL 3360	7 / (813) 636-8200 / janu:	s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06325
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 39

Site Name(s) (address if none) 440 NW 21st Avenue Survey Project Name I-95 at Broward Boulevard I	Multiple Listing (DHR only) Survey # (DHR only)
National Register Category (please check one)	□ structure □ district □ site □ object □ private-nonspecific □ city □ county □ state □ federal □ Native American □ foreign □ unknown
Street Number Direction Street Name  Address: 440 NW 21st  Cross Streets (nearest / between) E side btwn NW 3rd C  USGS 7.5 Map Name FORT LAUDERDALE NORTH  City / Town (within 3 miles) Fort Lauderdale Ir  Township 50s Range 42E Section 4 %  Tax Parcel # 5042 04 30 0770  Subdivision Name Dorsey Riverbend  UTM Coordinates: Zone 16 16 17 Easting 5 8 3 1	USGS Date 1983 Plat or Other Map
	HISTORY
Current Use Other Use  Moves: yes Ino unknown Date: Alterations: yes Ino unknown Date: Additions: yes Ino unknown Date: Architect (last name first): unknown	Cabin)         From (year):         1950         To (year):         To (year):         2017
Is the Resource Affected by a Local Preservation Ordinano	ce?
Challe as a second	DESCRIPTION  Futuring Plant 7 and 1
Roof Type(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll Roof secondary strucs. (dormers etc.) 1.	Exterior Plan         L-shaped         Number of Stories         1           2.         3.         3.           2.         3.         3.           2.         3.         3.           2.         2.         3.
be 1970s replacements	-sash; window right of front door altered for AC unit; appear to ents) Decorative vents on north and south sides
northwest corner of property; chain-link fer	
NR List Date SHPO – Appears to meet criteria for N KEEPER – Determined eligible:	R listing: Syes On Sinsufficient info Date Init. Syes On Date Only  R listing: Syes On Date Only  Only  Only  Only  Only  Init.  Date Only  Only

Site #8 \_ BD06325


DESCRIPTION (continued)	
Chimney: No. o Chimney Material(s): 1. 2. 3. Structural System(s): 1. Concrete block 2. 3. Foundation Type(s): 1. Continuous 2. Foundation Material(s): 1. Concrete Block 2. Main Entrance (stylistic details) West-facing 1970s panel door with rectangular light and decorative patternentry porch with concrete stoop  Porch Descriptions (types, locations, roof types, etc.) Entry porch under northwest roof extension with simple square back porch under northeast roof extension with square supports	
Condition (overall resource condition):     Excellent   Image: Im	ns.
Archaeological Remains Check if Archaeolog	jical Form Completed
RESEARCH METHODS (check all that apply)	
☑FMSF record search (sites/surveys) □ library research □ building permits □ cocupant/owner interview □ plat maps ☑ property appraiser / tax records □ cultural resource survey (CRAS) □ historic photos ☑ other methods (describe) Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)	Survey (DEP) ecord search
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style register. It is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood lacks integrity with several alterations, demolitions, and in-fills.	
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & dev 1 3 5 5.	
2 4 6	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document type Field maps Maintaining organization Janus Research  File or accession #'s	
2) Document type Field notes Maintaining organization Janus Research Document description File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information (address / phone / fax / e-mail)  Affiliation Janus Research  Affiliation (813) 636-8200 / janus@janus-research	.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

# PHOTOGRAPH





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06326
Field Date	9-27-2017
Form Date	10-3-2017
Recorder #	3.8

	nterchange	_ Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Boulevard In National Register Category (please check one)	□structure □district □site □object	_ Survey # (DRK Only)
Ownership: ☐private-profit ☐private-nonprofit ☑private-individual	□private-nonspecific □city □county □state □fe	ederal  Mative American  foreign unknown
	CATION & MAPPING	
Address: Street Number Direction Street Name  NW 21st	Street Type  Avenue	Suffix Direction
Cross Streets (nearest/between) E side btwn NW 3rd Ct	and NW 5th St	
USGS 7.5 Map Name FORT LAUDERDALE NORTH  City / Town (within 3 miles) Fort Lauderdale In	USGS Date 1983 Plat or Othe	er Map
Township <u>50s</u> Range <u>42E</u> Section <u>4</u> ¼		
Tax Parcel # _5042 04 30 0780	Landgrant	guar name.
Tax Parcel # 5042 04 30 0780  Subdivision Name Dorsey Riverbend  UTM Coordinates: Zone □16 図17 Easting □ □ □	Block	Lot
UTM Coordinates: Zone □16 図17 Easting □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	Northing Nor	
Name of Public Tract (e.g., park)	Coordinate System & Datum _	
	HISTORY	
1050 - 111		
Construction Year: 1950 ■ approximately □ yeo Original Use Private Residence (House/Cottage/G		(vear)
Current Use Private Residence (House/Cottage/C		
Other Use	From (year): To	
Moves: yes nounknown Date:	Original address  Nature New windows/doors, enc.	loged/new neveh
	Nature Extension of northeast	
Architect (last name first): unknown	Builder (last name first): unkno	wn
Ownership History (aspecially grisinal august dates profession at )		
Ownership History (especially original owner, dates, profession, etc.)		
Is the Resource Affected by a Local Preservation Ordinance	e? □yes ⊠no □unknown Describe	
Is the Resource Affected by a Local Preservation Ordinance	e? □yes ⊠no □unknown Describe DESCRIPTION	
Is the Resource Affected by a Local Preservation Ordinance  StyleMasonry Vernacular  Exterior Fabric(s) 1Stucco	e?yes	Number of Stories1
Is the Resource Affected by a Local Preservation Ordinance  StyleMasonry Vernacular  Exterior Fabric(s) 1Stucco  Roof Type(s) 1Gable	DESCRIPTION  Exterior Plan L-shaped 2. 3 2. Flat	Number of Stories 1 33.
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll	e?yes	Number of Stories1 333.
Is the Resource Affected by a Local Preservation Ordinance  StyleMasonry Vernacular  Exterior Fabric(s) 1Stucco  Roof Type(s) 1Gable	e?	Number of Stories1
Is the Resource Affected by a Local Preservation Ordinance  StyleMasonry Vernacular  Exterior Fabric(s) 1Stucco  Roof Type(s) 1Gable  Roof Material(s) 1Composition roll  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.)Metal 1/1 single-hung-	e? □yes ☒no □unknown Describe □  DESCRIPTION  Exterior Plan L-shaped  2.	Number of Stories 1 3. 3. 3. 5 be 1990s replacements
Is the Resource Affected by a Local Preservation Ordinance  Style Masonry Vernacular  Exterior Fabric(s) 1. Stucco  Roof Type(s) 1. Gable  Roof Material(s) 1. Composition roll  Roof secondary strucs. (dormers etc.) 1.	e?	Number of Stories 1 3. 3. 3. 5 be 1990s replacements
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung- Distinguishing Architectural Features (exterior or interior ornamer	e?yes	Number of Stories1 333
StyleMasonry Vernacular Exterior Fabric(s) 1Stucco Roof Type(s) 1Gable Roof Material(s) 1Composition roll Roof secondary strucs. (dormers etc.) 1	DESCRIPTION  Exterior Plan L-shaped  2.	Number of Stories 1  3
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung- Distinguishing Architectural Features (exterior or interior ornamer	DESCRIPTION  Exterior Plan L-shaped  2.	Number of Stories 1  3
StyleMasonry Vernacular Exterior Fabric(s) 1Stucco Roof Type(s) 1Gable Roof Material(s) 1Composition roll Roof secondary strucs. (dormers etc.) 1	DESCRIPTION  Exterior Plan L-shaped  2.	Number of Stories 1  3
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung- Distinguishing Architectural Features (exterior or interior ornamer c. 1965 northeast corner extension under fla Ancillary Features / Outbuildings (record outbuildings, major lands corner; paved walkway from entry porch to dr	DESCRIPTION  Exterior Plan L-shaped  2	Number of Stories1 3 3 3 be 1990s replacements  uth sides; hurricane shutters;  ved driveway in southwest ence around property
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung- Distinguishing Architectural Features (exterior or interior ornamer c. 1965 northeast corner extension under fla  Ancillary Features / Outbuildings (record outbuildings, major lands corner; paved walkway from entry porch to dr	DESCRIPTION  Exterior Plan L-shaped  2.	Number of Stories1  3
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition roll Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung- Distinguishing Architectural Features (exterior or interior ornamer c. 1965 northeast corner extension under fla  Ancillary Features / Outbuildings (record outbuildings, major lands corner; paved walkway from entry porch to dr	DESCRIPTION  Exterior Plan L-shaped  2	Number of Stories1 3 3 3 be 1990s replacements  uth sides; hurricane shutters;  ved driveway in southwest ence around property


Site #8 \_ BD06326

	DESCRIPTION	DN (continued)	
Foundation Type(s): 1. Continuous Foundation Material(s): 1. Concrete Stoop  Porch Descriptions (types, locations, room west side of original process of the control of the	rete block 2.  retered for types, etc.) Original enclosed in orch; scrolled iron supports	enclosed original porch un in 2000s; new entry porch un have concrete block base;	nder new entry porch with
Narrative Description of Resource _ extension of the northeast	Dexcellent ⊠good □fair □det This Masonry Vernacular resi corner was completed c. 1965 made under a new west side r	dence has a simple form ar 5. In the early 2000s, the	
	RESEARCH METHO	DS (check all that apply)	
☑FMSF record search (sites/surver  ☐FL State Archives/photo collection  ☐ FL State Archives/photo collection  ☐ FL State Archives/photo collection  ☐ Cultural resource survey (CRAS)  ☐ C	eys)	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
	OPINION OF RESOUI	RCE SIGNIFICANCE	
Explanation of Evaluation (required, v Florida. It is in the Dorse neighborhood lacks integrit	ional Register listing individually? ional Register listing as part of a district whether significant or not; use separate sheet if any Riverbend neighborhood, where with several alterations,	yes ⊠no □insuffict? □yes ⊠no □insuffict needed) This residence is outlined in a historic Africandemolitions, and in-fills.	American neighborhood. The
Area(s) of Historical Significance (set 1	ee <i>National Register Bulletin 15</i> , p. 8 for categor		community planning & development", etc.)
2	4		
	DOCUMEN	NTATION	
1) Document type Field maps Document description	d with the Site File - including field notes, a	inalysis notes, photos, plans and other implaintaining organization	ortant documents
	Ma F		
Document description			
	RECORDER IN	FORMATION	
Recorder Name Janus Researc Recorder Contact Information 11 (address / phone / fax / e-mail)	h 07 N. Ward St., Tampa FL 3360		s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06327
Field Date	9-27-2017
Form Date	10-3-2017
Recorder #	37

	e) 432 NW 21st Ave				ole Listing (DHR only)
		levard Interchange  Structure			ey # (DHR only)
					Native American ☐foreign ☐unknown
Ownership. Dphvate-profit	private-nonpront Aprivat	te-individual <b>p</b> rivate-norispeciii	ic Licity Licounty Listate	Eleuerar	Inative American Libreign Lunknown
		LOCATION &	MAPPING		
Street Number	<u>Direction</u> <u>Street Na</u>	<u>ame</u>	Street Type	Suffix	<u>Direction</u>
Address: 432	NW 21st		Avenue		
		NW 3rd Ct and NW 5th		OII 14	
					Broward
Township 50s Rang	ge 42E Section _	4 <b>¼</b> section: LINW	□SW □SE □NE	: Irregular-r	name:
Tax Parcel # 5042 04	30 0790		Landgrant		Lot
JULIA Coordinates: 7 one	Sey Riverpena	E 0 2 1 E E Morthino			L0l
Other Coordinates: Zone	LIO LII LASIIII	5 8 3 1 5 5 <b>N</b> orthing	urdinato Systom & Datu	m	
Traine of Lubile Hack (E.g	., park)				
		HISTO	RY		
Construction Year: 195	<u>S</u> approximate	ely year listed or earli	er □year listed or l	ater	
Original Use Private	Residence (House/	Cottage/Cabin) From	n (year):1950	lo (year):	
	Residence (House/	Cottage/Cabin) From			
Other Use	Doto	Original add	n (year):	_ ro (year):	<del></del>
Moves: ☐yes ☒no Alterations: ☐yes ☒no	unknown Date:	Original add	11622		
Additions: Syes one	unknown Date:	Nature Nature	act side englosure		
	IKIIOWII		ulluci (last halle ilist). <u>ul</u>	IKIIOWII	
		ofession, etc.)			
Ownership History (especia	ally original owner, dates, pro	ofession, etc.)			
Ownership History (especia	ally original owner, dates, pro	n Ordinance? □yes ⊠no	unknown Describ		
Ownership History (especia	ally original owner, dates, pro	ofession, etc.)	unknown Describ		
Ownership History (especials the Resource Affected I	ally original owner, dates, proby a Local Preservation	n Ordinance? □yes ☑nc	□unknown Describ TION	e	
Ownership History (especial Is the Resource Affected Is Style Masonry Vernace	ally original owner, dates, proby a Local Preservation	n Ordinance? ☐yes ☑no  DESCRIP  Exterior Plan	□unknown Describ  TION  Rectangular	e	Number of Stories1
Ownership History (especial Is the Resource Affected Is  Style Masonry Vernace Exterior Fabric(s) 1. Stu	ally original owner, dates, proby a Local Preservation cular	n Ordinance?	TION  Rectangular	e	Number of Stories1
Ownership History (especial Is the Resource Affected Is  Style Masonry Vernace Exterior Fabric(s) 1. Stu Roof Type(s) 1. Gab	by a Local Preservation  cular  cco	n Ordinance?	TION  Rectangular	e 3 3	Number of Stories 1
Ownership History (especial  Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct	by a Local Preservation  cular  ccco  le  position shingles  CS. (dormers etc.) 1.	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up	TION  Rectangular  2.	e 3 3 3	Number of Stories 1
Ownership History (especial  Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct	by a Local Preservation  cular  ccco  le  position shingles  CS. (dormers etc.) 1.	n Ordinance?	TION  Rectangular  2.	e 3 3 3	Number of Stories 1
Ownership History (especial  Is the Resource Affected  StyleMasonry Vernace Exterior Fabric(s) 1Stu Roof Type(s) 1Gab Roof Material(s) 1Com Roof secondary struct Windows (types, materials, et	by a Local Preservation  cular  ccco  cle  position shingles CS. (dormers etc.) 1.  c.) Metal 4-light	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windo	TION  Rectangular  2.  w awnings on orig	e 3 3 3 inal house	Number of Stories1
Ownership History (especial  Is the Resource Affected  Style Masonry Vernace Exterior Fabric(s) 1. Stu Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct Windows (types, materials, et	by a Local Preservation  cular .cco .le .position shingles .cs. (dormers etc.) 1c.) Metal 4-light  al Features (exterior or inf	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windo	TION  Rectangular  2.  w awnings on orig  addition under fl	e 3 3 3 inal house	Number of Stories1
Ownership History (especial  Is the Resource Affected  Style Masonry Vernace Exterior Fabric(s) 1. Stu Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct Windows (types, materials, etc.)  Distinguishing Architecture	by a Local Preservation  cular .cco .le .position shingles .cs. (dormers etc.) 1c.) Metal 4-light  al Features (exterior or inf	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windo	TION  Rectangular  2.  w awnings on orig  addition under fl	e 3 3 3 inal house	Number of Stories1
Ownership History (especial Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stu Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struce Windows (types, materials, etc.)  Distinguishing Architecture north/south sides;	by a Local Preservation  cular  cco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or interest of the structors)	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments)c. 1975 cick" banding on west	TION  Rectangular  2.  w awnings on orig  addition under fl	0 3 3 3 inal house at roof;	Number of Stories 1
Ownership History (especial Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct Windows (types, materials, etc.)  Distinguishing Architectur north/south sides;  Ancillary Features / Outbut	by a Local Preservation  by a Local Preservation  cular  cco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or interpretation)  molded stucco "br	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments) _ c. 1975 ick" banding on west	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed.	0 3 3 3 inal house at roof;	Number of Stories 1  decorative vents on  ine front yard and stone-
Ownership History (especial Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct Windows (types, materials, etc.)  Distinguishing Architectur north/south sides;  Ancillary Features / Outbut	by a Local Preservation  by a Local Preservation  cular  cco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or inf molded stucco "br	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments)c. 1975 cick" banding on west	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed.	0 3 3 3 inal house at roof;	Number of Stories 1  decorative vents on  ine front yard and stone-
Ownership History (especial Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct Windows (types, materials, etc.)  Distinguishing Architectur north/south sides;  Ancillary Features / Outbut	by a Local Preservation  by a Local Preservation  cular  cco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or inf molded stucco "br	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments) _ c. 1975 ick" banding on west	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed.	0 3 3 3 inal house at roof;	Number of Stories 1  decorative vents on  ine front yard and stone-
Ownership History (especial Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof Secondary struct Windows (types, materials, etc.  Distinguishing Architectur north/south sides;  Ancillary Features / Outbut	by a Local Preservation  by a Local Preservation  cular  cco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or inf molded stucco "br	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments) _ c. 1975 ick" banding on west	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed.	0 3 3 3 inal house at roof;	Number of Stories 1  decorative vents on  ine front yard and stone-
Ownership History (especial Is the Resource Affected I  StyleMasonry Vernace Exterior Fabric(s) 1Stu Roof Type(s) 1Gab Roof Material(s) 1Com Roof secondary struct Windows (types, materials, etc.)  Distinguishing Architectur. north/south sides;  Ancillary Features / Outbupaved walkway from	by a Local Preservation  cular  ccco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or int molded stucco "br  lidings (record outbuilding entry to sidewalk	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windo  terior ornaments)c. 1975 rick" banding on west  [s, major landscape features; use of the content o	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed. eway in northwest	0 3 3 3 inal house at roof;	Number of Stories 1  decorative vents on  ine front yard and stone-
Ownership History (especial Is the Resource Affected I  Style Masonry Vernace Exterior Fabric(s) 1. Stur Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struct Windows (types, materials, etc.)  Distinguishing Architectur north/south sides;  Ancillary Features / Outbut	by a Local Preservation  cular  ccco  le  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or int molded stucco "br  lidings (record outbuilding entry to sidewalk	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments) _ c. 1975 ick" banding on west	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed. eway in northwest	0 3 3 3 inal house at roof;	Number of Stories 1  decorative vents on  ine front yard and stone-
Ownership History (especial Is the Resource Affected I  StyleMasonry Vernace Exterior Fabric(s) 1Stu Roof Type(s) 1Gab Roof Material(s) 1Com Roof secondary struct Windows (types, materials, et  Distinguishing Architecture north/south sides;  Ancillary Features / Outbut paved walkway from  DHR USE	by a Local Preservation  cular  ccco  cle  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or int molded stucco "br  sildings (record outbuilding entry to sidewalk	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments)c. 1975 cick" banding on west  OFFICIAL EVA	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed. eway in northwest	e	Number of Stories 1  decorative vents on  ine front yard and stone- property  DHR USE ONLY
Ownership History (especial Is the Resource Affected Style Masonry Vernace Exterior Fabric(s) 1. Stu Roof Type(s) 1. Gab Roof Material(s) 1. Com Roof secondary struce Windows (types, materials, et  Distinguishing Architecturn north/south sides;  Ancillary Features / Outbut paved walkway from  DHR USE  NR List Date St	by a Local Preservation  cular  ccco  cle  position shingles  CS. (dormers etc.) 1.  c.) Metal 4-light  al Features (exterior or int molded stucco "br  sildings (record outbuilding entry to sidewalk	DESCRIP  Exterior Plan  2. 2. Flat 2. Built-up  awning; fabric windouterior ornaments) c. 1975 cick" banding on west  s, major landscape features; use of the company of th	TION  Rectangular  2.  w awnings on orig  addition under fl side  continuation sheet if needed. eway in northwest	e	Number of Stories


Site #8 \_ BD06327

	DESCRIPTION	JN (continued)	
Foundation Type(s): 1. Conc.  Foundation Material(s): 1. Conc.  Main Entrance (stylistic details) West entry porch	ial(s): 1	angular light and decorati	ve square design under
		idence has a simple form. ?	The large addition on the
Archaeological Remains			Check if Archaeological Form Completed
	RESEARCH METHO	DS (check all that apply)	
☑FMSF record search (sites/survection ☐FL State Archives/photo collection ☑property appraiser / tax records ☐ cultural resource survey (CRAS) ☑ other methods (describe) ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	library research city directory newspaper files historic photos	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
	OPINION OF RESOU	RCE SIGNIFICANCE	
Explanation of Evaluation (required, v Florida. It is in the Dorse neighborhood lacks integrit	ional Register listing as part of a district whether significant or not; use separate sheet if any experience of the result of t	ct?yesxnoinsuffice needed)This residence is outlich is a historic Africandemolitions, and in-fills.	American neighborhood. The
Area(s) of Historical Significance (set 1	ee <i>National Register Bulletin 15</i> , p. 8 for categor		community planning & development", etc.)
2	4	6	
	DOCUME	NTATION	
1) Document type Field maps Document description  2) Document type Field notes	d with the Site File - including field notes, a M	aintaining organization  Janus Research  File or accession #'s  aintaining organization  Janus Research	
Document description			
	RECORDER IN	NFORMATION	
Recorder Name Janus Researc Recorder Contact Information 11 (address / phone / fax / e-mail)	h 07 N. Ward St., Tampa FL 3360		s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06328
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 36

Site Name(s) (address if none) 428 NW			Multiple Listing (DHR only)
	ward Boulevard Interchange		Survey # (DHR only)
	ck one)		t □federal □Native American □foreign □unknown
Divate-profit private-none			lederal Livative American Livreign Lanknown
	LOCATION &		0.55.01
Address: Street Number Direction  428  NW	n Street Name 21st	Street Type  Avenue	Suffix Direction
	de btwn NW 3rd Ct and NW 5th S		
	ERDALE NORTH USGS		other Map
City / Town (within 3 miles) Fort Laude	erdaleIn City Limits? 🗷 y	es □no □unknown (	CountyBroward
Township 50s Range 42E	Section4 1/4 section: NW	□SW □SE □NE	Irregular-name:
Tax Parcel # 5042 04 30 0800		Landgrant	Lot
Subdivision Name Dorsey River	pend  Footing Floral 1 Floral Morthing	Block	Lot
Other Coordinates: X:	Easting 5 8 3 1 5 1 Northing Coor	dinate System & Datum	
Name of Public Tract (e.g., park)	1 0001	diliate System & Datum	
	HISTOI	RY	
Construction Year: 1950	approximately  year listed or earlie	r 🗖 vear listed or lat	er
Original Use Private Residence	(House/Cottage/Cabin) From	(year): 1950	To (year):
Current Use Private Residence	(House/Cottage/Cabin) From	(year):	To (year): 2017
Other Use	From	(year):	To (year):
	Date: Original addr	ess	
Alterations: Xyes no unknown			
Additions: Jyes In Junknown	Date: Nature	nilder (last name first): 1111k	nown
Ownership History (especially original ow	ner, dates, profession, etc.)	ander (last hame hist). din	inowii
	,,		
Is the Resource Affected by a Local F	Preservation Ordinance? ☐yes ☑no	□unknown Describe	
	DESCRIP	TION	
-			
Style Masonry Vernacular	Exterior Plan R	ectangular	Number of Stories 1
Poof Type(s) 1 Gable	Z		3 3
Roof Material(s) 1. Composition	shingles 2.		_ 3
Roof secondary strucs. (dormers e	etc.) 1	2	
Windows (types, materials, etc.) Metal	2-light casement; appear to b	oe 2010s replacemen	nts
D			
Distinguishing Architectural Features		ails visible on en	try porch roof extension;
decorative vents on north ar	id south sides		
Ancillary Features / Outbuildings (reco	rd outbuildings, major landscape features; use co	ontinuation sheet if needed.)	Chain-link fence with wood gate
	ord outbuildings, major landscape features; use coveway in northwest corner is w		Chain-link fence with wood gate cars
	- · · · · · · · · · · · · · · · · · · ·		
	- · · · · · · · · · · · · · · · · · · ·		
around back yard; paved driv	veway in northwest corner is w	ide enough for two	cars
	- · · · · · · · · · · · · · · · · · · ·	ide enough for two	
DHR USE ONLY	OFFICIAL EVA	ide enough for two	DHR USE ONLY
DHR USE ONLY  NR List Date SHPO - Appea	veway in northwest corner is w	ide enough for two	cars


Site #8 \_ BD06328

DESCRIPTION (continued)	
Chimney: Noo_ Chimney Material(s): 1	<u> </u>
Porch Descriptions (types, locations, roof types, etc.) _Entry porch under west side roof extension with rectangular stucco supports and concrete stoop; back porch under northeast roof extension	
Condition (overall resource condition):     Excellent   X   Good   Tair   Deteriorated   Truinous	
Archaeological Remains Deck if Archaeological Form Con	npleted
RESEARCH METHODS (check all that apply)	
☑FMSF record search (sites/surveys) ☐Iibrary research ☐ building permits ☐ occupant/owner interview ☐ plat maps ☑ property appraiser / tax records ☐ newspaper files ☐ cultural resource survey (CRAS) ☐ historic photos ☑ other methods (describe) ☐ Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) ☐ building permits ☐ occupant/owner interview ☐ plat maps ☐ Public Lands Survey (DEI ☐ historic photos ☐ interior inspection ☐ HABS/HAER record search ☐ HABS/HAER record search ☐ interior inspection ☐ HABS/HAER record search ☐ interior inspection ☐ HABS/HAER record search ☐ interior inspection ☐ HABS/HAER record search ☐ occupant/owner interview ☐ Public Lands Survey (DEI ☐ HABS/HAER record search ☐ occupant/owner interview ☐ Public Lands Survey (DEI ☐ occupant/owner interview ☐ plat maps ☐ Public Lands Survey (DEI ☐ occupant/owner interview ☐ Public Lands Survey (DEI ☐ occupant/owner interview ☐ plat maps ☐ Public Lands Survey (DEI ☐ occupant/owner interview ☐ plat maps	
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in Sout Plorida. It is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood. The neighborhood lacks integrity with several alternations, demolitions, and in-fills.	
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc 1 5 5	
2 4 6	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  Document type Field maps  Document description Maintaining organization Janus Research  File or accession #'s	
2) Document type Field notes Maintaining organization Janus Research File or accession #'s	
RECORDER INFORMATION	
Recorder NameJanus Research	

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06329			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	35			

Site Name(s) (address if none) 424 NW 21st Avenue Survey Project Name 1-95 at Broward Boulevard Int	Multiple Listing (DHR only) Survey # (DHR only)
National Register Category (please check one) Subuilding	
	private-nonspecific
LOC	ATION & MAPPING
Street Number   Direction   Street Name	Street Type Suffix Direction  Avenue
Cross Streets (nearest/between) E side btwn NW 3rd Ct	
USGS 7.5 Map Name FORT LAUDERDALE NORTH	USGS Date 1983 Plat or Other Map
	City Limits? ☑ yes ☐ no ☐ unknown County ☐ Broward
Township 50s Range 42E Section 4 % S	ection: NW SW SE NE Irregular-name:
Subdivision Name Dorsey Riverbend	Landgrant Lot
UTM Coordinates: Zone LI6 MI/ Easting 5 8 3 1 5	6 Northing 2 8 8 9 9 3 8
Other Coordinates: X: Y: Y:	Coordinate System & Datum
Name of Public Tract (e.g., park)	
	HISTORY
Construction Year: 1950   ■ approximately   year	
Original Use Private Residence (House/Cottage/Ca	<u>bin)</u> From (year): 1950 To (year):
Other Use Private Residence (House/Cottage/Ca	bin)         From (year):         To (year):         2017           From (year):         To (year):
Moves: yes Ino Junknown Date:	Original address
Alterations:    yes □no □unknown Date: 1980s	Nature Decorative and hurricane shutters
	Nature Shed, detached enclosure / attached it
Ownership History (especially original owner, dates, profession, etc.)	Builder (last name first): unknown
Is the Resource Affected by a Local Preservation Ordinance?	yes ⊠no □unknown Describe
	DESCRIPTION
	Exterior Plan Irregular Number of Stories 1
	2. Stone 3.
Rnof Material(s)  1. Gable  1. Composition shingles	2. <u>Hip</u> 3 3 3.
	2 3
Windows (types, materials, etc.) Metal 2/2 single-hung-s	ash; most covered in 1980s hurricane shutters; west side
windows have 1980s decorative shutters  Distinguishing Architectural Features (exterior or interior organients)	S) c. 1965 detached addition has gable roof; c. 1970 enclosure
attaching original house with c. 1965 addition	
A - W F - t / O the didings /	
· · · · · · · · · · · · · · · · · · ·	ape features; use continuation sheet if needed.) c. 1965 shed in northeast corner er is wide enough for three cars; chain-link fence around back
yard	22 15 wide 5150511 202 51125 50125, 111111 11111 11111 11111
DUDUSE ONLY OF	
	FICIAL EVALUATION DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NR I  KEEPER – Determined eligible:	isting: ☐yes ☐no ☐insufficient info Date Init ☐yes ☐no Date
NEET EN DOLUMINOU CHIGIDIC.	

Site #8 BD06329

	DE	SCRIPTION	(continued)		
Chimnou: No. o Chimnou Ma	torial(c). 1		2		
Chimney: No. o Chimney Ma Structural System(s): 1. Con	arata bladi	ຳ		2	<del></del>
Foundation Type(s): 1. Con	tinuous	2		5	
Foundation Material(s): 1coi					
Main Entrance (stylistic details)					rch with concrete stoop
Main Entrance (stylistic details)	,po ideing paner deel		io dobigii diid	or onery per	
Porch Descriptions (types, locations	roof types, etc.) Entry po	rch under west	side roof ex	tension wit	h scrolled iron supports
and concrete stoop					**
Condition (overall resource condition):	□excellent ⊠good [	☐ fair ☐ deterior	rated   ruinous	S	
					e c. 1965 addition with a
gable roof was originall		after, c. 1970	, the area be	etween the o	riginal house and the
addition was enclosed un	<del></del>				<u> </u>
Archaeological Remains					☐Check if Archaeological Form Completed
	DECEADOL	METHODS	(-bb11-4b	4 []	
	RESEARCH	IMETHODS	(cneck all tha	t apply)	
<b>▼</b> FMSF record search (sites/su	rveys) 🔲 library res	search [	building permits		☐ Sanborn maps
☐FL State Archives/photo colle			occupant/owner		□ plat maps
	ds □newspap	er files	neighbor intervi	ew	☐ Public Lands Survey (DEP)
□cultural resource survey (CRA			interior inspection	on	☐ HABS/HAER record search
▼other methods (describe) _ His					
Bibliographic References (give FM	SF manuscript # if relevant, use of	continuation sheet if ne	eded)		
	OPINION OF	F RESOURC	E SIGNIFIC	CANCE	
Appears to meet the criteria for N			□yes <b>⊠</b> no		nt information
Appears to meet the criteria for N					nt information
Explanation of Evaluation (require					
neighborhood lacks integr					merican neighborhood. The
Area(s) of Historical Significance					amunity planning 8, dovelopment" etc.)
1		J, p. o for categories. e			
2.				6.	
	D	OCUMENT.	ATION		
Accessible Documentation Not F	iled with the Site File - inclu	ding field notes, analys	is notes, photos, plar	ns and other importa	ant documents
Document type Field maps     Pocument description		Maiillai	accession #/s	anus Research	
Document description					
2) Document type Field notes					
<b>D</b> ocument description		<b>F</b> ile or	accession #'s		
	RECO	RDER INFO	RMATION		
Recorder NameJanus Resea			ffiliation Janus R		
Recorder Contact Information	1107 N. Ward St., Ta	mpa FL 33607 /	(813) 636-82	200 / janus@	janus-research.com
(address / phone / fax / e-mail)					


Required Attachments


- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

# PHOTOGRAPH



# **SKETCH MAP**





☑ Original ☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06330			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	3.4			


Site Name(s) (address if none) 420 NW 21st Avenue Survey Project Name 1-95 at Broward Boulevard Interchange	Multiple Listing (DHR only) Survey # (DHR only)
National Register Category (please check one) ⊠building ☐structure ☐district Ownership: ☐private-profit ☐private-nonprofit ☐private-individual ☐private-nonspecific ☐city	site object
LOCATION & MA	PPING Street Type Suffix Direction
Address: 420 NW 21st  Cross Streets (nearest/between) E side btwn NW 3rd Ct and NW 5th St  LIGHT STREET STR	
USGS 7.5 Map Name FORT LAUDERDALE NORTH USGS Date City / Town (within 3 miles) Fort Lauderdale In City Limits? ■ yes □	no unknown County Broward
Township 50s Range 42E Section 4 1/4 section: NW Strax Parcel # 5042 04 30 0820 La Subdivision Name Dorsey Riverbend	andgrant
UTM Coordinates: Zone 16 217 Easting 5 8 3 1 5 3 Northing 2 8 Other Coordinates: X: Y: Coordinate Name of Public Tract (e.g., park)	8 9 9 2 4  9 System & Datum
HISTORY	
Other Use  Moves: ☐yes ☒no ☐unknown Date: ☐ Original address  Alterations: ☒yes ☐no ☐unknown Date: ☐1990s Nature ☐ Windows  Additions: ☒yes ☐no ☐unknown Date: ☐c. 1955 Nature ☐ Northes  Architect (last name first): unknown ☐ Builder  Overage to its Uistana (v. 1988)	1950   To (year):
Is the Resource Affected by a Local Preservation Ordinance? ☐yes ☑no ☐un	
Style Masonry Vernacular Exterior Plan Irregular	Number of Stories1
Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Gable 2. Flat	3
Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.	3
Windows (types, materials, etc.) Metal 6/6 single-hung-sash; appear to b	e 1990s replacements; hurricane shutters
Distinguishing Architectural Features (exterior or interior ornaments)	
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continua northwest corner of property; stone-paved front porch; gravel chain-link fence	
DHR USE ONLY OFFICIAL EVALUA	
NR List Date SHPO – Appears to meet criteria for NR listing: ☐yes ☐no ☐NR Criteria for Evaluation: ☐a ☐b ☐c ☐d (see Nation)	Date

Site #8 BD06330


	DESCRIPTIC	on (continued)	
Chimnov: No. o Chimnov Material(s): 1		2	
Chimney: Noo Chimney Material(s): 1 Structural System(s): 1Concrete block	2	2	
Foundation Type(s): 1. Continuous		3	·
Foundation Material(s): 1. Concrete Block			
Main Entrance (stylistic details) West-facing 19			oorch with stone-paved stoop
Porch Descriptions (types, locations, roof types, etc.)	Stone-paved entry p	orch under west side roof	extension with scrolled
iron supports			
Condition (overall resource condition): ☐excellent			
Narrative Description of ResourceThis Mason			
addition in the northeast corner and	the northwest carp	ort were completed c. 195	5, shortly after the house
was first constructed.			Charles Archarderical Farms Commissed
Archaeological Remains			Check if Archaeological Form Completed
RESI	EARCH METHO	DS (check all that apply)	
	library research	building permits	☐ Sanborn maps
	city directory	☐ occupant/owner interview ☐ neighbor interview	□ plat maps
	Inewspaper files Inistoric photos	☐ interior inspection	☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
✓ other methods (describe) Historic aerial		Hillerior inspection	LITADS/TIALIT Tecold Sedicit
Bibliographic References (give FMSF manuscript # if re		if needed)	
Dibliographic Professions (give Final manassisper in the	novant, aso continuation shoot		
ODIA	ON OF BEGOVE		
OPIN	ION OF RESOUR	RCE SIGNIFICANCE	
Appears to meet the criteria for National Register	listing individually?	□yes <b>×</b> no □insuff	icient information
Appears to meet the criteria for National Register			icient information
Explanation of Evaluation (required, whether significan	nt or not; use separate sheet if	needed) This residence is o	of a common style in South
Florida. It is in the Dorsey Riverben			
neighborhood lacks integrity with sev			
Area(s) of Historical Significance (see National Regis			
1	3 4.	5	
2	4		
	DOCUMEN	NTATION	
Accessible Documentation Not Filed with the Site	File - including field notes, a	nalysis notes, photos, plans and other imp	portant documents
1) Document typeField maps	Ma	intaining organization Janus Research	<del></del>
Document description			
2) Document type Field notes			
Document description	F	ile or accession #'s	
	RECORDER IN	FORMATION	
		Affiliation Janus Research	
Recorder Contact Information1107 N. Ward (address / phone / fax / e-mail)	St., Tampa FL 3360	7 / (813) 636-8200 / janu	s@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06331			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	33			

Survey Project Name I-95 at Broward Boulevan	Multiple Listing (DHR only)
National Register Category (please check one)	
Ownershipprivate-profitprivate-nonprofitprivate-indivi	idual private-nonspecific city county state federal Native American foreign unknown
	LOCATION & MAPPING
Street Number <u>Direction</u> Street Name	Street Type Suffix Direction
Address: 416 NW 21st	Avenue
Cross Streets (nearest/between) E side btwn NW 3r	
USGS 7.5 Map Name FORT LAUDERDALE NORTH	USGS Date 1983 Plat or Other Map
	In City Limits? ■ yes □no □unknown County ■ Broward
Townsnip 50s Range 42E Section 4	
Subdivision Name Denger Birrenbend	Lanuyranı
JUDINSION Name Dorsey Riverbend	Landgrant Lot
Other Coordinates: X: V: Lasting Signal V:	Coordinate System & Datum
Name of Public Tract (e.g., park)	Octobridate System & Datam
	HISTORY
Construction Voor: 1950 Francounter-	Dysor listed or carlier — Dysor listed or later
Construction Year: 1950 Sapproximately  Original Use Private Residence (House/Cotts	ge/Cabin) From (year): 1950 To
Current Use Private Residence (House/Cotta	age/Cabin) From (year): To (year): To (year): To (year):
	From (year): To (year):
Moves: ☐yes ☒no ☐unknown Date:	Original address
Alterations:	Os Nature Windows and doors replaced
Additions: Syes Ono Ounknown Date: 199	Os Nature Shed roof addition on northeast corner
	Builder (last name first): unknown
Ownership History (especially original owner, dates, profession	n, etc.)
Is the Resource Affected by a Local Preservation Ordi	nance? Jyes Ino Junknown Describe
	DESCRIPTION
Style Masonry Vernacular	Exterior Plan L-shaped Number of Stories 1
	2 3
	2. Shed 3.
Roof Type(s) 1 Gable	
Roof Type(s) 1. Gable	2. 3.
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles	2 3
Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	2 3
Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	2 3
Roof Type(s)  1. Gable  Roof Material(s)  1. Composition shingles  Roof secondary Strucs. (dormers etc.) 1.  Windows (types, materials, etc.)  1990s replacements	2 3
Roof Type(s)  1. Gable  Roof Material(s)  1. Composition shingles  Roof secondary Strucs. (dormers etc.) 1.  Windows (types, materials, etc.)  1990s replacements	23
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  Metal 1/1 single-h 1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension	23
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major	2
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major	23
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 single-h 1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major)	2
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  Metal 1/1 single-h 1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major	2
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major to front porch in northwest corner of pro-	2
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 1/1 single-h 1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major)	2
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major to front porch in northwest corner of pro-	2
Roof Type(s)  1. Gable Roof Material(s)  1. Composition shingles Roof secondary strucs. (dormers etc.)  Windows (types, materials, etc.)  1990s replacements  Distinguishing Architectural Features (exterior or interior or addition under shed roof extension  Ancillary Features / Outbuildings (record outbuildings, major to front porch in northwest corner of pro-	2


Site #8 \_ BD06331

DESCRIPTION (continued)
Chimney: No. o Chimney Material(s): 1. 2. 3.  Structural System(s): 1. Concrete block 2. 3.  Foundation Type(s): 1. Continuous 2.  Foundation Material(s): 1. Concrete Block 2.  Main Entrance (stylistic details) West-facing 1990s panel door under entry porch with concrete stoop
Porch Descriptions (types, locations, roof types, etc.) Entry porch under west side roof extension with rectangular stucco supports and concrete stoop; uncovered back patio in northeast corner
Condition (overall resource condition):     Excellent   Image: Im
Archaeological Remains Check if Archaeological Form Completed
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys)  ☐ library research  ☐ building permits  ☐ Sanborn maps ☐FL State Archives/photo collection  ☐ city directory  ☐ occupant/owner interview  ☐ plat maps ☑property appraiser / tax records  ☐ newspaper files  ☐ neighbor interview  ☐ Public Lands Survey (DEP) ☐ cultural resource survey (CRAS)  ☐ historic photos  ☐ interior inspection  ☐ HABS/HAER record search ☑ other methods (describe) ☐ Historic aerial photography ☐ Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed) ☐ Continuation sheet if needed ☐ Co
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Level Super
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1 5 5
2 4 6
DOCUMENTATION
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document typeField maps Maintaining organization Janus Research File or accession #'s
2) Document type _Field notes Maintaining organization Janus Research File or accession #'s
RECORDER INFORMATION
Recorder NameJanus Research

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06332			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	32			

	if none) 412 NW 21st Avenue			Multiple Listing (DHR only)	
	I-95 at Broward Boulevard In			Survey # (DHR only)	
	tegory (please check one)				
Ownership:private-p	orofit private-nonprofit private-individual	private-nonspecific city		rederalinative Americanroreign	unknown
	LO	CATION & MAP			
Street Num			Street Type	Suffix Direction	
	NW 21st	1 1	Avenue		
	/between) <u>E side btwn NW 3rd Ct</u> e FORT LAUDERDALE NORTH			thor Man	
	iles) Fort Lauderdale In				
	Range 42E Section 4 1/4				
Tax Parcel # 5042	04 30 0840	Lar	ndarant	megalar name	
Subdivision Name	04 30 0840 Dorsey Riverbend	B	lock	Lot	
UTIVI Coordinates: Zo	one 🗀 16 💌 1/ 🕒 Easting   5   8   3   1	5 3 Northing 2 8 8	9 8 9 3		
Other Coordinates: >	X: Y:	Coordinate	System & Datum		
Name of Public Tract	t (e.g., park)				
		ШСТОВУ			
		HISTORY			
Construction Year:	1950 <b>⊠</b> approximately □ ye	ear listed or earlier	] year listed or late	er	
Original Use Priva	ate Residence (House/Cottage/	Cabin) From (year):	1950	To (year):	
Current Use Priva	ate Residence (House/Cottage/	Cabin) From (year):		To (year):	
Other Use	<del></del>	From (year):	·	To (year):	
	No □unknown Date:	Original address			
Alterations: Xyes	no unknown Date: 1990s/2010	Nature Windows	/doors replace	ed, driveway repaved	
Additions: Syes S	lnounknown Date: <u>c1970</u> t): <u>unknown</u>	NatureEast_sic	act name first): unls	norm	
Ownershin History (e.	specially original owner, dates, profession, etc.)	<b>D</b> ulluel (la	asi name ilisi). <u>utiki</u>	iiowii	
Ownership History (c.	specially original owner, dates, profession, etc.,				
Is the Resource Affect	cted by a Local Preservation Ordinanc	e? □yes ⊠no □unk	nown Describe		
	,	-			
		DESCRIPTION	N .		
Style Masonry Ve	rnacular	Exterior Plan Rectang	gular	Number of Stories	S1
Exterior Fabric(s) 1.	Stucco	2		3	
Roof Type(s) 1.	Gable	2		3	
Roof Material(s) 1.	Composition shingles	_ 2Built-up		_ 3	
Roof secondary	strucs. (dormers etc.) 1.		2		
<b>WINDOWS</b> (types, materia	als, etc.) <u>Metal 2/2 single-hung</u>	-sash; most covered	by shutters		
	ectural Features (exterior or interior orname	nts) Decorative ver	nts on north/s	couth sides, shutters on a	most
	0 east side addition has flat				mos c
Ancillary Features / C	Outbuildings (record outbuildings, major lands	scape features; use continuation	on sheet if needed.)_I	Driveway, walkway, north	side,
and back patio	paved in stone c. 2013; chain	-link fence around	back yard		
DHR I	USE ONLY O	FFICIAL EVALUAT	ION	DHR USE ONLY	
		listing Dues Des C	Tingufficient info		
NR List Date	SHPO – Appears to meet criteria for NF KEEPER – Determined eligible:	r listing: □yes □no □ □yes □no		Date Init.	
Owner Objection			nal Register Bulletin		
,		,	, and the second		

Site #8 BD06332


DESCRIPTION (continued)	
Chimney: Noo Chimney Material(s): 1	
Foundation Type(s): 1. Continuous 2. Foundation Material(s): 1. Concrete Block 2. Main Entrance (stylistic details) West-facing 1990s panel door with decorative light and decorative iron	n screen under
entry porch with concrete stoop  Porch Descriptions (types, locations, roof types, etc.) Entry porch under northwest roof extension with square we low decorative balustrade, and concrete stoop	
Condition (overall resource condition):     Excellent   Image   Image	ations. The
Archaeological Remains Check if Arch.	aeological Form Completed
RESEARCH METHODS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐Ibrary research</li> <li>☐ building permits</li> <li>☐ Sanborn of the control occupant/owner interview</li> <li>☐ Description of the control occupant/owner interview</li> <li>☐ Public La</li> </ul>	nds Survey (DEP) AER record search
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common separate.   This is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood lacks integrity with several alterations, demolitions, and in-fills.	ighborhood. The
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning 1 3 5 5	& development", etc.)
2	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document type Field maps Maintaining organization Janus Research  File or accession #'s	
2) Document type Field notes Maintaining organization Janus Research Document description File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-rese (address/phone/fax/e-mail)	arch.com


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06333
Field Date	9-27-2017
Form Date	10-3-2017
Recorder #	31


Site Name(s) (address if none) 408 NW 21st Av		Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Bot		Survey # (DHR only)
National Register Category (please check one)		lobject _state
Owner Snipprivate-profitprivate-nonprofit _zpriv	ate-individual Exprivate-nonspecific Edity Excounty E	State Diederal Divative American Dioreign Dunknown
	LOCATION & MAPPING	
Street Number <u>Direction</u> Street N		Suffix Direction
Address: 408 NW 21st		e
Cross Streets (nearest / between) E side btwn		
		at or Other Map
		own County Broward
Township 50s Range 42E Section	4	□NE Irregular-name:
Tax Parcel # 5042 04 30 0850	Langrani	Lot
JULY Coordinates: Zono 114 V17 Faction	BIOCK	L0l
UTM Coordinates: Zone ☐16 ☑17 Easting Other Coordinates: X:	Coordinate System &	Datum
Name of Public Tract (e.g., park)		Datum
	HISTORY	
2 1 1 1 1 1 1 1 1 1 1 1 1		
Construction Year: 1950 🗷 approxima	ely gear listed or earlier gyear listed	d or later
Original Use Private Residence (House,	Cottage/Cabin From (year): 1950	To (year):
Current Use Private Residence (House, Other Use		
	Original address	To (year):
Alterations: Syes Ino Inknown Date: _	1990s Nature Iron security ba	ars and awnings added
Additions: Syes on ounknown Date:	1980s Nature Carport on north	hwest corner
		): unknown
Ownership History (especially original owner, dates, p		,·
Is the Resource Affected by a Local Preservation	on Ordinance? □yes ☑no □unknown Des	scribe
	DESCRIPTION	
Style Masonry Vernacular		Number of Stories1
Exterior Fabric(s) 1. Studeo	2	3
Roof Type(s) 1. Gable	2	3
ROOT Material(S) I. Composition shingle	<u> </u>	3
Roof secondary strucs. (dormers etc.) 1 Windows (types, materials, etc.)Metal 2/2 sir		). 
Williams (types, materials, etc.) Metal 2/2 sli	gre-nung-sasn	
Distinguishing Architectural Features (exterior or i	nterior ornaments) Decorative vents on no	orth/south sides: 1990s window iron
security bars and metal awnings; sc		
Ancillary Features / Outbuildings (record outbuilding	gs, major landscape features; use continuation sheet if ne	eded.) Asphalt-paved driveway in
northwest corner of property; stone	-pave walkway from entry to sidewal	k; chain-link fence around property
DHR USE ONLY	OFFICIAL EVALUATION	DHR USE ONLY
	criteria for NR listing:yesnoinsufficient	
KEEPER – Determined eli		Date
☐ Owner Objection NR Criteria for Evaluation:	□a □b □c □d (see <i>National Register</i>	Duileui 13, μ. 2)

Site #8 \_ BD06333


DESCRIPTION (continued)
Chimney: No. o Chimney Material(s): 1. 2. 3. Structural System(s): 1. Concrete block 2. 3. Foundation Type(s): 1. Continuous 2. Foundation Material(s): 1. Concrete Block 2. Main Entrance (stylistic details) West-facing panel door with decorative light under entry porch with concrete stoop
Porch Descriptions (types, locations, roof types, etc.) Entry porch under west side roof extension with scrolled iron supports and concrete stoop
Condition (overall resource condition):     Excellent   Sqood   Fair   deteriorated   ruinous
Archaeological RemainsCheck if Archaeological Form Completed
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys) ☐ library research ☐ building permits ☐ occupant/owner interview ☐ plat maps ☑ property appraiser / tax records ☐ newspaper files ☐ neighbor interview ☐ ultural resource survey (CRAS) ☐ historic photos ☐ interior inspection ☐ HABS/HAER record search ☑ occupant/owner interview ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search ☑ other methods (describe) Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?    Jyes   Jye
DOCUMENTATION
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents    Document type Field maps   Maintaining organization Janus Research
RECORDER INFORMATION
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06334
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 30


	if none) 404 NW 21st Avenue			ultiple Listing (DHR only)
	J-95 at Broward Boulevard Interchan			ırvey # (DHR only)
	tegory (please check one) 🗷 building 🗆 structure			I Chatter Associate Charles Charles
Ownership:private-pr	orofit □private-nonprofit ☑private-individual □private-no	onspecific <b>Li</b> city <b>Li</b> county	staterederal	I Livative American Liroreign Liunknown
	LOCATIO	N & MAPPING		
Street Numb		Street T		uffix Direction
	NW 21st		ue	
	/between) E side btwn NW 3rd Ct and NW		Dlat or Other Me	
	efort_lauderdalenorthiles)_Fort_lauderdaleIn City Limi			
	Range 42E Section 4 14 section:			
Tax Parcel # 5042	14 30 0860	l andgrant	LINE IIIeguio	di-fiditie.
Subdivision Name I	04 30 0860 Dorsey Riverbend	Block		Lot
UTM Coordinates: Zo	one □16 ☑17 Easting 5 8 3 1 5 4 N	orthing 2 8 8 9 8 6	3	
Other Coordinates: X	X: Y:	_ Coordinate System	& Datum	
Name of Public Tract	t (e.g., park)			
		CEODY		
	H	STORY		
Construction Year	1951 🗷 approximately 🗖 year listed	or earlier	ted or later	
Original Use Priva	ate Residence (House/Cottage/Cabin)	From (year): 195	To (vea	ar):
Current Use Priva	ate Residence (House/Cottage/Cabin)	From (year):	To (yea	ar):2017
Other Use		From (year):	To (yea	ar):
	≼no □unknown Date: Origin	nal address		
Alterations: xyes				
Additions:  yes				
	t): unknown			
Ownership history (es	specially original owner, dates, profession, etc.)			<del>-</del>
Is the Resource Affec	cted by a Local Preservation Ordinance?	<b>Σ</b> no Πunknown Γ	)escribe	
15 the resource range	•			
	DESC	CRIPTION		
Style Masonry Ver	rnacular Exterior	Plan Irregular		Number of Stories 1
Exterior Fabric(s) 1.	Stucco 2.		3.	
Roof Type(s) 1	Gable 2. Fla	t	3	
Roof Material(s) 1	Composition shingles 2. Bui	lt-up	3	
Roof secondary	strucs. (dormers etc.) 1.		2	
	als, etc.) Metal 2/2 single-hung-sash ar		fixed window	s on either side of front
	replacements; some windows boarded u			
	ectural Features (exterior or interior ornaments) <u>Pos</u> ches; NE room extended twice (east a			
supports are arc	ches; NE room extended twice (east a	10 HOPUH, C1965/15	970); C1975 F	NE/SE Additions
Ancillary Features / C	Outbuildings (record outbuildings, major landscape featur	es: use continuation sheet if	needed) Paved	driveways on north side and
	r of property; stone pavers on west			
DHR L	USE ONLY OFFICIAL	EVALUATION		DHR USE ONLY
NR List Date	SHPO – Appears to meet criteria for NR listing:			e Init
—————————————————————————————————————	KEEPER – Determined eligible:	lyes  □no ]d   (see <i>National Regis</i>		e 2)
		IU LOCK MANUNAL REUM	ICI DUIICIII IO. D. Z	<u></u>


Site #8 \_ BD06334

	DESCRIPTION	ON (continued)	
Chimney: Noo_ Chimney Material(s): 1 Structural System(s): 1Concrete_block Foundation Type(s): 1Continuous Foundation Material(s): 1Concrete_Block Main Entrance (stylistic details)West-facing_roof Porch Descriptions (types, locations, roof types, etc.) extension; altered to current state	2	n oval light under entry po	rch with arches under flat
Condition (overall resource condition):   Narrative Description of Resource   This re  room was extended E c. 1965. The N  added, one in the SE corner and a second condition.	sidence has a common E room was extended N new NE room.	style. The porch was extend c. 1970. Finally, c. 1975,	
RE	SEARCH METHO	DS (check all that apply)	
<ul> <li>☑ FMSF record search (sites/surveys)</li> <li>☐ FL State Archives/photo collection</li> <li>☑ property appraiser / tax records</li> <li>☐ cultural resource survey (CRAS)</li> <li>☑ other methods (describe)</li> <li>☐ Historic aeria</li> </ul>		□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	□ Sanborn maps □ plat maps □ Public Lands Survey (DEP) □ HABS/HAER record search
Bibliographic References (give FMSF manuscript #	if relevant, use continuation sheet	if needed)	
ODI	NION OF DESOLI	RCE SIGNIFICANCE	
OFI	NION OF RESOUL	CE SIGNIFICANCE	
Appears to meet the criteria for National Regis Appears to meet the criteria for National Regis Explanation of Evaluation (required, whether signif Florida. It is in the Dorsey Rivery neighborhood lacks integrity with s	ter listing as part of a distriction of	t? yes Ino insufficienceded) This residence is of ich is a historic African-A	
Area(s) of Historical Significance (see National Re			nmunity planning & development", etc.)
1	3	5	
2	4	6	
	DOCUMEN	NTATION	
Accessible Documentation Not Filed with the S  1) Document type Field maps Document description	<b>M</b> a	intaining organizationJanus Research	
2) Document type Field notes			
Document description			
	RECORDER IN	FORMATION	
Recorder Name		Affiliation Janus Research	
Recorder Contact Information1107 N. Wa (address / phone / fax / e-mail)	rd St., Tampa FL 3360	7 / (813) 636-8200 / janus@	janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06335
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 29


Survey Project Name T	ne) 2019 NW 3rd Court				Itiple Listing (DHR only)	
	-95 at Broward Boulevard				vey # (DHR only)	
	Dry (please check one) ⊠building □private-nonprofit ⊠private-individua				Notive American Ofereign	- Lunknoum
Ownership. Dprivate-profit	private-nonpront <b>Ex</b> private-individua	iiprivate-nonspeciiicci	ty <b>L</b> County L	_statelederal	ivative Americanioreign	LIUTKHOWH
	LO	OCATION & MA				
Street Number	Direction Street Name		Street Type		fix Direction	
Address: 2019	NW 3rd					
	tween) NE corner of NW 3rd			at ar Othar May	n	
	FORT LAUDERDALE SOUTH Fort Lauderdale					
	nge 42E Section 4					
Tay Parcel # 5042 04	30 0970	74 Section	andarant	_ineguia	1-Hame	
Subdivision Name Dor	30 0870 sey Riverbend		.anugrani <b>R</b> lock		I ot	
UTM Coordinates: <b>7</b> one	□16 <b>⊠</b> 17 <b>E</b> asting 5 8 3 :	1 5 4 <b>N</b> orthing 2 8	8 9 8 4 5		Lot	
Other Coordinates: X:	Y:	Coordinat	e Svstem & [	Datum		
Name of Public Tract (e.	g., park)		j - i - i -			
- (-	· , ———————————————————————————————————					
		HISTORY				
Construction Voor 10	955 <b>⊠</b> approximately □	year listed or carlier	□voar listoa	d or lator		
Original Use Private	Residence (House/Cottage	ycai iisicu ül edilici e/Cabin) From (voa	r). 1955 1956	וטו ומו <del>ט</del> ו דה <i>(ע</i> הם	r)·	
Current Use Private	Residence (House/Cottage	/Cabin) From (yea	r) <u></u>	To (yea	r)· 2017	
Other Use	(, , , , , , , , , , , , , , , , , ,	From (yea	r):	To (yea	r):	
Moves:  □yes 🔀no	□unknown Date:	Original address	- /	-		
Alterations:		Naturesome w	indows rep	placed		
Additions: □yes ▼no	□unknown Date:	Nature				
Architect (last name first): u	ınknown	Builder	(last name first)	): <u>unknown</u>		
Ownershin History (esnec	ially original owner, dates, profession, et	. )				
Ownership mistory (espec	ially original owner, dates, profession, et	c.)				
		<u> </u>				
	by a Local Preservation Ordinar	<u> </u>				
		nce? □yes ⊠no □u	nknown Des			
Is the Resource Affected	by a Local Preservation Ordinar	nce? □yes ⊠no □u	nknown Des	scribe		
Is the Resource Affected  Style Masonry Verna	by a Local Preservation Ordinar	DESCRIPTIO  Exterior Plan Recta	nknown Des	scribe	Number of Stories	1
Is the Resource Affected  StyleMasonry Verna Exterior Fabric(s) 1st	by a Local Preservation Ordinar	DESCRIPTIO  Exterior Plan Recta  2.	nknown Des	scribe	Number of Stories	
Is the Resource Affected  StyleMasonry Verna Exterior Fabric(s) 1st Roof Type(s) 1Ga	by a Local Preservation Ordinar  acular  ucco  ble	DESCRIPTIO  Exterior Plan Recta  2.  2.	nknown Des	3 3	Number of Stories	
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co	by a Local Preservation Ordinar  cular  ucco  ble  mposition shingles	DESCRIPTIO  Exterior Plan Recta  2.  2.  2.  2.	nknown Des	3 3 3	Number of Stories	
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru	by a Local Preservation Ordinar  uccular  ucco  ble  mposition shingles  UCS. (dormers etc.) 1.	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2.	nknown Des	3 3 3	<b>N</b> umber of Stories	
StyleMasonry Verna Exterior Fabric(s) 1st Roof Type(s) 1Ga Roof Material(s) 1Co Roof secondary stru Windows (types, materials, e	by a Local Preservation Ordinar  cular  ucco  ble  mposition shingles	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. g-sash and 4-light	nknown Des	3 3 3	<b>N</b> umber of Stories	
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, 6 fixed and 4-light	by a Local Preservation Ordinar  acular  ucco  ble  mposition shingles  JCS. (dormers etc.) 1.  etc.) Metal 2/2 single-hun	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. 19-sash and 4-light ome 1990s replaceme	nknown Des	3	Number of Stories	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, 6 fixed and 4-light Distinguishing Architectu	by a Local Preservation Ordinar  acular  ucco  ble  mposition shingles  UCS. (dormers etc.) 1.  etc.) Metal 2/2 single-hun  awning on either side; so	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 9-sash and 4-light ome 1990s replacements) Molded stuce	nknown Des	3	Number of Stories	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro	by a Local Preservation Ordinar accular accomble apposition shingles accomposition accomposition shingles accomposition shingles accomposition accomposition shingles accomposition accomposition shingles accomposition accompositi	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. Mg-sash and 4-light Dome 1990s replacements) Molded stuccest carport with at	nknown Des	3333sripartite 1	Number of Stories  eft of door with ce	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro Ancillary Features / Out	by a Local Preservation Ordinar  acular  ucco  ble  mposition shingles  JCS. (dormers etc.) 1.  etc.)Metal 2/2 single-hun awning on either side; so  ral Features (exterior or interior ornar in porch supports; southwe	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. Meg-sash and 4-light Description Recta Moded stuccest carport with at	nknown Des	3333sripartite largert support support shed/uti	Number of Stories  eft of door with ceports and banding or lity room	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro Ancillary Features / Out	by a Local Preservation Ordinar accular accomble apposition shingles accomposition accomposition shingles accomposition shingles accomposition accomposition shingles accomposition accomposition shingles accomposition accompositi	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. Meg-sash and 4-light Description Recta Moded stuccest carport with at	nknown Des	3333sripartite largert support support shed/uti	Number of Stories  eft of door with ceports and banding or lity room	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro Ancillary Features / Out	by a Local Preservation Ordinar  acular  ucco  ble  mposition shingles  JCS. (dormers etc.) 1.  etc.)Metal 2/2 single-hun awning on either side; so  ral Features (exterior or interior ornar in porch supports; southwe	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. Meg-sash and 4-light Description Recta Moded stuccest carport with at	nknown Des	3333sripartite largert support support shed/uti	Number of Stories  eft of door with ceports and banding or lity room	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro Ancillary Features / Out	by a Local Preservation Ordinar  acular  ucco  ble  mposition shingles  JCS. (dormers etc.) 1.  etc.)Metal 2/2 single-hun awning on either side; so  ral Features (exterior or interior ornar in porch supports; southwe	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. Meg-sash and 4-light Description Recta Moded stuccest carport with at	nknown Des	3333sripartite largert support support shed/uti	Number of Stories  eft of door with ceports and banding or lity room	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro Ancillary Features / Outb paved driveway; pa	by a Local Preservation Ordinar accular accomble apposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition and accomposition accomposition of accomposition accompo	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. Moreover 1990s replacements) Molded stuccest carport with at and	nknown Des	3333sripartite largert support support shed/uti	Number of Stories  eft of door with ce  ports and banding or  lity room  lly asphalt- and stoperty	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, efixed and 4-light Distinguishing Architectuside; scrolled iro Ancillary Features / Out	by a Local Preservation Ordinar accular accomble apposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition and accomposition accomposition of accomposition accompo	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. 2. Meg-sash and 4-light Description Recta Moded stuccest carport with at	nknown Des	3333sripartite largert support support shed/uti	Number of Stories  eft of door with ceports and banding or lity room	ntral
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary stru Windows (types, materials, of fixed and 4-light Distinguishing Architectuside; scrolled iro  Ancillary Features / Outto paved driveway; pa	by a Local Preservation Ordinar accular accomble apposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition and accomposition accomposit	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. Moreover 1990s replacements) Molded stuccest carport with at and scape features; use continuo sidewalk; chain-leading of the state	nknown Des	3333	Number of Stories  eft of door with ce  ports and banding or  lity room  lly asphalt- and stoperty  DHR USE ONLY	ntral n south one-
Style Masonry Verna Exterior Fabric(s) 1. St Roof Type(s) 1. Ga Roof Material(s) 1. Co Roof secondary strue Windows (types, materials, fixed and 4-light Distinguishing Architectuside; scrolled iro  Ancillary Features / Outto paved driveway; pa  DHR US  NR List Date S	by a Local Preservation Ordinar accular accomble apposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition shingles accomposition and accomposition accomposition of accomposition accompo	DESCRIPTIO  Exterior Plan Recta 2. 2. 2. 2. Median A-light Description Moded stuccest carport with at and a sidewalk; chain-less continue of sidewalk; chain-less carport with a sidewalk; chain-less carport with	nknown Des	3333sripartite lararport support support shed/uti	Number of Stories  eft of door with ce  ports and banding or  lity room  lly asphalt- and stoperty  DHR USE ONLY	ntral n south one-


Site #8 BD06335

DESCRIPTION (continued)
Chimney: Noo_Chimney Material(s): 1
Porch Descriptions (types, locations, roof types, etc.) Entry porch with raised concrete pad under south side roof extension with scrolled iron supports
Condition (overall resource condition):     Excellent   Image: Im
Archaeological Remains Check if Archaeological Form Completed
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys) ☐ library research ☐ building permits ☐ sanborn maps ☐ city directory ☐ occupant/owner interview ☐ plat maps ☐ public Lands Survey (DEP) ☐ cultural resource survey (CRAS) ☐ historic photos ☐ interior inspection ☐ HABS/HAER record search ☑ other methods (describe) ☐ Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in South  Florida. It is in the Dorsey Riverbend neighborhood, which is a historic African-American neighborhood. The neighborhood lacks integrity with several alterations, demolitions, and in-fills.  Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1.
DOCUMENTATION
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document description
RECORDER INFORMATION
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06336			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	25			


Site Name(s) (address if none) _2					le Listing (DHR only)
Survey Project Name I-95 a					y # (DHR only)
National Register Category (ple					Native American ☐foreign ☐unknow
Ownership. Dprivate-profit Dpriv	ate-nonpront <b>Ex</b> private-individual	private-nonspecific Licity	/countystate	e <u>l</u> lederal <u>l</u>	INative American Litoreign Lunknow
	LO	CATION & MA	PPING		
	<u>Direction</u> <u>Street Name</u>		Street Type	Suffix I	<u>Direction</u>
Address: 2016	NW 3rd		Court		
Cross Streets (nearest / between)					
USGS 7.5 Map Name FORT	LAUDERDALE SOUTH	<b>U</b> SGS Date		Other Map _	
City / Town (within 3 miles) Fort					
Township 50s Range 4	2E Section 4	4 section: LINW LIS	W ∐SE ∐NE	. Irregular-n	ame:
Tax Parcel # 5042 04 30	1060	La	anagrant		Lat
JULIA Coordinates: 7 on 14	Riverpena  Facting [5] 2   1	T7 1 Morthing 2 9	310CK		Lot
Other Coordinates: X:	N.		System & Datin	m	
Name of Public Tract (e.g., par	 rk)	Coordinate	System & Data		
	'Y				
		HISTORY			
0		and Patentine P		-1	
Construction Year: 1965	_ <b>⊠</b> approximately □	year listed or earlier [	year listed or la	ater	
Original Use Private Resi	dence (House/Cottage,	(Cabin) From (year	):1965	10 (year):	
Current Use Private Resi	dence (House/Corrage,	From (year	): ):	To (year):	2017
Moves: Tyes In Tur	nknown Date:	Original address	)	. To (year).	
Alterations:   yes   no   un	nknown Date:	Nature			
Additions: □yes ⊠no □ur	nknown Date:	Nature			
Architect (last name first): unkno	wn	Builder	(last name first): ur	ıknown	
Ownership History (especially ori	ginal owner, dates, profession, etc	:.)			
Is the Resource Affected by a	Local Preservation Ordinan	ce? □yes <b>⊠</b> no □un	known Describe	9	
		DESCRIPTIO	N		
0.1					N 1 (0) 1
Style Masonry Vernacula	<u>r</u>	_ Exterior Plan Irregi	ılar		Number of Stories1
Poof Typo(s) 1. Stucco				3	
Poof Material(s) 1 Compage	ition chingles			3	
	ormers etc.) 1.		2	3	
Windows (types, materials, etc.)					
(types, materials, etc.)		·			
Distinguishing Architectural Fe	atures (exterior or interior ornam	ents)Two car garag	ge in northea	st corner	; molded stucco "brick"
garage corners, door su	urround, and banding	in northwest corner	r; concrete s	creens at	porch
			tion sheet if needed.)	Paved ha	lf-circle driveway; pool
in back yard; chain-lin	nk fence around back	yard			
DHR USE ON	LY	OFFICIAL EVALUA <sup>*</sup>	TION		DHR USE ONLY
ND Liet Date CUDO	Appears to most criteria for N	ID licting: Dyon Dro	Dincufficient info	Data	Init
	<ul> <li>Appears to meet criteria for N R – Determined eligible:</li> </ul>	lik listing: □yes □no   □yes □no			Init
	eria for Evaluation: 🔲 a 🔲 l	—, —	onal Register Bulle		
		(300 / Valid	g.o.o. Dullo		


Site #8 BD06336

	DESCRIPT.	ION (continued)	
Chimney No o Chimney Materia	al(s)· 1	2	
Chimney: No. o Chimney Materia Structural System(s): 1. Concre	ete block 2.	3.	
Foundation Type(s): 1. Continu	nuous 2		
Foundation Material(s): 1. Concre			
Main Entrance (stylistic details)Nortl	n-facing double wooden door	rs with molded stucco "brick	" door surround and flanked
by porch concrete screens			
Porch Descriptions (types, locations, roof		recessed under main roof w	ith concrete screens on
either side of the front do	or and a concrete stoop		
Condition (overall resource condition):	excellent 🗷 good 🗆 fair 🗀 c	deteriorated	
Narrative Description of Resource			-car garage on the east
side and a concrete screene	d porch.		
			<u>_</u>
Archaeological Remains			Check if Archaeological Form Completed
	RESEARCH METH	ODS (check all that apply)	
TEMOS accorded to the control of the			Combon was
▼FMSF record search (sites/survey)      □ EL State Archives/photo collection		<ul><li>□ building permits</li><li>□ occupant/owner interview</li></ul>	☐ Sanborn maps ☐ plat maps
☐ FL State Archives/photo collection ☐ FL State	n	☐ neighbor interview	□ Public Lands Survey (DEP)
□ cultural resource survey (CRAS)	☐ historic photos	☐ interior inspection	HABS/HAER record search
■other methods (describe) Histor			
Bibliographic References (give FMSF n		eet if needed)	
		·	
	OPINION OF RESOL	URCE SIGNIFICANCE	
•			
Appears to meet the criteria for Natio		_,	cient information
Appears to meet the criteria for Nation Explanation of Evaluation (required, where the criteria for Nation Company) is a second of the criteria for Nation (required, where the criteria for Nation Na			cient information
		which is a historic African-	
neighborhood lacks integrity			
Area(s) of Historical Significance (see			
1	3	5	
2	4	6	
	DOCUMI	ENTATION	
• " • • • • • • • • • • • • • • • • • •	W W OF E		
Accessible Documentation Not Filed  Document type Field maps	with the Site File - including field notes	s, analysis notes, photos, plans and other imp	ortant documents
1) Document description		Maintaining organization Janus Research File or accession #'s	
		Maintaining organization Janus Research  File or accession #'s	
Document description		The or accession # 3	
	RECORDER I	INFORMATION	
Recorder Name Janus Research	1	Affiliation Janus Research	
Recorder Contact Information 110			s@janus-research.com
(address / phone / fax / e-mail)			

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06337
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 26

Site Name(s) (address if none) 2008 NW 3rd Court		Multiple Listing (DHR only)
Survey Project Name <u>I-95 at Broward Boulevard I</u> :  National Register Category (please check one)		Survey # (DHR only)
Ownership: private-profit private-nonprofit private-individual		☐federal ☐Native American ☐foreign ☐unknown
LO	CATION & MAPPING	
Street Number <u>Direction</u> Street Name	Street Type	Suffix Direction
Address: 2008 NW 3rd	Court	
Cross Streets (nearest/between) S side btwn NW 20th F		hor Mon
USGS 7.5 Map Name FORT LAUDERDALE SOUTH  City / Town (within 3 miles) Fort Lauderdale In		
Township 50s Range 42E Section 4 1/4		
Tax Parcel # 5042 04 30 1050	Landgrant	irregular-name.
Subdivision Name Dorsey Riverbend	Block	Lot
Tax Parcel # 5042 04 30 1050  Subdivision Name Dorsey Riverbend  UTM Coordinates: Zone □16 ☑17 Easting 5 8 3 1	9 6 <b>N</b> orthing 2 8 8 9 7 9 4	
Other Coordinates: X: Y: Y:	Coordinate System & Datum	
Name of Public Tract (e.g., park)		
	HISTORY	
Construction Year: 1962 ■ approximately □ year	ear listed or earlier	or
Original Use Private Residence (House/Cottage/		
Current Use Private Residence (House/Cottage/	Cabin) From (year):	To (vear): 2017
Other Use	From (year):	To (year):
Moves: pes In Date:	From (year): Original address Nature Windows/doors replace	
Alterations:   yes  no  unknown  Date:  1980s	NatureWindows/doors replace	ed
Additions:   yes   x no	Nature	20wn
Architect (last name first): unknown  Ownership History (especially original owner, dates, profession, etc.)	Dullder (last flame first). driver	IOWII
Is the Resource Affected by a Local Preservation Ordinanc	e? ☐yes ☑no ☐unknown Describe _	
	DESCRIPTION	
Style Masonry Vernacular		
Exterior Fabric(s) 1. Stucco		
Roof Type(s)  1. Cross-gabled  Poof Material(s)  1. mile supposition	_ 2	_ 3
Roof Material(s) 1. Tile unspecified  Roof secondary strucs. (dormers etc.) 1.	_ Z	_ 3
Windows (types, materials, etc.) Metal 6/6 and 8/8 sing	gle-hung-sash; 6/6 are double win	ndows on either side of the
front door; appear to be 1980s replacements		
Distinguishing Architectural Features (exterior or interior orname	nts) <u>Scored stucco at garage cor</u>	ners; double door entry with two
steps was installed in the 1980s		
Anaillany Footures / Outhwildings (	f	
Ancillary Features / Outbuildings (record outbuildings, major lands in back yard with lanai; iron fence around b		Paved half-circle driveway; pool
DHR USE ONLY C	FFICIAL EVALUATION	DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NF	R listing:   yes   no   linsufficient info	Date Init
KEEPER – Determined eligible:	□yes □no	Date
	☐c ☐d (see National Register Bulletin	


Site #8 \_ BD06337

	DESCRIPTION	DN (continued)		
Chimney: Noo_ Chimney Material(s): 1 Structural System(s): 1. Concrete block Foundation Type(s): 1. Continuous Foundation Material(s): 1. Concrete Block Main Entrance (stylistic details) North-facing	2 k 2			
Porch Descriptions (types, locations, roof types, etc.)	None observed			
Condition (overall resource condition): ☐excellent Narrative Description of Resource			d few alterations.	
Archaeological Remains			☐Check if Archaeological Form Completed	
RE	SEARCH METHO	DS (check all that apply)		
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐Historic aeria</li> <li>Bibliographic References (give FMSF manuscript #</li> </ul>	☐ library research ☐ city directory ☐ newspaper files ☐ historic photos al photography	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search	
OPI	NION OF RESOUI	RCE SIGNIFICANCE		
Appears to meet the criteria for National Regis Appears to meet the criteria for National Regis Explanation of Evaluation (required, whether signification in the Dorsey Rivers neighborhood lacks integrity with s	ter listing as part of a distriction cant or not; use separate sheet if then a neighborhood, which was neighborhood, which was neighborhood, which was neighborhood, which was neighborhood.	ct?		
Area(s) of Historical Significance (see National Re	egister Bulletin 15, p. 8 for categor	ies: e.g. "architecture", "ethnic heritage", "cor		
1 2	3 4	5 6		
DOCUMENTATION				
Accessible Documentation Not Filed with the S  1) Document type Field maps Document description	<b>M</b> a	nintaining organization		
2) Document type Field notes	Ma	nintaining organization		
Document description				
	RECORDER IN	FORMATION		
Recorder Name Janus Research Recorder Contact Information 1107 N. Was (address / phone / fax / e-mail)		Affiliation Janus Research 07 / (813) 636-8200 / janus@	janus-research.com	

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06338		
Field Date	9-27-2017		
Form Date	10-3-2017		
Recorder #	27		


Survey Droject Name I-95 at Broward Roulevard Inte	Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Boulevard Int	
National Register Category (please check one) Subuilding	structure □district □site □object  private-nonspecific □city □county □state □federal □Native American □foreign □unknown
Ownership. Dprivate-profit Dprivate-horiprofit Exprivate-individual Dprivate-individual Dprivate-individua	onvale-nonspecific Licity Licounty Listate Lifederal Linative American Lifeteigh Lighthown
LOCA	ATION & MAPPING
Street Number <u>Direction</u> Street Name	Street Type Suffix Direction
Address: 2001 NW 3rd	Court
Cross Streets (nearest / between) NW corner of NW 3rd Ct	USGS Date 1983 Plat or Other Map
	ty Limits? ■ yes □no □unknown County <u>Broward</u>
	ection: DNW DSW DSE DNE Irregular-name:
Tay Parcol # 5042 04 20 0800	Landgrant
Subdivision Name Dorsey Riverhend	Landgrant Lot
UTM Coordinates: Zone ☐16 ☑17 Easting 5 8 3 2 0	5 Northing 2 8 8 9 8 3 9
Other Coordinates: X: Y:	Coordinate System & Datum
Name of Public Tract (e.g., park)	
	HISTORY
Construction Voor. 1959 Wannrovimetaly Dyon	licted or carlier — Dycar licted or later
Construction Year: 1959 ■ approximately □ year Original Use Private Residence (House/Cottage/Cal	ilsted of earlier Liyear listed of fater
Current Use Private Residence (House/Cottage/Cal	pin) From (year): To (year): 2017
Other Use	From (year): To (year):
Moves: □yes ☑no □unknown Date:	Original address
Alterations: xyes no no no Date: c. 2000	Nature Garage door replaced
	Nature North enclosure with second entry
	Builder (last name first): unknown
• II III /	
Ownership History (especially original owner, dates, profession, etc.) _	
	□yes ☑no □unknown Describe
Is the Resource Affected by a Local Preservation Ordinance?	□yes ☑no □unknown Describe
Is the Resource Affected by a Local Preservation Ordinance?	□yes ⊠no □unknown Describe □ DESCRIPTION
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular E	□yes ☑no □unknown Describe □  DESCRIPTION  xterior Plan Irregular Number of Stories 1
Is the Resource Affected by a Local Preservation Ordinance?  StyleMasonry Vernacular E  Exterior Fabric(s) 1Stucco	□yes ☑no □unknown Describe  DESCRIPTION  xterior Plan Irregular
Is the Resource Affected by a Local Preservation Ordinance?  StyleMasonry Vernacular E  Exterior Fabric(s) 1Stucco  Roof Type(s) 1Hip	□yes ☑no □unknown Describe  DESCRIPTION  xterior Plan Irregular
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles	□yes ☑no □unknown Describe □  DESCRIPTION  xterior Plan Irregular
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	□yes ☑no □unknown Describe  DESCRIPTION  xterior Plan Irregular Number of Stories 1 2. 3. 2. 3. 2. 3. 2. 2. 3. 2. 2. 2. 3. 2. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	□yes ☑no □unknown Describe  DESCRIPTION  xterior Plan Irregular Number of Stories 1 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-saccentral 3-light	□yes ☑no □unknown Describe  DESCRIPTION  xterior Plan Irregular Number of Stories 1 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-saccentral 3-light	DESCRIPTION  xterior Plan Irregular Number of Stories 1 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri	DESCRIPTION  Atterior Plan Irregular Number of Stories 1  2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri  Ancillary Features / Outbuildings (record outbuildings, major landsca	DESCRIPTION  **xterior Plan
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri	DESCRIPTION  **xterior Plan
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri  Ancillary Features / Outbuildings (record outbuildings, major landsca	DESCRIPTION  **xterior Plan
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri  Ancillary Features / Outbuildings (record outbuildings, major landsca	DESCRIPTION  **xterior Plan
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri  Ancillary Features / Outbuildings (record outbuildings, major landscasidewalk; stone pavers lead from driveway to be	DESCRIPTION  **xterior Plan Irregular
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri  Ancillary Features / Outbuildings (record outbuildings, major landscasidewalk; stone pavers lead from driveway to be	DESCRIPTION  **xterior Plan
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-saccentral 3-light	DESCRIPTION  Atterior Plan Irregular Number of Stories 1  2. 3. 2. 3. 2. 3. 2. 3. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Is the Resource Affected by a Local Preservation Ordinance?  Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Hip Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 6/6 single-hung-saccentral 3-light fixed and 6/6 single-hung-sash Distinguishing Architectural Features (exterior or interior ornaments) iron supports and railing on porch; some hurri  Ancillary Features / Outbuildings (record outbuildings, major landscasidewalk; stone pavers lead from driveway to be	DESCRIPTION    Atterior Plan   Irregular   Number of Stories   1   2   3   2   3   2   2   3   2   3   2   3   2   3   3


Site #8 BD06338

	DESCRIPTION	JIN (continued)	
Chimney: No. o Chimney Material(s): 1		2	
Chimney: No. o Chimney Material(s): 1 Structural System(s): 1 Concrete block	2.	3.	<del></del>
Foundation Type(s): 1. Continuous	2.		
Foundation Material(s): 1. Concrete Block			
Main Entrance (stylistic details)S-facing_pane		tive squares under entry po	rch with concrete stoop;
E-facing second entry on NE addition			
Porch Descriptions (types, locations, roof types, etc.)	Entry porch on sout	th side with scrolled iron a	supports and railing;
concrete stoop			
Condition (overall resource condition): ☐excellent	⊠good □fair □det	eriorated Druinous	
Narrative Description of Resource This Maso			car garage in the
southeast corner. The northeast add			
			_ <u>_</u>
Archaeological Remains			□Check if Archaeological Form Completed
RES	EARCH METHO	DS (check all that apply)	
	□library research	□ building permits	☐ Sanborn maps
	☐ city directory	☐ occupant/owner interview ☐ neighbor interview	□ plat maps
1 1 3 11	□newspaper files □historic photos	☐ interior inspection	☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
■other methods (describe) Historic aerial		Шителог изресцоп	MIADS/HALICICCOID Scarcii
Bibliographic References (give FMSF manuscript # if		t if needed)	
OPIN	NON OF RESOUR	RCE SIGNIFICANCE	
Appears to meet the criteria for National Register		_,	ent information
Appears to meet the criteria for National Registe Explanation of Evaluation (required, whether signification)			ent information
Florida. It is in the Dorsey Riverbe			
neighborhood lacks integrity with se			
Area(s) of Historical Significance (see National Reg			
1		5	
2	4	6	
	DOCUMEN	NTATION	
	DOCONIE		
Accessible Documentation Not Filed with the Sit	te File - including field notes, a	nalysis notes, photos, plans and other impor	tant documents
1) Document type Field maps	Ma	aintaining organization Janus Research	
Document description			
2) Document type Field notes			
Document description	l	·lle or accession #'s	
	RECORDER IN	FORMATION	
Decorder Name Towns Decords			
Recorder NameJanus Research  Recorder Contact Information1107 N. Ward		Affiliation Janus Research	@ianus_research com
(address / phone / fax / e-mail)	a be., rampa ru 3300	, (013, 030-0200 / Janus	SJAMAD TEDEATON.COM

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE





☑ Original
☐ Update



Site Name(s) (address if none) 1800-1803 W Broward Boulevard

## HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06339		
Field Date	9-27-2017		
Form Date	10-3-2017		
Recorder #	23		

\_\_ Multiple Listing (DHR only) \_\_\_\_\_

**Shaded Fields** represent the minimum acceptable level of documentation. Consult the *Guide to Historical Structure Forms* for detailed instructions.

Survey Project Name I-95 at Broward Boulevard Interchange Survey # (DHR only)

National Register Category (please check one) ⊠building ☐ structure ☐ district ☐ site ☐ object  Ownership: ☐ private-profit ☐ private-nonprofit ☑ private-individual ☐ private-nonspecific ☐ city ☐ county ☐ state ☐ federal ☐ Native American ☐ foreign ☐ unknown
Street Number   Direction   Street Name   Street Type   Suffix Direction
HISTORY
Construction Year: 1963
Is the Resource Affected by a Local Preservation Ordinance? ☐yes ☑no ☐unknown Describe
DESCRIPTION
Style Masonry Vernacular Exterior Plan L-shaped Number of Stories 1  Exterior Fabric(s) 1. Stucco 2. 3.  Roof Type(s) 1. Flat 2. Other 3.  Roof Material(s) 1. Built-up 2. 3.  Roof secondary strucs. (dormers etc.) 1. 2.  Windows (types, materials, etc.) 1980s commercial storefront window next to entry door in southeast corner  Distinguishing Architectural Features (exterior or interior ornaments) Original bays on north side enclosed; east half of building has a barrel roof, west half has a flat roof; east side parapet hides most of barrel roof
Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.) Chain-link fence around property; parking lot in southeast corner near entrance; adjacent non-historic two-story building in northeast corner
DHR USE ONLY  OFFICIAL EVALUATION  DHR USE ONLY  SHPO – Appears to meet criteria for NR listing:

Site #8 \_ BD06339

DESCRIPTION (continued)	
Chimney: Noo_ Chimney Material(s): 1	
Porch Descriptions (types, locations, roof types, etc.) None observed	
Condition (overall resource condition):   Excellent   Good   fair   deteriorated   ruinous  Narrative Description of Resource  This Masonry Vernacular has a simple form and few alterations. The adjacent historic two-story building replaced a historic building formerly associated with this building.	non-
Archaeological Remains Check if Archaeological Form C	Completed
RESEARCH METHODS (check all that apply)	
☑FMSF record search (sites/surveys) □ library research □ building permits □ sanborn maps □ plat maps ☑ property appraiser / tax records □ newspaper files □ neighbor interview □ cultural resource survey (CRAS) □ historic photos ☑ other methods (describe) ☐ Historic aerial photography Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)	
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This commercial building is of a common so in South Florida. It is in the Riverside Park neighborhood, which is a historic African-American	tyle
neighborhood. The neighborhood lacks integrity with several alterations, demolitions, and in-fills.  Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development",  1	
2. 4. 6.	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document type Field maps Maintaining organization Janus Research  File or accession #'s	
2) Document typeField notes Maintaining organization Janus Research File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com (address/phone/fax/e-mail)	


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06340		
Field Date	9-27-2017		
Form Date	10-3-2017		
Recorder #	22		


	Multiple Listing (DHR only)
Survey Project Name I-95 at Broward Boulevard Interchange	
National Register Category (please check one) Subuilding Structure	
Ownership: ☐private-profit ☐private-nonprofit ☑private-individual ☐private-nonspeci	fic  city  county  state  Mederal  Native American  foreign  unknown
LOCATION &	MAPPING
Street Number Direction Street Name	Street Type Suffix Direction
Address: 709 SW 20th	Terrace Terrace
Cross Streets (nearest/between) West side, north of SW 8th Street	
USGS 7.5 Map Name FORT LAUDERDALE SOUTH USG	
City / Town (within 3 miles) Fort Lauderdale In City Limits?	· · · · · · · · · · · · · · · · · · ·
Township 50s Range 42E Section 9 1/4 section: □NV	V □SW □SE □NE Irregular-name:
Tax Parcel # _5042 09 25 0090  Subdivision Name	Landgrant
Subdivision Name  LTM Contribution 7 and 1717 Facting Floridate Morthin	Block Lot Lot
UTM Coordinates: Zone □16 ☑17 Easting 5 8 3 2 0 6 Northing Other Coordinates: X: Y: Coordinates:	J[2] 8] 8] 8] 4] 1] 5] ordinate System & Datum
Name of Public Tract (e.g., park)	Juliale System a dalum
Name of Fublic Tract (c.y., park)	
HISTO	DRY
Construction Year: 1954 ■ approximately □ year listed or earl	ier year listed or later
Original Use Private Residence (House/Cottage/Cabin) From	m (year): lo (year):
Current Use Private Residence (House/Cottage/Cabin) From	m (year): 10 (year): 2017
	m (year): To (year):
Moves: ☐yes ☑no ☐unknown Date: Original add Alterations: ☑yes ☐no ☐unknown Date: Nature _s	creened front porch, new windows/doors
Additions: Syes Ino Introduction Date: 1980s Nature	
Architect (last name first): unknown	W addition, SW back porch  Builder (last name first): unknown
Ownership History (especially original owner, dates, profession, etc.)	
Is the Resource Affected by a Local Preservation Ordinance?  yes  In	Describe
DECORU	
DESCRII	PTION
Style Masonry Vernacular Exterior Plan	Irregular Number of Stories 1
Style Masonry Vernacular Exterior Plan	Irregular Number of Stories 1
StyleMasonry VernacularExterior PlanExterior Fabric(s)1. Stucco2.Roof Type(s)1. Hip2. Flat	Irregular Number of Stories 1 33.
StyleMasonryVernacularExterior PlanExterior Fabric(s)1. Stucco2.Roof Type(s)1. Hip2. FlatRoof Material(s)1. Composition shingles2. Built-up	Irregular         Number of Stories         1           3.         3.           3.         3.           3.         3.
Style       Masonry       Vernacular       Exterior Plan         Exterior Fabric(s)       1. Stucco       2.         Roof Type(s)       1. Hip       2. Flat         Roof Material(s)       1. Composition shingles       2. Built-up         Roof secondary strucs. (dormers etc.)       1.	Number of Stories
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windows	Number of Stories
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double window replacements	Irregular  3. 3. 3. 3. 2. 2. 2. 2. 2. 3. 3. 3. 3. 3. 3. 3. 4. 5. 5. 6. 7. 6. 7. 8. 8. 8. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windows replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded	Irregular  3. 3. 3. 3. 2. 2. 2. 2. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double window replacements	Irregular  3. 3. 3. 3. 2. 2. 2. 2. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windoreplacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs	Irregular  3. 3. 3. 3. 2. 2. 2. 2. 3. 3. 3. 3. 3. 4. 5. 5. 6. 7. 6. 6. 7. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8. 8.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double winds replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use	Irregular  3. 3. 3. 3. 5. 7. 8. 9. 9. 9. 9. 9. 9. 9. 9. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windoreplacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs	Irregular  3. 3. 3. 3. 5. 7. 8. 9. 9. 9. 9. 9. 9. 9. 9. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double winds replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use	Irregular  3. 3. 3. 3. 5. 7. 8. 9. 9. 9. 9. 9. 9. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double winds replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use	Irregular  3. 3. 3. 3. 5. 7. 8. 9. 9. 9. 9. 9. 9. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windoreplacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use around property; new paving on carport, carport extensions.)	Irregular  3. 3. 3. 3. 2. bw in southeast corner; appear to be 1980s  stucco "stacked stone" banding on east side; awning on north side extends carport  continuation sheet if needed.) Wood and chain-link fencing on, and driveway
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double winds replacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use	Irregular  3. 3. 3. 3. 2. bw in southeast corner; appear to be 1980s  stucco "stacked stone" banding on east side; awning on north side extends carport  continuation sheet if needed.) Wood and chain-link fencing on, and driveway
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windoreplacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use around property; new paving on carport, carport extensions.)	3
Style Masonry Vernacular Exterior Plan  Exterior Fabric(s) 1. Stucco 2.  Roof Type(s) 1. Hip 2. Flat  Roof Material(s) 1. Composition shingles 2. Built-up  Roof secondary strucs. (dormers etc.) 1.  Windows (types, materials, etc.) Metal 3-light awning; double windoreplacements  Distinguishing Architectural Features (exterior or interior ornaments) Molded porches, carport, and northwest addition have flat roofs  Ancillary Features / Outbuildings (record outbuildings, major landscape features; use around property; new paving on carport, carport extension  DHR USE ONLY OFFICIAL EV  NR List Date SHPO – Appears to meet criteria for NR listing: Jyes KEEPER – Determined eligible: Jyes	Number of Stories   1   3.   3.   3.   3.   5.   5.   5.   5.


Site #8 BD06340


DESCRIPTION (continued)	
Chimney: No. 1 Chimney Material(s): 1. Concrete block 2. Brick  Structural System(s): 1. Concrete block 2. 3.  Foundation Type(s): 1. Continuous 2.	
Foundation Material(s): 1. Concrete Block 2.  Main Entrance (stylistic details) East-facing panel door under screened in entry porch	
Porch Descriptions (types, locations, roof types, etc.) East entry porch screened in; 1980s back porch in southwest corner; both have flat roofs	
Condition (overall resource condition):     Sexcellent   Sexcellent   General deteriorated	ions_
Archaeological RemainsCheck if Archaeological Form Co	ompleted
RESEARCH METHODS (check all that apply)	
☑FMSF record search (sites/surveys)	
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in Sour Florida. It is in the Riverside Park neighborhood, which is a historic African-American neighborhood. The neighborhood lacks integrity with several alterations, demolitions, and in-fills.	
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", ethnic heritage & development & develo	
2	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document typeField maps Maintaining organization Janus Research File or accession #'s	
2) Document type _Field notes Maintaining organization Janus Research File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com  (address/phone/fax/e-mail)	


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE









☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06341		
Field Date	9-27-2017		
Form Date	10-3-2017		
Recorder #	21		

	ifnone) 713 SW 20th Terrace			ultiple Listing (DHR only)
	I-95 at Broward Boulevard I			urvey # (DHR only)
	egory (please check one)			I Dhiating Associates Dispersion Durch
Ownershipprivate-pr	on private-nonpron private-individual	private-nonspecificcityc	county <u>I</u> state <u>I</u> ledera	Il □Native American □foreign □unknown
	LO	CATION & MAPPI	NG	
	<u>Direction</u> <u>Street Name</u>	St T	reet Type <u>Sı</u>	uffix Direction
Address: 713	D	_	errace	
	/between) West side, north of s			
USGS 7.5 Map Name	FORT LAUDERDALE SOUTH	USGS Date 198	83_ Plat or Other Ma	ap
	es) Fort Lauderdale  r			
Township 50s	Range 42E Section 9 4	section: LINW LISW L	JSE ∐NE Irregul	ar-name:
Tax Parcel # 5042	09 25 0080	Landg	rant	Lat
Subdivision Name	no 114 117 Facting [ 0 2 2	Morthing 2 9 9 9	<u> </u>	Lot
Other Coordinates: X	7. V.	Coordinate Svs	stem & Datum	
Name of Public Tract	(e.g., park)	Coordinate Sys	stem & Datum	
	(o.g., party)			
		HISTORY		
0	1052	Pakada	- Patad 1	
Construction Year:	1953 Napproximately Dy	ear listed or earlier	ar listed or later	or).
Original Use Priva	te Residence (House/Cottage/	Cabin) From (year):	1953 IO (ye	ar):
Other Use	te Residence (House/Cottage/		To (ye	
Moves.	no 🗖 unknown Date:	Original address	10 ye	ai)
Alterations: Syes	Ino Dunknown Date: 1980s	Nature Carport en	closed, opening	altered
Additions: Syes	Ino Dunknown Date: 1980s	Nature Northwest	enclosed addition	on
	): unknown			
	specially original owner, dates, profession, etc.			
Is the Resource Affect	ted by a Local Preservation Ordinand	e? □yes ⊠no □unknow	n Describe	
		DESCRIPTION		
Style Magenry Ver	rnagular		_	Number of Stories1
Fytorior Fabric(s) 1	Stucco	2		Number of Stories1
Roof Material(s) 1.	Composition shingles	2. Built-up		
	Strucs. (dormers etc.) 1.		2	
	ıls, etc.) Metal 1/1 single-hung	-sash, 1-light fixed,	and 5-light awn	ning; tripartite with
central awning a	and fixed; some 1980s replace	ments when openings a	ıltered	
	ectural Features (exterior or interior orname			n east side; enclosed
carport on north	side; porch, carport, and r	orthwest addition hav	re flat roof	
A 111	Valley 9 Program			
•		-		wood fence around property
makes most of ho	ouse not visible; two fence of	ates, one opens to pa	ived driveway	
-545-4	ICE ONLY	SECOLAL EVALUATION	\\	DUD LICE ONLY
DHR U	JSE ONLY C	OFFICIAL EVALUATION	N	DHR USE ONLY
NR List Date	SHPO – Appears to meet criteria for Ni	R listing: Tives Tino Tino	sufficient info Date	te Init
NR List Date	SHPO – Appears to meet criteria for NI KEEPER – Determined eligible:	R listing: □yes □no □ins □yes □no		te Init te
Ancillary Features / C	Outbuildings (record outbuildings, major land ouse not visible; two fence of	Iscape features; use continuation st	heet if needed.) Tall v	wood fence around property


Site #8 \_ BD06341


DESCRIPTION (continued)
Chimney: No. o Chimney Material(s): 1. 2. 3. Structural System(s): 1. Concrete block 2. 3. Foundation Type(s): 1. Continuous 2. Foundation Material(s): 1. Concrete Block 2. Main Entrance (stylistic details) East-facing 1980s 4-light panel door under entry porch south of enclosed carport
Porch Descriptions (types, locations, roof types, etc.) Entry porch under flat roof overhang south of enclosed carport with simple metal support
Condition (overall resource condition):     excellent   Image: Im
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys)       ☐ library research       ☐ building permits       ☐ Sanborn maps         ☐FL State Archives/photo collection       ☐ city directory       ☐ occupant/owner interview       ☐ plat maps         ☑ property appraiser / tax records       ☐ newspaper files       ☐ neighbor interview       ☐ Public Lands Survey (DEP)         ☐ cultural resource survey (CRAS)       ☐ historic photos       ☐ interior inspection       ☐ HABS/HAER record search         ☑ other methods (describe)       ☐ Historic aerial photography
Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing individually?  Suppose to meet the criteria for National Register listing individually?  Suppose to meet the criteria for National Register listing individually?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing individually?  Suppose to meet the criteria for National Register listing individually?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the criteria for National Register listing as part of a district?  Suppose to meet the crite
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1
2
DOCUMENTATION
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents    Document type Field maps
2) Document type _Field notes
RECORDER INFORMATION
Recorder Name Janus Research  Recorder Contact Information (address / phone / fax / e-mail)  Affiliation Janus Research  Affiliation Janus Research  (813) 636-8200 / janus@janus-research.com

Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE







## Page 1

☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8 BD06342
Field Date 9-27-2017
Form Date 10-3-2017
Recorder # 20

**Shaded Fields** represent the minimum acceptable level of documentation. Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none)				<b>M</b> ultiple L	isting (DHR only) _	
	at Broward Boulevard Interd				(DHR only)	
	olease check one) 🗷 building 🔲 stru rivate-nonprofit 🗷 private-individual 🔲 priva				us American —foreign	- Lunknoum
Ownershipprivate-profitpr	ivate-nonpront <b>Ex</b> private-individual <b>Expriva</b>	te-nonspecificcity	countystate _	ieuerariwati	ve American Liroreign	LIUTKHOWH
	LOCAT	ION & MAPP				
Street Number			Street Type	Suffix Direc	<u>ction</u>	
Address: 717			Terrace			
	n) NW corner of SW 20th Ter			than Man		
	t lauderdale south  t lauderdale In City L					
	42E Section 9 14 section					
Tay Parcel # 5042 00 25	42E <b>S</b> ection 9 <b>74</b> Section	I and	arant	irregulai-Haili	t	
Subdivision Name	0070	Bloc	91ani `k	I	ot	
UTM Coordinates: <b>Z</b> one □1	6 🗷 17 Easting 5 8 3 2 1 1	Northing 2 8 8 8	377			
Other Coordinates: X:	Y:	Coordinate Sy	stem & Datum			
Name of Public Tract (e.g., p	ark)					
		HISTORY				
Construction Vear: 1953	_ ⊠approximately □year list	ed or earlier	ear listed or late	or .		
Original Use Private Res		Erom (vear).	1953	To (vear).		
Current Use Private Res	sidence (House/Cottage/Cabin	From (year):		To (year):	2017	
Other Use		From (year):		To (year):		
Moves:  □yes 🗷 no □	unknown Date:O	riginal address				
Alterations:			windows and	doors		
Additions: ☐yes ☒no ☐	unknown Date: N	ature				
Architect (last name first): unkn	own	Builder (last	name first): unki	nown		
Ownership History (especially of	original owner, dates, profession, etc.)					
Is the Descuree Affected by	a Local Preservation Ordinance?	vos <b>V</b> no <b>D</b> unkno	wn Doscribo			
is the Resource Affected by a	1 Eocal i reservation ordinance:	lyes Milo Mulikilo	WII DESCRIBE			
	DE	SCRIPTION				
Style Masonry Vernacul	ar Exte	ior Plan Ishaped			Number of Stories	1
Fyterior Fabric(s) 1 Studge	o 2	ioi i iaii <u>ii shapea</u>		3	_Number of Stories	
Roof Type(s) 1. Hip	2. 1			3.		
Roof Material(s) 1. Compos	sition shingles 2. I	Built-up		3		
Roof secondary strucs.	(dormers etc.) 1.		2			
Windows (types, materials, etc.)	Metal 1/1 single-hung-sash	and 2-light fix	xed; triple	window left	t of front door	
	eatures (exterior or interior ornaments)		exterior, p	olain stucc	o window surrou	ınds;
carport on north side	has flat roof with simple m	etal supports				
Anaillany Faaturas / Outhuildi	ings (	-1	-l			
	ings (record outbuildings, major landscape for coperty; chain-link fence ar		sneet if needed.)	Intormal gr	ravel driveway i	Ln
northeast corner of p	ropercy; charm-link rence ar	ound property				
	NI V	IAL EVALUATIO	NA I	DI	ID LICE ONLY	
DHR USE O	NLY OFFIC	IAL EVALUATIO	ON	DH	IR USE ONLY	
	NLY OFFIC  — Appears to meet criteria for NR listing				IR USE ONLY	
NR List Date SHPC		:  yes  no  in		Date	Init	

# HISTORICAL STRUCTURE FORM

Site #8 \_ BD06342

DESCRIPTION (continued)
Chimney: Noo_ Chimney Material(s): 1
Porch Descriptions (types, locations, roof types, etc.) Entry porch with concrete stoop under flat roof of carport with simple metal supports
Condition (overall resource condition):     Excellent   Signature   Signature
Archaeological RemainsCheck if Archaeological Form Complete
RESEARCH METHODS (check all that apply)
☑FMSF record search (sites/surveys)
OPINION OF RESOURCE SIGNIFICANCE
Appears to meet the criteria for National Register listing individually?   Appears to meet the criteria for National Register listing as part of a district?   Byes Ino Dissufficient information  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in South  Florida. It is in the Riverside Park neighborhood, which is a historic African-American neighborhood. The
neighborhood lacks integrity with several alterations, demolitions, and in-fills.  Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1 5 5
2 4 6
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  Document type Field maps Maintaining organization Janus Research  File or accession #/s
Document description File or accession #'s
RECORDER INFORMATION
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com  (address/phone/fax/e-mail)


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

If submitting an image file, it must be included on disk or CD <u>AND</u> in hard copy format (plain paper is acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.







## Page 1

☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06343			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	19			

**Shaded Fields** represent the minimum acceptable level of documentation. Consult the *Guide to Historical Structure Forms* for detailed instructions.

	Multiple Listing (DHR only)	
Survey Project Name 1-95 at Broward Boulevard In		
National Register Category (please check one) Subuilding		
Ownersnip: I private-profit I private-nonprofit I private-individual I	□private-nonspecific □city □county □state □federal □Native American □foreign □u	nknown
LOG	CATION & MAPPING	
Street Number Direction Street Name	Street Type Suffix Direction	
Address: 1914 SW 8th	Street	
Cross Streets (nearest/between) S side btwn SW 20th Te		
USGS 7.5 Map Name FORT LAUDERDALE SOUTH	USGS Date 1983 Plat or Other Map City Limits? ■ yes □ no □ unknown County Broward	
Toy Parcel # 5040 00 05 0050	section: NW SW SE NE Irregular-name:	
Cubdivision Nama	Latiuytatil Rlock lat	
IITM Coordinates: 7 one 1716 X17 Fasting 5 8 3 2 3	Landgrant Block Lot Lot	
Other Coordinates: X: Y:	Coordinate System & Datum	
Name of Public Tract (e.g., park)	Coordinate of Storm & Datam	
, , , , , , , , , , , , , , , , , , , ,		
	HISTORY	
Construction Year:1953_ ⊠ approximately □ year	ear listed or earlier	
Original   Separate   Private Residence (House/Cottage/C	Cabin) From (year): 1953 To (year):	
Current Use Private Residence (House/Cottage/C	Cabin) From (year): To (year):	
	From (year): To (year):	
Moves:    yes   no   unknown Date:	Original address	
Alterations: xyes no unknown Date: 1990s	Nature Windows and doors replaced	
Additions: ☐yes ☒no ☐unknown Date:	Nature	
	Builder (last name first): unknown	
Ownership History (especially original owner, dates, profession, etc.)		
Is the Resource Affected by a Local Preservation Ordinance Style Masonry Vernacular	DESCRIPTION  Exterior Plan Rectangular  Number of Stories	1
Is the Resource Affected by a Local Preservation Ordinance  StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco	DESCRIPTION  Exterior Plan Rectangular Number of Stories	1
Is the Resource Affected by a Local Preservation Ordinance  StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable	DESCRIPTION  Exterior Plan Rectangular  2.	1
Is the Resource Affected by a Local Preservation Ordinance  Style Masonry Vernacular  Exterior Fabric(s) 1. Stucco  Roof Type(s) 1. Gable  Roof Material(s) 1. Composition shingles	DESCRIPTION  Exterior Plan Rectangular  2.	1
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1.	DESCRIPTION  Exterior Plan Rectangular  2.	1
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung-s	DESCRIPTION  Exterior Plan Rectangular  2.	1
Style _Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) _Metal 1/1 single-hung-replacements; some boarded up	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 2. Flat 3. 2. Built-up 3. 2. Sash; double window right of front door appear to be 1990s	1
Style _Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) _Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 2. Flat 3. 2. Built-up 3. 2. Sash; double window right of front door appear to be 1990s  Molded stucco "stacked stone" banding on north side;	1
Style _Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) _Metal 1/1 single-hung-replacements; some boarded up	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 2. Flat 3. 2. Built-up 3. 2. Sash; double window right of front door appear to be 1990s  Molded stucco "stacked stone" banding on north side;	1
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 2. Flat 3. 2. Built-up 3. 2. Sash; double window right of front door appear to be 1990s  Molded stucco "stacked stone" banding on north side;	1
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room. Ancillary Features / Outbuildings (record outbuildings, major lands)	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2.	1
Style Masonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.) Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room. Ancillary Features / Outbuildings (record outbuildings, major lands)	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 3. 3. 2. Flat 3. 2. Built-up 3. 3. 2. Sash; double window right of front door appear to be 1990s  and Molded stucco "stacked stone" banding on north side; coof	1
StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.)Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room and the composition of the com	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 3. 3. 2. Flat 3. 2. Built-up 3. 3. 2. Sash; double window right of front door appear to be 1990s  and Molded stucco "stacked stone" banding on north side; coof	1
StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.)Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room and the composition of the com	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 3. 3. 2. Flat 3. 2. Built-up 3. 3. 2. Sash; double window right of front door appear to be 1990s  and Molded stucco "stacked stone" banding on north side; coof	1
StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.)Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room and the composition of the com	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 3. 3. 2. Flat 3. 2. Built-up 3. 3. 2. Sash; double window right of front door appear to be 1990s  and Molded stucco "stacked stone" banding on north side; coof	1
StyleMasonry Vernacular Exterior Fabric(s) 1. Stucco Roof Type(s) 1. Gable Roof Material(s) 1. Composition shingles Roof secondary strucs. (dormers etc.) 1. Windows (types, materials, etc.)Metal 1/1 single-hung-replacements; some boarded up Distinguishing Architectural Features (exterior or interior ornamen carport, porch, and utility room have flat room and the composition of the com	DESCRIPTION  Exterior Plan Rectangular Number of Stories  2. 3. 2. Flat 3. 2. Built-up 3. 2. Sash; double window right of front door appear to be 1990s  Molded stucco "stacked stone" banding on north side; coof  Coape features; use continuation sheet if needed.) Molded stucco "stacked stone" gravel driveway on northeast corner of property; chain-link  FFICIAL EVALUATION DHR USE ONLY	1

# HISTORICAL STRUCTURE FORM

Site #8 \_ BD06343

DESCRIPTION (continued)	
Chimney: Noo_Chimney Material(s): 1	
Porch Descriptions (types, locations, roof types, etc.) Entry porch under flat roof with simple metal supports; molded stucco "stacked stone" low wall on north and west sides	
Condition (overall resource condition): Dexcellent    good	
Archaeological Remains Check if Archaeological Form Comp	oleted
RESEARCH METHODS (check all that apply)	
☑FMSF record search (sites/surveys)	
OPINION OF RESOURCE SIGNIFICANCE	
Appears to meet the criteria for National Register listing individually?  Appears to meet the criteria for National Register listing as part of a district?  I yes  Ino  Insufficient information  Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)  This residence is of a common style in South  Florida. It is in the Riverside Park neighborhood, which is a historic African-American neighborhood. The  neighborhood lacks integrity with several alterations, demolitions, and in-fills.	·
Area(s) of Historical Significance (see <i>National Register Bulletin 15</i> , p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)  1	
2	
DOCUMENTATION	
Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents  1) Document type Field maps Maintaining organization Janus Research  Occument description File or accession #'s	
2) Document type Field notes Maintaining organization Janus Research Document description File or accession #'s	
RECORDER INFORMATION	
Recorder Name Janus Research  Recorder Contact Information 1107 N. Ward St., Tampa FL 33607 / (813) 636-8200 / janus@janus-research.com  (address/phone/fax/e-mail)	


Required Attachments

- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

If submitting an image file, it must be included on disk or CD <u>AND</u> in hard copy format (plain paper is acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.







# Page 1

☑ Original
☐ Update



# HISTORICAL STRUCTURE FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

<b>S</b> ite #8	BD06344			
Field Date	9-27-2017			
Form Date	10-3-2017			
Recorder #	18			

**Shaded Fields** represent the minimum acceptable level of documentation. Consult the *Guide to Historical Structure Forms* for detailed instructions.

	fnone) 1910 SW 8th Street				_isting (DHR only) _	
	I-95 at Broward Boulevard I				(DHR only)	
	egory (please check one)  building ofit  private-individual				ive American Inforeign	Hunknown
Ownership: Dphvate-pr					Ne American Libreign	driknown
		CATION & MAP		0		
Address: Street Numb	<u>Direction</u> <u>Street Name</u> <b>SW 8th</b>		Street Type Street		ction	
	between) S side btwn SW 20th T	rer and Riverside I				
	FORT LAUDERDALE SOUTH			Other Map		
	es) <u>Fort Lauderdale</u> In					
Township <u>50s</u> F	Range 42E Section 9 1/4	section: □NW □SW	V □SE □NE	Irregular-nam	e:	
Tax Parcel # 5042	09 25 0040	La	ndgrant			
Subdivision Name	ne □16 区17 Easting 5 8 3 2	El 7 Northing 2 9 6	lock	I	Lot	
Other Coordinates: X	:: Y: Y:	Coordinate	<u>31417</u> Svstem & Datun	n		
Name of Public Tract	(e.g., park)	Coordinate	System & Datum			
		HISTORY				
Construction Year	1955 <b>⊠</b> approximately □ ye	ear listed or earlier	Tyear listed or la	ater		
Original Use Triple		_ , ,	:1955			
	ex	From (year)	:	To (year):	2017	
Other Use		From (year)	:	To (year):		
	no Date:	<pre> Original address Nature Replace</pre>	a			
Alterations:		Nature	d windows and			
Architect (last name first	); <u>unknown</u>	Builder (	last name first): un	.known		
Ownership History (es	pecially original owner, dates, profession, etc.)					
Is the Resource Affec	ted by a Local Preservation Ordinanc	e? □yes <b>⊠</b> no □unk	known Describe	<u> </u>		
		DESCRIPTION	V			
Ch. I					Normalis and Charles	
Style Masonry Ver	rnacular Stucco	EXTERIOR Plan Rectan	ıgular	2	_Number of Stories	1
Roof Type(s) 1	Gable	- <sup>2</sup> ·		3		
Roof Material(s) 1.	Composition shingles	2		3		
Roof secondary :	strucs. (dormers etc.) 1.		2			
Windows (types, materia	ls, etc.) Metal 1/1 single-hung	-sash; several doub	ole windows;	appear to b	e 1980s replace	ments
Diation viabion Anabita	at wal Factories ( ) is a second					
vents	ctural Features (exterior or interior orname	nts) Molded stucco	"stacked sto	one" banding	on north side;	<u>attic</u>
Venes						
Ancillary Features / O	utbuildings (record outbuildings, major land	scape features; use continuati	ion sheet if needed.)	Gravel park	ing area in nor	theast
corner of proper	ty					
	IOE ONLY	EELOLAL EVALUE	FIGN		ID HOE ONLY	
DHR U	JSE ONLY C	PFFICIAL EVALUAT	ION	DH	IR USE ONLY	
NR List Date	SHPO – Appears to meet criteria for NF	R listing: □yes □no [	insufficient info	Date	Init	
	KEEPER – Determined eligible:	□yes □no		Date		
☐Owner Objection	NR Criteria for Evaluation: ☐a ☐b	□c □d (see <i>Natio</i>	nnal Register Bullet	<i>tin 15</i> , p. 2)		

# HISTORICAL STRUCTURE FORM

Site #8 \_ BD06344

	DESCRIPTION	DN (continued)	
Chimney: Noo_ Chimney Material( Structural System(s): 1. Concret Foundation Type(s): 1. Continu Foundation Material(s): 1. Concret Main Entrance (stylistic details) One no porch with concrete stoop  Porch Descriptions (types, locations, roof ty entrances	e Block 2 rth-facing, one west-facin pes, etc.) Recessed entry porc	g, one east-facing; 1980s	panel doors under recessed
Condition (overall resource condition):   Narrative Description of Resource   T			few alterations.
Archaeological Remains			□Check if Archaeological Form Completed
	RESEARCH METHO	DS (check all that apply)	
<ul> <li>☑FMSF record search (sites/surveys)</li> <li>☐FL State Archives/photo collection</li> <li>☑property appraiser / tax records</li> <li>☐cultural resource survey (CRAS)</li> <li>☑other methods (describe)</li> <li>☐Historic</li> <li>Bibliographic References (give FMSF main</li> </ul>	□library research □city directory □newspaper files □historic photos □ aerial photography	□ building permits □ occupant/owner interview □ neighbor interview □ interior inspection	☐ Sanborn maps ☐ plat maps ☐ Public Lands Survey (DEP) ☐ HABS/HAER record search
	OPINION OF RESOUL	RCE SIGNIFICANCE	
Appears to meet the criteria for National Appears to meet the criteria for National Explanation of Evaluation (required, when Florida. It is in the Riversian neighborhood lacks integrity Area(s) of Historical Significance (see An Area (see	al Register listing as part of a district the significant or not; use separate sheet if de Park neighborhood, which with several alterations,	Ct?yesxnoinsuffi needed)This triplex is of h is a historic African-And demolitions, and in-fills.	nerican neighborhood. The
1	3	5	
2	4	6	
	DOCUMEN	NTATION	
Accessible Documentation Not Filed w  1) Document type Field maps Document description  2) Document type Field notes Document description	ith the Site File - including field notes, a Ma F Ma	nalysis notes, photos, plans and other impaintaining organization	
	RECORDER IN	FURMATION	
Recorder Name Janus Research Recorder Contact Information 1107 (address / phone / fax / e-mail)	N. Ward St., Tampa FL 3360		s@janus-research.com

Required Attachments


- **1** USGS 7.5' MAP WITH STRUCTURE LOCATION PINPOINTED IN RED
- **②** LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- 3 PHOTO OF MAIN FACADE, ARCHIVAL B&W PRINT OR DIGITAL IMAGE FILE

If submitting an image file, it must be included on disk or CD <u>AND</u> in hard copy format (plain paper is acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.









#### Page 1

☑Original ☐Update



# RESOURCE GROUP FORM FLORIDA MASTER SITE FILE

Version 4.0 1/07

Site #8	BD06347
Field Date_	9-27-2017
orm Date	10-3-2017
Recorder#	2.4

NOTE: Use this form to document districts, landscapes, building complexes and linear resources as described in the box below. Cultural resources contributing to the Resource Group should also be documented individually at the Site File. Do not use this form for National Register multiple property submissions (MPSs). National Register MPSs are treated as Site File manuscripts and are associated to the individual resources included under the MPS cover using the Site File manuscript number.

Check ONE box that best describes the Resource Group:  Historic district (NR category "district"): buildings and NR structures only: NO archaeological sites  Archaeological district (NR category "district"): archaeological sites only: NO buildings or NR structures  Mixed district (NR category "district"): includes more than one type of cultural resource (example: archaeological sites and buildings)  Building complex (NR category usually "building(s)"): multiple buildings in close spatial and functional association  Designed historic landscape (NR category usually "district" or "site"): can include multiple resources (see National Register Bulletin #18, page 2 for more detailed definition and examples: e.g. parks, golf courses, campuses, resorts, etc.)  Rural historic landscape (NR category usually "district" or "site"): can include multiple resources and resources not formally designed (see National Register Bulletin #30, Guidelines for Evaluating and Documenting Rural Historic Landscapes for more detailed definition and examples: e.g. farmsteads, fish camps, lumber camps, traditional ceremonial sites, etc.)  Linear resource (NR category usually "structure"): Linear resources are a special type of rural historic landscape and can include canals, railways, roads, etc.
Resource Group Name salvation Army Complex
LOCATION & MAPPING
Street Number   Direction   Street Name   Street Type   Suffix Direction    Address: 1901   W   Broward   Boulevard    City/Town (within 3 miles)   Fort Lauderdale   In Current City Limits?   Syes □ no □ unknown    County or Counties (do not abbreviate)   Broward    Name of Public Tract (e.g., park)
1) Township 50S Range 42E Section 4 1/4 section: NW SW SE NE Irregular-name:  2) Township Range Section 1/4 section: NW SW SE NE  3) Township Range Section 1/4 section: NW SW SE NE  4) Township Range Section 1/4 section: NW SW SE NE  4) Township Name Section 1/4 section: NW SW SE NE  USGS 7.5' Map(s) 1) Name FORT LAUDERDALE SOUTH USGS Date 1983  2) Name USGS Date 1983
Plat, Aerial, or Other Map (map's name, originating office with location)  Landgrant
Verbal Description of Boundaries (description does not replace required map)Bounded by I-95 to the west, West Broward Boulevard
to the south, the North Fork of the New River to the east and north, and the North Fork Riverfront Park in the northeast corner.
DHR USE ONLY OFFICIAL EVALUATION DHR USE ONLY
NR List Date SHPO – Appears to meet criteria for NR listing: SHPO – Appears to

## **RESOURCE GROUP FORM**

	HISTORY & DE	SCRIPTION	
Construction Year: <u>1957</u> ■ approxima Architect/Designer(last name first): <u>unknown</u> Total number of individual resources included i	tely  year listed or earli	eryear listed or later Builder(last name first): _unkn	own
Total number of individual resources included i Time period(s) of significance (choose a period from 1Twentieth C American	n the list or type in date range(s), e.	g. <i>1895-1925</i> )	
2	4		
Narrative Description (National Register Bulletin 16A	pp. 33-34; fit a summary into 3 lines	s or attach supplementary sheets if needed)	See continuation sheet.
RESI	EARCH METHODS	(check all that apply)	
■FMSF record search (sites/surveys)	□library research	□building permits	□Sanborn maps
■FL State Archives/photo collection	□city directory	□occupant/owner interview	□plat maps
■property appraiser / tax records □cultural resource survey	<ul><li>□newspaper files</li><li>□historic photos</li></ul>	☐neighbor interview☐interior inspection	□Public Lands Survey (DEP) □HABS/HAER record search
▼other methods (specify) Historic aeria	al photography	·	
Bibliographic References (give FMSF Manuscript #	ifrelevant) <u>See continuat</u>	ion sheet.	
OPI	NION OF RESOUR	CE SIGNIFICANCE	
Potentially eligible individually for National Reg Potentially eligible as contributor to a National Explanation of Evaluation (required, see <i>National Research</i> ).	Register district? egister Bulletin 16A p. 48-49. Attach	yes ⊠no ∏insufficient infi yes ⊠no ∏insufficient infi longer statement, if needed, on separate s	ormation
Breec.			
Area(s) of Historical Significance (see <i>National Re</i>	raictor Pullatin 15 p. 0 for catagories	o a "architacture" "othnic heritage" "com	amunity planning 8 dayslanment" etc.)
1	3	5. <u></u> 5	indinity planning a development, etc.)
2	4	6	
	DOCUMEN	TATION	
Accessible Documentation Not Filed with the S	ite File - including field notes, ana	alysis notes, photos, plans and other importa	ant documents
1) Document type Field maps Document description			
Document type Field not og		taining organization Janus Research	
7)	File		
	RECORDER INF	FORMATION	
Recorder Name Janus Research		Affiliation Janus Research	
Recorder Contact Information			janus-research.com

# Required Attachments

- PHOTOCOPY OF USGS 7.5' MAP WITH DISTRICT BOUNDARY CLEARLY MARKED
- 2 LARGE SCALE STREET, PLAT OR PARCEL MAP WITH RESOURCES MAPPED & LABELED
- **3** TABULATION OF ALL INCLUDED RESOURCES (name, FMSF #, contributing? Y/N, resource category, street address or township-range-section if no address)
- PHOTOS OF GENERAL STREETSCAPE OR VIEWS (Optional: aerial photos, views of typical resources) Photos may be archival B&W prints <u>OR</u> digital image files. If submitting digital image files, they must be included on disk or CD <u>AND</u> in hard copy format (plain paper is acceptable). Digital images must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.

#### A. NARRATIVE DESCRIPTION OF SITE

This resource group is comprised of seven concrete block Masonry Vernacular and two metal frame Industrial Vernacular style building located on an approximately 14.5-acre property at 1901 W Broward Boulevard in Section 4 of Township 50 South, Range 42 East on the Fort Lauderdale South (1962, photorevised 1983) United States Geological Survey (USGS) quadrangle map. The property is bounded by I-95 to the west, W Broward Boulevard to the south, the North Fork Riverfront Park in the northeast corner, and the North Fork of the New River to the east and north. Although the historic buildings were likely associated with demolished historic buildings west of the boundaries, much of the area around the intersection of W Broward Boulevard and the Seaboard Air Line (CSX) Railroad (8BD4649) was affected by the construction of I-95. Since the buildings in the area that may have been associated with the extant historic buildings were demolished for I-95, the current western boundary for the Salvation Army Complex follows I-95, which curves in a northwest-southeast direction.

Most of the property is paved, with landscaping around the buildings, and the edges of the property. Four of the Masonry Vernacular building are historic, and the other seven buildings on the complex are non-historic. Two buildings are located within the project APE, the c. 1967 Adult Rehabilitation Center and the c. 2000 Super Store. The Adult Rehabilitation Center is the largest building on the complex, and portions of the building serve as storage, auction area, and the donation drop off location.

The development of the Salvation Army Complex and the area around it has been gradual. The original use of the property is unknown, but the Salvation Army obtained the property in 1980 (Broward County 1980). A review of historic aerials shows that four of the Masonry Vernacular buildings are historic. The oldest building on the complex, Warehouse 1, can be seen in the 1958 aerial (Figure 1). By 1968, five more buildings were constructed: Warehouse 2, Warehouse 3, the Adult Rehabilitation Center, and two smaller buildings in the northwest and southeast corners of the property that were demolished in the 1990s (Figure 2). The 1958 and 1968 aerials also show a building next to the railroad that may have been a train station, but this building and three others that may have been associate with the Salvation Army Complex were demolished in the 1970s when I-95 was built. By 1988, Warehouses 4 and 5 and Offices 1 and 2 were constructed (Figure 3). A current aerial shows the addition to the Adult Rehabilitation Center, c. 1990, and the Super Store, c. 2000 (Figure 4).



Figure 1: 1958 aerial of Salvation Army Complex (8BD6347)



Figure 2: 1968 aerial of Salvation Army Complex (8BD6347)



Figure 3: 1988 aerial of Salvation Army Complex (8BD6347)




Figure 4: Current aerial of Salvation Army Complex (8BD6347), property boundaries in red



Figure 5: Salvation Army Complex (8BD6347), Warehouse 1, c. 1957, looking North

#### Warehouse 1

Warehouse 1 is the oldest building on the complex having been constructed c. 1957 (Figure 5). This one and a half story Masonry Vernacular warehouse was built in two phases. The west half of the building was completed c. 1957, and shortly after in 1958 the east half of the building was completed. The building is constructed of concrete block painted white. There are nine bays with rolling garage doors on each of the north and south sides. The windows on the west end of the building have iron security bars, which make it impossible to see what style the windows are. There is a set of stairs with a small platform leading to a metal door on the west side. That is the only known entrance, because the east side of the building is not visible. There are flat roof overhangs on the north, east, and south sides of the east half of the building. The building has a flat built-up roof.



Figure 6: Salvation Army Complex (8BD6347), Warehouse 2, c. 1967, looking Northwest

#### Warehouse 2

This one and a half story Masonry Vernacular building sits just south of Warehouse 1. It was constructed c. 1967 of concrete block covered in white stucco (Figure 6). There are two bays with rolling garage doors on each of the north and south sides. The building has no windows, and there is no other visible entrance. The west end of the building is only one story tall with no windows or doors, and its purpose is unclear. The building has a flat, built-up roof.

#### Warehouse 3

This one and a half story Masonry Vernacular building sits just north of Warehouse 1. It has a simple form and was constructed c. 1967 of concrete block with a shed roof overhang on the north side. There are three loading bays on the north side. The main entrance is a west-facing panel door in the southwest corner. There are two double windows and three single windows on the west side. Iron security bars cover the windows. The south side of the building is blank, and the east side is not visible. The building has a flat, built-up roof.



Figure 7: Salvation Army Complex (8BD6347), Adult Rehabilitation Center, c. 1967, looking Northeast

#### Adult Rehabilitation Center

This Masonry Vernacular building sits southeast of Warehouses 1 and 2, at the northwest corner of W Broward Boulevard and NW 18<sup>th</sup> Avenue. It was once a warehouse, but is currently used as the Salvation Army Adult Rehabilitation Center (Figure 7). This building was constructed c. 1967 of concrete block and is covered in brick painted grey. It has always been irregularly shaped, originally having four large connected massings. The two-story portion of the building in the northwest corner was likely the original office. It has evenly spaced one-over-one single-hung-sash windows on the east side of the second story. The west side has several single door entrances on the first floor and double windows on the second floor. There are only two windows on the south side of the second story. All the windows sit under flat roof overhangs.

The one-story, L-shaped massing south of the two-story office is currently used as the entrance to the Adult Rehabilitation Center. It has one-light fixed windows on the south side. A concrete screen wall encloses the uncovered patio. There is a large Salvation Army sign on the southern concrete screen wall. A single, south-facing commercial glass door with transom and side light serves as the only entrance from the building to the uncovered patio. The building's main entrance sits under a flat roof overhang supported by one large concrete block column. The south-facing commercial glass double door has storefront windows surrounding it. A secondary entrance sits under the same roof

overhang. It is a simpler east-facing commercial glass door with a transom and no side lights. There is landscaping around this portion of the building with shrubs and trees lining the south side, entrance, and uncovered patio.

The central and east portions of the building were originally warehouses with loading bays on the north and south sides. The central portion is five bays wide. The bays have been enclosed with what appears to be plywood painted grey to match the brick. There is a small roof overhang above the bays. The original north side bays are no longer visible due to a large addition completed c. 1990. The north and west sides of the addition are not visible. However, from NW 18<sup>th</sup> Avenue three single metal door entrances and one loading bay are visible on the east side of the addition. No windows are visible. There are two doors and a bay recessed in a raised loading dock on the east side of the original central portion of the building. The large north addition is currently used as the "as is" auction area.

The original east portion of the building was extended south c. 1980, so that its south side was in line with the south side of the central portion of the building. The extension is five bays wide like the central portion. On the east side of the extension, which is not in line with the original east side, has a metal double door entrance. The original east side is blank except for three one-light fixed windows. There are flat roof overhands along the south and east sides of the east portion. The north side continues to be used as a loading dock, as this is currently the donation drop off location. The raised loading dock is L-shaped along the north side of the east portion and the east side of the original central portion of the building. Due to low visibility it's unclear exactly how many bays are recessed in the raised loading dock, but there are at least two bays. One bay is east-facing, and the other is north-facing. The loading dock has a flat roof extension with four supports along the north side, and a ramp at the northeast corner.

All portions and additions of the building have flat, built-up roofs Most of the area around the Adult Rehabilitation Center has been paved for parking and loading. There have been several alterations and addition to this building. Most of the windows appear to have been replaced in the 1980s. The main south-facing entrance was likely altered to accommodate the 1980s commercial glass double doors and window wall. Many other doors also appear to be 1980s replacements. Despite substantial additions and surrounding development, the south front of the building retains much of its historic feel.



Figure 8: Salvation Army Complex (8BD6347), Warehouse 4, c. 1985, looking West

#### Warehouse 4

This Industrial Vernacular building sits just north of the Adult Rehabilitation Center. It has a simple form and was constructed c. 1985 with a metal steel frame covered in metal siding. The north and south sides are blank with no window or door openings. The west side of the building is not visible. The east side has a simple metal door in the southeast corner with a two-light sliding window to its right. There are also two large bays with rolling garage doors on the east side. The roof is side-gabled and covered in standing seam metal sheets.

#### Warehouse 5

This Masonry Vernacular building sits just west of Warehouse 1. It has a simple form and was constructed c. 1985 of concrete block covered in stucco. The north and south sides are blank with no window or door openings. The north side is longer than south side, so that the slanted west side is parallel to the I-95 ramp west of it. The west side of the building is not visible and backs up to a line of trees and I-95. The east side has two metal doors, two widows, and two loading bays with rolling garage doors. The loading bays are in the northeast and southeast corners. The windows are one-light fixed and covered in metal security bars. The building has a flat, built-up roof.



Figure 9: Salvation Army Complex (8BD6347), Office 1, c. 1978, looking Northwest

# Office 1

This Industrial Vernacular building sits just northwest of Warehouse 4 (Figure 9). It has a simple form and was constructed c. 1978 with a metal steel frame covered in metal siding. The northwest side is blank with no window or door openings. The northeast side has six five-light awning windows, three in the center and three on the left side. The southwest side is not visible. The entrance is a simple metal door on the southeast side, which sits under a canvas awning. There is a similar awning over the three windows. The three windows are five-light awning similar to those on the northeast side. The front-gabled roof is covered in 5V crimped metal sheets.



Figure 10: Salvation Army Complex (8BD6347), Office 2, c. 1985, looking West

#### Office 2

This two-story Masonry Vernacular building sits in the northwest corner of the property along the North Fork of the New River (Figure 10). It was constructed c. 1985 of concrete block and is covered in grey stucco. The building has an irregular form, and the west portion of the building was formerly a warehouse. The north and west sides of the building are not visible. The east portion of the building is only one-story tall, and contains both the main and secondary entrances recessed along its south side. The east side has four recessed bays with metal, one-light fixed windows at the top. The eastfacing main entrance is a metal door with a square light recessed in the southeast corner under a canvas awning. There are four south-facing thin vertical windows recessed in the same space. The south-facing secondary entrance is a simple metal door to the left of the main entrance. It is also recessed and has a canvas awning. There were originally seven bays along the south side of the two-story portion of the building. Only the bay in the southwest corner has remained altered. The one directly to the right of it was completely enclosed with plain stucco. Each of the remaining five bays to the right were enclosed with scored stucco and a row of five four-light awning windows at the top. Both portions of the building have a flat, built-up roof.



Figure 11: Salvation Army Complex (8BD6347), Super Store, c. 2000, looking Northeast

#### Super Store

This Masonry Vernacular building sits just east of the Adult Rehabilitation Center, at the northeast corner of W Broward Boulevard and NW 18<sup>th</sup> Avenue. The Super Store was constructed c. 2000 of concrete blocked and covered in stucco. The building is generally rectangular; however, the southwest and southeast corners extend out slightly. There are storefront windows that run from just north of and around the southwest corner, along the south side, around the southeast corner, and ending just north of the southeast corner. There are metal awnings over the windows. The south-facing commercial glass double doors with transom and side lights sits amongst the storefront windows under a portico. A two-story entry portico is located centrally along the south side, and is taller than the rest of the building. Other than the storefront windows, the east and west sides are blank with no other openings. The north side has a simple metal door and a loading bay with rolling garage door in the northeast corner. There are stucco walls around the AC units on the north side. Most of the area around the Super Store is paved for parking. The building has a flat, built-up roof.

#### B. DISCUSSION OF SIGNIFICANCE

The Salvation Army was founded in London in 1865 by William Booth (Salvation Army 2014). He was dedicated to working with the poor and homeless. In 1879 the Salvation

Army came to the United States starting in Philadelphia before quickly expanding into New York (Salvation Army 2014). The organization was instrumental in both World Wars in providing help to soldiers and civilians alike.

In Broward County, Ivy Stranahan helped establish the Salvation Army in 1926 and was one of its original board members (Salvation Army 2014). Today, the group owns several properties throughout Broward County. They acquired the property discussed here in 1980. The historic buildings on the property had served a different purpose before that is unclear. Despite the proximity to the Seaboard Air Line (CSX) Railroad (8BD4649), the building complex does not appear associated with the railroad.

The Industrial Vernacular and Masonry Vernacular styles are highly prevalent approaches to architectural design for industrial complexes in Florida and the Salvation Army Complex buildings are common examples of the styles from their period and place of construction. Of the nine buildings within the complex, four are historic. The area around the complex has been substantially altered through the 1970s construction of I-95 and the development along Broward Boulevard. Additionally, the four historic Masonry Vernacular buildings have sustained substantial alterations. Therefore, the Salvation Army Complex located at 1901 W Broward Boulevard is considered National Register—ineligible under Criteria A, B, C, or D, both individually and as part of a historic district.

# C. HISTORY AND BIBLIOGRAPHY OF PAST WORK AT SITE

#### Broward County, Records, Taxes and Treasury Division

1980 Special Warranty Deed. Granted by William R. Robbins (a.k.a. W. R. Robbins) to The Salvation Army, Inc., a Georgia corporation. For the portions of Section 4 of Township 50 South, Range 42 East, which make up the Salvation Army Complex.

#### Florida Department of Transportation

2017 Aerial Photography. APLUS: Aerial Photo Look Up System. Photographs from 1973, 1984, 1993, 2000, 2009 and 2016 Collier County flights. Electronic documents, https://fdotewp1.dot.state.fl.us/AerialPhotoLookUpSystem/, accessed October 3, 2017.

#### The Salvation Army, Broward County


Our History. Subpage of the Main Salvation Army website. Webpage accessed on October 4, 2017, at http://www.salvationarmyflorida.org/fortlauderdale/about-us/our-mission.

#### University of Florida, George A. Smathers Libraries


Aerial Photography: Florida Collection. Photographs from 1953 and 1963 Collier County flights. University of Florida Digital Collections. Electronic documents, http://ufdc.ufl.edu/aerials, accessed October 3, 2017.

# PHOTOGRAPH










# **PHOTOGRAPH**




# **PHOTOGRAPH**









Appendix B | SHPO Letters for FMSF Survey Nos. 19752 and 20623

## Florida Department of Transportation

RICK SCOTT GOVERNOR

Ms. Linda Anderson

Florida Division Office

U.S. Department of Transportation Federal Highway Administration

545 John Knox Road, Suite 200 Tallahassee, Florida 32303

3400 W. Commercial Blvd. Fort Lauderdale, FL 33309

January 29, 2013

ANANTH PRASAD, P.E.
SECRETARY
BURE AU OF
BURE AU OF
BURE AU OF
3: 1-9

Subject:

Request for Review

Cultural Resource Assessment Survey (CRAS)

SR 9/I-95 from SR 848 (Stirling Road) to north of SR 816 (Oakland Park Boulevard)

Financial Management Number: 429804-1-22-01

ETDM Number: 13168 Broward County, Florida

Dear Ms. Anderson:

FDOT, District 4 is currently conducting a Project Development & Environment (PD&E) study for the proposed widening of SR-9/I-95 in Broward County, Florida. The limits of the project are from Stirling Road to north of Oakland Park Boulevard. The primary purpose of the project is to relieve congestion along the I-95 corridor by converting the existing High Occupancy Vehicle (HOV) lanes to tolled express lanes and adding one additional lane to the median, in each direction. All improvements will be constructed within current FDOT right of way (ROW). This CRAS was undertaken in order to locate and evaluate archaeological and historic resources within the Area of Potential Effect (APE) and to assess eligibility for inclusion in the National Register of Historic Places (NRHP) according to criteria set forth in 36 CFR 60.4.

No newly or previously recorded archaeological sites were identified within the project APE. The historic resources survey resulted in the identification of four previously recorded historic resources and one newly recorded resource within the APE. The resources include one cemetery, one roadway section, one railroad, and two canals. Florida Master Site File (MSF) forms were not updated for three of the previously recorded resources, as they were found to be unchanged since their recordation. The MSF form for the Seaboard Air Line (CSX) Railroad was updated. Previously recorded segments of this resource have been determined to be eligible for listing on the NRHP. The segment that is the subject of this CRAS is also considered eligible for listing. The newly recorded resource, the North Woodlawn Cemetery, is also considered eligible for listing in the NRHP. A Determination of Eligibility (DOE) for the cemetery is included with this CRAS.

SR-9 (I-95) FM 429804.1 Cultural Resources Assessment Survey

A reconnaissance survey was also undertaken in order to identify any significant historic resources adjacent to the current I-95 ROW. The reconnaissance survey resulted in the identification of four previously recorded historic resources, one of which is currently listed (Link Trainer Building) and two of which are considered eligible for listing (CSX Railroad Station and the CSX Railroad Bridge). The Dania Canal Railroad Bridge was determined ineligible for listing in 1999; however, this resource should be reevaluated, as it is likely a contributing resource to a potential CSX Railroad linear historic district.

Please complete the signature block below and forward the additional report copy to SHPO. If you have questions regarding the subject project, please contact me at 954-777-4325, or Lynn Kelley at 954-777-4334.

Sincerely,

Ann Broadwell

Environmental Administrator

FDOT - District 4

Enclosures

Cc: Ray Hol

Ray Holzweiss-District Four

Roy Jackson - CEMO

Project File

SR-9 (I-95) FM 429804.1 Cultural Resources Assessment Survey

The FHWA finds the attached Cultural Resources Assessment Report complete and sufficient and **☆** approves / \_\_\_ does not approve the above recommendations and findings.

The FHWA requests the SHPO's opinion on the sufficiency of the attached report and the SHPO's opinion on the recommendations and findings contained in this cover letter and in the comment block below.

### **FHWA Comments:**

SEE ATTACHED FHUA COMMONTS FOOT PESPONSES OF 3-20-73.
PUERSE ADDRESS COMMENTS OPIDION TO LINDA AMBERSON FIRMA.
P: 850-553-2226. E: link, anderson edst.gov. PLEASE CC:
LYUL KELLEY FLOT DY; MARK CLASGENS PHWA. 2 ROY JACKSON, FOUT COMO.

David C. Hawk

**Acting Division Administrator** Florida and Puerto Rico Divisions Federal Highway Administration

Date

The Florida State Historic Preservation Officer finds the attached Cultural Resources Assessment Report complete and sufficient and concurs with the recommendations and findings provided in this cover letter for SHPO/DHR Project File Number 2013-897

Robert Bendus

Director, and State Historic Preservation Officer

Florida Division of Historical Resources

### Anderson, Linda (FHWA)

From:

Anderson, Linda (FHWA)

Sent:

Wednesday, March 06, 2013 12:06 PM

To:

Kelley, Lynn (Lynn.Kelley@dot.state.fl.us)

Cc:

Jones, Ginny L. (Ginny.Jones@DOS.MyFlorida.com); 'Jackson, Roy'

Subject: CRAS for SR 9/I-95 from Stirling Road to North of Oakland Park Blvd., FM # 42980412201

FHWA has reviewed the CRAS for SR 9/I-95 from Stirling Road to North of Oakland Park Blyd., FM # 42980412201, and has the following comments:

- 1. Does this CRAS clear drainage facilities? Please note pond on plan sheet 8 in area of high site potential. Is this an existing pond or a planned pond? If planned, was it tested for archaeological resources in a previous CRAS? If not, why wasn't it tested during this CRAS?
- 2. FHWA's understanding of this project is that the outer edges of outer lanes will not move; instead, lanes will be added in the median. If this is the case, why was shovel testing done outside of lanes, especially in areas where FDOT ROW appears to be too narrow for ponds?
- 3. Per page 69, no shovel testing was done in areas of low archaeological probability. Per Roy Jackson, low probability zones should have a 100m testing interval with judgment exercised as there are a number of acceptable reasons for not digging in low probability zones. Please test areas of low probability or provide a detailed explanation about why shovel testing is not appropriate in these areas.

FHWA is concerned about the thoroughness of archaeological field testing, but concurs with the NRHP-eligibility determinations for historic resources. FHWA will reserve its determination on the project until it receives a response to the above comments.

Meanwhile, the CRAS will be sent to SHPO via shuttle today for concurrent review. Please cc SHPO on FDOT responses to the above comments. SHPO needs to refrain from concurrence or lack of until FHWA has made its determination.

#### Thanks.

Linda Anderson Environmental Protection Specialist Federal Highway Administration 545 John Knox Rd., Ste. 200 Tallahassee, FL 32303

P: 850-553-2226 F: 850-942-8308 From:

Kelley, Lynn

To:

Anderson, Linda (FHWA); Fusconi, Vincent

Subject:

FW: response to FHWA comments: CRAS for SR 9/I-95 from Stirling Road to North of Oakland Park Blvd., FM #

42980412201

Date:

Thursday, March 21, 2013 3:45:50 PM

Attachments:

FHWA comments response edited noon 3 14.docx

Hi Linda,

(In red ink)
I was wondering if the attached responses had answered your concerns. Let me know – thanks!

From: Kelley, Lynn

Sent: Wednesday, March 20, 2013 1:37 PM

**To:** Linda.Anderson@dot.gov

Cc: Fusconi, Vincent; Holzweiss, Ray; Broadwell, Ann L

Subject: FW: response to FHWA comments: CRAS for SR 9/I-95 from Stirling Road to North of Oakland

Park Blvd., FM # 42980412201

Linda, please see attached responses. Please let me know if this is helpful. Thank you!

1. Does this CRAS clear drainage facilities? Please note pond on plan sheet 8 in area of high site potential. Is this an existing pond or a planned pond? If planned, was it tested for archaeological resources in a previous CRAS? If not, why wasn't it tested during this CRAS? – Drainage facilities are not specifically addressed in the CRAS, but all planned drainage facilities for this project fall within the existing FDOT ROW. As such, any new drainage facilities would have fallen within the archaeological APE that was tested for the current project.

The pond on plan sheet 8 that is mentioned is an existing pond. The reference to this pond is only made in Appendix E – Shovel Test Maps. This appendix contains the plan maps overlain with the locations of excavated shovel tests and other notes that were taken during the field survey. The location of this existing pond was noted during the field survey to explain why no shovel testing was conducted there. This notation is not included anywhere else in the CRAS (for instance, in Appendix C).

2. FHWA's understanding of this project is that the outer edges of outer lanes will not move; instead, lanes will be added in the median. If this is the case, why was shovel testing done outside of lanes, especially in areas where FDOT ROW appears to be too narrow for ponds? – The outer edges of lanes will be moved throughout much of the corridor. It is only in the vicinity of North Woodlawn Cemetery that FDOT has made a commitment not to widen or conduct any ground disturbance beyond the edge of the existing pavement.

As with most projects, field testing and research conducted for this CRAS was conducted as multiple alternatives and engineering options were being considered. As such, the archaeological fieldwork was designed at the time to adequately test all possible alternatives, including widening past the edge of existing pavement. The initial results of the CRAS were provided to the FDOT design team as early as possible in order to help them design alternatives that avoid and minimize impacts on any potential cultural resources.

The recommended alternative proposes to widen I-95 on the outside in order to accommodate the new Express Lanes system in the median. However, at the vicinity of the North Woodlawn Cemetery, I-95 will be widened by approximately 6-ft toward the median to avoid impacting this resource. The existing edge outside edge of pavement will remain and the inside shoulder width will be reduced to accommodate the express and general purpose lanes with no impacts to the cemetery.

3. Per page 69, no shovel testing was done in areas of low archaeological probability. Per Roy Jackson, low probability zones should have a 100m testing interval with judgment

exercised as there are a number of acceptable reasons for not digging in low probability zones. Please test areas of low probability or provide a detailed explanation about why shovel testing is not appropriate in these areas. — The archaeological testing was perhaps not explained well enough in the CRAS report. A more detailed explanation is provided here.

A Research Design that included background research for this project, including initial zones of archaeological probability, was prepared and presented to FDOT before any field-testing was conducted. The initial Archaeological Site Potential Zones included in the Research Design were reformatted as Figures 9-1, 9-2, and 9-3 within the current CRAS report.

However, it should be noted that, because of the highly urbanized nature of the project corridor, the initial field reconnaissance and utility coordination revealed that very little of the project corridor was actually testable. This was due to a number of factors including the extensive modifications to the natural ground surface associated with the construction and subsequent modification of the Interstate and the presence of extensive buried utilities. Because of this, some portions of the project corridor that were initially evaluated as having high or moderate archaeological site potential were evaluated in the field as untestable. This was also true for all portions of the project corridor that were initially evaluated as having low archaeological site potential in the original Research Design.

The field crew did their best to include notes and take photographs that document why testing in large portions of the project corridor was not possible. Their notes are overlain on plan maps in Appendix E. Noted disturbances that precluded archaeological testing includes existing ponds, berms, buried utilities, etc.

20623

## Florida Department of Transportation

RICK SCOTT GOVERNOR

3400 W. Commercial Blvd. Fort Lauderdale, FL 33309

ANANTH PRASAD, P.E. SECRETARY

November 7, 2013

Mr. Luis Lopez U.S. Department of Transportation Federal Highway Administration 400 W. Washington Street, Room 4101 Orlando, FL 32801

Subject:

Request for Review

Cultural Resources Assessment Survey (CRAS)

SR-842/Broward Boulevard Bridge Replacement Project

Financial Management #: 429958-1-32-01

Broward County, Florida

Dear Mr. Lopez:

The Florida Department of Transportation, District 4, is currently designing a project which will involve the replacement of both the eastbound and westbound bridges (860063 & 860284) on SR-842/Broward Boulevard in the City of Fort Lauderdale. The project also involves drainage improvements, new signalization and lighting, and minor right-of-way acquisition to facilitate driveway connections and transitions. The Class of Action for this project is Minor Categorical Exclusion (MiCE).

The purpose of the CRAS was to identify any significant cultural resources such that they can be avoided as the project proceeds. The Area of Potential Effect (APE) for historic resources included all parcels immediately adjacent to the proposed improvements. The survey resulted in the identification of one previously recorded historic resource (Sailboat Bend Historic District [8BD4428]) and two newly recorded historic resources (1701 W. Broward Boulevard [8BD4997] and 1500 W. Broward Boulevard [8BD4998]) within the project APE. Both of the historic structures are considered ineligible for inclusion in the National Register on an individual basis, as they have common, simple styles and no significant historical associations. There is currently insufficient information with which to make a determination on the National Register–eligibility of the Sailboat Bend Historic District (8BD4428). Only a small portion of the district consisting of two non-historic commercial buildings and 1500 W. Broward Boulevard (8BD4998) are located within the project APE. It should be noted that 1500 W. Broward Boulevard would likely be considered a contributing resource to the district if the district is ever found to be National Register–eligible in the future. A complete survey of this entire district is beyond the scope of the current project. It should also be noted that the two highway bridges were found to be non-historic based on the field reconnaissance.

Cultural Resources Assessment Survey Broward Boulevard Bridge Replacement FM 429958.1

The FMSF search and literature review identified two archaeological sites (8BD2906 and 8BD2915) located within parcels adjacent to the project APE. No newly recorded archaeological sites were identified within the boundaries of the project APE. Eighteen (18) shovel tests were advanced; however no cultural material was identified.

Based on the results of this survey, FDOT has determined that the proposed improvements will not have an adverse effect on any sites or properties that have historical, cultural of sacred significance or that otherwise meet the minimum criteria for listing in the NR. FDOT requests concurrence with this determination.

Please complete the signature block below and forward the additional report copy to SHPO. If you have questions regarding the subject project, please contact me at 954-777-4325, or Lynn Kelley at 954-777-4334.

Sincerely,

Ann Broadwell

Environmental Administrator

FDOT - District 4

Enclosures

Cc:

Sabrina Aubery- District Four

Project File

Cultural Resources Assessment Survey
Broward Boulevard Bridge Replacement
FM 429958.1

The FHWA finds the attached Cultural Resources Assessment Report complete and sufficient and
approves / \_\_\_ does not approve the above recommendations and findings.

The FHWA requests the SHPO's opinion on the sufficiency of the attached report and the SHPO's opinion on the recommendations and findings contained in this cover letter and in the comment block below.

FHWA Comments:

David C. Hawk
Acting Division Administrator
Florida and Puerto Rico Divisions

72-19-2013 Date

Federal Highway Administration


The Florida State Historic Preservation Officer finds the attached Cultural Resources Assessment Report complete and sufficient and concurs with the recommendations and findings provided in this cover letter for SHPO/DHR Project File Number 2013-5669


Robert F. Bendus, Director Division of Historical Resources

and State Historic Preservation Officer

Date


## **Appendix C | Field Conditions**





Boulevard Interchange PD&E Study (FP ID No.: 435513-1, ETDM No. 14226)

Historic Cemetery






**Field Conditions** 


Boulevard Interchange PD&E Study (FP ID No.: 435513-1, ETDM No. 14226)


Fort Lauderdale Archaeological Zone

Historic Cemetery



2









**Field Conditions** 

Boulevard Interchange PD&E Study (FP ID No.: 435513-1, ETDM No. 14226)

Fort Lauderdale Archaeological Zone

Historic Cemetery





# Appendix D | Survey Log

Ent D (FMSF only)



## **Survey Log Sheet**

Florida Master Site File Version 4.1 1/07 Survey # (FMSF only)

Consult Guide to the Survey Log Sheet for detailed instructions.

	lden	tification an	d Bibliographic In	formation	
<b>S</b> urvey Project (name an	d project phase)CRAS_I	[-95 at Bro	oward Boulevard	Interchange	
Report Title (exactly as o	n title page) Cultural	Resource	Assessment Surv	rey Project Develo	pment & Environment
	/SR 9 at SR 842/Br				
	·				
Report Authors (as on tit	le page, last names first)	1. Janus Re	esearch	3.	
Publication Date (year)	2017 <b>Total N</b>	lumber of Pag	ges in Report (count t	text, figures, tables, not site	e forms) 134
					e the style of <i>American Antiquity</i> .)
Janus Research, 1	107 N. Ward Street	, Tampa FI	33607		
	rk (even if same as author)				rer
Affiliation of Fieldwork	ers: Organization Janus	Research		City _ T	ampa
•	n't use county name, or comm				
<b>1.</b> I-95	3. Broward Bo	oulevard	5	7	
2. SR 9	4. SR 842		6 <b>.</b>	8	
	ation, government unit, orga				
Name		•	, ,	orida Dept of Transporta	tion - District 4
Address/Phone/E-mail	3400 West Commerc				
Recorder of Log Sheet					Completed 10-5-2017
	a continuation of a prev				·
to time our voy or project	a continuation of a pro-	nous projecti	<u>⊡</u> 1100.	Troviduo darvoy "o (Fivie	
			Mapping		
			11 3		
	which field survey was done		· ·		
1. Broward	3. 4.			5	
2	4.			6	
HCCC 1:24 DOD Man N	ames/Year of Latest Rev	icion lettech e	dditional about if naces	2011	
•				•	V
1. Name FORT LAUDERS		Year_ 1983			
2. Name FORT LAUDERS	PALE SOUTH	Year_ 1983			Year
3. Name		Year	6. Name		Year
		Descript	tion of Survey Are	a	
Dates for Fieldwork: S	Start a se sold End	9-27-2017	Total Area Sur	rveved (fill in ana)	hectares 102 acres
	cts or Areas Surveyed		_ TOTAL ALGA SUI	voyeu (iiii iii olle)	
If Corridor (fill in one for a	' -		foot Lone	gth: kilometers	miles
II CUITIUUI (IIII III OIIE TOP E	acii) <b>vv</b> iutilII	neters	feet $oldsymbol{L}$ enį	yınkilonleters	

	Resear	ch and Field Me	thods		
Types of Survey (check all that apply):	⊠archaeological □damage assessment	⊠architectural □monitoring repor	☐historical/	_	underwater
Scope/Intensity/Procedures Pede	estrian survey for	archaeology;	survey and	documentat	ion for historic
resources.					
Preliminary Methods (check as many a	as apply to the project as a v	whole)			
	□library research- <i>local public</i>		local property or tax	records $\square$	other historic maps
	library-special collection - <i>non</i>		newspaper files		soils maps or data
	▼Public Lands Survey (maps at		literature search		windshield survey
	local informant(s)		Sanborn Insurance m	iaps 🔀	aerial photography
▼other (describe): Janus Library					
Archaeological Methods (check as ma	any as apply to the project as	s a whole)			
Check here if <b>NO</b> archaeological metho					
surface collection, controlled	shovel test-o	ther screen size		□block excavatio	n (at least 2x2 m)
surface collection, <u>un</u> controlled	water screen			soil resistivity	
☐ shovel test-1/4"screen ☐ shovel test-1/8" screen	posthole test	S		□magnetometer □side scan sonar	
shovel test 1/16" screen	□auger tests □coring			⊠pedestrian surve	av
shovel test-unscreened		ion (at least 1x2 m)		□unknown	·1
other (describe):	_			_	
Historical/Architectural Methods (cl  Check here if NO historical/architectural building permits commercial permits interior documentation  other (describe): aerial photogra	al methods were used.  demolition permits exposed ground inspected local property records		neighbor interview occupant interview occupation permits		□subdivision maps ☑tax records □unknown
	Survey Results	(cultural resour	rces recorded)		
Site Significance Evaluated? ⊠Yo	es □No				
Count of Previously Recorded Sites	1	Count of Newly	<b>Recorded Sites</b>	48	
Previously Recorded Site #'s with S	ite File Update Forms (List	site #'s without "8"	'. Attach additiona	l pages if necess	ary.) BD3414
Newly Recorded Site #'s (Are all orig	inals and not updates? List s	site #'s without "8".	Attach additional <sub>I</sub>	pages if necessar	y.) BD6298-BD6344, BD6347
Site Forms Used: ☐ Site File Pa	per Form 🗵 Site File	Electronic Recordi	ng Form		
***REQUIRED: ATTACH PLOT OF SURVEY AREA ON PHOTOCOPY OF USGS 1:24,000 MAP(S)***					
SHPO USE ONLY	SI	HPO USE ONLY	<u>′</u>		SHPO USE ONLY
Origin of Report: □872 □CARL □Grant Project #	]UW	☐Compliance Rev	Academic iew: CRAT #	□Contract □	Avocational
Type of Document:		al Survey	Survey □Cell To □Structure Detailed		nitoring Report rry, Hist. or Archival Doc

**P**lotability:

**D**ocument Destination:

